

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 23 July 2018 5:15 PM
To: 'Yeong Siew Lien'
Cc: "SUR"
Subject: RE: WC 6725P OD (CTI)

Dear Annie,

As instructed by our client, please proceed at repair cost not exceeding \$35,000.00 (inclusive supplementary) to repair the insured vehicle WC 6725P (Excess \$ 1,500/-) on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Monday, 23 July 2018 4:58 PM

To: 'Yeong Siew Lien' <slmoter@yahoo.com.sg>

Cc: "SUR" <sur@lkkauto.com>

Subject: RE: WC 6725P OD (CTI)

Dear Annie,

As instructed by our client, please proceed to repair the insured vehicle WC 6725P (Excess \$ 1,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeong Siew Lien [mailto:slmoter@yahoo.com.sg]

Sent: Thursday, 19 July 2018 10:24 AM

To: slmoter@yahoo.com.sg; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: "SUR" <sur@lkkauto.com>

Subject: Re: WC 6725P OD (CTI)

Dear Shirley,

As Spoken, Please confirm acceptance to the final cost of repair@Lump sum \$35,000.00 (before \$1,500.00 of excess & no GST). Thanks you.

Best Regards,

Annie Yeong

Fook Heng Motor Service

On Thu, 19/7/18, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Subject: WC 6725P OD (CTI)

To: slmoter@yahoo.com.sg

Cc: ""SUR"" <sur@lkkauto.com>

Date: Thursday, 19 July, 2018, 9:35 AM

Dear

Annie,

As spoken, Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 32,000.00

. Thank you. Best Regards, Shirley Hiew | Case Handler LKK Auto Consultants Pte Ltd Phone:

6256-3561 | email: Sur@lkkauto.com |

fax: 6256-4315 Blk 51, Paya Ubi

Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)