

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0838/2018
DATE : 06-JUL-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : LOW MOH KHONG
ADDRESS : APT BLK 824 YISHUN STREET 81
#06-592
S(760824)
TELEPHONE NO : 96215483

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100428538
VEHICLE NO : SKV3249J
MODEL CODE : SJ5CK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB201781452(5Y100K)
CHASSIS NO : JF1SJ5KC5FG056079
MILEAGE : 1 KM
DATE IN : 06/07/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 03/07/2018

Print Date : 06/07/2018
Print Time : 18:24:58

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV3249J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SLQ1247S - AXA		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION:YISHUN AVENUE 2 DATE:03/07/2018 TIME:1845HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND PANEL	1680.00	2801
4	ZZ/003	RESPRAY REAR BUMPER AND PANEL	1260.00	4201
5	ZZ/004	TO SUPPLY & INSTALL REVERSE SENSOR-2 EYES	300.00	?
6	ZZ/005	SUNDRIES	100.00	201
TOTAL LABOUR CHARGES			3340.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV3249J

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
1 REAR BUMPER ASSY	57704SG012	<i>Ad</i> 540.00	<i>✓</i>		
2 BRKT CORNER R RH	57707SG060	<i>Sn</i> 18.00	<i>X</i>		
3 BRKT CORNER R LH	57707SG070	<i>Sn</i> 18.00	<i>X</i>		
4 BRKT SD R RH	57707SG080	<i>Sn</i> 14.40	<i>X</i>		
5 BRKT SD R LH	57707SG090	<i>Sn</i> 14.40	<i>X</i>		
6 BEAM COMPL R EU	57711SG0219P	288.00	<i>7</i>		
7 CARGO STEP PANEL S/S	E7710SG000	<i>DU</i> 460.00	<i>✓</i>		
SUB TOTAL		1352.80	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		270.56	0.00	0.00	0.00
GRAND TOTAL		1082.24	0.00	0.00	0.00
OVERALL TOTAL		1082.24			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKV3249J

TOTAL LABOUR CHARGES	3340.00
TOTAL SPARE PARTS CHARGES	1082.24
GRAND TOTAL	4422.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Not Authorized
Respray B4 paint
2 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: