

Surveyor:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$5

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(YES / NO)

Nature of Accident:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

50

(Agreed / Assessed) BOLA S/N No.: NIL.

Repair Cost:

\$5

1193.68

Loss of Rental (LOR):

\$5

225.00

(

3

days)

x \$150

Loss of Use (LOU):

\$5

-

(\$

x

days)

Loss of Income (LOI):

\$5

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5

7.45

Medical:

\$5

-

Disbursement:

\$5

-

(e.g. Tow/ Independent)

Legal Cost:

\$5

-

Total:

\$5

1426.13

Global Sum \$5:

1426.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

1426.00

Name 1:

Lim Yew Boon Spray Paint Co.

Payee 2: (Strike if N.A.)

\$5

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$5

-

Name 3:

-

LKK:

IDAC:

Bernard

cc 4, AG 180 12525, Kpa3

10-7-18

10-7-18

10-7-18

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

SLF 3422Y

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

06396813256

2004 79754

mazda 3

C/P 279 @ Rishan ST 24

HP:

D.O.A:

3066018

(YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

Em 56 L

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

LX8.

ASS. REC. BY:

REF: A/G/

12528/119 10

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 ~~04~~ days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: EM 56L Yr Regn: 07.12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Conq Hybrid c.c. 2494

Colour: M. Conq A/C: Insured / Std / NI / NA

Sp. Reading: 220817 T/Radio: Insured / Std / NI / NA

Eng/No: NR053CK5004002272

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/50 ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

1-kan Koda

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 30/6/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 20/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S IN

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/8 File pass to Catherine

PIP \$ 2387.35 (Reel \$ 1657.40 / 419.1)

Data/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Data/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHERIDAN WAY #07-16
 CHARTER BUILDING SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP18/043

Date : 02/08/2018

Vehicle Num. : EM 56L

Make/Model : TOYOTA CAMRY HYBRID CVT-2012

Chassis/Eng# : MR053CK5004002272/2AR0580170

Accident Date : 30/06/2018

Claim No. :

Reference : LYB/EM56L/AIG/tp/sl

Policy No. :

Not wither

Automy 84 paint

3 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

82381.35

LIST ITEMS :

1. REAR BUMPER
2. REAR BUMPER RETAINER
3. REAR BUMPER BRACKET
4. REAR BUMPER REFLECTOR/LH
5. REAR TAILLAMP/LH
6. REAR TAILLAMP LOWER PANEL/LH
7. REAR REVERSE SENSOR

List Total S\$:

25.00% Discount S\$:

<i>also</i>	<i>CM</i>	901.80	<i>✓</i>
86.70		173.40	<i>✓</i>
121.80	<i>R</i>	243.60	<i>X</i>
	<i>in</i>	81.40	<i>X</i>
	<i>CM</i>	421.30	<i>✓</i>
	<i>R</i>	128.10	<i>X</i>
271.70	<i>in</i>	543.40	<i>X</i>
		2,493.00	
		623.25	
		1,869.75	

LABOUR :

TO CHECK REAR WIRING FUNCTION

206
35.00

TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS

✓ 120.00 *X*

TO CHECK WATER SEEPAGE

✓ 60.00 *X*

TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS

60.00 *✓*

TO REPAIR PANEL BEAT ON LEFT REAR FENDER, INNER PANEL,
 TO RE-ALIGN ON REAR AFFECTED BOOT LID & LABOUR TO

CONTINUE / ...

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 178, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Bus Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHERIDAN WAY #07-16
 CHARLES BUILDING SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP18/043

Date : 02/08/2018
 Vehicle Num. : EM 56L
 Make/Model : TOYOTA CAMRY HYBRID CVT-2012
 Chassis/Eng# : MR053CK5004002272/2AR0680170
 Accident Date : 30/06/2018
 Claim No. :
 Reference : LYB/EM56L/AIG/tp/si
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REPLACE ABOVE PARTS		<i>900</i> 900.00
		TO PUTTY, PRIMER & SPRAY PAINT ON LEFT REAR FENDER, INNER PANEL, REAR BUMPER, REVERSE SENSOR & TOUCH UP ON REAR AFFECTED BOOT LID USING 2K PAINT		<i>650</i> 1,000.00
		Labour Total S\$:		2,175.00

E. & O.E.

Total S\$: 4,044.75



for LIM YEW BOO SPRAY PAINT CO.

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department
 Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP18/043

Date : 02/08/2018
 Vehicle Num. : EM 56L
 Make/Model : TOYOTA CAMRY HYBRID CVT-2012
 Chassis/Eng# : MR053CK5004002272/2AR0680170
 Accident Date : 30/06/2018
 Claim No. :
 Reference : LYB/EM56L/AIG/tp/sl
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

- LIST ITEMS :
1. 1 REAR BUMPER
 2. 2 REAR BUMPER RETAINER
 3. 2 REAR BUMPER BRACKET
 4. 1 REAR BUMPER REFLECTOR/LH
 5. 1 REAR TAILLAMP/LH
 6. 1 REAR TAILLAMP LOWER PANEL/LH
 7. 2 REAR REVERSE SENSOR

List TotalS\$:
 25.00% Discount S\$:

- LABOUR :
- TO CHECK REAR WIRING FUNCTION
 - TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS
 - TO CHECK WATER SEEPAGE
 - TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS

TO REPAIR PANEL BEAT ON LEFT REAR FENDER, INNER PANEL,
 TO RE-ALIGN ON REAR AFFECTED BOOT LID & LABOUR TO

also oil CM 901.80 ✓
 86.70 173.40 ✓
 121.80 243.60 X
 CM 81.40 X
 CM 421.30 ✓
 128.10 ✓
 271.70 543.40 ✓
 2,493.00
 623.25
 1,869.75

206
 35.00

120.00 X

60.00 X

60.00 ✓

CONTINUE / ...

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department
 Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP18/043

Date : 02/08/2018
 Vehicle Num. : EM 56L
 Make/Model : TOYOTA CAMRY HYBRID CVT-2012
 Chassis/Eng# : MR053CK5004002272/2AR0680170
 Accident Date : 30/06/2018
 Claim No. :
 Reference : LYB/EM56L/AIG/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REPLACE ABOVE PARTS	1550 900.00	600
		TO PUTTY, PRIMER & SPRAY PAINT ON LEFT REAR FENDER, INNER PANEL, REAR BUMPER, REVERSE SENSOR & TOUCH UP ON REAR AFFECTED BOOT LID USING 2K PAINT	500 1,000.00	500
		Labour Total S\$:	2,175.00	650.

E. & O.E.

Total S\$: 4,044.75



for LIM YEW BOO SPRAY PAINT CO.

Hsiao Tong (LKKAUTO)

From: Lee, Ming-Yao <MingYao.Lee@aig.com>
Sent: Tuesday, 31 July 2018 9:46 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: <Seek Instruction> Your Ref: 8012364441SG *Our Ref: CC4/AIG18012525/pa3 [ACCIDENT INVOLVING SLF 3422Y(OI) AND EM 56L(TP) ON 30/06/2018]

Hi Hsiao Tong,

Agreed with your view. Since insured's driver has stated the same as concurred with scene photos provided by third party. Closest scenario should be BOLA S24(a). 50/50 is fair.

You may proceed to handle the claim as proposed. Please do update us if any.

Thanks & Best Regards,
George Lee
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1769 | Fax +(65) 6835 7416

Ming-Yao.Lee@aig.com | www.aig.com.sg

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: 30 July 2018 16:55
To: Lee, Ming-Yao
Subject: <Seek Instruction> Your Ref: 8012364441SG *Our Ref: CC4/AIG18012525/pa3 [ACCIDENT INVOLVING SLF 3422Y(OI) AND EM 56L(TP) ON 30/06/2018]

Your Ref: **8012364441SG**
Our Ref: CC4/AIG18012525/pa3

Dear Sirs,

ACCIDENT INVOLVING SLF 3422Y(OI) AND EM 56L(TP) ON 30/06/2018

We refer to the above matter.

Third party reported that he was making a 3 pint turn(reverse), suddenly OI drove out from the handicap lot and both cars collided.

Our insured reported that he stopped beside the handicap lot to attend a urgent phone message. After that, he engaged driving gear to do a 3 point turn. He started to move forward and next thing he know is third party had collided onto his car.

We have contacted OID, Mr Koh to verify the nature of accident. He said that he was moving forward while third party reversed and both vehicles collided onto each other. OID agreed to let insurance to handle the matter.

Based on both parties report & circumstances of the accident, we would like to propose 50/50 as both parties should exercise caution (1 vehicle is moving out from stationary & the other was reversing).

Kindly let us have your comments/instruction in order for us to proceed further.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 30 July 2018 4:55 PM
To: Lee, Ming Yao (MingYao.Lee@aig.com)
Subject: <Seek Instruction> Your Ref: 8012364441SG *Our Ref: CC4/AIG18012525/pa3
[ACCIDENT INVOLVING SLF 3422Y(OI) AND EM 56L(TP) ON 30/06/2018]

Your Ref: **8012364441SG**
Our Ref: CC4/AIG18012525/pa3

Dear Sirs,

ACCIDENT INVOLVING SLF 3422Y(OI) AND EM 56L(TP) ON 30/06/2018

We refer to the above matter.

Third party reported that he was making a 3 pint turn(reverse), suddenly OI drove out from the handicap lot and both cars collided.

Our insured reported that he stopped beside the handicap lot to attend a urgent phone message. After that, he engaged driving gear to do a 3 point turn. He started to move forward and next thing he know is third party had collided onto his car.

We have contacted OID, Mr Koh to verify the nature of accident. He said that he was moving forward while third party reversed and both vehicles collided onto each other. OID agreed to let insurance to handle the matter.

Based on both parties report & circumstances of the accident, we would like to propose 50/50 as both parties should exercise caution (1 vehicle is moving out from stationary & the other was reversing).

Kindly let us have your comments/instruction in order for us to proceed further.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 13 August 2018 3:40 PM
To: 'Serene LIM'
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Without Prejudice

Hi Serene,

We refer to the above matter.

Based on all the available information on hand, we are of the view both parties should exercise caution on this matter.

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation and not jeopardizing our insured claim against the liable party, we are prepared to offer 50% towards your client's claim.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene LIM <serene@autocare.com.sg>
Sent: Wednesday, 1 August 2018 5:57 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Hi

Pls revert asap

Thank you & Regards
Serene LIM

Hsiao Tong (LKKAUTO)

From: Serene LIM <serene@autocare.com.sg>
Sent: Thursday, 27 September 2018 3:57 PM
To: Hsiao Tong (LKKAUTO)
Subject: Fw: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018
Attachments: ATA.pdf; Final Bill.pdf; LTA receipt-20180703-124349.pdf; Rental Agreement.pdf

Hi Hsiao Tong

Can confirm below asap

Regards
Serene@LYB

From: Serene LIM
Sent: Thursday, September 20, 2018 10:35 AM
To: Hsiao Tong
Subject: Fw: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Hi Hsiao Tong

Kindly revert below quantification

Thank you

Thank you & Regards
Serene LIM
Lim Yew Boo Spray Paint Co
Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332
E-mail: serene@autocare.com.sg

From: Serene LIM
Sent: Thursday, September 13, 2018 5:12 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Hi Hsiao Tong

We are quantifying the below

RC \$2387.20 ³⁵
COR \$540
LTA \$7.45
Total \$2934.65

Pls revert, Thanks

Thank you & Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332

E-mail: serene@autocare.com.sg

From: Hsiao Tong (LKKAuto)

Sent: Monday, August 13, 2018 3:40 PM

To: Serene LIM

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Without Prejudice

Hi Serene,

We refer to the above matter.

Based on all the available information on hand, we are of the view both parties should exercise caution on this matter.

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation and not jeopardizing our insured claim against the liable party, we are prepared to offer 50% towards your client's claim.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene LIM <serene@autocare.com.sg>

Sent: Wednesday, 1 August 2018 5:57 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Hi

Pls revert asap

Thank you & Regards
Serene LIM
Lim Yew Boo Spray Paint Co
Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332
E-mail: serene@autocare.com.sg

From: Hsiao Tong (LKKAuto)
Sent: Friday, July 13, 2018 5:30 PM
To: <mailto:serene@autocare.com.sg>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Without Prejudice

Hi Serene,

We refer to the above matter.

Liability is unclear at this moment.

We are in the midst of verifying the accident circumstances with our insured and get back to you asap.

Kindly bear with us for time being.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene LIM [<mailto:serene@autocare.com.sg>]
Sent: Wednesday, 11 July 2018 2:08 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: Fw: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Hi Hsiao Tong

We spoke, pls assist urgently on this case as AIG had delay our survey assignment as your Ms Catherine had aware too.

Thank you & Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332

E-mail: serene@autocare.com.sg

From: Serene LIM

Sent: Monday, July 09, 2018 4:41 PM

To: Mithoosingh, Aashweenjeetkaur

Cc: Tan, Lily (AIG) ; Fong, Andy-SY ; Kaur, Baljit ; Chin, Lee-Ying ; Abu Kassim, Noor Mariesa ; Md Ishak, Mohd Imran ; Lim, Sheng Yang ; Supramaniam, Darshene ; Azlan, Syazairdina ; Fan, Winnie-LW ; Chan, Yoke Shi

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Hi Aashweenjeet Kaur (Aashween)

We had replied on [5/7/2018@1103am](#) and also today at [9/7/2018@10.30am](#) to assigned LKK to contact us asap

Attached both email record

Appreciate if you could assign LKK to contact us without any delay.

Thank you & Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332

E-mail: serene@autocare.com.sg

From: Mithoosingh, Aashweenjeetkaur

Sent: Monday, July 09, 2018 4:25 PM

To: serene@autocare.com.sg

Cc: Tan, Lily (AIG) ; Fong, Andy-SY ; Kaur, Baljit ; Chin, Lee-Ying ; Abu Kassim, Noor Mariesa ; Md Ishak, Mohd Imran ; Lim, Sheng Yang ; Supramaniam, Darshene ; Azlan, Syazairdina ; Fan, Winnie-LW ; Chan, Yoke Shi

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Without Prejudice

Your Reference : EM56L

Our Reference : SLF3422Y

Dear Sir/Madam,

We refer to our email below. We have not receive your reply within stipulated period.

Pursuant to Appendix C of Pre-Action Protocol for NIMA cases, citation 2.4. We will proceed to appoint our in house surveyor for the pre-repair inspection.

Thanks & Regards,

Aashweenjeet Kaur (Aashween)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1002215
aashweenjeetkaur.mithoosingh@aig.com | www.aig.com

IMPORTANT NOTICE

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Mithoosingh, Aashweenjeetkaur
Sent: Monday, July 09, 2018 9:57 AM
To: serene@autocare.com.sg
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Azlan, Syazairdina; Fan, Winnie-LW; Chan, Yoke Shi
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Dear Sir/Madam,

Reminder for pre-repair survey.

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thanks & Regards,

Aashweenjeet Kaur (Aashween)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1002215
aashweenjeetkaur.mithoosingh@aig.com | www.aig.com

IMPORTANT NOTICE

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Mithoosingh, Aashweenjeetkaur
Sent: Friday, July 06, 2018 5:03 PM
To: serene@autocare.com.sg
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Azlan, Syazairdina; Fan, Winnie-LW; Chan, Yoke Shi
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Dear Sir/Madam,

Reminder for pre-repair survey.

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thanks & Regards,

Aashweenjeet Kaur (Aashween)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1002215

aashweenjeetkaur.mithoosingh@aig.com | www.aig.com

IMPORTANT NOTICE

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Chan, Yoke Shi

Sent: Thursday, July 05, 2018 10:33 AM

To: serene@autocare.com.sg

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Fan, Winnie-LW

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Without Prejudice

Your Reference : EM56L

Our Reference : SLF3422Y

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd

Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Serene LIM [<mailto:serene@autocare.com.sg>]

Sent: Tuesday, July 03, 2018 12:51 PM

To: AIG SGP, Claims-Survey

Subject: PRI : EM56L & SLF3422Y ALONG OPEN CARPARK AT BLK 279 BISHAN STREET 24 ON 30/6/2018

To : Motor Claims Dept (Arrangement of Surveyor Unit)

RE: NOTICE TO THIRD PARTY INSURERS TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKINGS DAY PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIN-INJURY MOTOR ACCIDENT CLAIMS (NIMA)

ACCIDENT INVOLVING EM56L & SLF3422Y ALONG OPEN CARPARK AT BLK 279 BISHAN STREET 24 ON 30/6/2018

We are the repairer for M/s Chuan Lim Constn Pte Ltd the owner of vehicle no. EM56L.

Please be informed that the said vehicle can be inspected at the following venue:

Lim Yew Boo Spray Paint Co

Blk 10 Sin Ming Industrial Estate #01-10 Singapore 575645

Tel: 64534177 Fax: 64593724 Email: serene@autocare.com.sg

Contact Person: Serene Lim Hp : +65 96852332

Please also provide us a list of 10 surveyors as your nominated SJE (Single Joint Expert)

PLEASE ARRANGE OFFICER-IN-CHARGE TO LET US KNOW ASAP IF WE COULD DO DIRECT SETTLEMENT FOR THIS CASE

I/ We enclosed herewith a copy of our client **SAS Statement** for your reference. Looking forward to your kind assistance and co-operative in this matter.

Please note that if you fail to conduct the pre-repair inspection within the next 2 days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you

Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Direct : +65 64545011

Mobile : +65 96852332

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 8 October 2018 12:41 PM
To: 'Serene LIM'
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Without Prejudice

Hi Serene,

We refer to your below email.

We propose settlement at a global sum of **\$1,420.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene LIM <serene@autocare.com.sg>
Sent: Monday, 8 October 2018 12:20 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Fw: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Hi Hsiao Tong

Pls confirm

Thank you & Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332

E-mail: serene@autocare.com.sg

From: Serene LIM

Hsiao Tong (LKKAUTO)

From: Serene LIM <serene@autocare.com.sg>
Sent: Monday, 8 October 2018 12:54 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

confirmed, pls fwd DV

From: Hsiao Tong (LKKAUTO)
Sent: Monday, October 08, 2018 12:41 PM
To: Serene LIM
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Without Prejudice

Hi Serene,

We refer to your below email.

We propose settlement at a global sum of \$1,420.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene LIM <serene@autocare.com.sg>
Sent: Monday, 8 October 2018 12:20 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Fw: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3422Y AND EM56L ON 30/06/2018

Hi Hsiao Tong

Pls confirm

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 1 August 2018 11:12 AM
To: 'cindykoh@thewritestuff.com.sg'; 'saychk@gmail.com'
Subject: ACCIDENT INVOLVING SLF 3422Y AND EM 56L ON 30/06/2018 AT CARPARK 279 @ BISHAN ST 24
Attachments: Scene Photos from EM56L.pdf

01 Aug 2018

YOUR REF : SLF 3422Y
OUR REF : CC4/AIG18012525/pa3

Dear Ms Koh Yean Leng Cindy/ Mr Koh Say Chong,

ACCIDENT INVOLVING SLF 3422Y AND EM 56L ON 30/06/2018 AT CARPARK 279 @ BISHAN ST 24

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from EM 56L against your insurance policy.

Based on both parties report & circumstances of the accident, we are of the view that both parties should exercise caution (1 vehicle is moving out from stationary & the other was reversing) on the matter. There is certainly a portion of liability on us. Therefore, our opinion is that the case most likely would be settled at equal liability.

If you feel strongly against our settlement offer to the third party, kindly let us have them in writing within the next **10 days** i.e. by 11/08/2018, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, CHUAN LIM CONSTRUCTION PTE LTD (the third party claimant")
of BLK 447 BRIGHT HILL DRIVE #08-117 SPORE 570447 (address), owner
of EM56L (vehicle no.) hereby authorize LIM YEW BOO SPRAY PAINT CO ("the workshop")
to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for
my vehicle no EM56L that was damaged pursuant to the accident which occurred
on 30/06/2018 (date) along CARPARL AT BLK 279 BISHAN STREET 24 (location)
involving vehicle no/s SLF3422Y ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 30 (day) of 06 (month) 20 18 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, LIM YEW BOO SPRAY PAINT CO ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,420.00 (Global Sum) for vehicle no. EM 56L that was damaged pursuant to the accident which occurred on 30/06/2018 (date) along OPEN CARPARK AT BLK 279 BISHAN ST 24 involving vehicle no/s SLF 3422Y.

This is pursuant to the inspection conducted on 20/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHUAN LIM CONSTRUCTION PTE LTD ("the third party claimant") of vehicle no. EM 56L make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to EM 56L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of Oct (month) 2018 (year)



KCC
Signed by appointed surveyor



[Signature]
Signed by "the workshop" (with chop)



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
Tel: 6453 4177 Fax: 6459 3724
Email: limyewboo@singnet.com.sg
Company Reg. No. : 200514/001.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-18
CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department
Contact : 64191000 Fax No. : 64193727 Claims Dept

Final Repair Bill : TP18/043

Date : 13/09/2018
Vehicle Num. : EM 56L
Make/Model : TOYOTA CAMRY HYBRID CVT-2012
Chassis/Eng# : MR053CK5004002272/2AR0680170
Accident Date : 30/06/2018
Claim No. :
Reference : LYB/EM56L/AIG/tp/si
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	REAR BUMPER		901.80
3.	1	REAR BUMPER RETAINER		86.70
	1	REAR TAILLAMP/LH		421.30
		List Total S\$:		1,409.80
		25.00% Discount S\$:		352.45
				1,067.35
		LABOUR :		
		TO CHECK REAR WIRING FUNCTION		20.00
		TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS		60.00
		TO REPAIR,PANEL BEAT ON LEFT REAR FENDER, INNER PANEL, TO RE-ALIGN ON REAR AFFECTED BOOT LID & LABOUR TO REPLACE ABOVE PARTS		600.00
		TO PUTTY,PRIMER & SPRAY PAINT ON LEFT REAR FENDER,INNER PANEL, REAR BUMPER, REVERSE SENSOR & TOUCH UP ON REAR AFFECTED BOOT LID USING 2K PAINT		560.00
		Labour Total S\$:		1,330.00
		E & O.E.	Total S\$:	2,387.35

for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E & O. E.



NO: 0859

RENTAL AGREEMENT

Date: 20/8/18

Our Reference: 178/IM56L	Reg. Vch. No. SDV 8999C	Make / Model Toyota Wish	Capacity 1800cc
Date Out 20/8/18	Time Out 9.05am		
Date In 23/8/18	Time In 3.05pm		
KM Out	KM In		

Hirer's Name **Chuan Lim Construction Pte Ltd**
Hirer's Address **81K 447, Bright Hill Drive**
#08-117, S'5f0447

PETROL LEVEL

Out	E	1/4	1/2	3/4	F
In	E	1/4	1/2	3/4	F

Rates do not include Petrol
No refund will be given for petrol left in vehicle

Tel No. (Resident) (Office) (HP)

NIRC / Passport No. **S17294981** Nationality **Singaporean**

Driving Licence No. **11** Pass Date **2/11/88**

Date of Birth **30/1/65** Age

Driver's Name **Oh Chee Tiong**

Driver's Address **81K 447, Bright Hill Drive**
#08-117, S'5f0447

Tel No. (Resident) (Office) (HP)

NIRC / Passport No. **S17294981** Nationality **Singaporean**

Driving Licence No. **11** Pass Date **2/11/88**

Date of Birth **30/1/65** Age

CHARGES	S\$	Cts
3 Day(s) @ S\$ 180	540	
Week(s) @ S\$		
Month(s) @ S\$		
Insurance		
Additional Rental Payable		
Surcharge of Petrol		
Total	540	
Less Deposit (Cash/Cheque No)		
Balance Payable / Refundable		

Refund Received (Cash/Cheque No)

IMPORTANT NOTES : Restricted to Singapore use only. Hirer is liable to pay for the first S\$3500 excess under Insurance Policy in any accident plus loss of earnings while damaged vehicle in under repair. Vehicle return during office hour only. No service on Public Holiday and Sunday. Driver must be above 22 years and 2 year driving experience.

Refund Acknowledgement ☐ By Cash ☐ By Cheque

Received S By Hirer X

Computered By

Remarks

I / We have read and hereby agree to the terms and conditions on both sides of this rental agreement.


Hirer's Signature





BLK 10, SIN MING IND. EST., #01-10
SINGAPORE 575645
TEL : 6453 4177 FAX : 6459 3724

No. 0011

OFFICIAL RECEIPT

Date : 20.08.18

Received from : Chuan Lim Constn Pte Ltd

the sum of Dollars : Five Hundred & forty only

being payment of : Rent 1 unit of car for SDV 8999C from 20.08.18 – 23.08.18

- ☐ Cash \$ 540.00
- ☐ Cheq No. _____

CAR RENTAL 2000 PTE LTD



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 03 Jul 2018 / 12:43:49

Receipt Date/Time : 03 Jul 2018 / 12:43:38

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180703-001079

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLF3422Y				
As at 30 Jun 2018/17:00:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLF3422Y Enquiry Fee 20180703124208625239	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180703124309607 Direct Debit: eNETS Debit (Internet Banking)			7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018 Edit Reg		10 Jul 2018 00:00 Edit Adj Rpt	S\$2,387.35 Edit Estimates	S\$2,387.35 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Koh Yean Leng Cindy , ID: S1752779G, Tel: +6599999999									
Main Claimant: CHUAN LIM CONSTRUCTION PTE LTD , Co. Reg. No.: 199600684W									
Vehicle Reg. No.:	EM56L	Date of Loss:	30/06/2018 17:00 - :59 [71 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0639681132SG	Policy/Cover Note No.:	2100479754 (Comprehensive) Coverage: 23/08/2017 - 22/08/2018						
Vehicle Reg. No. (Insured):	SLF3422Y	Policy No. (Claimant):	17-MV005685-R01						
		Excess:							
Repairer:	Lim Yew Boo Spray Paint Co (HQ) Bldg 10 Sin Ming Industrial Estate, #01-10, 575645 Sin Ming - Tel: 96852332								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EM56L (0639681132SG)
[SLF3422Y]
TP
CHUAN LIM CONSTRUCTION PTE LTD
Jun 30 2018 5:00PM
[Koh Yean Leng Cindy]
Lim Yew Boo Spray Paint Co

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser																																																																																	
Letters/Correspondences																																																																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>No</th> <th>Finalized On</th> <th>LKK Auto Consultants Pte Ltd (HQ)</th> <th>Thumbnail</th> <th>Print</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>(Draft)</td> <td>Third Party Express Settlement - Payment Breakdown</td> <td></td> <td>Edit</td> </tr> </tbody> </table>			No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	<div>1 per page</div> <div><input checked="" type="checkbox"/></div>																																																																							
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print																																																																																
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit																																																																																
Photos/Images																																																																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>No</th> <th>Relabel/Reorder</th> <th>LKK Auto Consultants Pte Ltd (HQ)</th> <th>Thumbnail</th> <th>Print</th> </tr> </thead> <tbody> <tr><td>1</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>2</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>3</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>4</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>5</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>6</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>7</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>8</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>9</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>10</td><td>29/09/18 12:54</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>11</td><td>29/09/18 12:54</td><td>Odometer Reading</td><td></td><td>Load JPG</td></tr> <tr><td>12</td><td>29/09/18 12:54</td><td>Chassis Number</td><td></td><td>Load JPG</td></tr> <tr><td>13</td><td>29/09/18 12:54</td><td>Reinspection Photo</td><td></td><td>Load JPG</td></tr> <tr><td>14</td><td>29/09/18 12:54</td><td>Reinspection Photo</td><td></td><td>Load JPG</td></tr> <tr><td>15</td><td>29/09/18 12:54</td><td>Reinspection Photo</td><td></td><td>Load JPG</td></tr> </tbody> </table>			No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	1	29/09/18 12:54	General View		Load JPG	2	29/09/18 12:54	General View		Load JPG	3	29/09/18 12:54	General View		Load JPG	4	29/09/18 12:54	General View		Load JPG	5	29/09/18 12:54	General View		Load JPG	6	29/09/18 12:54	General View		Load JPG	7	29/09/18 12:54	General View		Load JPG	8	29/09/18 12:54	General View		Load JPG	9	29/09/18 12:54	General View		Load JPG	10	29/09/18 12:54	General View		Load JPG	11	29/09/18 12:54	Odometer Reading		Load JPG	12	29/09/18 12:54	Chassis Number		Load JPG	13	29/09/18 12:54	Reinspection Photo		Load JPG	14	29/09/18 12:54	Reinspection Photo		Load JPG	15	29/09/18 12:54	Reinspection Photo		Load JPG	<div>3 per page</div> <div><input checked="" type="checkbox"/></div>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print																																																																																
1	29/09/18 12:54	General View		Load JPG																																																																																
2	29/09/18 12:54	General View		Load JPG																																																																																
3	29/09/18 12:54	General View		Load JPG																																																																																
4	29/09/18 12:54	General View		Load JPG																																																																																
5	29/09/18 12:54	General View		Load JPG																																																																																
6	29/09/18 12:54	General View		Load JPG																																																																																
7	29/09/18 12:54	General View		Load JPG																																																																																
8	29/09/18 12:54	General View		Load JPG																																																																																
9	29/09/18 12:54	General View		Load JPG																																																																																
10	29/09/18 12:54	General View		Load JPG																																																																																
11	29/09/18 12:54	Odometer Reading		Load JPG																																																																																
12	29/09/18 12:54	Chassis Number		Load JPG																																																																																
13	29/09/18 12:54	Reinspection Photo		Load JPG																																																																																
14	29/09/18 12:54	Reinspection Photo		Load JPG																																																																																
15	29/09/18 12:54	Reinspection Photo		Load JPG																																																																																
Documentation																																																																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>No</th> <th>Relabel/Reorder</th> <th>LKK Auto Consultants Pte Ltd (HQ)</th> <th>Thumbnail</th> <th>Print</th> </tr> </thead> <tbody> <tr><td>1</td><td>10/07/18 15:33</td><td>ACKNOWLEDGEMENT EMAIL TO AIG DD 10.07.2018</td><td></td><td>Load PDF</td></tr> <tr><td>2</td><td>10/07/18 15:33</td><td>EMAIL FROM AIG DD 10.07.2018</td><td></td><td>Load PDF</td></tr> <tr><td>3</td><td>10/07/18 15:33</td><td>TP GIA REPORT</td><td></td><td>Load PDF</td></tr> <tr><td>4</td><td>10/07/18 15:33</td><td>LTA receipt</td><td></td><td>Load PDF</td></tr> <tr><td>5</td><td>30/07/18 16:49</td><td>TP SCENE PHOTOS</td><td></td><td>Load PDF</td></tr> <tr><td>6</td><td>21/08/18 22:06</td><td>TP ESTIMATE - MARKED</td><td></td><td>Load PDF</td></tr> <tr><td>7</td><td>16/10/18 11:19</td><td>WORKSHOP INVOICE</td><td></td><td>Load PDF</td></tr> <tr><td>8</td><td>16/10/18 11:19</td><td>AUTHORISATION TO ACT FORM</td><td></td><td>Load PDF</td></tr> <tr><td>9</td><td>16/10/18 11:19</td><td>Release Voucher</td><td></td><td>Load PDF</td></tr> <tr><td>10</td><td>16/10/18 11:19</td><td>RENTAL RECEIPT</td><td></td><td>Load PDF</td></tr> <tr><td>11</td><td>16/10/18 11:19</td><td>LETTER TO OI</td><td></td><td>Load PDF</td></tr> </tbody> </table>			No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	1	10/07/18 15:33	ACKNOWLEDGEMENT EMAIL TO AIG DD 10.07.2018		Load PDF	2	10/07/18 15:33	EMAIL FROM AIG DD 10.07.2018		Load PDF	3	10/07/18 15:33	TP GIA REPORT		Load PDF	4	10/07/18 15:33	LTA receipt		Load PDF	5	30/07/18 16:49	TP SCENE PHOTOS		Load PDF	6	21/08/18 22:06	TP ESTIMATE - MARKED		Load PDF	7	16/10/18 11:19	WORKSHOP INVOICE		Load PDF	8	16/10/18 11:19	AUTHORISATION TO ACT FORM		Load PDF	9	16/10/18 11:19	Release Voucher		Load PDF	10	16/10/18 11:19	RENTAL RECEIPT		Load PDF	11	16/10/18 11:19	LETTER TO OI		Load PDF	<div>1 per page</div> <div><input checked="" type="checkbox"/></div>																					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print																																																																																
1	10/07/18 15:33	ACKNOWLEDGEMENT EMAIL TO AIG DD 10.07.2018		Load PDF																																																																																
2	10/07/18 15:33	EMAIL FROM AIG DD 10.07.2018		Load PDF																																																																																
3	10/07/18 15:33	TP GIA REPORT		Load PDF																																																																																
4	10/07/18 15:33	LTA receipt		Load PDF																																																																																
5	30/07/18 16:49	TP SCENE PHOTOS		Load PDF																																																																																
6	21/08/18 22:06	TP ESTIMATE - MARKED		Load PDF																																																																																
7	16/10/18 11:19	WORKSHOP INVOICE		Load PDF																																																																																
8	16/10/18 11:19	AUTHORISATION TO ACT FORM		Load PDF																																																																																
9	16/10/18 11:19	Release Voucher		Load PDF																																																																																
10	16/10/18 11:19	RENTAL RECEIPT		Load PDF																																																																																
11	16/10/18 11:19	LETTER TO OI		Load PDF																																																																																
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>No</th> <th>Finalized On</th> <th>AIG Asia Pacific Insurance Pte. Ltd. (SG)</th> <th>Thumbnail</th> <th>Print</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11/07/18 14:23</td> <td>OI GIA REPORT</td> <td></td> <td>Load PDF</td> </tr> </tbody> </table>			No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	1	11/07/18 14:23	OI GIA REPORT		Load PDF																																																																								
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print																																																																																
1	11/07/18 14:23	OI GIA REPORT		Load PDF																																																																																

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF3422Y (Insd veh)	Model:	TOYOTA CAMRY 2.5 (A)
	EM56L (TP veh)		
Date of Accident:	30/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	4,044.75
Final Repair Cost	:	\$	1,420.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	3 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	1,420.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability 50 (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Lim Yew Boo Spray Paint Co.	:	\$ 1,420.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

16 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18012525/KPA3Q2

Date: 16/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100479754
Claimant Vehicle EM56L **Insured Vehicle No :** SLF3422Y
No :
 Date of Loss: 30/06/2018 Nature of Claim: TP Claim No: 0639681132SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EM56L**
 Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: 2AR0680170
 Reg. Date: 17/07/2012 (Man. Year: 2012) Chassis No: MR053CK5004002272
 Colour: Metallic Grey Odometer: 220617 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50Z R17 Rear Tyre Size: 225/50Z R17
 Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm
 Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,869.75	1,057.35	812.40	43.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,175.00	1,330.00	845.00	38.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,044.75	2,387.35	1,657.40	40.98
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
		(S\$) 2,837.35		
Liabe Amount (50.00%) (S\$)		1,418.68		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,426.13		
Global Sum Settlement (S\$)		1,420.00		

INSPECTION

Date of Assignment: 10/07/2018
 Date Inspected: 20/08/2018 Inspected At: Lim Yew Boo Spray Paint Co (HQ)
 Blk 10 Sin Ming Industrial Estate, #01-10
 Singapore 575645
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	901.80 FL	*901.80 FL
2	1		*REAR BUMPER RETAINER	N/S Distorted	173.40 FL	*86.70 FL
3	2		*REAR BUMPER BRACKET	Repair	243.60 FL	*- FL
4	1		*REAR BUMPER REFLECTOR /LH	Serviceable	81.40 FL	*- FL
5	1		*REAR TAILLAMP /LH	Cracked	421.30 FL	*421.30 FL
6	1		*REAR TAILLAMP LOWER PANEL/LH	Repair	128.10 FL	*- FL
7	2		*REAR REVERSE SENSOR	Serviceable	543.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,493.00	1,409.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	623.25	352.45
Total Parts (\$\$)	1,869.75	1,057.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING FUNCTION	New	35.00	20.00
2	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	0.00
3	TO CHECK WATER SEEPAGE	New	60.00	0.00
4	TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS	New	60.00	60.00
5	TO REPAIR PANEL BEAT ON LEFT REAR FENDER ,INNER PANEL,TO RE-ALIGN ON REAR AFFECTED BOOT LID & LABOUR TO REPLACE ABOVE PARTS	New	900.00	600.00
6	TO PUTTY,PRIMER & SPRAY PAINT ON LEFT REAR FENDER ,INNER PANEL,REAR BUMPER,REVERSE SENSOR & TOUCH UP ON REAR AFFECTED BOOT LID USING 2K PAINT	New	1,000.00	650.00
Gross Labour Cost (\$\$)			2,175.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >