

ASS. REC. BY:

REF: CS/AGL18012543/Arb

Special Instruction:

Surveyor

Action

ASSIGNMENT (Office)

From (Person):

Julie

of

AGL

Date/Time:

10/7/2018 1:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SKP 9577D

Insured:

SKF 829P

at Workshop m/s

New Hock Teck

Tel:

6747 9244

of

Blk 1 Kaki Bukit Ave 6 401-43

Policy No.:

Claim No.:

C10001766 / JM

Sum Insured:

Excess:

Make of Veh.:

D.O.A.

09/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

10/7/2018 1:37pm

Person Contacted:

Subaji

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 9577D - NA / Ath17005652/h4

D.O.A.: 22/03/2017

SKF 829P - X

Confirm LIS \$5K, @ 6 days

Red: \$785135, 61%

REF:

ASS. REC. BY: Abrian King

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

/	
N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: **Yes** or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: **Yes** or No

Est. Repairs: \_\_\_\_\_ days Res.: **Yes** or No

Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKP9577D Yr Regn: 2014, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c 1598

Colour: White A/C: **Insured / Std / NI / NA**

Sp. Reading: 76149 T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: MROS3REH104518369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 10/07/18

Survey held at NHT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Budget Direct.</u>
	<u>MV: 63K</u>
	<u>PV: 51K</u>
	<u>Nett: 12K</u>

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 6

1) typist

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Add Fee:  : Site Insp (\$)

Transportation:

Report Format: TP

: Interview (\$)

\_\_\_\_ \$ + R5. \_\_\_\_ \$

Lump Sum / 1.5%: 5K

: Tech. Invs. (\$)

) Photos

: Weekend (\$)

) Others

TOTAL

**Catherine Chong (LKK Auto)**

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Tuesday, 10 July, 2018 12:37 PM  
**To:** sur@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** FW: SKP9577D CLAIMING AGAINST SKF829P DOA:09.07.18 | C10001766/JM  
**Attachments:** SKP9577D PRI.pdf

Hi Team

Please accept PRI survey and survey on a without prejudice basis.

Thank you,  
-Julie


**From:** Admin nht <admin@nhtmotor.com>  
**Sent:** Tuesday, 10 July, 2018 11:44 AM  
**To:** Claims <claims@budgetdirect.com.sg>  
**Cc:** Chloe <chloe@nhtmotor.com>  
**Subject:** SKP9577D CLAIMING AGAINST SKF829P DOA:09.07.18

Without Prejudice

Hi Motor Claim Dept

As spoken with your staff Mr Albert, please kindly arrange LKK for PRI,thanks.

Please take note this claim is under "New Hock Teck Motor Pte Ltd"



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

MSME18088983 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 10/07/2018 15:39  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	10/07/2018 15:39
Date Of Accident	09/07/2018 22:30
Exact Location Of Accident	TAMPINES AVE 9 & TAMPINES CENTRAL 7
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SKP9577D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WEI XIA
NRIC No	S7362355C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92786966
Alternative Phone No	OFFICE-92786966
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098435481
Cover Note Number	
<b>Driver</b>	
Name of Driver	LI HONGWEI
NRIC No	S6962915F
Date Of Birth	17/08/1969
Occupation	INDOOR
Date Of Driving Pass	18/08/2004
Driving Experience	13 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91396759
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 687B WOODLANDS DRIVE 75 #02-45  
 Postcode 732687  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS DRIVING STRAIGHT ALONG TAMPINES AVE 9 AND TAMPINES CENTRAL 7 AT CENTER LANE OF 3 LANES. I WAS STATIONARY AS TRAFFIC LIGHT ON RED. SUDDNELY, I FELT AN IMPACT. VEHICLE B COLLIDED ONTO REAR PORTION OF MY VEHICLE AND CAUSED DAMAGES. BOTH OF US ALIGHTED. VEHICLE B ADMITTED HIS FAULT AND APOLOGISED WITH ME. I WISH TO LODGE THE REPORT CLAIM AGAINST VEHICLE B.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKF829P  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	LI HONG WEI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKP9577D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

## Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information to collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:


  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

FORM 10 (Rev. 1/2017)

NEW FLOOR TECH

Sketch Plan #2 Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along Tampines Ave 9 x Tampines Central 7 at center lane of 3 lanes.

I was stationary as traffic light on red. Suddenly, I felt an impact. Veh "B" collided into rear portion of my vehicle and caused damaged.

Both of us alighted, veh "B" admitted his fault and apologized with me.

I wish lodge the report claim against veh "B". 

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/PIN No.:

# ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3  
#01-80 SINGAPORE 159723  
TEL: 67215133 67217433 FAX: 67243712

Pg 1

## ESTIMATE REPAIR

Auto & General Insurance (S) Pte Ltd

Date: 6.7.2018

Owner's Name : Lim Lay Pheng

Vehicle No : SLP559D

Claim Type: Third Party Claim

Vehicle Make & Model : Mazda3 5-Door Hatchback 1.5L SP

Chassis No: JM6BN24A8H0131439

Registration Date : 24 May 2017 (YOM 2016) COE Expiry Date 23 May 2027

DOA: 5.7.2018

No	Description	Qty	Unit	Estimate	Rate (\$)
1	Rear Bumper	1	\$	DE ✓	950.00
2	Rear Bumper Side Retainer	1	\$	X	71.20
3	Rear Bumper Clips	10	\$	re ✓	42.00
4	Rear Bumper Tow Cover	2	\$	X	60.00
5	Rear Bumper Reflector	2	\$	X	100.80
6	Rear Tail Gate	1	\$	repair	1,268.70
7	Rear Tail Gate Inner Compartment Clips	15	\$	X	42.00
8	Rear Tail Gate Logo	1	\$	re ✓	74.40
9	Rear Tail Gate Logo " Skyativ "	1	\$	re ✓	63.60
10	Rear Tail Gate Logo " Mazda 3 "	1	\$	re ✓	53.40
11	Reverse Sensor	4	\$	<del>slender X</del>	<del>776.80</del>
12	Reverse Sensor Seal	4	\$	X	69.20
13	Rear Reinforcement	1	\$	?	537.30
14	Rear End Panel	1	\$	repair	624.70
15	Front Bumper	1	\$	cut ✓	825.50
16	Front Bumper Side Retainer	2	\$	re ✓	37.40
17	Front Bumper Clips	10	\$	re ✓	40.00
18	Front Bumper Grille Base	1	\$	cut ✓	129.00
19	Front Bumper Grille Chrome	2	\$	cut ✓	365.00
20	Front Bumper Foglamp Garnish	1	\$	X	43.20
21	Front Bumper Foglamp Chrome	2	\$	X	135.40
22	Front Support Panel	2	\$	X	469.70
23	Front Reinforcement Bar	1	\$	?	478.80
24	Front Headlamp LH & RH	2	\$	?	7,197.20
25	Panel Radiator Grille	1	\$	DE ✓	338.50
				Total (A):	\$ 14,792.60
				Less 20%:	\$ 2,958.52
				Total:	\$ 11,834.08

Paints \$ 6391.40  
 17.20% \$ 5113.12  
 + S&H \$ 55.00  
 + labour \$ 1900.00  
\$ 9068.12

Paul  
 @ 12/07/18

25A B. 6 RH - cut / LH - X

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
 Owner ID: 2355C

**Vehicle Details**

Vehicle No.: SKP9577D  
 Vehicle to be Exported: No  
 Intended De-registration Date: 10 Jul 2018  
 Vehicle Make: TOYOTA  
 Vehicle Model: TOYOTA COROLLA ALTIS 1.6L CVT  
 Primary Colour: White  
 Manufacturing Year: 2014  
 Engine No.: 1ZR455665  
 Chassis No.: MR053REH104518369  
 Maximum Power Output: 90.0 kW (120 bhp)  
 Open Market Value: \$18,650.00  
 Original Registration Date: 27 Oct 2014  
 First Registration Date: 27 Oct 2014  
 Transfer Count: 1  
 Actual ARF Paid: \$13,650.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 26 Oct 2024  
 PARF Rebate Amount: \$10,237.00

**Intended COE Rebate Details**

COE Expiry Date: 26 Oct 2024  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Period(Years): 10  
 QP Paid: \$64,841.00  
 COE Rebate Amount: \$40,804.00  
**Total Rebate Amount: \$51,041.00**

The information contained herein is correct as at 10 Jul 2018

OK



**Toyota Corolla Altis 1.6A** \$62,800 \$9,260 /yr 22-Jul-2014 1,598 cc - Sedan Available

10% Drive Away! 1 Owner, Excellent Condition, Accident Free, Service And Maintain By Borneo Motor, Trade In Available, Come And View It Now.  
Prime Cars Credit

Posted: 07-Jul-2018 Tags: 2014 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

PREMIUM LIST



**Toyota Corolla Altis 1.6A** \$64,800 \$9,320 /yr 25-Sep-2014 1,598 cc 68,887 km Sedan Available

\$0 Drive Away Available! All Time Favourite, Reliable Sedan, Well Kept In Tip Top Condition, For You To View And Believe! Buy It From Us With A Peace Of Mind, Ring Us Up For An Exclusive Test Drive. O...

Mayfair Motoring  
Posted: 09-Jul-2018 Tags: 2014 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

PREMIUM LIST



**Toyota Corolla Altis 1.6A** \$63,500 \$9,030 /yr 17-Oct-2014 1,598 cc 88,000 km Sedan Available

1 Lady Owner. Low Mileage. Full Servicing Records. Selling At Paper Value Plus Body. Interest Rate As Low As 1.98%. Trade In Available. Call Or Msg Now For Viewing! Price Negotiable. No Dealers Please...

Posted: 08-Jul-2018 Tags: 2014 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

DIRECT OWNER



**Toyota Corolla Altis 1.6A Elegance** \$65,800 \$9,360 /yr 27-Oct-2014 1,598 cc - Sedan Available

All Time Favourite, Reliable Sedan, Well Kept In Tip Top Condition, For You To View And Believe! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After S...

Dickson Automobile  
Posted: 07-May-2018 Tags: 2014 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



### Save on petrol with OCBC 365 credit card!

Enjoy huge petrol savings of up to 23%, attractive cashback on your monthly spend, and 2 years annual fee waiver. Apply now and start enjoying today.

Find out more!



**Toyota Corolla Altis 1.6A Elegance** \$64,800 \$9,190 /yr 29-Oct-2014 1,598 cc 92,134 km Sedan Available

\$0 Down Payment Drive Away! And Also Available For Bank Loan, High Trade In! Full Agent Maintain By Borneo Motor, Buy With Peace Of Mind! All Kinds Of Loan Call Now For More Info!

Benefit Auto Enterprise Pte Ltd  
Posted: 08-Jul-2018 Tags: 2014 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

PREMIUM LIST



**Toyota Corolla Altis 1.6A Elegance** \$64,800 \$8,970 /yr 15-Dec-2014 1,598 cc 51,980 km Sedan Available

1 Owner, Fully Agent Service. Down Payment Start As Low As \$3800 Onwards. Welcome Old Car 1-1 Exchange Without Cash Top Up. Vintage Carplate Number

Posted: 06-Jul-2018 Tags: 2014 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

PREMIUM LIST



**Toyota Corolla Altis 1.6A** \$63,699 \$8,780 /yr 19-Dec-2014 1,598 cc - Sedan Available

Super Well Kept By Careful Owner. Fully Maintained By Agent, Just Done Servicing And New Air Con Compressor. All Time Reliable And Popular Family Sedan, Owner Upgrading. Too Good To Miss This Marvelou...

Posted: 05-Jul-2018 Tags: 2014 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

CONFIRMED LIST

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for pure import cars. Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to CUE cars & OPC cars. You can also buy from a car auction, look up car items, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota altis, toyota altis Singapore, used toyota altis Singapore, used vehicles Singapore or even buy used toyota altis Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CUE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart, All rights reserved.





新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

ADLYN LEE

Budget Direct

10/07/2018

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

T? Budget Direct.  
Janice  
MR053REH104518369

Accident date: 09/07/2018

Estimated repair cost for vehicle no: SKP9577D TOYOTA ALTIS 1.6 A '14

S/n	Qty	Items / List	U/price	Amount
1	1	Rear Boot Lid <i>cracked</i>		\$781.90 ✓
2	2	Rear Boot Lid Hinge <i>Not new</i>	\$174.10	\$348.20 x
3	1	Rear Boot Lid Emblem Logo		\$122.10 → 40.90
4	1	Rear Boot Lid Corolla Logo <i>new</i>		\$123.05 → 43.60
5	1	Rear Boot Lid Altis Logo		\$141.45 → 54
6	2	Rear Boot Lid Side Reflector <i>lit</i>	\$361.90	\$723.80 ✓
7	1	Rear Boot Lid Number Plate <i>Not new</i>		\$50.00 x
8	1	Rear Boot Lid Centre Chrome Moulding <i>Not new</i>		\$374.50 x
9	1	Rear Boot Lid Camera <i>Not new</i>		\$680.00 x
10	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$374.45 → 258.2
11	1	Rear Boot Lid Inner Rubber <i>lit</i>		\$231.35 ✓
12	1	Rear Boot Lid Inner Trim Board <i>Not new</i>		\$781.85 x
13	10	Rear Boot Lid Inner Trim Board Clip <i>Not new</i>	\$6.50	\$65.00 x
14	2	Rear Tail Lamp <i>cracked</i>	\$374.45	\$748.90 ✓
15	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
16	2	Rear Tail Lamp Lower Bracket <i>Not new</i>	\$134.45	\$268.90 x
17	1	Rear Bumper <i>Deformed</i>		\$561.60 ✓
18	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 → 30
19	2	Rear Bumper Side Retainer <i>new</i>	\$134.10	\$65.00 ✓
20	2	Rear Bumper Side Reflector <i>Not new</i>	\$132.10	\$65.00 x
21	1	Rear Bumper Reinforcement <i>Bent</i>		\$374.50 ✓
22	2	Rear Bumper Mud Shield <i>2 Not</i>	\$172.85	\$345.70 +
23	8	Rear Bumper Mud Shield Clip <i>new</i>	\$6.50	\$52.00 x
24	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00 → 200/500
25	1	Rear End Panel <i>Dented</i>		\$649.20 ✓
26	1	Rear End Panel Top Garnish <i>Deformed</i>		\$321.10 → 242.70
27	1	Rear End Panel Lock Switch <i>cracked</i>		\$188.00 ✓
28	2	Rear Fender Inner Trim Board <i>Not new</i>	\$781.85	\$1,563.70 x

29	16	Rear Fender Inner Trim Board Clip	Not New	\$6.50	\$104.00 X
30	1	Rear Spare Tyre Panel	Repair		\$972.45 X
31	1	Rear Spare Tyre Panel Top Cover	Not New		\$328.25 X
32	1	Rear Spare Tyre Panel & End Panel Sealant	Not New		\$450.00 X
33	1	Rear Exhaust	Repair		\$781.10 X
34	2	Rear Exhaust Mounting	Not New		\$61.20 X
35	1	Rear Centre Exhaust	Not New		\$1,218.25 X

502565 SN200  
376923

Subtotal :- \$14,393.50

**Labour charges**

To remove & refit cushion		<del>\$280.00</del> 50
To remove & refit reverse sensor		<del>\$100.00</del> 40
To remove & refit camera		<del>\$180.00</del> 40
To remove & refit rear & centre exhaust		<del>\$380.00</del> 80
To check wiring		<del>\$100.00</del> 30
Towing fee	2280	\$100.00 X
Tuff kote		<del>\$150.00</del> 40
Panel beating		<del>\$1,400.00</del> 1000
Spray painting		<del>\$1,400.00</del> 1000

Subtotal :- \$3,810.00

Total :- \$12,851.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total: 6249.23  
h/s. SK  
06 Days  
SK



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI18012543/Arbq2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 10-08-2018	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. SKF 829P	Veh. Inspected SKP 9577D	
	Policy No.	Coverage (\$)	0.00
	Claim No. C10001766/JM	Excess (\$)	0.00
	Assign From JULIE	Assign Date	10/07/2018
2. Vehicle Particulars & Condition			
	Make & Model TOYOTA ALTIS	c.c	1598
	Engine No. HIDDEN	Year of Reg.	2014
	Chassis No. MR053REH104518369	Colour	WHITE
	Odometer 76149	Steering	IN ORDER
	Brakes IN ORDER	Modification	SPORTS RIM
	General GOOD		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	205/55 R16	YOKOHAMA
	L/H Front Tyre	205/55 R16	YOKOHAMA
	R/H Rear Tyre	205/55 R16	YOKOHAMA
	L/H Rear Tyre	205/55 R16	YOKOHAMA
			Balance
			6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date 09/07/2018	Inspection Date	10/07/2018
	Survey held at NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 9577D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BOOT LID	BUCKLED	781.90	781.90
2	REAR BOOT LID HINGE @\$174.10	NOT NECESSARY	348.20	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	122.10	40.90
1	REAR BOOT LID COROLLA LOGO	NECESSARY	123.05	43.60
1	REAR BOOT LID ALTIS LOGO	NECESSARY	141.45	54.00
2	REAR BOOT LID SIDE REFLECTOR @\$361.90	CUT	723.80	723.80
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID CENTRE CHROME MOULDING	NOT NECESSARY	374.50	-
1	REAR BOOT LID CAMERA	NOT NECESSARY	680.00	-
1	REAR BOOT LID INNER LOCK	DAMAGED	374.45	258.20
1	REAR BOOT LID INNER RUBBER	CUT	231.35	231.35
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	781.85	-
10	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	65.00	-
2	REAR TAIL LAMP @\$374.45	CRACKED	748.90	748.90
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP LOWER BRACKET @\$134.45	NOT NECESSARY	268.90	-
1	REAR BUMPER	DEFORMED	561.60	561.60
10	REAR BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	REAR BUMPER SIDE RETAINER @\$134.10	NECESSARY	65.00	65.00
2	REAR BUMPER SIDE REFLECTOR @\$132.10	NOT NECESSARY	65.00	-
1	REAR BUMPER REINFORCEMENT	BENT	374.50	374.50
2	REAR BUMPER MUD SHIELD @\$172.85	NOT NECESSARY	345.70	-
8	REAR BUMPER MUD SHIELD CLIP @\$6.50	NOT NECESSARY	52.00	-
1	REAR END PANEL	DENTED	649.20	649.20
1	REAR END PANEL TOP GARNISH	DEFORMED	321.10	242.70
1	REAR END PANEL LOWER SWITCH	CRACKED	188.00	188.00
2	REAR FENDER INNER TRIM BOARD @\$781.85	NOT NECESSARY	1,563.70	-
16	REAR FENDER INER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	104.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	972.45	-
1	REAR SPARE TYRE PANEL TOP COVER	NOT NECESSARY	328.25	-
1	REAR SPARE TYRE PANEL & END PANEL SEALANT	NOT NECESSARY	450.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	781.10	-

Report Ref No. CS/AGI18012543/Arbq2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR EXHAUST MOUNTING	NOT NECESSARY	61.20	-
1	REAR CENTRE EXHAUST	NOT NECESSARY	1,218.25	-
	LESS 25% DISCOUNT		-	-1,256.41
			14,013.50	3,769.24
	<b>SPECIAL NETT ITEMS</b>			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
			380.00	200.00
	<b>LABOUR</b>			
	TO REMOVE & REFIT CUSHION .		280.00	50.00
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	40.00
	TO REMOVE & REFIT CAMERA .		180.00	40.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST .		380.00	80.00
	TO CHECK WIRING .		100.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	40.00
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL AND REAR EXHAUST .		1,400.00	1,000.00
	SPRAY PAINTING .		1,400.00	1,000.00
			4,090.00	2,280.00
<b>GRAND TOTAL</b>			<b>18,483.50</b>	<b>6,249.24</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,000.00</b>

Report Ref No. CS/AGI18012543/Arbq2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.