

INS. CASE OWNER:

1006 / III180 / 12582, Aja3n2

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/12/18
Joy

SIX 7364J } NA/PA18012390 / 24 : 60A, 12/18

HEAD TO REAR

18-12-18

LUD IN
FOR MANDATE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

Loss of Use (LOU):

S\$

Loss of Income (LOI):

S\$

LOR only

LOU only

LOR + LOU

LOR + LOI

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

HUA FENG AUTOMOTIVE ENGINEERING &

RECONSTRUCTION

REF:

ASS. REC. BY: Abrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJX7364J Yr Regn: 2010, JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Polo c.c. 1197Colour: White A/C: Insured / Std / NI / NASp. Reading: 134874 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZ226R2A4051660Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/45R17R: 205/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/07/18Survey held at Huac FerryDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP111</u>
	<u>MV: 22K.</u>
	<u>PV: 153K.</u>
	<u>Nett: 6.7K.</u>
<u>19-11-18</u>	<u>L/S \$2,300</u>
	<u>R (\$9,125.54 / 80%)</u>

3078C

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (%)

Sheet1
HUA FENG AUTOMOTIVE

ENGINEERING & RECONSTRUCTION

BLOCK 1 KAKI BUKIT AVENUE 6 #01-107 AUTOBAY @ KB (S) 417883

Tel : (65) 69664526 HP: 92712214 Fax: (65) 67476918

ELIMASWATY BINTE YANTO

Blk 1 Kaki Bukit Ave 6

01-107

Singapore 417883

10th Jul 2018

Accident date: 07th Jul 2018

Estimated repair cost for vehicle no: SJX7364J VOLKSWAGEN POLO 1.4 AT '10

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear boot lid <i>Ref</i>		\$1,177.60 <i>x</i>
2	1	Rear boot lid Polo logo <i>Ref</i>		\$54.77 <i>x</i>
3	1	Rear boot lid inner lock <i>2</i>		\$185.00 <i>x</i>
4	1	Rear boot lid inner rubber <i>Ref</i>		\$165.00 <i>x</i>
5	1	Rear boot lid inner trim board <i>Ref</i>		\$355.00 <i>x</i>
6	1	Rear boot lid windscreen seal		\$125.00 <i>x</i>
7	2	Rear tail lamp <i>2</i>	\$301.77	\$603.54 <i>x</i>
8	2	Rear tail lamp panel <i>Ref</i>	\$177.50	\$355.00 <i>x</i>
9	4	Rear tail lamp clips	\$5.00	\$20.00 <i>x</i>
10	1	Rear End Panel Top Garnish <i>Ref</i>		\$119.33 <i>x</i>
11	1	Rear End Panel <i>Ref</i>		\$517.33 <i>x</i>
12	2	Rear End Panel side top <i>Ref</i>	\$152.25	\$304.50 <i>x</i>
13	1	Rear Bumper <i>Ref</i>		\$663.75 <i>x</i>
14	2	Rear Bumper Side Bracket <i>Ref</i>	\$97.33	\$194.66 <i>x</i>
15	1	Rear Bumper reinforcement <i>Bent</i>		\$355.00 <i>x</i>
16	8	Rear bumper clips <i>Ref</i>	\$5.00	\$40.00 <i>x</i>
17	1	Rear Bumper inner sponge <i>Ref</i>		\$115.00 <i>x</i>
18	1	Rear Bumper lower sponge <i>Ref</i>		\$125.00 <i>x</i>
19	1	Rear bumper center top bracket <i>Ref</i>		\$165.00 <i>x</i>
20	10	Rear bumper center top bracket devit <i>Ref</i>	\$5.00	\$50.00 <i>20</i>
21	1	rear bumper number plate lamp <i>Ref</i>		\$175.00 <i>x</i>
22	1	rear bumper number plate <i>Ref</i>		\$50.00 <i>x</i>
23	4	Rear bumper reverse sensor <i>Ref</i>	\$201.77	\$807.08 <i>200</i>
24	1	rear spare tyre panel top cover <i>Ref</i>		\$558.00 <i>x</i>
25	1	rear exhaust <i>Ref</i>		\$955.00 <i>x</i>

1961.08
1863.02

26	1	rear tool box <i>new</i>	\$620.00 <i>x</i>
----	---	--------------------------	-------------------

Subtotal :-	\$8,855.56
-------------	------------

Labour charges

To Remove & refix cushion

\$120.00 *50*

Tuff kote

\$120.00 *x*

To Check Wiring System

1080
\$80.00 *30*

To Remove & install rear exhaust

\$250.00 *x*

Panel beating

\$1,000.00 *500*

Spray painting

\$1,000.00 *500*

Subtotal :-	\$2,570.00
-------------	------------

Total:-	\$11,425.56
---------	-------------

total: 2943.02
L/S: 2.3K
O/S: 0.3Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3078C

Vehicle Details

Vehicle No.: SJX7364J
Vehicle to be Exported: Yes
Intended De-registration Date: 09 Jul 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: POLO 1.2L AT 6R14F7
Primary Colour: White
Manufacturing Year: 2010
Engine No.: LTA1100925
Chassis No.: WVVZZZ6RZAU051660
Maximum Power Output: 77.0 kW (103 bhp)
Open Market Value: \$17,056.00
Original Registration Date: 05 Jul 2010
First Registration Date: 05 Jul 2010
Transfer Count: 3
Actual ARF Paid: \$17,056.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Jul 2020
PARF Rebate Amount: \$9,380.00

Intended COE Rebate Details

COE Expiry Date: 04 Jul 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$30,051.00
COE Rebate Amount: \$5,967.00
Total Rebate Amount: \$15,347.00

The information contained herein is correct as at 09 Jul 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3078C
Vehicle Details	
Vehicle No.:	SJX7364J
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.2L AT 6R14F7
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	LTA1100925
Chassis No.:	WVWZZZ6RZAU051660
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$17,056.00
Original Registration Date:	05 Jul 2010
First Registration Date:	05 Jul 2010
Transfer Count:	3
Actual ARF Paid:	\$17,056.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jul 2020
PARF Rebate Amount:	\$9,380.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jul 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$30,051.00
COE Rebate Amount:	\$5,959.00
Total Rebate Amount:	\$15,339.00

The information contained herein is correct as at 10 Jul 2018

OK



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2011, Lexus RX450H, \$55,000

 Well Maintained By Owner,
Regularly Servicing.
Direct Owner StarAd 

AutoInn
An Inspiration For Car Buyers

**click here to view
our PRISTINE USED CARS
at GREAT PRICES**

Browse by Category Save Search Print Sort by Date Posted 20 results/page

15 vehicles | **Search** Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Polo	Any	Any	2010	Any	Any	Any	Available
------------------	------	-----	-----	------	-----	-----	-----	-----------



☐ **Volkswagen Polo 1.4A** \$19,800 \$7,190 /yr 24-Mar-2010 1,390 cc - Hatchback Available

Consignment Unit. Serviced Regularly With Wear And Tear Parts Replaced. Well Kept Interior With Cozy Brown Leather. Loan And Trade In Welcome. Contact Us To Find Out More!

Posted: 09-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ **Volkswagen Polo 1.4A** \$22,800 \$8,940 /yr 25-Mar-2010 1,390 cc 133,535 km Hatchback Available

Very Well Maintained By EX Meticulous Owner! Accident Free. No Touch Up Required! All Our Vehicles Has Undergone A Check By Our In House Mechanics! Peace Of Mind When Buying From Us! Please Call Us For...

Posted: 06-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ **Volkswagen Polo 1.4A** \$21,808 \$7,990 /yr 23-Apr-2010 1,390 cc 86,600 km Hatchback Available

Beautiful Red VW Polo For Sale. Just Arrived. New Paint And In Top Condition, No Repairs Needed As The Car Has Been Regularly Serviced, Interior And Exterior Condition Looks New. Low Mileage Done. Car...


Posted: 12-Jun-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ **Volkswagen Polo 1.4A** \$22,800 \$8,390 /yr 05-May-2010 1,390 cc - Hatchback Available

New Road Tax Till Nov 2018, In Top Condition, No Repairs Needed As The Car Has Been Regularly Serviced, Interior/Exterior Condition Looks New, Hot Red Exterior With Red And Black Interior, Bank And In...

Posted: 10-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



**Buying a pre-owned car, but
Unsure of its Condition?**
Get: STA Car Evaluation



☐ **Volkswagen Polo 1.4A** \$21,800 \$7,780 /yr 10-May-2010 1,390 cc 90,000 km Hatchback Available

Original Paint & Condition. Very Well Maintained By Previous Owner, Beautiful Red Exterior With Black Leather Upholstery. Low Mileage Unit With Low Depreciation. Easy To Handle And Smooth Driving Exper...

Posted: 08-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ **Volkswagen Polo 1.4A** \$23,500 \$7,950 /yr 13-Jul-2010 1,390 cc 137,000 km Hatchback Available

Flawless White Paintwork Kept To The Best In It's Original Condition, This Vehicle Is Maintained With High Standards By Previous Owner And Not Limiting To It's Interior Which Compliments Everything Ab...

Wheeler Dealers 2018 Pte Ltd

Posted: 19-May-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ **Volkswagen Polo 1.2A** \$28,000 \$9,530 /yr 26-Jul-2010 1,197 cc 131,380 km Hatchback Available

Full Disclosure Given Upon Dealing. Accident-Free Price Slighty Negotiable. Update: 9-June: All Standard Wear And Tear Replaced. 215/45r16 Made In Japan Toyo Tires Just Changed On 28-May-18. Ideal ...

Prem Roy Motoring

Posted: 08-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen

SHOW LISTED HISTORY

Compare 

☐ **Volkswagen Polo 1.2A** \$25,500 \$8,270 /yr 29-Jul-2010 1,197 cc 124,600 km Hatchback Available

One Owner, Sporty White, Fun And Safe European Car. Smooth Engine, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And



In House Loan Available! Trade In Welcome. Call For Appoint...

★ Posted: 29-Jun-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ Volkswagen Polo 1.4A \$27,800 \$9,800 /yr 04-Aug-2010 1,390 cc 118,000 km Hatchback Available

Workshop Warranty Covered. Drive With No Worry. Very Nice And Superb Condition! Affordable VW Hatchback With Decent Cabin Space Well Suited For Young Families Or Executives. Original Paintwork, 100% A...

★ Posted: 07-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ Volkswagen Polo 1.2A TSI \$24,880 \$7,910 /yr 04-Aug-2010 1,197 cc 130,000 km Hatchback Available

Owner Upgrade To New Car. Very Well Maintained & In Excellent Condition As Owner Groom Regularly. A Fun And Safe European Car & One Of The Most Fuel Efficiency Hatchback. Smooth Gear Transmission And ...

DISCLAIMER

★ Posted: 19-Jun-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



How much is your car really worth?

Find out how much your car can sell for. Quotz helps owners like you, sell their cars at the HIGHEST PRICE guaranteed! If we fail, you'll get \$100 CASH! Free valuation via phone/online. Absolutely No obligations!

Find out more!



☐ Volkswagen Polo 1.2A TSI \$25,800 \$7,900 /yr 16-Sep-2010 1,197 cc 83,650 km Hatchback Available

Best Buy! Low Mileage Of Only 83000 Kms Travelled! 120 Points STA Check And Accident Free Report For A Peace Of Mind! High Trade In And In House Financing Available! View Now!

★ Posted: 09-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ Volkswagen Polo 1.4A \$26,000 \$7,880 /yr 01-Nov-2010 1,390 cc 115,000 km Hatchback Available

One Owner Only! Low Genuine Mileage At 115,000KM, 4 New Break Disc And Break Pad! Beautiful White Unit Selling At Low Depreciation! 100% Accident Free! Buy With A Peace Of Mind! Trade In Is Available....

PREMIUM

★ Posted: 30-Jun-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ Volkswagen Polo 1.4A \$25,800 \$7,770 /yr 15-Nov-2010 1,390 cc - Hatchback Available

Elegant Blue Paintwork With Clean And Well Kept Red Leather Interior! Well Taken Care By Previous Owner In Tip Top Condition, For You To View And Believe! Price Negotiable For Serious Buyers! High Tra...

★ Posted: 05-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ Volkswagen Polo 1.2A \$26,888 \$7,700 /yr 29-Nov-2010 1,197 cc 112,000 km Hatchback Available

\$5k Drive Away! Monthly \$695, Owner Upgrade, Regular Maintain And Service, Well Kept Condition, Original Paintwork, No More Repair Needed! Smooth Gear Transmission And Quiet Engine In Original Condi...

★ Posted: 29-Jun-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen



☐ Volkswagen Polo 1.2A TSI \$26,998 \$7,740 /yr 30-Nov-2010 1,197 cc 133,558 km Hatchback Available

Be Our Next Happy Buyer To Own This Well-kept Vehicle At Most Reasonable And Affordable Price! Tip Top Conditions! Rare Sporty Grey Color Unit! New 4PCS Tires! Wear & Tear Replaced! Guaranteed No Repa...

★ Posted: 06-Jul-2018 Tags: 2010 Volkswagen Polo, Volkswagen Polo, Volkswagen, Polo, Used Volkswagen

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads


20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Polo, Polo Singapore, used Polo Singapore, used Polo, used vehicles Singapore or even buy used Polo Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



SHORTLISTED HISTORY

Compare

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2018 Edit Reg		10 Jul 2018 00:00 Edit Adj Rpt	\$2,300.00 Edit Estimates	\$2,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		CHAI SHEAN YANG, ID: S7934693D							
Main Claimant:		ELIMASWATY BINTE YANTO, ID: S8723078C							
Vehicle Reg. No.:		SJX7364J	Date of Loss:	07/07/2018 07:00 - :59 [96 Months and 2 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / MC20182600	Policy/Cover Note No.:	17MPC00027700 (Comprehensive)					
Vehicle Reg. No. (Insured):		SLH2515J	Policy No. (Claimant):	MT/00378986/01					
		Excess:							
Repairer:		Hua Feng Automotive Engineering & Reconstruction (HQ) BLK 1 KAKI BUKIT AVE 6 #01-107 AUTOBAY, 417883 Kaki Bukit - Tel: 9271 2214							
Handling Insurer:		India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]							
Claimant's Insurer:		Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/07/2018]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (11/01/2019): Alert - Adj Mandate Approved (\$3007.45) - SJX7364J - Claim Handler: C. Meenachi - III_SG (23/07/2018): Alert - Adj Mandate Approved (\$0.00) - SJX7364J - Claim Handler: C. Meenachi									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJX7364J (MC20182600)
[SLH2515J]

TP

ELIMASWATY BINTE YANTO
Jul 7 2018 7:00AM

[CHAI SHEAN YANG]

Hua Feng Automotive Engineering & Reconstruction

Upload Documents			Upload Photos		Compose New Letter		View Use Viewer	
Video							1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail	Print
1	03/09/18 13:58	Video - Accident					Load MP4	
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	23/08/18 10:35	General View					Load JPG	☒
2	23/08/18 10:35	General View					Load JPG	☒
3	23/08/18 10:35	General View					Load JPG	☒
4	23/08/18 10:35	General View					Load JPG	☒
5	23/08/18 10:35	General View					Load JPG	☒
6	23/08/18 10:35	General View					Load JPG	☒
7	23/08/18 10:35	General View					Load JPG	☒
8	23/08/18 10:35	General View					Load JPG	☒
9	23/08/18 10:35	General View					Load JPG	☒
10	23/08/18 10:35	General View					Load JPG	☒
11	23/08/18 10:35	General View					Load JPG	☒
12	23/08/18 10:35	General View					Load JPG	☒
13	23/08/18 10:35	General View					Load JPG	☒
14	23/08/18 10:35	General View					Load JPG	☒
15	23/08/18 10:35	General View					Load JPG	☒
16	23/08/18 10:35	General View					Load JPG	☒
17	23/08/18 10:36	Reinspection Photo					Load JPG	☒
18	23/08/18 10:36	Reinspection Photo					Load JPG	☒
19	23/08/18 10:36	Reinspection Photo					Load JPG	☒
20	23/08/18 10:36	Reinspection Photo					Load JPG	☒
21	23/08/18 10:36	Reinspection Photo					Load JPG	☒
22	23/08/18 10:36	Reinspection Photo					Load JPG	☒
23	23/08/18 10:36	Reinspection Photo					Load JPG	☒
24	23/08/18 10:36	Reinspection Photo					Load JPG	☒
25	23/08/18 10:36	Reinspection Photo					Load JPG	☒
26	23/08/18 10:36	Reinspection Photo					Load JPG	☒
27	23/08/18 10:36	Reinspection Photo					Load JPG	☒
28	23/08/18 10:36	Reinspection Photo					Load JPG	☒
29	23/08/18 10:36	Reinspection Photo					Load JPG	☒
30	23/08/18 10:36	Reinspection Photo					Load JPG	☒
31	23/08/18 10:36	Reinspection Photo					Load JPG	☒
32	23/08/18 10:36	Reinspection Photo					Load JPG	☒
33	23/08/18 10:36	Reinspection Photo					Load JPG	☒
34	23/08/18 10:36	Reinspection Photo					Load JPG	☒
35	23/08/18 10:36	Reinspection Photo					Load JPG	☒
36	23/08/18 10:36	Reinspection Photo					Load JPG	☒
37	23/08/18 10:36	Reinspection Photo					Load JPG	☒
38	23/08/18 10:36	Reinspection Photo					Load JPG	☒

39	23/08/18 10:36	Reinspection Photo		Load JPG	☒
40	23/08/18 10:36	Reinspection Photo		Load JPG	☒
41	23/08/18 10:36	Reinspection Photo		Load JPG	☒
42	23/08/18 10:36	Reinspection Photo		Load JPG	☒
43	23/08/18 10:36	Reinspection Photo		Load JPG	☒
44	23/08/18 10:36	Reinspection Photo		Load JPG	☒
45	23/08/18 10:36	Reinspection Photo		Load JPG	☒
46	23/08/18 10:36	Reinspection Photo		Load JPG	☒
47	23/08/18 10:36	Reinspection Photo		Load JPG	☒
48	23/08/18 10:36	Reinspection Photo		Load JPG	☒
49	23/08/18 10:36	Reinspection Photo		Load JPG	☒
50	23/08/18 10:36	Reinspection Photo		Load JPG	☒
51	23/08/18 10:36	Reinspection Photo		Load JPG	☒
52	23/08/18 10:36	Reinspection Photo		Load JPG	☒
53	23/08/18 10:36	Reinspection Photo		Load JPG	☒
54	23/08/18 10:36	Reinspection Photo		Load JPG	☒
55	23/08/18 10:36	Reinspection Photo		Load JPG	☒
56	23/08/18 10:36	Reinspection Photo		Load JPG	☒
57	23/08/18 10:36	Reinspection Photo		Load JPG	☒
58	23/08/18 10:36	Reinspection Photo		Load JPG	☒
59	23/08/18 10:36	Reinspection Photo		Load JPG	☒
60	23/08/18 10:36	Reinspection Photo		Load JPG	☒
61	23/08/18 10:36	Reinspection Photo		Load JPG	☒
62	23/08/18 10:36	Reinspection Photo		Load JPG	☒
63	23/08/18 10:36	Reinspection Photo		Load JPG	☒
64	23/08/18 10:36	Reinspection Photo		Load JPG	☒
65	23/08/18 10:36	Reinspection Photo		Load JPG	☒
66	23/08/18 10:36	Reinspection Photo		Load JPG	☒
67	23/08/18 10:36	Reinspection Photo		Load JPG	☒

Documentation

1 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/07/18 19:57	TP GIA REPORT	Load PDF	
2	21/12/18 11:41	RENTAL RECEIPT	Load PDF	
3	21/12/18 11:41	LOD	Load PDF	
4	13/02/19 09:40	AUTHORISATION TO ACT FORM	Load PDF	
5	13/02/19 09:40	DISCHARGE VOUCHER	Load PDF	
6	13/02/19 09:41	WORKSHOP INVOICE	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 14:06	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18012582/AJA3N2

Date: 13/02/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: 17MPC00027700
 Claimant Vehicle No: SJX7364J Insured Vehicle No: SLH2515J
 Date of Loss: 07/07/2018 Nature of Claim: TP Claim No: MC20182600

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJX7364J
 Make & Model: VOLKSWAGEN POLO, 1.2 L AT 6R14F7 (A) Engine No: LTA1100925
 Reg. Date: 05/07/2010 (Man. Year: 2010) Chassis No: WWWZZZ6RZAU051660
 Colour: White Odometer: 134874 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,855.56	1,863.03	6,992.53	78.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,080.00	1,490.00	57.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,425.56	2,943.03	8,482.53	74.24
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	11,425.56	2,300.00	9,125.56	79.87
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,007.45		
Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment: 10/07/2018
 Date Inspected: 10/07/2018 Inspected At: Hua Feng Automotive Engineering & Reconstruction (HQ)
 BLK 1 KAKI BUKIT AVE 6 #01-107
 AUTOBAY
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2018)
Parts:	144	VOLKSWAGEN POLO 1.2 L AT 6R14F7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX7364J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Repair	1,177.60 F	*- FL
2	1	*REAR BOOT LID POLO LOGO	Not Necessary	54.77 F	*- FL
3	1	*REAR BOOT LID INNER LOCK	Not Necessary	185.00 F	*- FL
4	1	*REAR BOOT LID INNER RUBBER	Not Necessary	165.00 F	*- FL
5	1	*REAR BOOT LID INNER TRIM BOARD	Not Necessary	355.00 F	*- FL
6	1	*REAR BOOT LID WINDSCREEN SEAL	Not Necessary	125.00 F	*- FL
7	2	*REAR TAIL LAMP	Not Necessary	603.54 F	*- FL
8	2	*REAR TAIL LAMP PANEL	Not Necessary	355.00 F	*- FL
9	4	*REAR TAIL LAMP CLIPS	Not Necessary	20.00 F	*- FL
10	1	*REAR END PANEL TOP GARNISH	Not Necessary	119.33 F	*- FL
11	1	*REAR END PANEL	Dented	517.33 F	*517.33 FL
12	2	*REAR END PANEL SIDE TOP	Repair	304.50 F	*- FL
13	1	*REAR BUMPER	Deformed	663.75 F	*663.75 FL
14	2	*REAR BUMPER SIDE BRACKET	Not Necessary	194.66 F	*- FL
15	1	*REAR BUMPER REINFORCEMENT	Bent	355.00 F	*355.00 FL
16	8	*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
17	1	*REAR BUMPER INNER SPONGE	Not Necessary	115.00 F	*- FL
18	1	*REAR BUMPER LOWER SPONGE	Not Necessary	125.00 F	*- FL
19	1	*REAR BUMPER CENTER TOP BRACKET	Cracked	165.00 F	*165.00 FL
20	10	*REAR BUMPER CENTER TOP BRACKET DEVIT	Necessary	50.00 F	*20.00 FL
21	1	*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	175.00 F	*- FL
22	1	*REAR BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
23	4	*REAR BUMPER REVERSE SENSOR	Damaged	807.08 F	*200.00 FL
24	1	*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	558.00 F	*- FL
25	1	*REAR EXHAUST	Not Necessary	955.00 F	*- FL
26	1	*REAR TOOL BOX	Not Necessary	620.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,855.56	1,961.08
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	98.05
Total Parts (\$\$)	8,855.56	1,863.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	50.00
2	TUFF KOTE	New	120.00	0.00
3	TO CHECK WIRING SYSTEM	New	80.00	30.00
4	TO REMOVE & INSTALL REAR EXHAUST	New	250.00	0.00
5	PANEL BEATING	New	1,000.00	500.00
6	SPRAY PAINTING	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,570.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >