

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO18012588/Gz4d3e2					
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date: 18-07-2018  Code: SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJQ 3390X	Veh. Inspected	JRY 8266	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD1802947/GPL	Excess (\$)	0.00	
	Assign From	IRENE HENRY	Assign Date	11/07/2018	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA INNOVA	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	PN1GW3EMX03061414	Colour	SILVER	
	Odometer	78021 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm	
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm	
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	10/07/2018	Inspect Date / Time	11/07/2018 ( 10:20 AM )	
	Survey held at	AUTOWERKE AUTOMOTIVE- 8	KAKI BKT AVE 4 #05-01/02		
	Repairer -				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				

Report Ref No. CS3/SMO18012588/Gz4d3e2

**Estimate Days of Repair** 

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.