

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 13 Jul 2018

## **Preliminary Advice**

Insured Vehicle No	: SKW3598X		
TP Vehicle No	: SJU1742G	Accident Date	: 06/07/2018
Make	: HYUNDAI AVANTE	Assignment Date	: 11/07/2018
Date of Inspection	: 11/07/2018	Est. Duration of Repair	: 24 days
Inspection At	: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...front and rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,985.57
Revised Amount	:S\$	19,030.66
Check Items (Estimated)	:S\$	8,467.84
Total	:S\$	27,498.50

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	16,000.00
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	8,614.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,386.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.