

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Wednesday, 1 August 2018 3:12 PM

To: 'kalidass@khimseah.com' <kalidass@khimseah.com>

Subject: ACCIDENT INVOLVING PA 2281Y AND GBF 847T ALONG/AT PUNGGOL WEST FLYOVER ENTRANCE TO TPE ON 09/07/2018

Importance: High

01 Aug 2018

Khim Seah Enterprise Pte Ltd

ATTN: The Management

Dear Sir/ Mdm

OUR REF : CC4/ASM18012692/Upb3

YOUR REF : P0902358 (PA 2281Y)

ACCIDENT INVOLVING PA 2281Y AND GBF 847T ALONG/AT PUNGGOL WEST FLYOVER ENTRANCE TO TPE ON 09/07/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from LIU'S BROTHER AUTO ENGINEERING WORKSHOP acting on behalf of the owner of GBF 847T against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Authorisation Letter/ Employment Letter of your driver from you company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



錦城企業私人有限公司
KHIM SEAH ENTERPRISE PTE LTD



Date : 03rd December 2018



To whom it may concern,

Re: Mr. CHIA WONG FAH,

This letter is written to confirm that Mr. CHIA WONG FAH (NRIC: S2162494B) has been authorized by Khim Seah Enterprise Pte Ltd to drive vehicle PA2281Y to perform work duties with a valid driving license.

Should you have any questions, please contact the undersigned.

Yours faithfully,



Liu Miaodi
HR Manager
Khim Seah Enterprise Pte Ltd



RE: IA ?

Type

🔔 Question

Message

Hi KC, we have uploaded a copy of LO LOA in SC. Kindly advise if we may proceed DS. Thank you. Hsiao
Tong - 17 March 2019

Reply

Hsiao Tong (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Monday, 18 March 2019 7:42 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: New message for service request 56863, vehicle number GBF847T

TYPE	SENT	FROM	SUBJECT	BODY	
	18/3/19 1:37 PM	CHAN Kian Chuan	Re:RE: IA ?	PLS PROCEED DS COR @ \$8,075.00 BEFORE GST	
	17/3/19 10:41 AM	LKK AUTO	RE: IA ?	Hi KC. we have uploaded a	

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)
Sent: Monday, 18 March 2019 2:09 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 56863, vehicle number GBF847T

G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: kianchuan.chan@axa.com.sg [mailto:kianchuan.chan@axa.com.sg]
Sent: Monday, 18 March 2019 1:38 PM
To: admin-d@lkkauto.com
Subject: New message for service request 56863, vehicle number GBF847T

AXA Insurance has sent you a message for claim number S8M00NZW.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG.
<https://www.avg.com>



<TP - Mandate IA> - S8M00NZW [ACCIDENT INVOLVING PA 2281Y(OI) & GBF 847T(TP) ON 09/07/2018]

Type

🔗 Question

Message

Liability: 100%. Insured driver rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$8,442.45(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 12 June 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 12/06/2019

Survey Details:

Date of loss	09.07.2018
Date of appointment	11.07.2018
Date of survey	11.07.2018
Location of survey	LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Vehicle Details:

Claim Type:	Third party
Vehicle number	GBF847T
Make and Model	Fiat Doblo Cargo Maxi (1598cc)
Date of registration	20.06.2016
Excess	
Market Value/ Book Value	\$ 60,000.00 (est)
Parf/COE Rebate	\$ 32,136.00 (est)
Nett Value/ ERV	\$ 27,864.00 (est)

Repair details:

Initial Estimate	\$ 17,134.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 8,863.19
Check items (estimate)	NIL
Labour	\$ 1,800.00
Supplementary	NIL
Total	\$ 10,663.19
Lump Sum(if applicable)	\$ 8,500.00

Number of days for repair	<u>4</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

COR @ \$8,075.00 as per AXA mandate

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 8,075.00	
Loss of use	\$ 360.00	(6days x \$60.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 8,442.45	

Hsiao Tong (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Thursday, 13 June 2019 8:55 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: New message for service request 56863, vehicle number GBF847T

<input type="checkbox"/>	18/3/19 1:37 PM CHAN Kian Chuan --- PLS PROCEED DS COR @ \$8,075.00 BEFORE GST	LSP	18/3/2019 7:29:21 PM
<input type="checkbox"/>	<u>Message Liability: 100%. Insured driver rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$8,442.45 (all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 12 June 2019</u>	CHT	12/6/2019 8:14:20 AM
<input type="checkbox"/>	6/12/19 10:29 AM CHAN Kian Chuan-----PLS PROCEED FOR SETTLEMENT NOT EXCEEDING \$8,442.45(all-in)	LSP	13/6/2019 8:42:42 AM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)
Sent: Wednesday, 12 June 2019 10:33 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 56863, vehicle number GBF847T

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: kianchuan.chan@axa.com.sg [mailto:kianchuan.chan@axa.com.sg]
Sent: Wednesday, 12 June, 2019 10:30 AM
To: admin-d@lkkauto.com
Subject: New message for service request 56863, vehicle number GBF847T

AXA Insurance has sent you a message for claim number S8M00NZW.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAUTO)

From: Susan Low <liusbro@ymail.com>
Sent: Saturday, 3 August 2019 3:28 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Your Ref: GBF847T180709 *Our Ref: CC4/ASM18012692/Upb3 [ACCIDENT INVOLVING PA 2281Y(AXA) AND GBF 847T ON 09/07/2018]

We hereby confirm acceptance of your offer.

Kindly let us have your discharge for our client's execution and your cheque made in our favour as soon as possible.

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

On Saturday, 20 July 2019, 10:39:57 am SGT, Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to your below email.

We have our principal instruction to offer as follows: -

1. Cost of Repair	\$ 8,075.00
2. Loss of Use (6days x \$60.00)	\$ 360.00
3. LTA/GIA Search Fee	\$ 7.45
TOTAL	\$ 8,442.45

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Susan Low <liusbro@gmail.com>

Sent: Wednesday, 10 July 2019 10:22 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Your Ref: GBF847T180709 *Our Ref: CC4/ASM18012692/Upb3 [ACCIDENT INVOLVING PA 2281Y(AXA) AND GBF 847T ON 09/07/2018]

We regret we are unable to accept yours offer.

We counter propose of your offer as follow settlement:-

Global Sum S\$8,800/- (All-In)

Thank.

Best Regards,

Susan Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67411730 Fax: 67445746

On Saturday, 15 June 2019, 12:19:05 pm SGT, Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Your Ref: **GBF847T180709**

Without Prejudice

Our Ref: CC4/ASM18012692/Upb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING PA 2281Y(AXA) AND GBF 847T ON 09/07/2018

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$8,400.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref: GBF847T180709

Date: 19/08/2018

Your Ref:

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG TPE / CHANGI
INVOLVING GBF847T AND PA2281Y ON 09/07/2018**

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**, the registered owners of m/vehicle – **GBF847T** at all material times of the above accident. Our/my vehicle was surveyed by “**AXA**” authorized appraiser and we/I based our/my claims on his recommendation for **S\$8,500-00** being the repair for **04** Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **PA2281Y** when the same was involved in the aforesaid accident with our/my m/vehicle – **GBF847T**.

We/I whereby you are the insurers of m/vehicle **PA2281Y** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GBF847T** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	8,500-00
(b) LOU for pre-repair notice 02 days @ S\$60-00		120-00
(c) LOU Fee for 04 days @ S\$60-00		240-00
(d) GIA / LTA search fee		7-45

Total Amount

S\$ 8,867-45

We/I enclose herewith copies of the supporting documents for vehicle no. **GF847T** as follows:-


- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,


The owner of m/vehicle **GF847T**
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18012692/Upb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: KIAN CHUAN

Date : 30-08-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 2281Y	Veh. Inspected	GBF 847T
Policy No.	P0902358	Coverage (\$)	0.00
Claim No.	S8M00NZW	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	12/07/2018

2. Vehicle Particulars & Condition

Make & Model	FIAT DOBLO CARGO (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZFA26300006C23135	Colour	WHITE
Odometer	54196	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	PIRELLI	6 mm
L/H Front Tyre	195/60 R16	PIRELLI	6 mm
R/H Rear Tyre	195/60 R16	PIRELLI	6 mm
L/H Rear Tyre	195/60 R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSATINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/07/2018	Inspection Date	11/07/2018
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 847T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RH TAILGATE (CONSISTENT)	DENTED / BENT	1,895.90	1,895.90
1	REAR RH TAILGATE LOCK TOP (CONSISTENT)	NOT NECESSARY	189.30	-
1	REAR RH TAILGATE LOCK LOWER (CONSISTENT)	TWISTED	192.90	192.90
1	REAR RH TAILGATE WEATHERSTRIP (CONSISTENT)	TORN	297.00	297.00
1	REAR RH TAILGATE OUTER GARNISH (CONSISTENT)	GRAZED	321.80	321.80
1	REAR RH TAILGATE "FIAT LOGO" EMBLEM (CONSISTENT)	NOT NECESSARY	87.80	-
1	REAR RH TAILGATE "PROFESSIONAL" EMBLEM (CONSISTENT)	NECESSARY	163.50	163.50
1	REAR RH TAILGATE GLASS (CONSISTENT)	SHATTERED	540.00	540.00
1	REAR LH TAILGATE (CONSISTENT)	DENTED / BENT	2,395.00	2,395.00
1	REAR LH TAILGATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	344.50	-
1	REAR LH TAILGATE LOCK (CONSISTENT)	NOT NECESSARY	331.00	-
1	REAR LH TAILGATE INNER TRIM BOARD (SN) (CONSISTENT)	NOT NECESSARY	384.90	-
1	REAR LH TAILGATE HANDLE OUTER GARNISH (CONSISTENT) }	GRAZED	369.80	369.80
1	REAR LH TAILGATE OUTER HANDLE (CONSISTENT) }		556.40	-
1	REAR LH TAILGATE "MAXI" EMBLEM (CONSISTENT)	NECESSARY	86.00	86.00
1	REAR LH TAILGATE "DOBLO" EMBLEM (CONSISTENT)	NECESSARY	118.00	118.00
1	REAR LH TAILGATE WIPER MOTOR (CONSISTENT)	CRACKED	428.00	428.00
1	REAR LH TAILGATE WIPER LINK (CONSISTENT)	NOT NECESSARY	165.30	-
1	REAR LH TAILGATE WIPER RUBBER (CONSISTENT)	NOT NECESSARY	98.00	-
1	REAR LH TAILGATE GLASS (CONSISTENT)	SHATTERED	841.50	841.50
1	REAR LH NUMBER PLATE OUTER GARNISH (CONSISTENT)	NO SUCH PARTS	387.00	-
1	REAR BUMPER (CONSISTENT)	DENTED / DEFORMED	745.00	689.02
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	475.30	475.30
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	CRACKED	117.60	117.60
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	430.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	347.70	-

Report Ref No. CC4/ASM18012692/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAIL LAMP LH (CONSISTENT)	NOT NECESSARY	462.70	-
	LESS 10% DISCOUNT		-	-893.13
			12,771.90	8,038.19
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH TAILGATE "90" EMBLEM (SN) (CONSISTENT)	NECESSARY	97.50	60.00
1	REAR RH TAILGATE "MULTIJET" EMBLEM (SN) (CONSISTENT)	NECESSARY	119.60	60.00
1	REAR RH TAILGATE "6 PAX" EMBLEM (SN) (CONSISTENT)	NECESSARY	12.00	10.00
1	REAR RH TAILGATE GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	REAR LH TAILGATE "70 KM/H" STICKER (SN) (CONSISTENT)	NECESSARY	12.00	10.00
1	REAR LH TAILGATE GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	65.00	65.00
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	220.00	200.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	58.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE & BASE (SN) (CONSISTENT)	BENT	48.00	40.00
1	REAR "CORPORATE" ADVERTISEMENT & ART WORK (SN) (CONSISTENT)	NECESSARY	400.00	300.00
			1,242.10	825.00
	<u>LABOUR</u>			
	REMOVE & INSTALL REAR RH & LH WINDSCREEN GLASS TO FACILITATE REPAIRS.		240.00	200.00
	REMOVE AND REFIX REAR RH & LH TAILGATE COMPONENTS & WIPER MECHANISM.		180.00	120.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTENING & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,200.00	550.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		1,200.00	800.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		80.00	20.00

Report Ref No. CC4/ASM18012692/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REAR REVERSE SENSOR.		100.00	50.00
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		120.00	60.00
			3,120.00	1,800.00
GRAND TOTAL			17,134.00	10,663.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,500.00

Report Ref No. CC4/ASM18012692/Upb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.