

Surveyor:

Marais

ASSIGNMENT (Office)

CWS

From (Person):

May Chua

of

FCI

Date/Time: 12/7/18 @ 2.18pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 34494

Insured:

SH 6440G

at Workshop m/s:

Rico 60 Auto

Tel:

88112101

of

8 kaki Bukit Ave 4 #02-24 Premier

Policy No:

Claim No:

D18005313MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

2.23pm @ 12/7/18

Person Contacted:

John

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SJF 34494 - NALINCH 17017928/24 DOA: 15/04/2017
	SH 6440G - CS/ICS18005861/KHbn2 DOA: 28/03/2018
13/7/18 @ 2.24pm	John said vehicle is still not in. Once in he will arrange.
13/8/18 - 2.23pm	Vehicle still not in yet (John)
9/10/18	Informed FCI pending workshop est by email
12/11/18	Email preli revised to FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJF3449 U
 at Workshop m/s: Rico
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: 27k.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SJF3449 Yr Regn: 27/5 08
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Honda Fit C.C. 1339
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GE61067401
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/50 R16
 R: Achilles
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Harwood
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 27/1/18 D.O.I. 5/10/18
 Survey held at _____
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or
Left
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
4/1/18 10 min LTA 18664 + 8336

9/1/18 confirmed L/S \$6500 with Kelvin. (Red 19, 1476.80, 7590)

MV: \$27K (Est) LTA: \$18,664 NV: \$8336

RECEIVED 12 NOV 2018

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?
12/11 - typist

Report Format: CWS
 Lump Sum / I.B.I. (\$) 6500/2

Days Of Repair: 9
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:
 Transportation: 50
 S + RS: 50
 Photos: 74
 Other: 17/1/18

15x15 = 225
170 + 225
50
50
74
<u>569</u>

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005313MFSH

Our ref: CS/FCI18012696/Uvd3

DATE: 12/11/2018

The Motor Claims Department
M/s: MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SJF 3449U


We thank for your instruction on 12/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 5/10/2018 at the premises of M/s RICO 60 AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$25,976.80
Revised Estimate Amount	: S\$6,500.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion. The chassis frame affected due to collision.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	10-07-2018	Our Ref No. D18005313MFSH
Accident Date	02-07-2018	Claim Type. Third Party
Insured Vehicle	SH6440G	Third Party Vehicle. SJF3449U
Survey Location	8 Kaki Bukit Avenue 4 #02-24 Premier @ Kaki Bukit	
Contact Person.	CASS CHUA	
Contact No.	62866060/ 0	Fax No. 62867060
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	RICO 60 AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242221)



PRI Documents



Close



PRI Header Details

Claim No	D18005313MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & RICO 60 /
Workshop Name	RICO 60 AUTO SERVICES PTE LTD (Contact Person : CASS CHUA)	Survey Location & Contact Details	8 Kaki Bukit Avenue 4 #02-24 Premier @ Kaki Bukit Mobile: 0 , Phone: 62866060 , Fax: 62867060 EmailId: CLAIMS@RICO60.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6440G	TP Vehicle No	SJF3449U
PRI Recieved Date	10-07-2018 06:39:36 PM	Surveyor Appointed Date	12-07-2018 02:17:29 PM	Surveyor Accept Date	12-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 12 November 2018 11:16 AM
To: 'Claim Workflow System'
Cc: 'MAYCHUA@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18005313MFSH/1, SJF 3449U
Attachments: SJF 3449U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJF 3449U
Date of survey: 5/10/2018
Number of days : 9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 9 October 2018 2:22 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005313MFSH/1, SJF 3449U

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJF 3449U on 5/10/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 12 July 2018 2:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005313MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 12 July 2018 2:18 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18005313MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 9 October 2018 2:22 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005313MFSH/1, SJF 3449U

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJF 3449U on 5/10/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 12 July 2018 2:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005313MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 12 July 2018 2:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005313MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find o](#)

[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Honda Jazz 1.3A \(COE till 06/2023\)](#)

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Honda Jazz 1.3A (COE till 06/2023)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)

Car Details

Price **\$30,888**

Depreciation \$6,590 /yr

Reg Date 13-Jun-2008
(4yrs 8mths 7days COE left)

Manufactured 2008

Mileage -

Transmission Auto

Engine Cap 1,339 cc

Road Tax \$590 /yr

Power 60.0 kW (80 bhp)
[View specs of the Honda Jazz \(2002-2006\)](#)

Curb Weight 1,040 kg

Features Powerful And Fuel Efficient 1.4A I-DSI SOHC Engine, CVT Auto Transmission, Dual SRS Airbags, ABS, Knockdown Rear Seats.

Accessories Leather Seats, Factory Fitted Audio System, Retractable Side Mirrors With Indicators, Solar Film, Sports Rims With Michelin Tyres.

Description Lady Owner. Clean, And Neat Interior, Very Well-Maintain, Supreme Condition, Servicing Just Done, No Repairs Needed, Viewing Strictly By Appointment Only.

COE \$19,107

OMV \$14,433

ARF \$14,433

Dereg Value \$17,913 as of today (change)

No. of Owners 2



Seller Infor

Contact Perso

Contact No.

Enquiry

USEFUL FOR

» Indemnity

» Receipt

» M01

[Compare](#)

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Honda Price Range Depreciation 2008 Vehicle Type

Advanced Search

Home » Used Cars » Victory Cars Trading Pte Ltd » Honda Fit 1.3A G (New 5-yr COE)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Honda Fit 1.3A G (New 5-yr COE)

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$29,800	?
Depreciation	\$5,960 /yr	?
Reg Date	30-May-2008 (5yrs COE left)	?
Manufactured	2008	?
Mileage	105,000 km (10.4k /yr)	?
Transmission	Auto	?
Engine Cap	1,339 cc	?
Road Tax	\$590 /yr	?
Power	73.0 kW (97 bhp) View specs of the Honda Fit (2008-2013)	?
Curb Weight	1,010 kg	?
Features	Work Late? Call Us For A After Work Hour Appointment. We Will Be Glad To Serve. No Obligations. Mechanical Or STA Inspection Welcomed. Cheapest!	?
Accessories	Fully Original, No Modifications, Double Din Player, Sports Rims, Leather Seats, Reverse Sensors, Solar Film.	?
Description	1 Owner, Very Well Kept, With New Tyres, Stock Condition. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Provide Loans, Trade In, Insurance And Scrap Services With Flexibility. Kindly Call Us Now For More Information. STA/VICOM/Own Workshop Pre Purchase Evaluation Welcomed!	?
COE	-	?
OMV	\$12,663	?
ARF	\$12,341	?
No. of Owners	1	?
Type of Veh	Hatchback	?
Category	COE Car, Premium Ad Car	?
Availability	Available	?

PREMIUM AD

Add to Shortlist Add to Compare Add a Note



Posted on: 04-Jul-2018 | Last Updated on: 04-Jul-2018

Tags: Honda Fit, 2008 Honda Fit, Honda, Fit, Used Honda

Upfront Payment

» more Financial info

Transfer Fee	\$25	?
Down Payment	\$8,940 (change)	Maximum 70% Loan ?
1st Instalment		?



Seller Information

Company	Victory Cars Trading Pte Ltd » dealer's pricelist » 78 vehs sold 37 vehs available
Address	65 Ubi Road 1 #04-24 Search cars nearby this location
Location	Oxley Bizhub
Office No	63854916
Contact Person(s)	Mr Lim 92470299 Mr Lee 86885879 Mr Tan 90999505

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Commercial Vehicle

PAN PACIFIC

SERVICE YOU DESERVE, PEOPLE YOU TRUST

MORE THAN 1,000 FLEET UNIT
Daily, Weekly, Monthly & Yearly Fleet Available

YUN NAM

IMPROVES SCALP HEALTH!

FREE
(U.P.: \$388)

1 FASTGro™ Hair Care Product Set
+
1 FASTGro™ Treatment

Get It Now

T&C apply



Compare

- Class 2 Bike Choices
- Audi is the least reliable car?
- Private Property prices.....still up or down? Part II

Honda Price Range Depreciation 2008 Vehicle Type

Advanced Search

Home » Used Cars » Mandai Motor Trading » Honda Fit 1.3A L (New 5-yr COE)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Honda Fit 1.3A L (New 5-yr COE)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$43,800	?
Depreciation	\$8,760 /yr	?
Reg Date	28-May-2008 (5yrs COE left)	?
Manufactured	2008	?
Mileage	-	?
Transmission	Auto	?
Engine Cap	1,339 cc	?
Road Tax	\$590 /yr	?
Power	73.0 kW (97 bhp) View specs of the Honda Fit (2008-2013)	?
Curb Weight	1,030 kg	?
Features	1.3L Fuel Efficient I-VTEC Engine, 5 Speed CVT Auto Transmissions, Dual Front SRS Airbags, ABS, EPS, Immobilizer, Knockdown Rear Seats, SRS Airbags.	?
Accessories	Sports Rims, Leather Seats, Audio Player, Reverse Sensors, Alarm System.	?
Description	New 5 Years COE, Good Condition, Fuel Efficient And Reliable, Well Maintained, Loan Available, Trade In Welcome, Price Negotiable, Call Or Visit Our Showroom For Viewing Now!	?
COE	-	?
OMV	\$12,141	?
ARF	\$12,141	?
No. of Owners	2	?
Type of Veh	Hatchback	?
Category	COE Car	?
Availability	Available	?

Add to Shortlist

Add to Compare

Add a Note

Posted on: 17-May-2018 | Last Updated on: 06-Jul-2018

Tags: Honda Fit, 2008 Honda Fit, Honda, Fit, Used Honda

Upfront Payment

» more Financial Info

Transfer Fee	\$25	?
Down Payment	\$13,140 (change)	Maximum 70% Loan ?
1st Instalment	\$607	?
Total Upfront Payment	\$13,772 (excluding insurance)	?

Estimates based on 70% loan at 3.75% interest rate. Check with seller for exact figure.

Items for Honda Fit

» View All



Seller Information

Company	Mandai Motor Trading » dealer's pricelist » 39 vehs sold 28 vehs available	
Address	31 West Coast Highway #01-08/09 Search cars nearby this location	
Location	West Coast Car Mart	
Office No	67775585	
Contact Person(s)	Mr Tee	90058812
	Mr Ee	96275585
	Ms Li Jin	97548093
	David	93860705

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.
Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7055J
Vehicle Details	
Vehicle No.:	SJF3449U
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	L13A4076303
Chassis No.:	GE61067401
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$11,467.00
Original Registration Date:	27 May 2008
First Registration Date:	27 May 2008
Transfer Count:	3
Actual ARF Paid:	\$11,467.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,096.00
COE Rebate Amount:	\$17,720.00
Total Rebate Amount:	\$17,720.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Oct 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 7055J

Vehicle Details

Vehicle No.: SJF3449U
Vehicle to be Exported: Yes
Intended De-registration Date: 06 Jul 2018
Vehicle Make: HONDA
Vehicle Model: FIT 1.3G A
Primary Colour: Blue
Manufacturing Year: 2008
Engine No.: L13A4076303
Chassis No.: GE61067401
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$11,467.00
Original Registration Date: 27 May 2008
First Registration Date: 27 May 2008
Transfer Count: 3
Actual ARF Paid: \$11,467.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 May 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$19,096.00
COE Rebate Amount: \$18,664.00
Total Rebate Amount: \$18,664.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Jul 2018

OK



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJF 3449 U
HONDA FIT
GE6

924
not authorized
claim
2/5# 6500/1
2/10/18
Toh pde Hteyng

ATTN:				
NO.	DESCRIPTION - PARTS	QTY	PRICE	
	Front bonnet	Buc	S 543.80	—
	Front bonnet hinge L+R	3x2	S 82.00	—
	Front bonnet lock	1x1	S 109.50	—
	Front bonnet rubber L+R	1x1	S 47.20	—
	Front bonnet air duct rubber	1x1	S 75.00	X
	Front bonnet stand	1x1	S 48.20	X
	Front bumper	543.20	S 623.00	—
	Front bumper towing cap	1x1	S 34.00	—
	Front bumper grille	1x1	S 129.60	X
	Front bumper reinforcement	1x1	S 272.10	—
	Front bumper retainer L+R	2x1	S 64.00	—
	Front bumper bracket L+R	2x1	S 76.00	X
	Front grille	1x1	S 177.00	X
	Front grille logo	1x1	S 56.00	X
	Front fender L+R	481.4 o/s n/s Buc	S 962.80	1x2
	Front fender cowling L+R	1x1	S 186.40	—
	Headlamp L+R	1x1	S 1,424.00	—
	Horn	1x1	S 66.70	X
	Aircon condensor	1x1	S 822.80	—
	Aircon condensor liquid pipe	1x1	S 112.90	X
	Aircon condensor discharge pipe	1x1	S 216.90	X
	Aircon condensor suction pipe	1x1	S 200.70	X
	Aircon condensor electric fan cowling assy	1x1	S 598.50	X
	Radiator	1x1	S 1,382.60	—
	Radiator electric fan cowling assy	1x1	S 582.70	X
	Radiator spare tank	1x1	S 65.60	X
	Radiator top hose	1x1	S 37.00	—
	Radiator bottom hose	1x1	S 28.00	X
	Radiator top bracket L+R	1x1	S 41.00	—
	Radiator thermostat housing	1x1	S 85.20	X
	washer tank	1x1	S 78.40	X
	washer tank neck	1x1	S 28.00	X
	Alternator	1x1	S 752.80	X
	ABS actuator	1x1	S 2,886.20	X
	Air cleaner box	1x1	S 284.50	X
	Intake manifold	1x1	S 792.30	X
	Battery cover	1x1	S 36.20	X
	Battery bracket	1x1	S 25.00	X
	Battery tray	1x1	S 27.00	X
	Engine mounting RH	1x1	S 268.40	X

	Engine mounting bracket RH	17	\$	113.80	X
	Engine mounting LH	17	\$	234.30	X
	Engine mounting bracket LH	17	\$	162.40	X
	Engine mounting rear	17	\$	187.90	X
	Engine mounting bracket rear	17	\$	126.70	X
	Engine mounting front	17	\$	176.80	X
	Engine mounting bracket front	17	\$	110.40	X
	Front support panel	Bud/Weld	\$	679.00	/
	Front wheel housing LH	R	\$	847.20	x
	Front chassis member LH+RH	R	\$	2,680.00	x
	Front chassis extension LH+RH	R	\$	1,680.00	X
	Front windscreen moulding	1750 5400	\$	180.00	X
	SUBTOTAL		\$	21,508.50	
	LESS 20%		\$	4,301.70	
	PARTS TOTAL		\$	17,206.80	
	SPECIAL NETT		QTY	PRICE	
	FRONT NUMBER PLATE	320	\$	80.00	40
	FRONT BUMPER CLIPS	M	\$	100.00	30
	RADIATOR COOLANT	M	\$	150.00	30
	FRONT BONNET ISOLATOR CLIPS	17	\$	100.00	X
	FRONT FENDER COWLING CLIPS	M	\$	100.00	50
	SPECIAL NETT TOTAL		\$	530.00	
	LABOUR		QTY	PRICE	
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN		\$	2,400.00	1200
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		\$	2,200.00	1200
	TO RUST PROOF ACCIDENT AFFECTED AREA		\$	160.00	100
	TO RNR FRONT WINDSCREEN	17	\$	200.00	X
	TO RNR ENGINE ASSY TO ASSIST WORK LOAD	17	\$	600.00	X
	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	17	\$	400.00	X
	TO CHECK CHASSIS ALIGNMENT	17	\$	400.00	X
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	17	\$	200.00	X
	TO RNR UNDERCARRIAGE SYSTEM	17	\$	800.00	X
	TO CHECK WHEEL ALIGNMENT	17	\$	200.00	X
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS		\$	150.00	100
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS		\$	80.00	30
	TO RNR TYRE AND WHEEL BALANCING	17	\$	100.00	X
	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.		\$	200.00	X
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD		\$	150.00	X
	LKK Auto Consultants hence notify the Repairer of the following:				
	• To resurvey before/after spray painting				
	• To display damaged part(s) during resurvey				
	• Parts prices are subject to confirmation				
	• Third party survey is on a "Without Prejudice" basis				
	• No illegal modification(s) is allowed				
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
	Acknowledged by Repairer				
	Signature:				
	Date:				
	LABOUR TOTAL		\$	8,240.00	
	GRAND TOTAL COST		\$	25,976.80	
				2780	
				8180	
				6544	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012696/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6440G	Veh. Inspected	SJF 3449U	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005313MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	12/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	GE61067401	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	HANKOOK	6 mm	
L/H Front Tyre	205/50 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/50 R16	ACHILLES	6 mm	
L/H Rear Tyre	205/50 R16	ACHILLES	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/07/2018	Inspection Date	05/10/2018	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 3449U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	BUCKLED	543.80	543.80
2	FRONT BONNET HINGE L+R	BENT	82.00	82.00
1	FRONT BONNET LOCK	TWISTED	109.50	109.50
2	FRONT BONNET RUBBER L+R	NECESSARY	47.20	47.20
1	FRONT BONNET AIR DUCT RUBBER	NOT NECESSARY	75.00	-
1	FRONT BONNET STAND	NOT NECESSARY	48.20	-
1	FRONT BUMPER	DISTORTED	623.00	543.20
1	FRONT BUMPER TOWING CAP	TORN	34.00	34.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	129.60	-
1	FRONT BUMPER REINFORCEMENT	DISTORTED	272.10	272.10
2	FRONT BUMPER RETAINER L+R	BENT	64.00	64.00
2	FRONT BUMPER BRACKET L+R	NO SUCH PARTS	76.00	-
1	FRONT GRILLE	NOT NECESSARY	177.00	-
1	FRONT GRILLE LOGO	NOT NECESSARY	56.00	-
2	FRONT FENDER L+R	N/S BUCKLED / O/S TO REPAIR SEE LABOUR	962.80	481.40
2	FRONT FENDER COWLING L+R	DEFORMED / TORN	186.40	186.40
2	HEADLAMP L+R	N/S BROKEN / O/S CRACKED	1,424.00	1,424.00
1	HORN	NOT NECESSARY	66.70	-
1	AIRCON CONDENSOR	BENT / TWISTED	822.80	822.80
1	AIRCON CONDENSOR LIQUID PIPE	NOT NECESSARY	112.90	-
1	AIRCON CONDENSOR DISCHARGE PIPE	NOT NECESSARY	216.90	-
1	AIRCON CONDENSOR SUCTION PIPE	NOT NECESSARY	200.70	-
1	AIRCON CONDENSOR ELECTRIC FAN COWLING ASSY	NOT NECESSARY	598.50	-
1	RADIATOR	BENT / CRACKED	1,382.60	1,382.60
1	RADIATOR ELECTRIC FAN COWLING ASSY	NOT NECESSARY	582.70	-
1	RADIATOR SPARE TANK	NOT NECESSARY	65.60	-
1	RADIATOR TOP HOSE	TWISTED	37.00	37.00
1	RADIATOR BOTTOM HOSE	NOT NECESSARY	28.00	-
2	RADIATOR TOP BRACKET L+R	TWISTED	41.00	41.00

Report Ref No. CS/FCI18012696/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR THERMOSTAT HOUSING	NOT NECESSARY	85.20	-
1	WASHER TANK	NOT NECESSARY	78.40	-
1	WASHER TANK NECK	NOT NECESSARY	28.00	-
1	ALTERNATOR	NOT NECESSARY	752.80	-
1	ABS ACTUATOR	NOT NECESSARY	2,886.20	-
1	AIR CLEANER BOX	NOT NECESSARY	284.50	-
1	INTAKE MANIFOLD	NOT NECESSARY	792.30	-
1	BATTERY COVER	NOT NECESSARY	36.20	-
1	BATTERY BRACKET	NOT NECESSARY	25.00	-
1	BATTERY TRAY	NOT NECESSARY	27.00	-
1	ENGINE MOUNTING RH	NOT NECESSARY	268.40	-
1	ENGINE MOUNTING BRACKET RH	NOT NECESSARY	113.80	-
1	ENGINE MOUNTING LH	NOT NECESSARY	234.30	-
1	ENGINE MOUNTING BRACKET LH	NOT NECESSARY	162.40	-
1	ENGINE MOUNTING REAR	NOT NECESSARY	187.90	-
1	ENGINE MOUNTING BRACKET REAR	NOT NECESSARY	126.70	-
1	ENGINE MOUNTING FRONT	NOT NECESSARY	176.80	-
1	ENGINE MOUNTING BRACKET FRONT	NOT NECESSARY	110.40	-
1	FRONT SUPPORT PANEL	BENT / TWISTED	679.00	679.00
1	FRONT WHEEL HOUSING LH	TO REPAIR SEE LABOUR	847.20	-
2	FRONT CHASSIS MEMBER LH+RH	TO REPAIR SEE LABOUR	2,680.00	-
2	FRONT CHASSIS EXTENSION LH+RH	TO REPAIR SEE LABOUR	1,680.00	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	180.00	-
	LESS 20% DISCOUNT		-4,301.70	-1,350.00
			17,206.80	5,400.00
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BROKEN	80.00	40.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	RADIATOR COOLANT (SN)	NECESSARY	150.00	30.00
1	FRONT BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	100.00	-

Report Ref No. CS/FCI18012696/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER COWLING CLIPS (SN)	NECESSARY	100.00	50.00
			530.00	150.00
	LABOUR			
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK & REALIGN.INCLUSIVE OF THE REPAIR OF O/S FRONT FENDER,FRONT WHEEL HOUSING LH,FRONT CHASSIS MEMBER LH+RH AND FRONT CHASSIS EXTENSION LH+RH.		2,400.00	1,200.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		2,200.00	1,200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.		160.00	100.00
	TO RNR FRONT WINDSCREEN.	NOT NECESSARY	200.00	-
	TO RNR ENGINE ASSY TO ASSIST WORK LOAD.	NOT NECESSARY	600.00	-
	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS.	NOT NECESSARY	400.00	-
	TO CHECK CHASSIS ALIGNMENT.	NOT NECESSARY	400.00	-
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	NOT NECESSARY	200.00	-
	TO RNR UNDERCARRIAGE SYSTEM.	NOT NECESSARY	800.00	-
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	200.00	-
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS.		150.00	100.00
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.		80.00	30.00
	TO RNR TYRE AND WHEEL BALANCING.	NOT NECESSARY	100.00	-
	TO DO DIAGNOSIS AND RESET,REPROGRAM OR CODING FAULT CODE.	NOT NECESSARY	200.00	-
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
			8,240.00	2,630.00
	GRAND TOTAL		25,976.80	8,180.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00

Report Ref No. CS/FCI18012696/Uvd3n2

MARKET VALUE: \$27,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$18,664.00=NETT VALUE: \$8,336.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.