

REPAIR ESTIMATE*

VEHICLE NO : SHA3632G

DATE 9. Jul. 2018

MAKE : HYUNDAI

MODEL : i40

DOA: 6. Jul. 2018

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover — <i>me</i>			\$562.30
10	Front Bumper Clips — <i>me</i>		\$2.20	\$22.00
1	Front Bumper Bracket Top (LH) <i>X me</i>			\$22.40
1	Front Bumper Side Bracket (LH) <i>X me</i>			\$24.60
1	Radiator Grille — <i>me</i>			\$417.10
1	Headlamp Support Panel <i>X me</i>			\$1,067.50
SUB TOTAL				\$2,115.90
LESS 20%				\$423.18
DISCOUNTED TOTAL				\$1,692.72
1	Front Licence Plate — <i>me</i>			\$25.00
				\$25.00
Labour Charge				
1	Panel Beating			\$300.00 <i>200</i>
1	Spray Painting Charge			\$300.00 <i>200</i>
1	Wiring Charge			\$50.00 <i>X 1</i>
TOTAL LABOUR				\$650.00
ESTIMATE TOTAL				\$2,367.72

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

②

DATE 9. Jul. 2018

MODEL : i40

DOA: 6. Jul. 2018

LS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper — <i>Paint</i>			\$603.60
10	Rear Bumper Clips — <i>see</i>		\$2.20	\$22.00
1	Rear Bumper Sponge x <i>see</i>			\$143.40
1	Rear Bumper Reinforcement x <i>see</i>			\$225.00
				\$504.40
	SUB TOTAL			\$1,498.40
	LESS 20%			\$299.68
	DISCOUNTED TOTAL			\$1,198.72
1	Advertisement – Rear Bumper — <i>see</i>			\$50.00
2	Advertisement – Rear Fenders – RH / LH — <i>see</i>		\$100.00	\$200.00
				\$250.00
	Labour Charge			
1	Panel Beating			250.00 200
1	Spray Painting Charge			250.00 200
	TOTAL LABOUR			\$500.00
	ESTIMATE TOTAL			\$1,948.72

Kaluh LKKK

N 11/7/13 103.hrs.

30 hrs.

L/S

Affor Repair p/h

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.