

ASS. REC. BY:

REF:

023/AXA17015306/190-1

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Tan Wen Cory

of

AXA

Date/Time:

13/7/2018

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SKW 4802A

Insured:

SEA 2498R

at Workshop m/s

N-51

Tel:

68420051

or BKJ Kaki Bukit #01-17

Policy No:

GA145705

Claim No:

COM4603

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

4/8/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle

IN/OUT

Date/Time	Action/Instruction (X)	Estimate	PRS
	SKW 4802A - NA	CTI 17015181	CS. DDA: 4/8/2017
	SEA 2498R - X		
	Disassemble Part	08/08/2017	
	After repair	11/08/2017	

200817 4:46pm Email to Cynthia Koh thru Mercedes

19/7/18 Submit to 3650, 5 days.
cred to 7950, 68%.

RECEIVED 20 JUL 2018

19/7/2018

...CLAIM SUBFOLDER...(Pending for Payment)

Paper Survey PRI BT

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Aug 2017		07 Aug 2017 15:54		08 Sep 2017 09:55 S\$0.00 (S\$107.00)		Pending for Payment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LEE, CHOON KHIANG, ID: S1887870G, Tel: +6581269498, Email: admin@INSURELINK.COM.SG								
Main Claimant:	TAN MENG HWA								
Vehicle Reg. No.:	SKW4802A	Date of Loss:	04/08/2017 14:00 - :59 [21 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0447003	Policy/Cover Note No.:	GA145705 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGB2498R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 17/08/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (12/07/2018): Please conduct Paper survey urgently AXA_SG (30/08/2017): C0447003/GA145705 AXA_SG (30/08/2017): TP settlement - C0447003/GA145705 AXA_SG (07/08/2017): WP / New TP Assignment - C0447003/GA145705 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHENG BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D'O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JA LIN
TAN YINGXIAN SELWYN

Unique Entity Number: 200721148H



✓Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490
Branch:
133 New Bridge Road
#10-03 Chinatown Point
Singapore 059413

HEAD OFFICE:
TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH
TEL : (65) 63580703
TEL : (65) 65330868

BRANCH
TEL : (65) 65342811 (Hunting)
TEL : (65) 65330869

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this

Our Ref : AKN-atv-Ins-N63-106994-18
Your Ref : SGB 2498 R

Date: 4 July 2018

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Department

URGENT

61160363

3019431043 - - -

WITHOUT PREJUDICE
BY HAND



LEE CHOON KHIANG
Apt Blk 256 Kim Keat Avenue
#03-162
Singapore 310256



CERTIFICATE OF POSTING
[For your information only]

Dear Sir,

CLAIMANT : TAN MENG HWA
ACCIDENT INVOLVING SKW 4802 A & SGB 2498 R ON 04-AUG-2017 ALONG SLIP ROAD FROM PIE TOWARDS CIRCUIT ROAD AT ABOUT 1405HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **04-AUG-2017 ALONG SLIP ROAD FROM PIE TOWARDS CIRCUIT ROAD AT ABOUT 1405HOURS** involving our client's vehicle registration number **SKW 4802 A** and vehicle registration number **SGB 2498 R** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair	\$12,305.00
02.	Rental fees	\$ 840.00
03.	Survey report fees	\$ 871.00
04.	Towing fees	\$ 100.00
05.	GIA & LTA search / report fees	\$ 41.84
06.	Cost Contribution (at this stage)	\$ 1,605.00
07.	Disbursements (at this stage)	\$ 50.00
	TOTAL	\$15,812.84

.../2 to be continued next page

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN MENG HWA
BLK 120B EDGEDALE PLAINS #09-287
SINGAPORE 822120

Contact : 96371247

TAX INVOICE

Date : 07/06/2018
Date in : 04/08/2017
Vehicle Num. : SKW4802A
Make/Model : NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR-2015
Chassis/Eng# : MNTBBAB17Z0024984/HR16975272B
Accident Date : 04/08/2017
Claim No : CLM14147
Reference : AUG-12/2017
Policy No. : DMPCSN1548661601 (06/11/2017)

LUMPSUM REPAIR BILL AS PER SURVEYOR REPORT REF : <u>0244-18-N51</u> DATED <u>14/05/2018</u> BY PAR AUTOMOTIVE CONSULTANCY	Amount S\$ 11,500.00
--	-------------------------



E. & O.E.	Sub S\$:	11,500.00
	Add GST (7 %) S\$:	805.00
	Total Amount S\$:	<u>12,305.00</u>

for N-51 AUTOMOTIVE PTE LTD



VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AKN-atv-Ins-N63-106994-18
Your Ref : SGB 2498 R

Date: 4 July 2018

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

LEE CHOON KHIANG

Apt Blk 256 Kim Keat Avenue
#03-162
Singapore 310256

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of SKW 4802 A;
- (b) Photographs taken at scene of accident;
- (c) LTANet Search;
- (d) Certificate of Insurance;
- (e) Registration Card;
- (f) Towing receipt;
- (g) Rental agreement, rental invoice & rental receipt;
- (h) Final Repair Bill;
- (i) Surveyor's report & invoice; and
- (j) 121 coloured photographs depicting the damages to motor vehicle SKW 4802 A.

(P.S:- Original photographs will be sent to insurance co. only)

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



(HEAD OFFICE)

Enc.

cc: client: Tan Meng Hwa

As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0244-18-N51

14 May 2018

Tan Meng Hwa
Blk 120B Edgedale Plains #09-287
Singapore 822120

INVOICE No. 0244-18-N51

Vehicle No. SKW4802A

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$871.00
	Total amount payable	<u>\$871.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0244-18-N51

14 May 2018

ACCIDENT VEHICLE SURVEY REPORT

Tan Meng Hwa
Blk 120B Edgedale Plains #09-287
Singapore 822120

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SKW4802A	<i>Odometer:</i>	57840km
<i>Make & Model:</i>	Nissan Sylphy 1.6 CVT	<i>Colour:</i>	Red
<i>Chassis number:</i>	MNTBBAB17Z0024984	<i>Date of accident:</i>	04/08/2017
<i>Year of Regn.:</i>	30/10/2015	<i>Date inspected:</i>	07/08/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	11/08/2017

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	4mm/Bridgestone	4mm/Bridgestone	195/60R16
<i>Rear:</i>	4mm/Bridgestone	4mm/Bridgestone	195/60R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front RH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON CONDENSER RH AIR GUIDE	1	warped	105.60	105.60 SVC X
FRONT BONNET	1	buckled	917.70	917.70 RX
FRONT BONNET WEATHERSTRIP	1	deformed	44.50	44.50 NN X
FRONT BUMPER	1	squashed	535.50	✓535.50 DD ✓
FRONT BUMPER INNER SPONGE	1	deformed	280.70	✓280.70 CUTV ✓
FRONT BUMPER REINFORCEMENT	1	bent	561.90	561.90 R X
FRONT BUMPER REINFORCEMENT RH BRACKET	1	bent	94.50	94.50 R X
FRONT GRILLE	1	fractured	356.60	✓356.60 CUTV ✓
FRONT RH DRIVE SHAFT	1	bent NN	1,134.70	1,134.70 SVC X
FRONT RH FENDER	1	buckled	623.60	✓623.60 DBV ✓
FRONT RH FENDER INNER SHIELD	1	fractured	70.10	✓70.10 CUTV ✓
FRONT RH HEADLAMP PANEL	1	buckled	161.90	161.90 R X
FRONT RH SHOCK ABSORBER TOP MOUNTING BEARING	1	necessary	45.00	-45.00 NN X
FRONT RH STEERING TIE ROD END	1	dislodged	79.20	△ 79.20 BTV ✓ NN
FRONT RH WHEEL HUB	1	dislodged	370.30	✓370.30 DLV ✓
FRONT STABILIZER BAR	1	bent	221.40	221.40 SVC X
FRONT STEERING RACK & PINION	1	bent	1,745.50	1,745.50 SVC X
Subtotal before discount			SS 7,348.70	SS 7,348.70 3234.60
Percentage discount 30% and 30%			SS 2,204.61	SS 2,204.61 970.38
Sub-total 1			SS 5,144.09	SS 5,144.09 2264.22
FRONT BONNET RUBBER GUIDE STOPPER L/R	2	deformed	40.00	-40.00 NN X
FRONT BUMPER COVER L/R	2	na	225.00	0.00 NNA
FRONT BUMPER INNER AIR GUIDE L/R- RH	1/2	warped	351.00	175.50 351.00 BTV ✓
FRONT BUMPER LOWER COVER	1	fractured	181.80	181.80 NN X
FRONT BUMPER LOWER GRILLE	1	fractured	255.40	135.40 255.40 CUTV ✓
FRONT BUMPER SIDE RETAINER L/R	2	necessary	57.60	✓57.60 NECV ✓
FRONT ENGINE CROSS MEMBER	1	bent	429.00	429.00 R X NN
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	64.60	✓64.60 NECV ✓
FRONT GRILLE BRACKET L/R	2	bent	41.00	✓41.00 BTV ✓
FRONT RH A.B.S SENSOR	1	shorted	359.30	-359.30 NN X
FRONT RH FENDER INNER PANEL	1	repair	422.40	0.00
FRONT RH FENDER LAMP	1	fractured	48.50	48.50 NN X
FRONT RH HEADLAMP	1	broken	449.30	✓449.30 SCRV ✓
FRONT RH HEADLAMP LOWER BRACKET	1	bent	14.40	✓14.40 BTV ✓
FRONT RH HEADLAMP TOP PANEL	1	buckled	196.00	196.00 R X
FRONT RH KNUCKLE ARM	1	distorted	433.40	433.40 SVC X
FRONT RH KNUCKLE ARM BEARING	1	dislodged	280.30	✓280.30 DLV ✓
FRONT RH LINKAGE	1	bent	32.30	32.30 NN X
FRONT RH LOWER ARM	1	bent	216.80	✓216.80 BTV ✓ NN
FRONT RH SHOCK ABSORBER	1	bent	347.60	347.60 SVC X
FRONT RH SHOCK ABSORBER TOP MOUNTING	1	necessary	78.40	78.40 SVC X
FRONT RH STEERING TIE ROD	1	reuse	79.50	0.00 SVC X

FRONT TOP PANEL UPPER COVER	1	fractured	370.40	370.40	SVC X
WASHER TANK	1	fractured	220.40	✓ 220.40	BR ✓
WASHER TANK MOTOR	1	shorted	47.40	47.40	SVC X
Subtotal before discount			S\$ 5,241.80	S\$ 4,514.90	1655.50
Percentage discount 10% and 10%			S\$ 524.18	S\$ 451.49	165.55
Sub-total 2			S\$ 4,717.62	S\$ 4,063.41	1489.95
FRONT BONNET INSULATOR MAT CLIPS - SET	1	necessary	30.00	30.00	NN X
FRONT BUMPER CLIPS - SET	1	necessary	50.00	30.00	NECV ✓
FRONT BUMPER INNER AIR GUIDE CLIPS L/R - SET	1	necessary	30.00	20.00	NECV ✓
FRONT GRILLE CLIPS - SET	1	necessary	40.00	20.00	NECV ✓
FRONT NUMBER PLATE	1	reuse	25.00	0.00	SVC
FRONT NUMBER PLATE HOLDER	1	reuse	50.00	0.00	SVC
FRONT RH FENDER INNER SHIELD CLIPS - SET	1	necessary	50.00	20.00	NECV ✓
FRONT RH HEADLAMP CLIPS - SET	1	necessary	30.00	20.00	NECV ✓
FRONT RH SPORT RIM 16"	1	abraded	600.00	600.00	R X
FRONT RH TYRE 195/60/15	1	abraded	300.00	300.00	NN X
FRONT TOP PANEL UPPER COVER CLIPS - SET	1	necessary	50.00	50.00	NECV ✓
RADIATOR COOLANT - BOT	1	necessary	80.00	80.00	NN X
Subtotal before discount			S\$ 1,335.00	S\$ 1,260.00	220.00
Sub-total 3			S\$ 1,335.00	S\$ 1,260.00	220.00
Parts-total			S\$ 11,196.71	S\$ 10,467.50	4194.17

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	180.00	150.00	NN
To remove, reinstall electrical wiring harness, check lighting. (to FR)	60.00	30.00	✓
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	600.00	500.00	150 Δ
To road test driving, check and resetting wheel alignments system.	180.00	180.00	
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,800.00	1,100.00	600.00 +100
To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.	1,500.00	600.00	1,000.00
To apply anti-rust chemical on repaired and replaced panel.	120.00	90.00	50 Δ
Labour Total	S\$ 4,440.00	S\$ 3,070.00	1700.00
Parts & Labour Total	S\$ 15,636.71	S\$ 13,537.50	5,894.17

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 11,500.00 and the recommended number of working days for the repairs is within 8 day(s).

ks
B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

Lump Sum repairs - \$ 11700
Est repairs 5 & days

Land Transport Authority
 10 Sin Ming Drive
 Singapore 575731

GST Registration No. : M4-0006529-2

Print Date/Time : 04 Aug 2017 / 17:20:05

Receipt Date/Time : 04 Aug 2017 / 17:20:05

Tax Invoice/Receipt

Receipt No. : ITNET-00000-170804-001388

Previous Receipt No. :

**S/N Item Description/
 Business Transaction
 Reference No.**

**Amount Before
 GST (\$\$) GST
 Amount (\$\$) Amount
 After GST (\$\$)**

Result of Insurance Enquiry - SGB2498R
 As at 04 Aug 2017/14:05:00
 Insurance Co: AXA INSURANCE PTE LTD

1 Insurance Enquiry - SGB2498R
 Enquiry Fee
 20170804171935863702

5.00 0.35 5.35

Sub-Total 5.00 0.35 5.35

Total Before Rounding 5.00 0.35 5.35

Rounding Difference 0.00

Total Amount Payable 5.35

Paid By

xxxxxxxxxxxx2392 Credit Card:
 Visa/MasterCard 5.35

Total 5.35

Cash Change 0.00

Tendered Amount 5.35

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

TWINCAR RENTAL

Business Registration Number : 53092815M

Blk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :

TAN MENG HWA
BLK 120B EDGEDALE PLAINS
#09-287
SINGAPORE 822120

INVOICE

Invoice No. 13-1818

Date 11/8/2017

		Hirer's Car No.	VHA No.	Terms
		SKW4802A	71391	CASH
No. of Day	Description	Per Day	Amount (S\$)	
7	Car Rental from the period of 04/08/2017 to 11/08/2017. Vehicle no. SLP4102L Singapore Dollars Eight Hundred and Forty Only	120.00	840.00	
			Total	\$840.00

TWINCAR RENTAL



A handwritten signature in black ink, appearing to be "Mh", is written over a horizontal line.

Authorised Signature



TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18
Singapore 417921 Tel: 6744 0510 / 6842 0051

VHA No: 71391 (NS)

ROC NO. 53092815M

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR Name: (as in I/C) <u>TAN MENG HWA</u> NRIC/PASSPORT No: <u>S 2406995 C</u> Address (Res): <u>BLK 120B EDGEMORE PLAINS</u> <u>#09-287 S(822/20)</u> Name & Address of Employer: _____ Occupation: _____ Driving Exp: _____ Driving Licence No: _____ D/L Type: Local / International Issue Date: <u>23/02/2017</u> Date of Birth: <u>11/03/1977</u> Tel: (O) _____ (R) _____ HP/PG <u>983+1247</u>	Vehicle No: <u>SLP 4102L</u> Replace Veh No: <u>SKW 4802A</u> Mileage Out: _____ Mileage Out: _____ Make & Model: <u>Honda Shuttle</u> Auto / Manual Group: _____ OUT: Date <u>4/8/2017</u> Time: <u>1706 HRS</u> HIRE/PERIOD EXPIRY _____ NON-WAIVER EXCESS : \$ _____																																								
ADDITIONAL DRIVER'S PARTICULARS Name: (as in I/C) _____ NRIC/PASSPORT No: _____ Address (Res): _____ Driving Licence No: _____ D/L Type: Local / International Issue Date: _____ Date of Birth: _____ Occupation: _____ Driving Exp: _____	<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th colspan="4">CHARGES</th> </tr> </thead> <tbody> <tr> <td>Daily</td> <td>⊙ \$ 120</td> <td>per day</td> <td>7 840 00</td> </tr> <tr> <td>Weekly</td> <td>⊙ \$</td> <td>per week</td> <td></td> </tr> <tr> <td>Monthly</td> <td>⊙ \$</td> <td>per month</td> <td></td> </tr> <tr> <td>Hours</td> <td>⊙ \$</td> <td>per hour</td> <td></td> </tr> <tr> <td>Others</td> <td>⊙ \$</td> <td></td> <td></td> </tr> <tr> <td>CDW</td> <td>⊙ \$</td> <td>per day/month</td> <td></td> </tr> <tr> <td>PAI</td> <td>⊙ \$</td> <td>per day/month</td> <td></td> </tr> <tr> <td>Delivery Service</td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="4" style="text-align: right;">SUB-TOTAL \$</td> </tr> </tbody> </table>	CHARGES				Daily	⊙ \$ 120	per day	7 840 00	Weekly	⊙ \$	per week		Monthly	⊙ \$	per month		Hours	⊙ \$	per hour		Others	⊙ \$			CDW	⊙ \$	per day/month		PAI	⊙ \$	per day/month		Delivery Service				SUB-TOTAL \$			
CHARGES																																									
Daily	⊙ \$ 120	per day	7 840 00																																						
Weekly	⊙ \$	per week																																							
Monthly	⊙ \$	per month																																							
Hours	⊙ \$	per hour																																							
Others	⊙ \$																																								
CDW	⊙ \$	per day/month																																							
PAI	⊙ \$	per day/month																																							
Delivery Service																																									
SUB-TOTAL \$																																									
VEHICLE CHECKLIST D - DENTS S - SCRATCHES A - ACCIDENTS <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> REAR </div> <div style="text-align: center;"> FRONT </div> <div style="text-align: center;"> TOP </div> <div style="text-align: center;"> LEFT </div> </div> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> RIGHT </div> <div style="text-align: center;"> FRONT </div> <div style="text-align: center;"> TOP </div> <div style="text-align: center;"> LEFT </div> </div>	PETROL LEVEL <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Out</th> <th>E</th> <th>1/4</th> <th>1/2</th> <th>3/4</th> <th>F</th> </tr> </thead> <tbody> <tr> <td>In</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> </tr> </tbody> </table> EXTENSION Collection Service _____ Misc. _____ TOTAL CHARGE \$ 840 00 Rented out by: _____ Hirer's Signature <u>[Signature]</u> Addition Driver's Signature _____	Out	E	1/4	1/2	3/4	F	In	E	1/4	1/2	3/4	F																												
Out	E	1/4	1/2	3/4	F																																				
In	E	1/4	1/2	3/4	F																																				
ACCESSORIES CHECK <input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps <input type="checkbox"/> Radio / Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges																																									

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCARD RENTAL in connection with this Agreement is true.

*** IMPORTANT**

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
<u>11/08/2017</u>	<u>16:50 HRS</u>				<u>[Signature]</u>





MOTOR PRIVATE CAR

CERTIFICATE OF INSURANCE
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Cov. Type: C
PLM 288240

ORIGINAL

CERTIFICATE No. **DMP05H1548661401** Engine No: **HR16975272B**
ChasNo: **NOTREBAN17M0024984**

1. Index Mark and Registration Number of Vehicle **SKW4602A**

2. Name of Policy Holder **MR TAN MENG HWA (CHEN MINGHUA)**

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment **07 November 2015 (07:07 Hours)** Named Drivers Ex Sect. I **S\$1,100.00**
Additional Ex Other than Named Drivers:
Ex Sect. I - Age <= 25 **S\$3,000.00**
Ex Sect. I - Age >= 26 **S\$500.00**
* Age as at date of accident
EX ON WINDSCREEN S\$100.00

4. Date of Expiry of Insurance **06 November 2017**

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.
The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time Waiver of Excess for the first S\$500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year.

HIRE PURCHASE CO. : UNITED OVERSEAS BANK LIMITED AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 96 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.


I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:


Authorised Officer


Authorised Signatory

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
 Owner ID: 6895C

Vehicle Details

Vehicle No.: SKW4802A
 Vehicle to be Exported: No
 Intended De-registration Date: 04 Aug 2017
 Vehicle Make: NISSAN
 Vehicle Model: SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
 Primary Colour: Red
 Manufacturing Year: 2015
 Engine No.: HR16975272B
 Chassis No.: MNTBBAB17Z0024984
 Maximum Power Output: 85.0 kW (113 bhp)
 Open Market Value: \$16,439.00
 Original Registration Date: 30 Oct 2015
 First Registration Date: 30 Oct 2015
 Transfer Count: 0
 Actual ARF Paid: \$16,439.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 29 Oct 2025
 PARF Rebate Amount: \$12,329.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Period(Years): 10
 QP Paid: \$57,301.00
 COE Rebate Amount: \$47,180.00
Total Rebate Amount: \$59,509.00

The information contained herein is correct as at 04 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
 Last updated on 30 Jul 2017 at 12:58 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/08/2017 10:09
Date Of Accident	04/08/2017 14:05
Exact Location Of Accident	SLIP RD EXIT FROM PIE AT CIRCUIT RD TURNING JUNC
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW4802A
Insured/Policyholder	
Name Of Registered Owner	MR TAN MENG HWA(CHEN MINGHUA)
NRIC No	S7706895C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96371247
Alternative Phone No	OTHERS-96371247
Vehicle Particulars	
Manufacturer	NISSAN
Model	SYLPHY
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1548661601
Cover Note Number	
Driver	
Name of Driver	MR TAN MENG HWA(CHEN MINGHUA)
NRIC No	S7706895C
Date Of Birth	11/03/1977
Occupation	OUTDOOR
Date Of Driving Pass	01/09/1997
Driving Experience	19 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96371247
Fax Number	
Contact Number	OTHERS-96371247
EEmail Address	NOEMAIL

Address	BLK 120B EDGEDALE PLAINS #09-287
Postcode	822120
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH THE DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGB2498R
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LEE CHOON KHIANG
NRIC/Passport Number	
Contact Number	81269498
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	MR TAN MENG HWA(CHEN MINGHUA)
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SKW4802A
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available a/crossnet.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Signature 07/08/17

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accide-1 Photo



Accident Photo





Enquire Vehicle & Owner Information (Vehicle No. SGB2498R As At 04 Aug 2017 / 14:05:00)[Home](#) > [Search Details](#)**Search Reason:** Insurance claim in relation to traffic accident**Law Firm Case No.:** N63-106994-18**Current Owner Details****Owner ID Type:** Singapore NRIC**Owner ID:** S1687870G**Owner Name:** LEE CHOON KHIANG**Registered Address Type:** HDB / HUDC**Registered Block/House No.:** 256**Registered Street Name:** KIM KEAT AVENUE**Registered Unit No.:** # 03 - 162**Registered Building Name:** -**Registered Postal Code:** 310256**Current Vehicle Details****Vehicle No.:** SGB2498R**Make Description/Model:** TOYOTA / VIOS 1.5E A**Insurance Company Name:** AXA INSURANCE PTE LTD



Thank you

Ng Ching Boon Eric has successfully logged out.

Your last login date and time was 03 Jul 2018, 18:10:54.

To return to ONE.MOTORING, please [click here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SGB2498R	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	03 Jul 2018 / 18:11:18



Your Ref: C0447003

Date: 24th July 2018

Our Ref: CS3/AXA17015306/Bqbc2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKW 4802A
INSURED VEHICLE: SGB 2498R
ACCIDENT DATE: 04/08/2017**

We thank you for your instruction on 12/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKW 4802A from M/s Par Automotive Consultancy.
- b) Final Repair Bill of SKW 4802A from M/s N-51 Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SKW 4802A.
- d) Colour damaged vehicle photographs of SKW 4802A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SKW 4802A
Make & Model : Nissan Sylphy 1.6 CVT
Year of Registration : 2015
Chassis Number : MNTBBAB17Z0024984
Engine Capacity : 1598 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 4802A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	AIRCON CONDENSER RH AIR GUIDE	SERVICEABLE	105.60	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	917.70	-
1	FRONT BONNET WEATHERSTRIP	NOT NECESSARY	44.50	-
1	FRONT BUMPER	DENTED	535.50	535.50
1	FRONT BUMPER INNER SPONGE	CUT	280.70	280.70
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	561.90	-
1	FRONT BUMPER REINFORCEMENT RH BRACKET	TO REPAIR SEE LABOUR	94.50	-
1	FRONT GRILLE	CUT	356.60	356.60
1	FRONT RH DRIVE SHAFT	NOT NECESSARY	1,134.70	-
1	FRONT RH FENDER	DISTORTED	623.60	623.60
1	FRONT RH FENDER INNER SHIELD	CUT	70.10	70.10
1	FRONT RH HEADLAMP PANEL	TO REPAIR SEE LABOUR	161.90	-
1	FRONT RH SHOCK ABSORBER TOP MOUNTING BEARING	NOT NECESSARY	45.00	-
1	FRONT RH STEERING TIE ROD END	NOT NECESSARY	79.20	-
1	FRONT RH WHEEL HUB	DISLodge	370.30	370.30
1	FRONT STABILIZER BAR	SERVICEABLE	221.40	-
1	FRONT STEERING RACK & PINION	SERVICEABLE	1,745.50	-
	LESS 30% DISCOUNT		-2,204.61	-671.04
			5,144.09	1,565.76
NETT ITEMS				
2	FRONT BONNET RUBBER GUIDE STOPPER L/R (N)	NOT NECESSARY	40.00	-
2	FRONT BUMPER COVER L/R (N)	NOT NECESSARY	225.00	-
2	FRONT BUMPER INNER AIR GUIDE L/R (N)	O/S BENT	351.00	175.50
1	FRONT BUMPER LOWER COVER (N)	NOT NECESSARY	181.80	-
1	FRONT BUMPER LOWER GRILLE (N)	CUT	255.40	135.60
2	FRONT BUMPER SIDE RETAINER L/R (N)	NECESSARY	57.60	57.60
1	FRONT ENGINE CROSS MEMBER (N)	NOT NECESSARY	429.00	-

Report Ref No. CS3/AXA17015306/Bqbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT GRILLE 'LOGO' EMBLEM (N)	NECESSARY	64.60	64.60
2	FRONT GRILLE BRACKET L/R (N)	BENT	41.00	41.00
1	FRONT RH A.B.S SENSOR (N)	NOT NECESSARY	359.30	-
1	FRONT RH FENDER INNER PANEL (N)	TO REPAIR SEE LABOUR	422.40	-
1	FRONT RH FENDER LAMP (N)	NOT NECESSARY	48.50	-
1	FRONT RH HEADLAMP (N)	SCRATCHED	449.30	449.30
1	FRONT RH HEADLAMP LOWER BRACKET (N)	BENT	14.40	14.40
1	FRONT RH HEADLAMP TOP PANEL (N)	TO REPAIR SEE LABOUR	196.00	-
1	FRONT RH KNUCKLE ARM (N)	SERVICEABLE	433.40	-
1	FRONT RH KNUCKLE ARM BEARING (N)	DISLodge	280.30	280.30
1	FRONT RH LINKAGE (N)	NOT NECESSARY	32.30	-
1	FRONT RH LOWER ARM (N)	NOT NECESSARY	216.80	-
1	FRONT RH SHOCK ABSORBER (N)	SERVICEABLE	347.60	-
1	FRONT RH SHOCK ABSORBER TOP MOUNTING (N)	SERVICEABLE	78.40	-
1	FRONT RH STEERING TIE ROD (N)	SERVICEABLE	79.50	-
1	FRONT TOP PANEL UPPER COVER (N)	SERVICEABLE	370.40	-
1	WASHER TANK (N)	BROKEN	220.40	220.40
1	WASHER TANK MOTOR (N)	SERVICEABLE	47.40	-
	LESS 10% DISCOUNT		-524.18	-143.87
			4,717.62	1,294.83
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BONNET INSULATOR MAT CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT BUMPER INNER AIR GUIDE CLIPS L/R (SN)	NECESSARY	30.00	20.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	40.00	20.00
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	FRONT NUMBER PLATE HOLDER (SN)	SERVICEABLE	50.00	-
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	20.00
1	SET FRONT RH HEADLAMP CLIPS (SN)	NECESSARY	30.00	20.00
1	FRONT RH SPORT RIM 16" (SN)	TO REPAIR SEE LABOUR	600.00	-
1	FRONT RH TYRE 195/60/15 (SN)	NOT NECESSARY	300.00	-

Report Ref No. CS3/AXA17015306/Bqbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT TOP PANEL UPPER COVER CLIPS (SN)	NECESSARY	50.00	50.00
1	BOT RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
			1,335.00	160.00
	LABOUR			
	TO REMOVE, REINSTALL AIR CON PARTS. VACUUMS, REFILL AIR CON GAS. (TO FR)	NOT NECESSARY	180.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)		60.00	30.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.		600.00	150.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM.		180.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,800.00	700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT BUMPER REINFORCEMENT, FRONT BUMPER REINFORCEMENT RH BRACKET, FRONT RH HEADLAMP PANEL, FRONT RH FENDER INNER PANEL, FRONT RH HEADLAMP TOP PANEL AND FRONT RH SPORT RIM 16".		1,500.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	50.00
			4,440.00	1,590.00
	GRAND TOTAL		15,636.71	4,610.59
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,650.00

Report Ref No. CS3/AXA17015306/Bqbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.