

cc 6, III 80 12759, Awa 3 82

LKK
FOA

ASSIGNMENT

Surveyor: UMP Date / Time: 12/7/18 Registered in Merimen: 31268

Pre-assign / CCU / FTE



Insured Vehicle No.: SHD 4443M
Name of Insured: CTP
Insured Tel No.: _____ HP: _____
Excess Sec II :SS _____ D.O.A: 9-7-18
Is driver the owner? (YES / ☒ NO) Nature of Accident: _____
If NO, Driver Name / Age: Yeo Eng Pheow
Driver Tel No.: 9618423 (V/L: ☒ YES / NO)

Claim No.: _____
Policy No.: mc00001
Make / Model: H. sonata
Place of Accident: PASIR PER DRIVE 3

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO
Insured Liability: % Final ? Yes / No

666 3620E



INSRS:
WSP: My Solution
Tel: _____
Liability: _____
RMKS: _____



INSRS:
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS:
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS:
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/Time		STAGE	DATE / PIC	
<u>12/7/18</u>	<u>666 3620E</u>	Non-Reporting ltr (1st):		
	<u>SHD 4443M</u>	Non-Reporting ltr (2nd):		
		Non-Reporting ltr (Final):		
		Notification ltr (if non-pickup):		
		Call OI:		
		After call ltr to OI:		
		Documentation Check List:	Handler Typist	
		Notification ltr (if non-pickup)	☒	
		After call ltr to OI:	☒	
		Authorisation To Act:	☒	
		Release Voucher:	☒	
		Final Repair Bill:	☒	
		Car Rental Invoice:	☒	
		Towing Invoice	☒	
		LTA / GIA :	☒	
		Medical Bill:	☒	
		PIR:	☒	
		Mandate/Reject Instruction:	☒	
		LOD	☒	
		Payment Breakdown Form:	☒	
		Post-Repair Photos:	☒	
		Others:	☒	
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____				
FINALIZATION Date/Time: _____ Confirm with: _____		Confirm by: <u>Adrain</u>		
Repair Cost: <u>115</u>	<u>S\$ 17,400.00</u> (<u>12</u> days) Reduction: <u>20,304.64</u> % <u>53</u>	Email ☒ Call ☐		
FINAL SETTLEMENT Date/Time: <u>18/1/2020</u> Confirm with: <u>SH</u>		Email ☒ Call ☐		
Final Liability: %	<u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>5</u>	If NO or B 28, Ass. Lia: _____		
Repair Cost: <u>(WGTST)</u>	<u>S\$ 19,153.00</u>			
Loss of Rental (LOR):	<u>S\$ -</u> (<u>0</u> days)			
Loss of Use (LOU):	<u>S\$ 900</u> (<u>\$ 60</u> x <u>15</u> days)			
Loss of Income (LOI):	<u>S\$ -</u> (<u>\$</u> x <u>0</u> days)			
LOR only ☐ LOU only ☒	<u>LOR + LOU</u> ☐ LOR + LOI ☐ [Tick only one]			
GIA/LTA Search	<u>S\$ 7.45</u>			
Medical:	<u>S\$ -</u>			
Disbursement:	<u>S\$ -</u> (e.g. Tow/ Independent)			
Legal Cost	<u>S\$ -</u>			
Total:	<u>S\$ 20,060.45</u>	Global Sum S\$: <u>20,000.00</u>		
FINAL PAYMENT Date/Time: _____ Confirm with: _____		Email ☒ Call ☐		
Payee 1:	<u>S\$ 20,000.00</u>	Name 1: <u>My Solution Pte Ltd</u>		
Payee 2 (Strike if N.A.)	<u>S\$ -</u>	Name 2: _____		
Payee 3 (Strike if N.A.)	<u>S\$ -</u>	Name 3: _____		

COPY SENT
24/3/2020

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: #6001

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 111

L/S = \$17,900 with 12 repair days.

MV: 67K
PV: 32.2K
Nett: 34.8K

(Red = \$20,704.64 / 53%).

* 12 repair days + 3 Sundays + 1 PRS = 15 days.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / L.B.E. (\$

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA	DATE	: 20/09/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBG3620E	HH: Adrian Ling	
MODEL	: NISSAN NV350	JNIMC2E252	
CHASSIS NO		Vivian	
<u>ACCIDENT DETAILS</u>		DATE	: 9-Jul-18
		TIME	: 18:45HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS (Nett)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT PANEL <i>Dented Repair</i>	1	\$ 1,266.30	\$ 1,266.30
2	FRONT BUMPER <i>Dented</i>	1	\$ 550.00	\$ 550.00
3	FRONT BUMPER SIDE RETAINER <i>Nett</i>	2	\$ 150.00	\$ 300.00
4	FRONT BUMPER FOGLAMP HOUSING <i>Nett</i>	1	\$ 109.20	\$ 109.20
5	FRONT BUMPER REINFORCEMENT (CENTRE) <i>But</i>	1	\$ 380.00	\$ 380.00
6	FRONT BUMPER REINFORCEMENT HOLDER <i>But</i>	2	\$ 110.00	\$ 220.00
7	FRONT BUMPER REINFORCEMENT LOWER <i>But</i>	1	\$ 160.00	\$ 160.00
8	FRONT BUMPER LOWER COVER <i>Del'd</i>	1	\$ 99.70	\$ 99.70
9	FRONT GRILLE <i>Missing</i>	1	\$ 490.00	\$ 490.00
10	FRONT GRILLE LOGO <i>Nett</i>	1	\$ 90.00	\$ 90.00
11	HEADLAMP <i>cracked</i>	2	\$ 466.30	\$ 932.60
12	FRONT WINDSCREEN <i>cracked</i>	1	\$ 1,190.30	\$ 1,190.30
13	FRONT WINDSCREEN MOULDING (SET) <i>Nett</i>	1	\$ 180.00	\$ 180.00
14	FRONT DOOR <i>3 Repair</i>	2	\$ 1,120.00	\$ 2,240.00
15	FRONT DOOR PILLAR	2	\$ 1,239.00	\$ 2,478.00
16	AIR VENT <i>cracked</i>	1	\$ 190.00	\$ 190.00
17	AIRBAG <i>Activated</i>	1	\$ 2,100.00	\$ 2,100.00
18	TURBO INNER COOLER <i>Dented</i>	1	\$ 2,255.90	\$ 2,255.90

2101.60.

19	RADIATOR <i>Dented</i>	1	\$ 830.00	\$ 830.00	✓
20	FAN BLADE <i>2 mp</i>	1	\$ 210.00	\$ 210.00	X
21	FAN MOTOR <i>1 New</i>	2	\$ 466.30	\$ 932.60	X
22	FAN COWLING ASSY <i>Cracked</i>	1	\$ 201.00	\$ 201.00	✓
23	POWER STEERING BELT <i>cut</i>	1	\$ 120.00	\$ 120.00	✓

24 *Steering Air Bag Clock Spring Activated* 354 354

TOTAL PRICE \$ 17,525.60

LESS 10% \$ 1,752.56

SUB TOTAL PRICE \$ 15,773.04

104684
942156

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00	✓ 30
2	FRONT PANEL STICKER <i>Net Net 200</i>	1	\$ 350.00	\$ 350.00	X 200.
3	FRONT PANEL COMPANY STICKER <i>New</i>	1	\$ 350.00	\$ 350.00	180
4	FRONT BUMPER CLIPS(SET) <i>New</i>	1	\$ 25.00	\$ 25.00	✓
5	FRONT BUMPER STICKER <i>Net Net</i>	1	\$ 250.00	\$ 250.00	X.
6	FRONT BUMPER FOGLAMP <i>Cracked</i>	2	\$ 322.20	\$ 644.40	✓
7	FRONT BUMPER INNER CROSS MEMBER <i>Ryir</i>	1	\$ 890.00	\$ 890.00	X.
8	CENTRE GRILLE CLIPS(SET) <i>New</i>	1	\$ 23.00	\$ 23.00	✓ 1899
9	FRONT WINDSCREEN SEALANT <i>3 New</i>	1	\$ 100.00	\$ 100.00	40
10	FRONT WINDSCREEN INNER SEAL	1	\$ 120.00	\$ 120.00	40
11	FRONT DOOR COMPANY STICKER <i>New</i>	2	\$ 650.00	\$ 1,300.00	450
12	FRONT DOOR LTA ADDRESS <i>New</i>	2	\$ 25.00	\$ 50.00	✓
13	HORN <i>Damaged</i>	1	\$ 103.00	\$ 103.00	✓
14	AIRBAG CONTROL UNIT <i>Activated</i>	1	\$ 970.00	\$ 970.00	✓
15	SAFETY BELT <i>Activated</i>	2	\$ 888.90	\$ 1,777.80	✓
16	TURBO INNER COOLER PIPE <i>Bent</i>	1	\$ 555.00	\$ 555.00	✓
17	AIRCON BLOWER MOTOR HOUSING <i>Cracked</i>	1	\$ 710.00	\$ 710.00	✓
18	AIRCON COOLING COIL <i>Cracked</i>	1	\$ 620.00	\$ 620.00	✓
19	AIRCON COOLING COIL HOUSING <i>Cracked</i>	1	\$ 1,600.00	\$ 1,600.00	✓
20	AIRCON COOLING COIL BRAKE VALVE <i>Valve 3*</i>	1	\$ 410.00	\$ 410.00	155
21	AIRCON COOLING COIL PIPE <i>Bent</i>	1	\$ 190.00	\$ 190.00	✓
22	AIRCON PIPE(H) <i>2 Bent</i>	1	\$ 260.00	\$ 260.00	✓
23	AIRCON PIPE(L)	1	\$ 180.00	\$ 180.00	✓
24	POWER STEERING COOLER <i>Bent</i>	1	\$ 322.00	\$ 322.00	✓
25	RECEIVER DRIVE <i>Dented</i>	1	\$ 222.00	\$ 222.00	✓
26	RECEIVER DRIVE BRACKET <i>Bent</i>	1	\$ 55.00	\$ 55.00	✓
27	HEATER CORE coil <i>Net Net</i>	1	\$ 1,800.00	\$ 1,800.00	X.
28	HEATER CORE PIPE <i>coil Bent</i>	4	\$ 133.60	\$ 534.40	250.

Nett
Nett
Nett
Nett

Nett
Nett
Nett
Nett
Nett
Nett

Nett

29	HEATER CORE HOSE ^{coil} <i>snapped.</i>	2	\$	90.00	\$	180.00
30	THERMOSTATE SENSOR <i>Damaged.</i>	1	\$	290.00	\$	290.00

Nett: 5504.80

S.N: A61240

less 10% : 4954.32

TOTAL \$ 14,931.60

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$2,600.00	1300	
2	SPRAY PAINTING TO AFFECTED AREA	\$2,000.00	800	
3	TUFF COAT	\$250.00	40	
4	WIRING CHECK	\$80.00	30	
5	CONDUCT WATER LEAKAGE TEST	\$80.00	X	
6	FRONT CHASSIS ALIGNMENT	\$250.00	X	
7	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$250.00	200	
8	REMOVE AND REFIX AIRCON COOLING COIL AND REFILL AIRCON GAS	\$120.00	/	
9	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	\$350.00	250	
10	REMOVE AND REFIX AIRCON BLOWER MOTOR	\$250.00	200	
11	REMOVE AND REFIX FRONT WINDSCREEN	\$120.00	X	
12	REMOVE AND REFIX AIRBAG	\$350.00	250	
13	REMOVE AND REFIX SAFETY BELT	\$300.00	100	
14	RESET AIRBAG	\$250.00	100	
15	REMOVE AND REFIX FRONT DOOR	\$250.00	X	

TOTAL

\$7,500.00

3390

ESTIMATE REPORT

TOTAL PARTS COST : \$ 30,704.64
TOTAL LABOUR COST : \$ 7,500.00

TOTAL REPAIR COST : \$ 38,204.64

38523-244

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Achin Lj

H/S 12 days

total 22378.28

H/S 17-9K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2471N
Vehicle Details	
Vehicle No.:	GBG3620E
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	YD25420242A
Chassis No.:	JN1MC2E26Z0008335
Maximum Power Output:	-
Open Market Value:	\$25,062.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,254.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$32,169.00
Total Rebate Amount:	\$32,169.00

The information contained herein is correct as at 12 Jul 2018

OK

SELL YOUR CAR YOURSELF

Get listed until it's sold + we will handle all the paperwork!

POST AN AD NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Toyota Alphard 2012.



New Road Tax, New Timing Belt
Borneo Car & Worst To Consider
In The Market.
Direct Owner StarAd

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.



Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

7 vehicles

Search

NV350

Advanced Search

Search

View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection NV350 Any Any 2017 Any Any Any Available



☐ Nissan NV350 2.5M \$67,800 \$7,940 /yr 25-Jan-2017 2,488 cc 9,000 km Van Available

Fuel Type: Diesel

Cheapest 2017 Unit! Check Out This Outstanding Unit! 1 Single Owner Only, Low Mileage Done, Under Agent Tan Chong 3 Plus 2 Years Or 140k Km Warranty, Made In Japan Model Making It Reliable Durable Lon...

DIRECT OWNER

Posted: 28-May-2018 Tags: 2017 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



☐ Nissan NV350 2.5M \$61,900 \$6,960 /yr 31-May-2017 2,488 cc 255 km Van Available

Fuel Type: Diesel

2018 Latest Agent Unit, No Hidden Costs, Ready Stock, High Loan/High Trade In Available, Call Our Friendly Sales Team Now.

PREMIUM AD

Posted: 09-Jul-2018 Tags: 2017 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



☐ Nissan NV350 2.5M \$69,900 \$7,810 /yr 24-Jun-2017 2,488 cc 18 km Van Available

Fuel Type: Diesel

Nissan NV350 Panel Van 2.5 SMT Euro V. 5 Years Or 140,000Km Warranty By Tan Chong Motor Sales. Free 3 x Servicing.

PREMIUM AD

Posted: 28-May-2018 Tags: 2017 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



☐ Nissan NV350 2.5M \$64,800 \$7,230 /yr 27-Jun-2017 2,488 cc 19,205 km Van Available

Fuel Type: Diesel

5 Door, Like New Condition! Spotless Exterior! In House Loan Available! Trade In Welcome. Warranty Available. Door Step Viewing Ok. Call Now For Viewing!

ABWIN (1994) Pte Ltd

Posted: 19-Jun-2018 Tags: 2017 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



Car Buying



Car Selling



Car Ownership



Car Aftermarket



On The Move



Lifestyle



☐ Nissan NV350 2.5M \$71,000 \$7,840 /yr 31-Jul-2017 2,488 cc - Van Available

Fuel Type: Diesel

Almost New Nissan NV350 Panel Van 2.5 SMT Euro V. Vehicle Still Under Warranty. In House Loan Available. Trade In Welcome. Call Now For Viewing.

Posted: 04-Jul-2018 Tags: 2017 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



☐ Nissan NV350 2.5M \$65,800 \$7,110 /yr 13-Oct-2017 2,488 cc - Van Available

Fuel Type: Diesel

Almost Brand New NV350, 5 Doors Diesel, High Loan With Lowest Interest Rate, High Trade In, Price Slash To The Lowest And Affordable, Ready Stock Available. Register As 1st Owner. Please Call Now To L...

PREMIUM AD

Posted: 12-Jun-2018 Tags: 2017 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



☐ Nissan NV350 2.5A \$72,900 \$7,780 /yr 23-Nov-2017 2,488 cc 18 km Van Available

Fuel Type: Diesel

Latest 2018 Euro 6 Nissan NV350 Panel Van 2.5 AT, 5 Years Or 140,000Km Warranty By Tan Chong Motor Sales. Free 3 x Servicing.

PREMIUM AD

Posted: 21-Jun-2018 Tags: 2017 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan

SHORTLISTED HISTORY

Compare [2]

Save this search criteria, to get email alerts whenever a match is found.

MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: CHEE FATT CO. (PTE.) LTD

CAR/ LORRY/CYCLE: REG NO: GBG 3620E POLICY NO:

ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. GBG 3620E from the repairers,

Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was Involved on or

about the 09 day of 07 2018 have been completed to my / our satisfaction, and that

I / we have no further claim on the above company in Respect thereof.

Date: Signature:

Co's Stamp: NRIC No:



11/7/2018 - Tow out from TP Road
12/7/2018 - PRI
15/7/2018 - Sunday
22/7/2018 - Sunday

Vehicle In - 11/7/2018

Vehicle Out - 25/7/2018

Low - 15 days x \$200
= \$3,000

View Received Message

This mail is associated with :

***GBG3620E (MCT18070272)**
[SHD4443M]

TP
CHEE FATT CO.(PTE.)LTD.
Jul 9 2018 6:00PM

MG Solution Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 17/07/2018 17:35 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$0.00) - GBG3620E - Claim Handler: Sundari Nagarajan

Approved:0.00:Request TP to forward us the video of the accident

DOCUMENTS SUMMARY

There are no documents.



**SINGAPORE
POLICE FORCE**

TRAFFIC POLICE
10 UBI AVE 3
SINGAPORE 408865
Tel : 65476244/43
Fax : 65474749

Your Ref: Pls Advise

Our Ref: TP/IP/38963/2018(TP113808/SR)

Date : 06/09/2018

SINGH & CO
77 HIGH STREET #10-09
HIGH STREET PLAZA
SINGAPORE 179433

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NOS: GBG3620E AND SHD4443M ON 09/07/2018.

I refer to your application dated 29/08/2018. I wish to draw to your attention to the item(s) marked "X" hereunder:-

- ☐ Please be informed that Traffic Police will not investigating into the accident as it is a non-injury case which did not fall within the various categories of exception. You may wish to know that this is pursuant to the Non-injury Accident Reporting Scheme which was implemented on 1 May 1999.
- ☐ This case is still under investigation by IO _____. Tel no: _____.
- ☐ No action is being taken against anyone in this case. This does not preclude further prosecution should new evidence emerge later. Our findings do not affect insurance and civil claims.
- ☐ Action is being taken against the driver of vehicle no: _____ for Inconsiderate Driving.
- ☒ **The driver of vehicle no: SHD4443M has accepted the offer of composition on 17/08/2018 for Inconsiderate Driving.**
- ☐ The driver of vehicle no: _____ has been given a warning for Careless Driving, respectively.
- ☐ The driver of vehicle no: _____ has pleaded guilty in Court no: 24 on _____ for Inconsiderate Driving.
- ☒ **A copy of Police Report T/20180709/2183 is attached as requested.**
- ☐ Please be informed that there is no record of this incident/accident in this case.
- ☐ There is no Police Report for vehicle no: _____.
- ☐ There is no Charge Sheet in this case.
- ☐ The Coroner's Inquiry was held on _____ in Court no: 22 C.I. No: _____.

Yours Faithfully


SITI ROHAIYAH KASMANI
for HEAD INVESTIGATION
TRAFFIC POLICE

*Delete where inapplicable

A FORCE FOR THE NATION

NP 510

View Received Message

This mail is associated with :

***GBG3620E (MCT18070272)
[SHD4443M]**

TP
CHEE FATT CO.(PTE.)LTD.
Jul 9 2018 6:00PM

MG Solution Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/10/2018 12:05 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - GBG3620E - Claim Handler: Sundari Nagarajan

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

Print Received Message

This mail is associated with :

***GBG3620E (MCT18070272)**
[SHD4443M]

TP

CHEE FATT CO.(PTE.)LTD.

Jul 9 2018 6:00PM

[-]

MG Solution Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 01/10/2019 11:25 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - GBG3620E - Claim Handler: Sundari Nagarajan

Maintained:Item No. 26 - Not fixed Item No. 34 - Not done

offer ~~maint~~ maintained.

*check w
survivor if
Rem 20 & 34
if these TP deal
replace 2*

Print Received Message

This mail is associated with :

***GBG3620E (MCT18070272)**
[SHD4443M]

TP
CHEE FATT CO.(PTE.)LTD.
Jul 9 2018 6:00PM
[-]
MG Solution Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 28/08/2019 10:25 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - GBG3620E - Claim Handler: Sundari Nagarajan

Maintained:Please try to negotiate COR: \$17,000 lump sum and 10 days repair.

~~CASH SALE~~ WORK ORDER No: AH7596



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL: 6743 1987 (3 LINES) FAX: 6743 0513

Reg No: 200413052W

Date: 11/7/18

Messrs: M. G.

Vehicle No: GBG 3620E Model No: T/Van

From: T. P. POND

To: Kaki Bukit Vi'com

Remark:

Time: 13:30 - 14:00 - 14:45 AMOUNT: \$60.00

NOTE: 本公司對所拖之車輛，在進行中和有任何損失或破壞，一概由車主自行負責。
NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人: [Signature] 收貨人: [Signature]
Authorised: Received by:

Print Received Message

This mail is associated with :

***GBG3620E (MCT18070272)**

[SHD4443M]

TP

CHEE FATT CO.(PTE.)LTD.

Jul 9 2018 6:00PM

[-]

MG Solution Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/09/2019 13:50 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20000.00) - GBG3620E - Claim Handler: Sundari Nagarajan

Approved:20000.00:Globalise settlement \$20,000/- all in

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jul 2018 Edit Reg		12 Jul 2018 00:00 Edit Adj Rpt	S\$17,900.00 Edit Estimates	S\$17,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	CHEE FATT CO.(PTE.)LTD., Co. Reg. No.: 197302471N		
Vehicle Reg. No.:	GBG3620E	Date of Loss:	09/07/2018 18:00 - :59 [11 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18070272	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHD4443M	Policy No. (Claimant):	1700033251
		Excess:	
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/07/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (23/10/2019): Alert - Adj Mandate Maintained - GBG3620E - Claim Handler: Sundari Nagarajan
- III_SG (01/10/2019): Alert - Adj Mandate Maintained - GBG3620E - Claim Handler: Sundari Nagarajan
- III_SG (24/09/2019): Alert - Adj Mandate Approved (S\$20000.00) - GBG3620E - Claim Handler: Sundari Na...
- III_SG (28/08/2019): Alert - Adj Mandate Maintained - GBG3620E - Claim Handler: Sundari Nagarajan
- III_SG (24/10/2018): Alert - Adj Mandate Approved (S\$0.00) - GBG3620E - Claim Handler: Sundari Nagara...
- III_SG (01/10/2018): Alert - Adj Mandate Approved (S\$0.00) - GBG3620E - Claim Handler: Sundari Nagara...
- III_SG (17/07/2018): Alert - Adj Mandate Approved (S\$0.00) - GBG3620E - Claim Handler: Sundari Nagara...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBG3620E (MCT18070272)**
[SHD4443M]

TP
CHEE FATT CO.(PTE.)LTD.
Jul 9 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
MG Solution Pte Ltd

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼

Video			1 per page ▼	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/10/18 11:22	TP VID	 Load AVI	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 13:55	PIR Result from TP	 Load JPG	☒
2	01/11/18 09:14	General View	 Load JPG	☒
3	01/11/18 09:14	General View	 Load JPG	☒
4	01/11/18 09:14	General View	 Load JPG	☒
5	01/11/18 09:14	General View	 Load JPG	☒
6	01/11/18 09:14	General View	 Load JPG	☒
7	01/11/18 09:14	General View	 Load JPG	☒
8	01/11/18 09:14	General View	 Load JPG	☒
9	01/11/18 09:14	General View	 Load JPG	☒
10	01/11/18 09:14	General View	 Load JPG	☒
11	01/11/18 09:14	General View	 Load JPG	☒
12	01/11/18 09:14	General View	 Load JPG	☒
13	01/11/18 09:14	General View	 Load JPG	☒
14	01/11/18 09:14	General View	 Load JPG	☒
15	01/11/18 09:14	General View	 Load JPG	☒
16	01/11/18 09:14	General View	 Load JPG	☒
17	01/11/18 09:14	General View	 Load JPG	☒
18	01/11/18 09:14	General View	 Load JPG	☒
19	01/11/18 09:14	General View	 Load JPG	☒
20	01/11/18 09:14	General View	 Load JPG	☒
21	01/11/18 09:14	General View	 Load JPG	☒
22	01/11/18 09:14	General View	 Load JPG	☒
23	01/11/18 09:14	General View	 Load JPG	☒
24	01/11/18 09:14	General View	 Load JPG	☒
25	01/11/18 09:14	General View	 Load JPG	☒
26	01/11/18 09:14	General View	 Load JPG	☒
27	01/11/18 09:14	General View	 Load JPG	☒
28	01/11/18 09:14	General View	 Load JPG	☒
29	01/11/18 09:14	General View	 Load JPG	☒
30	01/11/18 09:14	General View	 Load JPG	☒
31	01/11/18 09:14	General View	 Load JPG	☒
32	01/11/18 09:14	General View	 Load JPG	☒

Claim Documents

***GBG3620E (MCT18070272)**
[SHD4443M]
TP
CHEE FATT CO.(PTE.)LTD.
Jul 9 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
MG Solution Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Video			1 per page ▼	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/10/18 11:22	TP VID	Load AVI	

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 13:55	PIR Result from TP	Load JPG	✓
2	01/11/18 09:14	General View	Load JPG	✓
3	01/11/18 09:14	General View	Load JPG	✓
4	01/11/18 09:14	General View	Load JPG	✓
5	01/11/18 09:14	General View	Load JPG	✓
6	01/11/18 09:14	General View	Load JPG	✓
7	01/11/18 09:14	General View	Load JPG	✓
8	01/11/18 09:14	General View	Load JPG	✓
9	01/11/18 09:14	General View	Load JPG	✓
10	01/11/18 09:14	General View	Load JPG	✓
11	01/11/18 09:14	General View	Load JPG	✓
12	01/11/18 09:14	General View	Load JPG	✓
13	01/11/18 09:14	General View	Load JPG	✓
14	01/11/18 09:14	General View	Load JPG	✓
15	01/11/18 09:14	General View	Load JPG	✓
16	01/11/18 09:14	General View	Load JPG	✓
17	01/11/18 09:14	General View	Load JPG	✓
18	01/11/18 09:14	General View	Load JPG	✓
19	01/11/18 09:14	General View	Load JPG	✓
20	01/11/18 09:14	General View	Load JPG	✓
21	01/11/18 09:14	General View	Load JPG	✓
22	01/11/18 09:14	General View	Load JPG	✓
23	01/11/18 09:14	General View	Load JPG	✓
24	01/11/18 09:14	General View	Load JPG	✓
25	01/11/18 09:14	General View	Load JPG	✓
26	01/11/18 09:14	General View	Load JPG	✓
27	01/11/18 09:14	General View	Load JPG	✓
28	01/11/18 09:14	General View	Load JPG	✓
29	01/11/18 09:14	General View	Load JPG	✓
30	01/11/18 09:14	General View	Load JPG	✓
31	01/11/18 09:14	General View	Load JPG	✓
32	01/11/18 09:14	General View	Load JPG	✓

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
33	01/11/18 09:14	General View	 Load JPG	☒
34	01/11/18 09:14	General View	 Load JPG	☒
35	01/11/18 09:14	General View	 Load JPG	☒
36	01/11/18 09:14	General View	 Load JPG	☒
37	01/11/18 09:14	General View	 Load JPG	☒
38	01/11/18 09:14	General View	 Load JPG	☒
39	01/11/18 09:14	General View	 Load JPG	☒
40	01/11/18 09:14	General View	 Load JPG	☒
41	01/11/18 09:14	General View	 Load JPG	☒
42	01/11/18 09:14	General View	 Load JPG	☒
43	01/11/18 09:14	General View	 Load JPG	☒
44	01/11/18 09:14	General View	 Load JPG	☒
45	01/11/18 09:14	General View	 Load JPG	☒
46	01/11/18 09:14	General View	 Load JPG	☒
47	01/11/18 09:14	General View	 Load JPG	☒
48	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
49	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
50	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
51	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
52	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
53	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
54	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
55	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
56	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
57	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
58	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
59	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
60	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
61	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
62	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
63	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
64	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
65	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
66	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
67	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
68	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
69	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
70	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
71	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
72	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
73	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
74	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
75	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
76	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
77	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
78	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
79	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
80	01/11/18 09:15	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
81	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
82	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
83	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
84	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
85	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
86	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
87	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
88	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
89	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
90	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
91	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
92	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
93	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
94	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
95	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
96	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
97	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
98	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
99	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
100	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
101	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
102	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
103	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
104	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
105	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
106	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
107	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
108	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
109	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
110	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
111	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
112	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
113	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
114	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
115	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
116	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
117	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
118	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
119	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
120	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
121	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
122	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
123	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
124	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
125	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
126	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
127	01/11/18 09:15	Reinspection Photo	 Load JPG	☒
128	01/11/18 09:15	Reinspection Photo	Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
129	01/11/18 09:15	Reinspection Photo	 Load JPG	✓
130	01/11/18 09:15	Reinspection Photo	 Load JPG	✓
131	01/11/18 09:15	Reinspection Photo	 Load JPG	✓
132	01/11/18 09:15	Reinspection Photo	 Load JPG	✓
133	01/11/18 09:15	Reinspection Photo	 Load JPG	✓
134	01/11/18 09:15	Reinspection Photo	 Load JPG	✓
135	01/11/18 09:15	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 12:47	TP GIA REPORT	 Load PDF	
2	05/08/19 17:38	LOD	 Load PDF	
3	05/08/19 17:38	LTA SEARCH	 Load PDF	
4	06/04/20 10:45	Authorisation to Act	 Load PDF	
5	06/04/20 10:45	DISCHARGE VOUCHER	 Load PDF	
6	06/04/20 10:45	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 14:50	Singapore Accident Statement-IV	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18012759/AGA3S2

Date: 06/04/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	GBG3620E	Insured Vehicle No :	SHD4443M
Date of Loss:	09/07/2018	Nature of Claim:	TP
		Claim No:	MCT18070272

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3620E	Engine No:	YD25420242A
Make & Model:	NISSAN NV350, 2.5 D Panel Van (M)	Chassis No:	JN1MC2E26Z0008335
Reg. Date:	27/07/2017 (Man. Year: 2017)	Odometer:	47742 km
Colour:	Yellow		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,023.24	18,992.78	12,030.46	38.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	3,390.00	4,110.00	54.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,523.24	22,382.78	16,140.46	41.90
Approved Total (Overridden) (S\$)		17,900.00		
(S\$)	38,523.24	17,900.00	20,623.24	53.53
+ GST 7.00/7.00% (S\$)	2,696.63	1,253.00	1,443.63	53.53
Nett Amount (S\$)	41,219.87	19,153.00	22,066.87	53.53
+ Loss of Use (15.0 x S\$60.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		20,060.45		
Global Sum Settlement (S\$)		20,000.00		

INSPECTION

Date of Assignment: 12/07/2018

Date Inspected: 12/07/2018 Inspected At:

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection
 Centre
 Singapore 415933

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Apr 2020)	
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3620E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Repair	1,266.30 FN	*- FN
2	1		*FRONT BUMPER	Deformed	550.00 FN	*550.00 FN
3	2		*FRONT BUMPER SIDE RETAINER	Necessary	300.00 FN	*170.00 FN
4	1		*FRONT BUMPER FOGLAMP HOUSING	Distorted	109.20 FN	*109.20 FN
5	1		*FRONT BUMPER REINFORCEMENT (CENTRE)	Bent	380.00 FN	*380.00 FN
6	2		*FRONT BUMPER REINFORCEMENT HOLDER	Bent	220.00 FN	*220.00 FN
7	1		*FRONT BUMPER REINFORCEMENT LOWER	Bent	160.00 FN	*160.00 FN
8	1		*FRONT BUMPER LOWER COVER	Deformed	99.70 FN	*99.70 FN
9	1		*FRONT GRILLE	Missing	490.00 FN	*490.00 FN
10	1		*FRONT GRILLE LOGO	Necessary	90.00 FN	*90.00 FN
11	2		*HEADLAMP	Cracked	932.60 FN	*932.60 FN
12	1		*FRONT WINDSCREEN	Cracked	1,190.30 FN	*1,190.30 FN
13	1		*SET FRONT WINDSCREEN MOULDING	Necessary	180.00 FN	*180.00 FN
14	2		*FRONT DOOR	Repair	2,240.00 FN	*- FN
15	2		*FRONT DOOR PILLAR	Repair	2,478.00 FN	*- FN
16	1		*AIR VENT	Cracked	190.00 FN	*190.00 FN
17	1		*AIRBAG	Activated	2,100.00 FN	*2,100.00 FN
18	1		*TURBO INNER COOLER	Dented	2,255.90 FN	*2,101.60 FN
19	1		*RADIATOR	Dented	830.00 FN	*830.00 FN
20	1		*FAN BLADE	Not Necessary	210.00 FN	*- FN
21	2		*FAN MOTOR	Not Necessary	932.60 FN	*- FN
22	1		*FAN COWLING ASSY	Cracked	201.00 FN	*201.00 FN
23	1		*POWER STEERING BELT	Cut	120.00 FN	*120.00 FN
24	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*30.00 FS
25	1		*FRONT PANEL STICKER	Necessary	350.00 FS	*200.00 FS
26	1		*FRONT PANEL COMPANY STICKER	Necessary	350.00 FS	*180.00 FS
27	1		*SET FRONT BUMPER CLIPS	Necessary	25.00 FS	*25.00 FS
28	1		*FRONT BUMPER STICKER	Not Necessary	250.00 FS	*- FS
29	2		*FRONT BUMPER FOG LAMP	Cracked	644.40 FS	*644.40 FS
30	1		*FRONT BUMPER INNER CROSS MEMBER	Repair	890.00 FS	*- FS
31	1		*SET CENTRE GRILLE CLIPS	Necessary	23.00 FS	*23.00 FS
32	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
33	1		*FRONT WINDSCREEN INNER SEAL	Necessary	120.00 FS	*40.00 FS
34	2		*FRONT DOOR COMPANY STICKER	Necessary	1,300.00 FS	*450.00 FS
35	2		*FRONT DOOR LTA ADDRESS	Necessary	50.00 FS	*50.00 FS
36	1		*HORN (10%)	Damaged	103.00 FS	*92.70 FS
37	1		*AIRBAG CONTROL UNIT (10%)	Activated	970.00 FS	*873.00 FS
38	2		*SAFETY BELT (10%)	Activated	1,777.80 FS	*1,600.02 FS
39	1		*TURBO INNER COOLER PIPE (10%)	Bent	555.00 FS	*499.50 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*AIRCON BLOWER MOTOR HOUSING	Cracked	710.00 FS	*710.00 FS
41	1		*AIRCON COOLING OIL	Cracked	620.00 FS	*620.00 FS
42	1		*AIRCON COOLING COIL HOUSING	Cracked	1,600.00 FS	*1,600.00 FS
43	1		*AIRCON COOLING COIL VALVE (@ \$155.00 DISC 10%)	Bent	410.00 FS	*139.50 FS
44	1		*AIRCON COOLING COIL PIPE (10%)	Bent	190.00 FS	*171.00 FS
45	1		*AIRCON PIPE (H) (10%)	Bent	260.00 FS	*234.00 FS
46	1		*AIRCON PIPE (L) (10%)	Bent	180.00 FS	*162.00 FS
47	1		*POWER STEERING COOLER (10%)	Bent	322.00 FS	*289.80 FS
48	1		*RECEIVER DRIVE (10%)	Dented	222.00 FS	*199.80 FS
49	1		*RECEIVER DRIVE BRACKET (10%)	Bent	55.00 FS	*49.50 FS
50	1		*HEATER COIL	Not Necessary	1,800.00 FS	*- FS
51	4		*HEATER COIL PIPE (@ \$250.00 DISC 10%)	Bent	534.40 FS	*225.00 FS
52	2		*HEATER COIL HOSE (10%)	Snapped	180.00 FS	*162.00 FS
53	1		*THERMOSTAT SENSOR (10%)	Damaged	290.00 FS	*261.00 FS
54	1		*STEERING AIRBAG CLOCK SPRING	Activated	354.00 FN	*354.00 FN

F=Franchise part, S=SpcNett, N=NettItemDisc.

Sub Total (S\$)	32,811.20	20,039.62
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,787.96	1,046.84
Total Parts (S\$)	31,023.24	18,992.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS.	New	2,600.00	1,300.00
2	SPRAY PAINTING TO AFFECTED AREA.	New	2,000.00	800.00
3	TUFF COAT.	New	250.00	40.00
4	WIRING CHECK.	New	80.00	30.00
5	CONDUCT WATER LEAKAGE TEST.	New	80.00	0.00
6	FRONT CHASSIS ALIGNMENT.	New	250.00	0.00
7	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.	New	250.00	200.00
8	REMOVE AND REFIX AIRCON COOLING COIL AND REFILL AIRCON.	New	120.00	120.00
9	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING.	New	350.00	250.00
10	REMOVE AND REFIX AIRCON BLOWER MOTOR.	New	250.00	200.00
11	REMOVE AND REFIX FRONT WINDSCREEN.	New	120.00	0.00
12	REMOVE AND REFIX AIRBAG.	New	350.00	250.00
13	REMOVE AND REFIX SAFETY BELT.	New	300.00	100.00
14	RESET AIRBAG.	New	250.00	100.00
15	REMOVE AND REFIX FRONT DOOR.	New	250.00	0.00
Gross Labour Cost (\$\$)			7,500.00	3,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >