

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

12 JUL 2018

E S T I M A T E

Estimate No. : b1 47657 Page No. : 1 of 5
Date Estimated : 12/07/2018
Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -
Hitachi Aqua-Tech Engineering Pte. Ltd.
40 Changi South Street 1

Singapore 486764

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN5445B	G884766	28/04/2017	530iA	0

DESCRIPTION

To replace rear bumper assembly, bumper carrier &
all attachments cause by accident.

VALUE
850 2,550.00

Painting on rear bumper assembly

882.00

To check electrical wiring systems at the rear section
for proper function.

150 177.00

Sundries.

40 80.00

Total Labour 1: 3,689.00

DESCRIPTION

Carrier, bum
EXHAUST SUPPORT
REAR BUMPER COVER (M)
REAR BUMPER LH GUIDE (M)
REAR BUMPER RH GUIDE (M)
REAR BUMPER CENTRE GUIDE (M)
REAR BUMPER PANEL PRIMED (M)
SET MOUNTING PDC/PMA SENSOR REAR (M)
REAR SILENCER HEAT INSULATION FRT
UNDERBODY PANELLING REAR
Ultrasonic s
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	582.20	582.20
1	47.45	47.45
1	176.45	176.45
1	54.40	54.40
1	54.40	54.40
1	60.05	60.05
1	1,587.75	1,587.75
1	62.95	62.95
1	111.50	111.50
1	41.30	41.30
1	380.65	380.65
6	5.05	30.30

Total Parts : 3,189.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 47657	Page No. : 2 of 5
Date Estimated	: 12/07/2018	
Prepared By	: Kevin Leong Wai Kit	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN5445B	G884766	28/04/2017	530ia	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>30/07/18 @ 1530</u>	Claim No. _____
Date & Time <u>30/07/18 @ 1530</u>	Excess S\$ _____
Surveyor's Name <u>RAHUL</u>	Sign _____
Surveyor's Tel <u>90000068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____
--

Labour 1	:	3,689.00
Parts	:	3,189.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	481.49
Grand Total	:	<u>7,359.89</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **