

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 16 Jul 2018

**Preliminary Advice**

Vehicle No	: SFY3P	Accident Date	: 10/07/2018
Make	: AUDI A4	Policy No.	: 2100467474-02
Assignment Date	: 16/07/2018	Excess	: S\$0.00
Date of Inspection	: 13/07/2018	Est. Duration of Repair	: 8 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s portion, u/c affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,764.00
Revised Amount	:S\$	8,304.00
Check Items (Estimated)	:S\$	25,663.00
Total	:S\$	33,967.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	58,757.00
Salvage Value	:S\$	
Margin for Repair	:S\$	56,243.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :