

慶福摩哆
 KENG HOCK AUTO
 SECTOR C, BLK 7 #01-84
 SIN MING ROAD SINGAPORE 575642
 TEL/FAX: 6458 5589 H/P: 9657 1534

Not Notwithstanding
 11 Day @ 3000/-
 Runny After Palm
 6 days

Quotation

Date:
 Terms:
 Regn. No: SLF 4489U
 Vehicle Make: Honda Yezel
 Mileage:

Parts Replaced / Labour Charges / Other Services	Qty	U/Price \$	Amount \$
Rear Fender	1	RM 1200.00	1200.00
Rear Fender left inner panel	1	RM 980.00	980.00
Rear Fender left outer garnish	1	RM 120.00	120.00
Rear wheel Arch	1	RM 350.00	350.00
Rear Petrol tank cover Lid	1	RM 120.00	120.00
Rear Petrol tank inlet hose	1	RM 280.00	280.00
Rear Fender left outer garnish	1	RM 110.00	110.00
Rear Bumper	1	RM 850.00	850.00
Rear Bumper side 2Poco	1	RM 400.00	400.00
Rear Bumper retainer	1	RM 80.00	80.00
Rear lamp	1	RM 930.00	930.00
Rear Bumper clip	1	RM 50.00	50.00
Rear lamp	1	RM 930.00	930.00
Rear wheel rim	1	RM 400.00	400.00

20%

Remove Rear upholstery 350.00
 Remove petrol tank 200.00
 Remove Rear left under carriage 280.00 X
 Anti. Rust proofing 180.00
 panel beating 1500.00
 Spray - painting 1200.00

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____

10,510

Customer's Signature