KIM CHWEE AUTO PTE LTD 1 Kaki Bukit Ave 6 #01-46,48,50 Autobay SINGAPORE 417883

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Albind
13/7/18
1/5# 1800-1/5-1

VEHICLE NO:S	SFS 301K	
QTY	PARTICULAR	- /-
1 PCS	FRONT BUMPER 1106.43	7/5/73.7 \$1,616.32
1 PCS	FRONT BUMPER LOWER SKIRTING P66.2/	\$966.50
1 PCS	FRONT BUMPER SIDE HOLDER O/S 49.50	3 er \$89.30
1 PCS	FRONT BUMPER FOG LAMP COVER O/S	70-2 \$99.20
1 PCS	FRONT BUMPER FOG LAMP O/S 366.05	CM \$450.00
1 SET	FRONT BUMPER CLIPS	Ner \$50.00
1 PCS	FRONT BUMPER REINFORCEMNT	∧ \$529.20 X
1 PCS	FRONT BUMPER SPONGE	10.7 \$120.52
1 PCS	FRONT GRILLE	11 \$708.75 X
1 PCS	BONNET	\$901.80 X
1 PCS	FRONT SUPPORT PANEL	↑ \$945.30 ×
1 PCS	FRONT FENDER O/S 700.35	3u c \$866.01
1 PCS	FRONT FENDER INNER SHIELD O/S 2/5. KS	1,1 \$265.40
1 SET	FRONT FENDER INNER SHIELD CLIPS O/S	re \$50.00/
1 PCS	FRONT DOOR O/S	↑ \$1,226.30 ★
1 PCS	FRONT LOWER ARM O/S 3 PS	34 \$566.50
1 PCS	FRONT KNUCKLE ARM O/S 42(//	BM \$620.30
1 PCS	FRONT KNUCKLE ARM BEARING O/S	ne \$350.00
1 PCS	FRONT SHOCK ABSORBER O/S	€ \$488.20 ×
1 PCS	HEADLAMP O/S 7.5 2-570	5no \$1,866.20
	10000	\$12,775.80
		6.12
	FRONT TYRE O/S	(8.8/ SUC \$300.00 X
	FRONT SPORT RIM '18INCH' O/S	↑ \$1,200.00 ×
	BONNET CARBON STICKER	cu7 \$380.00 22 c
	LABOUR CHRAGES:	
	TO CHECK WIRING	\$80.00 30
	TO SPRAY RUST PROOFING	\$120.00 50
	TO CONDUCT WHEEL ALIGNMENT	\$150.00/20
	TO DISMENTLE & REPLACING FRONT UNDERCAF	
	LABOUR FOR PANEL BEATING & REPLACING PAR	
	TO PUTTY & SPRAY PAINTING	\$1,500.00 900
	TOT	A STATE OF THE PROPERTY OF THE
	101	ΑΕ Ψ17,000.00