

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

10/07/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE HYBRID - SLZ260L

1pc	front bonnet	Buy \$	985.50	✓
1pc	front bonnet inner rubber	Buy \$	158.50	X
1pc	front "H" logo	Buy \$	85.50	✓
1pc	front centre grille base	\$	395.50	?
1pc	front centre grille outer garnish	\$	350.95	?
1pc	front centre grille chrome	CM \$	185.50	✓
1pc	front centre grille top garnish	\$	180.40	?
1pc	front bumper	Buy \$	1,105.80	✓
1pc	front bumper reinforcement	\$	520.90	?
2pcs	front bumper side retainer @\$35.50	dis \$	71.00	X
2pcs	front bumper side garnish @\$281.70	Buy \$	563.40	X
1pc	front bumper centre lower grille	Buy \$	159.50	X
2pcs	front headlamp @\$2320.90	\$	4,641.80	?
2pcs	front headlamp lower bracket @\$40.80	\$	81.60	?

less 20%

\$ 9,485.85

\$ 1,897.17

\$ 7,588.68

1pc front number plate & casing

Buy s.nett \$ 50.00 X

wiring

\$ 60.00 201

tuffkote

\$ 60.00 301

spray painting

\$ 950.00 4401

labour charges

\$ 900.00 4001

Total

\$ 9,608.68



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: