

INS. CASE OWNER:

Shawn

CC 4 / ALG 180 12894, K pa3 9/

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

18/7/18

Date / Time:

16/7/18

Registered in Merimen:

16/7/18
677-200 314356

Pre-assign / CCU / FTE

SGZ 118 9m



Insured Vehicle No.:

Name of Insured:

CHAN XIN-BEI VARIERE

Insured Tel No.:

HP: 98271311

Excess Sec II :S\$

D.O.A: 12/7/18

Is driver the owner?

(YES /)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKX 80785



INSRS:
WSP: BH Auto
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

19/7/18	SKX 80785, X ; SGZ 118 9m - X
20/7/18	Read email from Shawn: PLS assist to reject TP claim based on B15. TP changed tone
20/7/18	Email to TP: Reject
21/7/18	* ALG instruction to reject TP claim. File pursue Mei Kuan to close.



PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	S\$	(days)	Reduction: %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No.:
Repair Cost:	S\$		
Loss of Rental (LOR):	S\$	(days)	
Loss of Use (LOU):	S\$	(\$ x days)	
Loss of Income (LOI):	S\$	(\$ x days)	
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐
[Tick only one]			
GIA/LTA Search	S\$		
Medical:	S\$		
Disbursement:	S\$	(e.g. Tow/ Independent)	
Legal Cost	S\$		
Total:	S\$	Global Sum S\$:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	S\$	Name 1:	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

21/7/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$250 + HST.

REF:

ALH

12894 / Kpa3 - (P)

ASSIGNMENT

From: Date: 18072018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKX 8078S

at Workshop only:

BH Auto

at

Blk 1 Sin Ming Ind Est 401-115.

Insured

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11cm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res: Yes or No

Lim Sum:

1.31 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Skx 8078S Yr Regn 12 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW A 218i

Colour:

M. Silver

A/C

Insured / Std / NI / NA

Sp. Reading

32381

T/Radio: Insured / Std / NI / NA

Engine:

C/No:

WBA1M32070V311285

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD. Arr. or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

8

mm

L/Bal:

7

mm

L/Bal:

8

mm

D.O.A:

12/7/18

D.O.A:

18/7/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

18/7 ALH 1011 to Catherine

Submit

P/P \$ 3501.10 (Real \$ 4918.30/55%) - excluded check items \$ 684.95

Date/Time, File Path to:



: Prel. Report

R:



: Final Report

Date/Time, File Return to:

S:

Add Fee:



Site Insp: \$



Interview: \$



Test: \$



Workshop: \$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transport:

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

TOTAL

Report Format:

Lump Sum / I.B. \$

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended De-registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Foreign Identification Number

3937T

SKX80785

No

13 Jul 2018

B.M.W.

218i CONVERTIBLE AT HID ABS

Silver

2015

F7181296B38B15A

WBA1M32070V311285

100.0 kW (134 bhp)

\$30,011.00

29 Dec 2015

29 Dec 2015

0

\$29,016.00

Yes

28 Dec 2025

\$21,762.00

28 Dec 2025

E - Open Category

10

\$62,019.00

\$45,564.00

\$67,326.00

The information contained herein is correct as at 13 Jul 2018

OK

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Classic PromotBest DealFast SellingHurry Down Now!



Flexible Loan, Trade In Are
Welcome, 100% Deposit Refund
For Unapproved Loan,
Classic Credit Stand



Browse by Category

< Back (1 2) Next >

Sort by Date Posted 20 results/page

30 vehicles

BMW 2

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	BMW 2	<i>Any</i>	<i>Any</i>	2015	<i>Any</i>	<i>Any</i>	<i>Any</i>	Available
	BMW 2 Series 216d Active Tourer	\$97,999	\$11,860 /yr	29-Dec-2015	1,496 cc	29,000 km	Hatchback	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Special 2.48% Banks Interest Rate! Certified Premium 110 Points Check, Agent Unit. 1 Owner Meticulously Well Taken Care Of, One Full Tank Able To Achieve 900km! Spacious Seatings With Large Boot Space...								
Premium Automobiles								
Posted: 13-Jul-2018 Tags: 2015 BMW 216d, BMW 216d, BMW, 216d, Used BMW								
	BMW 2 Series 218i Active Tourer	\$94,999	\$11,470 /yr	25-Sep-2015	1,499 cc	70,000 km	Hatchback	Available
Immaculate Condition! 1 Owner, Full Serviced Histories And Warranty By With PML, Premium 110 Points Check, Agent, Owner Upgraded To New Audi, Flexible Financing Available. SMS/Call Now For Viewing!								
Premium Automobiles								
Posted: 13-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW								
	BMW 2 Series 218i Active Tourer	\$97,800	\$12,080 /yr	28-Aug-2015	1,499 cc	33,678 km	Hatchback	Available
\$0 Down Payment For Limited Period Only! Other Loan Packages From Bank/In House/Balloon Scheme Available With Most Attractive And 100% Fast Approval Rates! 1 Owner Only! Full Serviced History And Vail...								
Le Motor Enterprise								
Posted: 13-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW								
	BMW 2 Series 218i Active Tourer	\$102,800	\$12,400 /yr	28-Oct-2015	1,499 cc	55,734 km	Hatchback	Available
In-House Loan And Balloon Scheme Available, No Gemmicks! Down Payment \$10280 With Monthly \$1453, Full PML Service Record, 1 Owner, Parallel Auto Parking Assist, Reverse Camera, Auto Bi Xenon Lights Wl...								
Posted: 13-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW								
Car Buying	Car Selling	Car Ownership		Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation				
Car Aftermarket	On The Move	Lifestyle						
	BMW 2 Series 218i Active Tourer	\$89,000	\$11,270 /yr	15-Jun-2015	1,499 cc	-	Hatchback	Available
Extremely Affordable Family Compact SUV, Ambient Lightings To Light Up The Interior! Selling Below Market At \$11K Depreciation/Year Only, Loan Up To \$63K With Low Bank Interest. Insurance/Trade-In Wel...								
Tradit.Com Pte Ltd								
Posted: 12-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW								
	BMW 2 Series 218i Active Tourer	\$95,800	\$12,830 /yr	14-May-2015	1,499 cc	35,000 km	Hatchback	Available
The Only Certified BMW Active Tourer! Low Fuel Consumption And Extreme Agility In Road Holding. Be Pampered With Ample Leg And Head Room Space, Piles Of Luggage Capacity At The Boot. Clad In Alpine Wh...								
Performance Premium Selection Limited								
Posted: 10-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW								
Compare	B*	Live	\$89,800	\$12,110 /yr	27-Feb-2015	1,499 cc	56,000 km	Available

**Tourer**

The Only Certified BMW Active Tourer! Low Fuel Consumption And Extreme Agility In Road Holding. Be Pampered With Ample Leg And Head Room Space. Piles Of Luggage Capacity At The Boot. Clad In Flamenco ...

Performance Premium Selection Limited

Posted: 10-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

**BMW 2 Series 218i Active Tourer****\$96,555****\$11,910 /yr****31-Aug-2015****1,499 cc****45,000 km****Hatchback****Available**

Full Agent Maintain, Servicing Just Done, Still Under PML Warranty. 95% Loan Available. 2.28% Loan Interest. Monthly \$925. Free Car Spa Polishing! Highest Trade In For Your Car. Low Down Payment, High...

Cars Inn Credit Pte Ltd

Posted: 07-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

**BMW 2 Series 218i Active Tourer****\$93,800****\$12,600 /yr****30-Apr-2015****1,499 cc****56,420 km****Hatchback****Available**

\$2,000 Republic Auto Warranty Service Credit! PML Unit, Maintained By Agent, Well Kept, Call For Viewing Or SMS To Arrange For Test Drive.

Republic Auto

Posted: 07-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

**BMW 2 Series 218i Active Tourer****\$79,800****\$10,540 /yr****27-Feb-2015****1,499 cc****43,000 km****Hatchback****Available**

Cheapest In The Market! 1 Owner Car. Excellent Condition! Low Fuel Consumption! No Repairs Needed. We Welcome VICOM/STA Evaluation! Call Now To Test Drive.

Posted: 02-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

**Save on petrol with OCBC 365 credit card!**

Enjoy huge petrol savings of up to 23%, attractive cashback on your monthly spend, and 2 years annual fee waiver. Apply now and start enjoying today.

Find out more!

**BMW 2 Series 218i Active Tourer****\$89,300****\$11,970 /yr****26-Feb-2015****1,499 cc****50,000 km****Hatchback****Available**

Graded B by **STRA**

Deposit 15%, One Owner, Fully Agent Maintained, 100% Accidents Free, Price Negotiable, Easy Loan/Trade In Available.

Posted: 02-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

**BMW 2 Series 218i Active Tourer****\$97,500****\$13,310 /yr****27-Jan-2015****1,499 cc****40,000 km****Hatchback****Available**

3 Years Agent Warranty. Mint Condition. Please Call For An Appointment. Extended Warranty Available. Loan And Trade In Provided.

Posted: 02-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

**BMW 2 Series 218i Active Tourer****\$91,800****\$12,260 /yr****29-Apr-2015****1,499 cc****45,811 km****Hatchback****Available**

100% Loan Available, 1 Owner, Low Mileage Done Only 45,811Kms, Full Serviced Histories With PML, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.

Faster Auto Trading

Posted: 01-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

**BMW 2 Series 218i Active Tourer****\$87,800****\$11,600 /yr****15-May-2015****1,499 cc****60,000 km****Hatchback****Available**

Fully Maintained By Agent PML! Agent Unit. Extended Warranty From PML May 2020 Or 200,000km. Price Negotiable, Consignment Unit. Appointment Only. Call Now.

Performance Carz Pte Ltd

Posted: 01-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

**BMW 2 Series 216d Gran Tourer****\$113,388****\$13,660 /yr****27-Nov-2015****1,496 cc****29,000 km****MPV****Available**

Fuel Type: Diesel (Euro 5 Engine and Above)

1 Owner. Down Payment \$12000. Very Low Mileage Done At 11500km Per Year. Under Agent Warranty. Spacious 7 Seats Gran Tourer Diesel With Extremely Low Fuel Of 22.7Km/L. Brand New Interior, Well Maintain...

Posted: 30-Jun-2018 Tags: 2015 BMW 216d, BMW 216d, BMW, 216d, Used BMW

**BMW 2 Series 218i Active Tourer****\$102,800****\$12,440 /yr****29-Oct-2015****1,499 cc****25,500 km****Hatchback****Available**

1 Owner Sporty Pearl White With Low Mileage 25,500 Km! Only As Owner Stationed Overseas, Full Serviced Histories And Warranty By With PML, Accident Free, High Loan Available, Trade In Welcome, Viewing ...

Posted: 01-Jul-2018 Tags: 2015 BMW 218i, BMW 218i, BMW, 218i, Used BMW

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd

AIG Building

78 Shenton Way #08-16

Singapore (079120)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6419 3000 Fax : 6835 7416

DEAR SIR / MADAM :

*Not Authored
1.B.1
Penny Bepary*

2 day

ACCIDENT REPAIR ON: SKX8078S

MODEL : BMW 218i CONVERTIBLE

POLICY NO : CN862140

CHASSIS NO : WBA1M32070V311285

YEAR OF MANUFACTURE : 2015

DATE / TIME OF ACCIDENT: 12/07/2018 Time: 1335Hrs at ALONG TANJONG RD BESIDE AMARA HOTEL.

THIRD PARTY VEHICLE NO: SGZ1189M

Date: 17/07/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Front bumper	1	983.00	Torn	983.00 ✓
2	Front bumper side retainer LH	1	19.00	Necessary	19.00 X
3	Front bumper side retainer RH	1	19.00	Necessary	19.00 X
4	Front bumper sponge	1	63.00	Cracked	63.00 X
5	Front bumper reinforcement	1	383.00	Bented	383.00 X
6	Front bumper nozzle LH	1	194.00	Cut	194.00 ✓
7	Front bumper nozzle cover LH	1	58.00	Torn	58.00 ✓
8	Front bumper fog lamp garnish cover LH	1	107.00	Scratches	107.00 ?
9	Front bumper fog lamp grille LH	1	79.00	Scratches	79.00 ?
10	Front bumper fog lamp LH	1	276.00	Broken	276.00 ?
11	Front fender LH	1	546.00	Dented	546.00 X
12	Front fender shield LH	1	151.00	Cut	151.00 ?
13	Front fender shield clips	10	5.00	Necessary	50.00 ?
14	Headlamp LH	1	1,903.00	Scratches	1,903.00 ✓
15	Headlamp lower bracket LH	1	58.00	Torn	58.00 ?
16	Front wheel rim LH	1	1,099.00	Scratches	1,099.00 X

Sub-Total: 5,988.00

Less: 5% discount - 299.40

Total Parts after 5% discount: 5,688.60

Special Nett Items

1	Anti-rust coating	2	80.00	na	160.00 X
					160.00

Total Parts: 5,848.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims are on "Without Prejudice" basis
- No illegal insurance claims allowed
- Supplementary claims are resurveyed and is subject to approval from Insurance Company

Acknowledged by: _____
Signature: _____

Labour Charges For LH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	900.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	900.00 250/

250/

250/

- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Provide skill labour to check and re-adjust wheel alignment
- 5 Provide skill labour to remove and refit/balancing wheel rim and tyre

60.00 2d
 ~ 80.00 x
 ~ 80.00 x

Total Labour:

2,020.00

Total Parts & Labour:

7,868.60

GST 7%

550.80

Grand Total:

8,419.40

Estimate Repair Duration

7 days

ACCIDENT VEHICLE OF : SKX8078S

Page : 2 of 2

2day

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

Name : Kenneth

Company : CIC/

Date : 18/7/18

Time : 11.20am

Contact No : _____

Email : _____

Hsiao Tong (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Friday, 20 July 2018 10:01 AM
To: 'Wui, Shawnkaijie'; Hsiao Tong (LKKAuto)
Cc: Admin A; assignments
Subject: RE: Case Assignment TP - SKX80785 - 12/07/2018 -

Dear Sir/Mdm,

Thank you for the email.

Dear Hsiao Tong,

Kindly assist.

FYNA Our Ref : CC4/AIG18012894/pa3

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wui, Shawnkaijie [mailto:Shawnkaijie.Wui@aig.com]
Sent: Friday, 20 July 2018 9:55 AM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: Case Assignment TP - SKX80785 - 12/07/2018 -

Dear Sirs,

Please assist to reject TP claims based on BOLA 15. TP changed lane.

Thanks and Regards,
Shawn Wui
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijie.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]
Sent: Tuesday, July 17, 2018 9:00 AM
To: Wui, Shawnkaijye
Subject: Case Assignment TP - SKX8078S - 12/07/2018 -

This mail is associated with :

***SKX8078S**

[SGZ1189M]

TP

LIU JIA

Jul 12 2018 1:00PM

[Chan Xin-Bei Valerie]

BH Auto Services Pte Ltd

Dear Wui, Shawn-KJ,

Please note that a claim has been assigned to you for handling in Merimen. For your action and follow up please.

This is an auto-generated email. Do not reply to this email.

Sent by : Wui, Shawn-KJ (AIG Asia Pacific Insurance Pte. Ltd.)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 24 July 2018 2:26 PM
To: 'BHAS - Jacelyn Loh'
Cc: BHAS - Moo Wen Zheng; BHAS - Anthony Lau; BHAS - Bernard Kee; Admin A
Subject: <REJECTION>- ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ1189M AND SKX8078S ON 12/07/2018 *** LKK REF: CC4/AIG18012894/pa3


Without Prejudice

Hi Sirs/ Mdm,

We refer to the above matter.

We attached here with a copy of our insured accident report for your easy reference. Our insured reported that your client changed lane and resulted the collision. We are of the view that BOLA scenario 15 is applicable. Your client should exercise greater caution while changing lane.

We regret to inform your that we have our principal instruction to deny liability and unable to look into your client claim.

SKETCH PLAN	
	A - SGZ1189M B - SKX8078S
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
On 12 July 2018 at 1:40 PM, I was driving along Tanjong Pagar Road on left most lane. A BMW car tried to cut into my lane from the lane on my right and the left front portion of her car hit the right body of my car.	

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>

Sent: Friday, 20 July 2018 4:53 PM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ1189M AND SKX8078S ON 12/07/2018 *** LKK REF: CC4/AIG18012894/pa3

Dear all,

Kindly advise on this liabilities status and forwards me sketch plan and statement.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: BHAS - Jacelyn Loh

Sent: Wednesday, 18 July 2018 12:38 PM

To: 'Mei Kwan (LKKAuto)' <Meikwan@lkkauto.com>; Admin A <admin-a@lkkauto.com>; 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>

Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ1189M AND SKX8078S ON 12/07/2018 *** LKK REF: CC4/AIG18012894/pa3

Dear all,

Received and thanks

Please Kindly advise on this liabilities status.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**


Address: Blk 1, Sector C, Sin Ming Industrial Estate
#01-111/113/115/117 Singapore: 575636
(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404
Email: jacelyn.loh@bhauto.com.sg
Website: <http://www.bhauto.com.sg>

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Tuesday, 17 July 2018 11:32 AM
To: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ1189M AND SKX8078S ON 12/07/2018 *** LKK REF: CC4/AIG18012894/pa3

Dear Sir / Madam,

We refer to the above matter.

Please be informed OI has reported. Please refer to the below OI's sketch plan and statement.

SKETCH PLAN	
	A - SGZ1189M B - SKX8078S
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
On 12 July 2018 at 1:40 PM, I was driving along Tanjong Pagar Road on left most lane. A BMW car tried to cut into my lane and the car on my right and the left front portion of her car hit the right body of my car.	

Kindly provide us evidence i.e. video and scene photo

Please note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 16 July, 2018 3:50 PM

To: 'BHAS - Jacelyn Loh' <jacelyn.loh@bhauto.com.sg>; Admin A <admin-a@lkkauto.com>

Cc: 'BHAS - Moo Wen Zheng' <wenzheng.moo@bhauto.com.sg>; 'BHAS - Anthony Lau' <anthony.lau@bhauto.com.sg>; 'BHAS - Bernard Kee' <bernard.kee@bhauto.com.sg>; assignments <assignments@lkkauto.com>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ1189M AND SKX8078S ON 12/07/2018

Dear Jacelyn,

Appointment confirmed.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Jacelyn Loh [<mailto:jacelyn.loh@bhauto.com.sg>]

Sent: Monday, 16 July, 2018 3:46 PM

To: 'Team A (admin-a@lkkauto.com)' <admin-a@lkkauto.com>; Nivitha (LKK Auto) <admin-d@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ1189M AND SKX8078S ON 12/07/2018

Dear ALL,

I would like to arrange surveyor on DATE:18/07/2018 AND TIME:11am of the above mentioned accident vehicle.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Vehicle currently not in workshop

Greatly appreciate it. Thank you and have a nice day.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: Jacelyn.loh@bhauto.com.sg
Website: <http://www.bhauto.com.sg>

From: BHAS - Jacelyn Loh
Sent: Monday, 16 July 2018 11:04 AM
To: 'Mithoosingh, Aashweenjeetkaur' <Aashweenjeetkaur.Mithoosingh@aig.com>; Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ1189M AND SKX8078S ON 12/07/2018

Dear sir / mdm,

We choose below surveyor: LKK Auto Consultants Pte Ltd

Ps- vehicle currently NOT our workshop.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: Jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: Mithoosingh, Aashweenjeetkaur [<mailto:Aashweenjeetkaur.Mithoosingh@aig.com>]
Sent: Monday, 16 July 2018 10:29 AM
To: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ1189M AND SKX8078S ON 12/07/2018

Without Prejudice

Your Reference : SKX8078S
Our Reference : SGZ1189M

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Aashweenjeet Kaur (Aashween)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1002215

aashweenjeetkaur.mithoosingh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally for any loss or damage arising in any way from its use.

From: BHAS - Jacelyn Loh [<mailto:jacelyn.loh@bhauto.com.sg>]

Sent: Friday, July 13, 2018 6:13 PM

To: AIG SGP, Claims-Survey

Cc: BHAS - Moo Wen Zheng; BHAS - Anthony Lau

Subject: pre repair inspection (OUR VEHICLE - SKX8078S / YOUR VEHICLE - SGZ1189M)

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently not in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jul 2018 Edit Reg		16 Jul 2018 00:00 Edit Adj Rpt	S\$3,501.10 Edit Estimates	S\$3,501.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Chan Xin-Bel Valerie, ID: S9026470B								
Main Claimant:	LIU JIA, ID: G0753937T								
Vehicle Reg. No.:	SKX8078S	Date of Loss:	12/07/2018 13:00 - :59 [30 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6772003133SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SGZ1189M	Policy No. (Claimant):	CN862140						
		Excess:							
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_5G (17/07/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX8078S (6772003133SG)
[SGZ1189M]
TP
LIU JIA
Jul 12 2018 1:00PM
[Chan Xin-Bel Valerie]
BH Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/07/18 14:28	General View		Load JPG	☒
2	24/07/18 14:28	General View		Load JPG	☒
3	24/07/18 14:28	General View		Load JPG	☒
4	24/07/18 14:28	General View		Load JPG	☒
5	24/07/18 14:28	General View		Load JPG	☒
6	24/07/18 14:28	General View		Load JPG	☒
7	24/07/18 14:28	General View		Load JPG	☒
8	24/07/18 14:28	Odometer Reading		Load JPG	☒
9	24/07/18 14:28	General View		Load JPG	☒
10	24/07/18 14:28	Chassis Number		Load JPG	☒
11	24/07/18 14:28	General View		Load JPG	☒

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/07/18 11:25	TP GIA REPORT		Load PDF	
2	17/07/18 11:27	ACKNOWLEDGEMENT EMAIL TO AIG DD 16.07.2018		Load PDF	
3	17/07/18 11:27	EMAIL FROM AIG DD 16.07.2018		Load PDF	
4	20/07/18 09:15	TP ESTIMATE - MARKED		Load PDF	
5	24/07/18 14:28	Email from Shawn dd 200718		Load PDF	
6	24/07/18 14:28	Email to TP_Reject dd 240718		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	17/07/18 08:55	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18012894/KPA3Q2

Date: 28/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKX8078S

Insured Vehicle No : SGZ1189M

Date of Loss: 12/07/2018

Nature of Claim: TP

Claim No: 6772003133SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX8078S**

Make & Model: BMW 218i, 1.5 CONVERTIBLE (A)

Reg. Date: 29/12/2015 (Man. Year: 2015)

Colour: Metallic Silver

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: F7181296B38B15A

Chassis No: WBA1M32070V311285

Odometer: 32381 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,848.60	2,981.10	2,867.50	49.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	520.00	1,500.00	74.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,868.60	3,501.10	4,367.50	55.51
+ GST 7.00/7.00% (S\$)	550.80	245.08	305.72	55.50
Nett Amount (S\$)	8,419.40	3,746.18	4,673.22	55.51
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 16/07/2018

Date Inspected: 18/07/2018 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C,
#01/111/113/115/117
Singapore 575636

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	983.00 FL	*983.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	19.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	19.00 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Serviceable	63.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	383.00 FL	*- FL
6	1		*FRONT BUMPER NOZZLE LH	Missing	194.00 FL	*194.00 FL
7	1		*FRONT BUMPER NOZZLE COVER LH	Missing	58.00 FL	*58.00 FL
8	1		*FRONT BUMPER FOG LAMP GARNISH COVER LH	*Check	107.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP GRILLE LH	*Check	79.00 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP LH	*Check	276.00 FL	*- FL
11	1		*FRONT FENDER LH	Repair	546.00 FL	*- FL
12	1		*FRONT FENDER SHIELD LH	*Check	151.00 FL	*- FL
13	10		*FRONT FENDER SHIELD CLIPS	*Check	50.00 FL	*- FL
14	1		*HEADLAMP LH	Cut	1,903.00 FL	*1,903.00 FL
15	1		*HEADLAMP LOWER BRACKET LH	*Check	58.00 FL	*- FL
16	1		*FRONT WHEEL RIM LH	Serviceable	1,099.00 FL	*- FL
17	2		*ANTI-RUST COATING	Not Necessary	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,148.00	3,138.00
- List Item Discount on L Items 5.00/5.00% (S\$)	299.40	156.90
Total Parts (S\$)	5,848.60	2,981.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	900.00	250.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	900.00	250.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	20.00
4	PROVIDE SKILL LABOUR TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	0.00
5	RPVIDE SKILL LABOUR TO REMOVE AND REFIT /BALANCING WHEEL RIM AND TYRE	New	80.00	0.00
Gross Labour Cost (\$\$)			2,020.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >