

SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com Business Regn No: 269436/00J

12, July 2018

India Intl Ins PL 64 Cecil Street #04-05/#06-02 IOB Building S 049711

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle No: SHC3965K Accident involving vehicle No: SJH4518L/SHC3965K DOA: 10/07/2018 AT RWS casino B1 Drop-off point

Dear officer incharge Estimate cost of repair for vehicle no: SJH4518L

To repair/reshape Left portion-2 doors,2 fender ,side mirror To spray paint

\$ 350.00 3001 \$ 1,200.00 7001

\$ 1,550.00

=========

Not Nothank

LKK Auto Consultants hence notify

- the Repairer of the following: To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: