

ASS. REC. BY:

REF: CS/MSG18012924/Urd3ⁿ²

Special Instruction:

Survivor
menimen

Marcus

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSIG

Date/Time: 17/07/18 @ 9.28am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 7384D

Insured:

SLJ 8741Y

at Workshop m/s:

New Hock Teck

Tel:

6747 9241

of

1 Kelki Bldg Ave 6 # 01-43 Autobuy

Policy No:

29085033 QMX

Claim No:

564449

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9:37am @ 17/7/18

Person Contacted:

Jukyi

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKG 7384D - X

SLJ 8741Y - X

Sent preli thru menimen.

MS16/
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKG 7384Dat Workshop m/s NH7

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 46

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKG 7384D Yr Regn: 10/12Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda city c.c. 1497Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 90545 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRT/GM 2650 CP020020Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 185/55-215

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 10/7/18 D.O.I. 17/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 40162 4 yrs. 3 mth. Depsk. net 583823/7/18 L/S # 3400 confirmed with AM ChoiRef: 89728, 741.

RECEIVED 01 AUG 2018

Date/Time, File Pass to?

☐ : Preli. Report1) expul☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: 7PLump Sum / LBK (\$ 30)20010210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2018		17 Jul 2018 09:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SELWYN LIM CHIN KIAT, ID: S8932155G, Tel: +6597422432		
Main Claimant:	MATTHEW ER YEONG YANG, ID: S0187550G		
Vehicle Reg. No.:	SKG7384D	Date of Loss:	10/07/2018 20:00 - :59 [69 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 564449	Policy/Cover Note No.:	29085033QMX (Comprehensive) Coverage: 06/06/2018 - 05/06/2019
Vehicle Reg. No. (Insured):	SLJ8741Y	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/07/2018]		
Driver/Custodian (Insured):	LEE INYEONG (29 / Female), NRIC: G2623971R, Tel: +6581228814		
Adj Asg. Remarks:	SJE - AGREED Liability : 100% Please appoint LKK AUTO CONSULTANTS to conduct the survey .		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18012924/Urd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 17-07-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLJ 8741Y	Veh. Inspected	SKG 7384D
Policy No.	29085033QMX	Coverage (\$)	0.00
Claim No.	564449	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	17/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/07/2018	Inspection Date	17/07/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 19 Jul 2018

Preliminary Advice

Insured Vehicle No	: SLJ8741Y	Accident Date	: 10/07/2018
TP Vehicle No	: SKG7384D	Assignment Date	: 17/07/2018
Make	: HONDA CITY	Est. Duration of Repair	: 6.00
Date of Inspection	: 17/07/2018		
Inspection At	: NEW HOCK TECK MOTOR PTE LTD (HQ) 1 KAKI BUKIT AVE 6, BLK C #01-43 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,128.00
Revised Amount	:S\$	5,154.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,154.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MSME18089609 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 11/07/2018 17:20
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/07/2018 17:20
Date Of Accident	10/07/2018 20:30
Exact Location Of Accident	SLIP RD OF TAMPINES LINK TWDS TAMPINES AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG7384D
Insured/Policyholder	
Name Of Registered Owner	MATTHEW ER YEONG YANG
NRIC No	S0187550G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96266427
Alternative Phone No	OFFICE-96266427

Vehicle Particulars

Manufacturer	HONDA
Model	CITY

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5061283551-04
Cover Note Number	

Driver

Name of Driver	LEONG KWONG LIANG ANDY
NRIC No	S8917717J
Date Of Birth	30/05/1989
Occupation	INDOOR
Date Of Driving Pass	29/04/2011
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88623237
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 43 JALAN SETIA
 Postcode 368461
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - NEPHEW
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : ISIAH LEONG JUN XIANG
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY AT SLIP ROAD OF TAMPINES LINK TO CHECK MAIN ROAD ONCOMING TRAFFIC BEFORE DRIVING OUT. SUDDENLY, I FELT AN IMPACT. VEHICLE B COLLIDED ONTO REAR PORTION OF MY VEHICLE AND CAUSED DAMAGES. BOTH OF US ALIGHTED. VEHICLE B ADMITTED HER FAULT AND APOLOGISED TO ME. I WISH TO LODGE THE REPORT FOR CLAIM AGAINST VEHICLE B.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLJ8741Y
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/sre permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


11/7/18

GPMS's Sketch Plan Pg. 1

NEW FACE BOOK

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at slip road of Tampines Link to check main road oncoming traffic before drove out.

Suddenly, I felt an impact. vln "B" collided onto rear portion of my vehicle and caused damaged.

Both of us alighted. vln "B" admitted her fault and apologised with me.

I wish lodge the report for claim against vln "B".

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7550G

Vehicle Details

Vehicle No.: SKG7384D

Vehicle to be Exported: No

Intended De-registration Date: 11 Jul 2018

Vehicle Make: HONDA

Vehicle Model: CITY 1.5L I-VTEC AUTO

Primary Colour: Grey

Manufacturing Year: 2012

Engine No.: L15A76803214

Chassis No.: MRHGM2650CP020020

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$16,549.00

Original Registration Date: 01 Oct 2012

First Registration Date: 01 Oct 2012

Transfer Count: 0

Actual ARF Paid: \$16,549.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Sep 2022

PARF Rebate Amount: \$11,584.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$68,000.00

COE Rebate Amount: \$28,692.00

Total Rebate Amount: \$40,276.00

The information contained herein is correct as at 11 Jul 2018

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7550G

Vehicle Details

Vehicle No.: SKG7384D
Vehicle to be Exported: No
Intended De-registration Date: 17 Jul 2018
Vehicle Make: HONDA
Vehicle Model: CITY 1.5L I-VTEC AUTO
Primary Colour: Grey
Manufacturing Year: 2012
Engine No.: L15A76803214
Chassis No.: MRHGM2650CP020020
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$16,549.00
Original Registration Date: 01 Oct 2012
First Registration Date: 01 Oct 2012
Transfer Count: 0
Actual ARF Paid: \$16,549.00 *8274*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Sep 2022
PARF Rebate Amount: \$11,584.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$68,000.00
COE Rebate Amount: \$28,578.00
Total Rebate Amount: \$40,162.00

The information contained herein is correct as at 17 Jul 2018

OK

Get Paid \$557 Every Day Online - And Quit Your Job In 30 Days

Discover method that makes everyday people all over the world extremely wealthy.

storyknow.com



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68%P.A@Gv Cars Financing
GV Credit Pte Ltd StarAd

Free VICOM evaluation
Free grooming and 6 months maintenance
In-house workshop ensures quality service
Member of SVTA and hire purchase association
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

Honda City

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda City		Any	Any	2011	Any	Any	Any	Available
	Honda City	1.5A LX	\$32,833	\$9,730 /yr	06-Jan-2011	1,497 cc	137,000 km	Sedan	Available
Posted: 16-Jul-2018 Tags: 2011 Honda City, Honda City, Honda, City, Used Honda									
	Honda City	1.5A LX	\$35,800	\$10,720 /yr	21-Jan-2011	1,497 cc	130,000 km	Sedan	Available
Only 1 Ownership, Genuinely Low Mileage.Superb Condition, Very Reliable And Fuel Efficient Saloon Car.Viewing Can Be Done At Your Doorstep.So Hurry Come And View, Test Drive Now! Make An Appointment W...									
Posted: 01-Jun-2018 Tags: 2011 Honda City, Honda City, Honda, City, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda City, Honda City Singapore, used Honda City Singapore, used Honda City, used vehicles Singapore or even buy used Honda City Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for: Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

Compare



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

MATTHEW ER YEONG YANG

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Not Allowed
13/07/2018
2/5 \$3400/-
6h.
17/7/18

Accident date: 13/07/2018

Estimated repair cost for vehicle no: SKG7384D HONDA CITY 1.5 A '12

S/n	Qty	Items / List	U/price	Amount
1	1	Rear Boot Lid	408.70	\$563.90
2	2	Rear Boot Lid Hinge	\$48.10	\$96.20
3	1	Rear Boot Lid Emblem Logo		\$34.10
4	1	Rear Boot Lid City Logo		\$26.80
5	1	Rear Boot Lid I-Vtec Logo		\$32.40
6	1	Rear Boot Lid Number Plate		\$50.00
7	1	Rear Boot Lid Centre Moulding		\$174.40
8	1	Rear Boot Lid Camera		\$550.00
9	1	Rear Boot Lid Inner Lock		\$125.10
10	1	Rear Boot Lid Inner Rubber		\$94.40
11	1	Rear Boot Lid Inner Trim Board		\$129.40
12	8	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$52.00
13	2	Rear Tail Lamp	\$287.50	\$575.00
14	4	Rear Tail Lamp Clip	\$8.00	\$32.00
15	2	Rear Tail Lamp Panel	\$114.40	\$228.80
16	1	Rear Bumper	463.70	\$470.70
17	8	Rear Bumper Clip	\$6.50	\$52.00
18	2	Rear Bumper Bracket	\$25.80	\$51.60
19	2	Rear Bumper Side Retainer	\$24.80	\$49.60
20	1	Rear Bumper Lower Spoiler		\$161.60
21	1	Rear Bumper Lower Spoiler Side Reflector	\$24.20	\$24.20
23	1	Rear Bumper Reverse Sensor		\$380.00
24	1	Rear End Panel	323.90	\$399.30
25	1	Rear End Panel Top Garnish	\$66.60	\$96.60
27	1	Rear L/H Fender		\$866.40
28	2	Rear Fender Inner Trim Board	\$197.30	\$394.60
29	1	Rear Spare Tyre Panel		\$554.00
30	1	Rear Spare Tyre Panel Top Cover	70.80	\$90.80

31	1	Rear Spare Tyre Panel & End Panel Sealant	rec 50	\$450.00	505.00
32	1	Rear Exhaust	X 11	\$457.80	X
33	1	Rear Exhaust Chrome Pipe	X 11	\$119.00	X
34	1	Rear Centre Exhaust	X 11	\$473.40	X
35	1	Rear Windscreen Moulding	X 11	\$131.90	X

Subtotal :- \$7,988.00

Labour charges

To remove & refit cushion	60	\$280.00
To remove & refit roof lining		\$380.00
To remove & refit reverse sensor	50	\$100.00
To remove & refit rear camera		\$180.00
To remove & refit rear & centre exhaust	11X	\$380.00
To remove & refit rear windscreen	11X	\$120.00
Gum	11X	\$50.00
To check wiring	30	\$100.00
Tuff kote	60	\$150.00
Panel beating	1200	\$1,800.00
Spray painting	1000	\$1,600.00

Subtotal :- \$5,140.00

Total:- \$13,128.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

P-1961.60
202
1569.28
S.N-290
Labour-2400
425-9.28
3407

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012924/URD3N2

Date: 03/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29085033QMX
Claimant Vehicle No :	SKG7384D	Insured Vehicle No :	SLJ8741Y
Date of Loss:	10/07/2018	Nature of Claim:	TP
		Claim No:	564449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG7384D	Engine No:	L15A76803214
Make & Model:	HONDA CITY, 1.5 L I-VTEC (A)	Chassis No:	MRHGM2650CP020020
Reg. Date:	01/10/2012 (Man. Year: 2012)	Odometer:	90545 km
Colour:	Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,038.00	1,859.28	6,178.72	76.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,090.00	2,400.00	2,690.00	52.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,128.00	4,259.28	8,868.72	67.56
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	13,128.00	3,400.00	9,728.00	74.10
+ GST 7.00/7.00% (S\$)	918.96	238.00	680.96	74.10
Nett Amount (S\$)	14,046.96	3,638.00	10,408.96	74.10

INSPECTION

Date of Assignment:	17/07/2018	
Date Inspected:	17/07/2018 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2018)	
Parts: 143	HONDA CITY 1.5 L I-VTEC (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SKG7384D)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented/Bent	563.90 F	*408.70 FL
2	2		*REAR BOOT LID HINGE	Repair	96.20 F	*- FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	34.10 F	*34.10 FL
4	1		*REAR BOOT LID CITY LOGO	Necessary	26.80 F	*26.80 FL
5	1		*REAR BOOT LID I-VTEC LOGO	Necessary	32.40 F	*32.40 FL
6	1		*REAR BOOT LID CENTRE MOULDING	Not Necessary	174.40 F	*- FL
7	1		*REAR BOOT LID CAMERA	Not Necessary	550.00 F	*- FL
8	1		*REAR BOOT LID INNER LOCK	Twisted	125.10 F	*43.10 FL
9	1		*REAR BOOT LID INNER RUBBER	Twisted	94.40 F	*74.40 FL
10	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	129.40 F	*- FL
11	8		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
12	1		*REAR TAIL LAMP	N/s Cracked	575.00 F	*174.70 FL
13	4		*REAR TAIL LAMP CLIP	Not Necessary	32.00 F	*- FL
14	2		*REAR TAIL LAMP PANEL	Repair	228.80 F	*- FL
15	1		*REAR BUMPER	Dented/Deformed	470.70 F	*463.70 FL
16	8		*REAR BUMPER CLIP	Necessary	52.00 F	*31.20 FL
17	2		*REAR BUMPER BRACKET	Not Necessary	51.60 F	*- FL
18	2		*REAR BUMPER SIDE RETAINER	Bent	49.60 F	*49.60 FL
19	1		*REAR BUMPER LOWER SPOILER	Deformed/Torn	161.60 F	*161.60 FL
20	1		*REAR BUMPER LOWER SPOILER SIDE REFLECTOR	Not Necessary	24.20 F	*- FL
21	1		*REAR END PANEL	Dented	399.30 F	*323.90 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	96.60 F	*66.60 FL
23	1		*REAR L/H FENDER	Repair	866.40 F	*- FL
24	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	394.60 F	*- FL
25	1		*REAR SPARE TYRE PANEL	Repair	554.00 F	*- FL
26	1		*REAR SPARE TYRE PANEL TOP COVER	Torn	90.80 F	*70.80 FL
27	1		*REAR EXHAUST	Not Necessary	457.80 F	*- FL
28	1		*REAR EXHAUST CHROME PIPR	Not Necessary	119.00 F	*- FL
29	1		*REAR CENTRE EXHAUST	Not Necessary	473.40 F	*- FL
30	1		*REAR WINDSCREEN MOULDING	Not Necessary	131.90 F	*- FL
31	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 FS	*40.00 FS
32	1		*REAR BUMPER REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	450.00 FS	*50.00 FS
34	1		*GUM	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,038.00	2,251.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	392.32
Total Parts (\$\$)	8,038.00	1,859.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION }	New	280.00	60.00
2	TO REMOVE & REFIT ROOF LINING }	New	380.00	-
3	TO REMOVE & REFIT REAR CAMERA }	New	180.00	50.00
4	TO REMOVE & REFIT REVERSE SENSOR }	New	100.00	-
5	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	-
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	-
7	TO CHECK WIRING	New	100.00	30.00
8	TUFF KOTE	New	150.00	60.00
9	PANEL BEATING	New	1,800.00	1,200.00
10	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			5,090.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >