

ASS. REC. BY:

REF

CS/MSG18012930/Uqd3/YK

Special Instruction

SURVEYOR

Meinman

Marcus

Irene Tan

ASSIGNMENT (Office)

MSG

Date/Time: 17/7/18 @ 9:27am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 4462 G

Insured:

SLL 7202 H

at Workshop n/s:

Yi Heng Motor

Tel:

6509 0052

of

Blk 1, Kaki Bukit Ave 6 #02-19

Policy No:

80454228QMY

Claim No:

564392

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:03am 17/7/18

Person Contacted:

Wan ping

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 4462 G - X
	SLL 7202 H - X
15/7/18 @ 4:52pm	revised to Irene Tan via Meinman.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18012930/Uqd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 17-07-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 7202H	Veh. Inspected	SKZ 4462G
Policy No.	80454228QMY	Coverage (\$)	0.00
Claim No.	564392	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	17/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/07/2018	Inspection Date	17/07/2018
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2018		17 Jul 2018 09:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AHMAD SANHAJIE BIN MOHAMED OSMAN , ID: S7105006H, Tel: +6597377843, Email: AHMADSG2519@GMAIL.COM								
Main Claimant:	TAN MINGYI EUNICE , ID: S8340743C								
Vehicle Reg. No.:	SKZ4462G	Date of Loss:	13/07/2018 08:00 - :59 [29 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 564392	Policy/Cover Note No.:	80454228QMY (Comprehensive) Coverage: 08/03/2018 - 07/03/2019						
Vehicle Reg. No. (Insured):	SLL7202H	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Yi Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/07/2018]								
Driver/Custodian (Insured):	AHMAD SANHAJIE BIN MOHAMED OSMAN (/ Male), NRIC: S7105006H, Tel: +6597377843								
Adj Asg. Remarks:	SJE : AGREED Liability : 100% Please appoint ADRAIN LING from LKK AUTO to conduct the survey . Kindly contact JASON/ WAN PING @ 6509 0052								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 18 Jul 2018

Preliminary Advice

Insured Vehicle No	: SLL7202H	Accident Date	: 13/07/2018
TP Vehicle No	: SKZ4462G	Assignment Date	: 17/07/2018
Make	: HONDA VEZEL	Est. Duration of Repair	: 5.00
Date of Inspection	: 17/07/2018		
Inspection At	: YI HENG MOTOR WORKSHOP (HQ) BLK 1 KAKI BT AVE 6 #02-19 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,601.52
Revised Amount	:S\$	5,090.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,090.96

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0743C
Vehicle Details	
Vehicle No.:	SKZ4462G
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4028279
Chassis No.:	RU11108279
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,571.00
Original Registration Date:	22 Jan 2016
First Registration Date:	22 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$9,571.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2026
PARF Rebate Amount:	\$7,178.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$33,848.00
Total Rebate Amount:	\$41,026.00

The information contained herein is correct as at 13 Jul 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0743C
Vehicle Details	
Vehicle No.:	SKZ4462G
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4028279
Chassis No.:	RU11108279
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,571.00
Original Registration Date:	22 Jan 2016
First Registration Date:	22 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$9,571.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2026
PARF Rebate Amount:	\$7,178.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$33,799.00
Total Rebate Amount:	\$40,977.00

The information contained herein is correct as at 17 Jul 2018

OK

Honda Vezel 1.5A S

Price	\$71,800
Reg date	25-Jan-2016
Manufactured	2015
Mileage	50,050 km
Transmission	Auto
Engine Capacity	1,496 cc
Road Tax	\$682 per year
Power	96.0 kW (128 bhp)
Curb Weight	1,210 kg
Features	1.5L I-VTEC Engine, 1288HP, CVT Automatic With Paddle Shifters, ABS, Airbags, Keyless Entry/Start/Stop, Auto Brake Hold, Cruise Control, CTBA.
Accessories	Leather Seats, Sports Rims, SONY DVD Player With Steering Controls/GPS, Reverse Sensors And Camera, Retractable Side Mirrors, Solar Film, Fog Lights.
Description	Confirm Cheapest "S" Model Vezel 1.5A. Super Low Mileage Done 50050km. Totally Like Brand New, See To Believe. 1 Owner. New Pearl White Paintwork, Road Tax Till Jan 19. 100% Accident Free. Call Now!
COE	\$45,002
OMV	\$20,340
ARF	\$15,476
Depreciation	\$8,510 / year
No. of owners	1
Type of Vehicle	SUV
Availability	Available

Seller Information

Company	Lake View Credit Pte Ltd	
	» dealer's pricelist	
	» 148 vehs sold 56 vehs available	
Address	61 Ubi Avenue 2 #03-08/09	
Location	Automobile Megamart View all Honda at this location	
Website	www.lakeviewcredit.com.sg	
Office No	67499895	
Contact Person(s)	Daniel	96896097
	Kelvin	98789995
	Cindy	97955756

PREMIUM AD



Posted on : 07-Jul-2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/07/2018 15:07
Date Of Accident	13/07/2018 08:20
Exact Location Of Accident	BRICKLAND RD (TWDS SUNGEI TENGAH)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ4462G
Insured/Policyholder	
Name Of Registered Owner	TAN MINGYI EUNICE
NRIC No	S8340743C
Email Address	NO EMAIL
Mobile Phone No	(LOCAL) +65-92374322
Alternative Phone No	OFFICE-92374322

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5077244284-02
Cover Note Number	

Driver

Name of Driver	TAN MINGYI EUNICE
NRIC No	S8340743C
Date Of Birth	20/12/1983
Occupation	INDOOR
Date Of Driving Pass	15/02/2005
Driving Experience	13 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92374322
Fax Number	
Contact Number	OFFICE-92374322
Email Address	NOEMAIL

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 13/07/19
2-15pm

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

YI HEN

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

13-07-18

OUR REF NO. : SKZ 4462G

TAN MINGYI, EUNICE

BLK 318C, YISHUN

AVE 9, #14-154

SINGAPORE 763318

ESTIMATE BILL FOR VEHICLE NO. SKZ 4462G

MODEL : HONDA VEZEL 1.5X

LIST ITEM

1) REAR WINDSCREEN MOULDING	rec ✓	66.50	284.30	✓
2) BOOT LID	DO/Ref ✓	95.3	1420.60	✓
3) BOOT LID WEATHERSTRIPE	twi ✓	135.70	235.60	✓
4) BOOT LID EMBLEM 'VEZEL'	rec ✓	18.20	68.00	✓
5) BOOT LID STOPPER	11 X	2 PCS @ \$ 15.20	30.40	X
6) BOOT LID LOCK	Ref ✓	198.50	398.50	✓
7) BOOT LID BADGE	11 X		62.00	X
8) REAR BUMPER	DD	762.70	893.60	✓
9) REAR BUMPER CLIP	rec ✓	8 PCS @ \$ 3.70	29.60	✓
10) REAR BUMPER SIDE ATTACHMENT	11 X	2 PCS @ \$ 62.50	125.00	X
11) REAR BUMPER REFLECTOR	11 X	2 PCS @ \$ 184.50	369.00	X
12) REAR END PANEL	DD	514.00	589.60	✓
13) REAR PANEL INNER GARNISH	twi	184.00	214.50	✓
14) SPARE TYRE PANEL	12 X		1130.60	X
15) SPARE TYRE BOARD	11 X		423.00	X
16) SPARE TYRE SPONGE	11 X		287.10	X
17) REAR EXHAUST SILENCER	11 X		587.00	X
18) REAR EXHAUST MOUNTING	11 X	2 PCS @ \$ 47.00	94.00	X
19) REAR ANTI ANTENNA SENSOR	2 ✓	181.40	247.00	✓
LESS DISCOUNT - 20%			7489.40	
			1497.88	
			5991.52	

not Advised
2 hrs
1/5 #3500/-
5 day. *[Signature]*
18/7/18

P-3082.60
202
2466.08
1960
4426.08
3520

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

SPECIAL NETT ITEM

1) REAR WINDSCREEN INNERSEAL	RM 30	60.00	
2) REAR WINDSCREEN GUM	RM 40	60.00	
3) REVERSE SENSOR WITH CONTROL UNIT	RM 200	350.00	
			470.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	20	50.00	
2) TO APPLY UNDERSEALING ON EFFECTED AREAS	60	120.00	
3) TO MOUNT VEHICLE ON CAR O LINER	11X	380.00	
4) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	50	120.00	
5) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	60	240.00	
6) TO REMOVE AND REFIX REAR EXHAUST SILENCER	11X	150.00	
7) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY ETC	20	220.00	
8) TO REMOVE AND REFIX REAR WINDSCREEN	120	220.00	
9) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC	600	1540.00	
10) TO RESPRAY ON THE AFFECTED AREAS	700	1100.00	
			4140.00
		GRAND TOTAL	<u>10601.52</u>

1860

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jul 2018		17 Jul 2018 09:27 Edit Adj Rpt	\$3,500.00 Edit Estimates	\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	AHMAD SANHAJIE BIN MOHAMED OSMAN , ID: S7105006H, Tel: +6597377843, Email: AHMADSG2519@GMAIL.COM								
Main Claimant:	TAN MINGYI EUNICE , ID: S8340743C								
Vehicle Reg. No.:	SKZ4462G	Date of Loss:	13/07/2018 08:00 - :59 [29 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 564392	Policy/Cover Note No.:	80454228QMY (Comprehensive) Coverage: 08/03/2018 - 07/03/2019						
Vehicle Reg. No. (Insured):	SLL7202H	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Yi Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/08/2018]								
Driver/Custodian (Insured):	AHMAD SANHAJIE BIN MOHAMED OSMAN (/ Male), NRIC: S7105006H, Tel: +6597377843								
Adj Asg. Remarks:	SJE : AGREED Liability : 100% Please appoint ADRAIN LING from LKK AUTO to conduct the survey . Kindly contact JASON/ WAN PING @ 6509 0052								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKZ4462G (564392)**

[SLL7202H]

TP

TAN MINGYI EUNICE

Jul 13 2018 8:00AM

[AHMAD SANHAJIE BIN MOHAMED OSMAN]

Yi Heng Motor Workshop

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	16/07/18 13:32	Accident Statement From: SC - Reg. No: SLL7202H, Claimant: AHMAD SANHAJIE BIN MOHAMED OSMAN					Load HTM	☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	18/07/18 16:52	Adjuster Immediate Advice					Load HTM	☒	
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	17/07/18 18:42	Chassis Number					Load JPG	☒	
2	17/07/18 18:43	Odometer Reading					Load JPG	☒	
3	17/07/18 18:44	General View					Load JPG	☒	
4	17/07/18 18:44	General View					Load JPG	☒	
5	17/07/18 18:44	General View					Load JPG	☒	
6	17/07/18 18:44	General View					Load JPG	☒	
7	17/07/18 18:44	General View					Load JPG	☒	
8	17/07/18 18:44	General View					Load JPG	☒	
9	17/07/18 18:44	General View					Load JPG	☒	
10	17/07/18 18:44	General View					Load JPG	☒	
11	17/07/18 18:44	General View					Load JPG	☒	
12	17/07/18 18:44	General View					Load JPG	☒	
13	17/07/18 18:44	General View					Load JPG	☒	
14	17/07/18 18:44	General View					Load JPG	☒	
15	17/07/18 18:44	General View					Load JPG	☒	
16	17/07/18 18:44	General View					Load JPG	☒	
17	17/07/18 18:44	General View					Load JPG	☒	
18	17/07/18 18:44	General View					Load JPG	☒	
19	17/07/18 18:44	General View					Load JPG	☒	
20	17/07/18 18:44	General View					Load JPG	☒	
21	17/07/18 18:44	General View					Load JPG	☒	
22	17/07/18 18:44	General View					Load JPG	☒	
23	17/07/18 18:44	General View					Load JPG	☒	
24	17/07/18 18:44	General View					Load JPG	☒	
25	17/07/18 18:44	General View					Load JPG	☒	
26	17/07/18 18:44	General View					Load JPG	☒	
27	17/07/18 18:44	General View					Load JPG	☒	
28	17/07/18 18:44	General View					Load JPG	☒	
29	17/07/18 18:44	General View					Load JPG	☒	
30	17/07/18 18:44	General View					Load JPG	☒	
31	17/07/18 18:44	General View					Load JPG	☒	
32	17/07/18 18:44	General View					Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	17/07/18 18:44	General View	 Load JPG	☒
34	17/07/18 18:44	General View	 Load JPG	☒
35	17/07/18 18:44	General View	 Load JPG	☒
36	17/07/18 18:44	General View	 Load JPG	☒
37	17/07/18 18:44	General View	 Load JPG	☒
38	17/07/18 18:44	General View	 Load JPG	☒
39	17/07/18 18:44	General View	 Load JPG	☒
40	17/07/18 18:44	General View	 Load JPG	☒
41	17/07/18 18:44	General View	 Load JPG	☒
42	17/07/18 18:44	General View	 Load JPG	☒
43	17/07/18 18:44	General View	 Load JPG	☒
44	17/07/18 18:44	General View	 Load JPG	☒
45	17/07/18 18:44	General View	 Load JPG	☒
46	17/07/18 18:44	General View	 Load JPG	☒
47	17/07/18 18:44	General View	 Load JPG	☒
48	17/07/18 18:44	General View	 Load JPG	☒
49	17/07/18 18:44	General View	 Load JPG	☒
50	17/07/18 18:44	General View	 Load JPG	☒
51	17/07/18 18:44	General View	 Load JPG	☒
52	17/07/18 18:44	General View	 Load JPG	☒
53	17/07/18 18:44	General View	 Load JPG	☒
54	17/07/18 18:44	General View	 Load JPG	☒
55	17/07/18 18:44	General View	 Load JPG	☒
56	17/07/18 18:44	General View	 Load JPG	☒
57	17/07/18 18:44	General View	 Load JPG	☒
58	17/07/18 18:44	General View	 Load JPG	☒
59	17/07/18 18:44	General View	 Load JPG	☒
60	17/07/18 18:44	General View	 Load JPG	☒
61	17/07/18 18:44	General View	 Load JPG	☒
62	17/07/18 18:44	General View	 Load JPG	☒
63	17/07/18 18:44	General View	 Load JPG	☒
64	17/07/18 18:44	General View	 Load JPG	☒
65	17/07/18 18:44	General View	 Load JPG	☒
66	17/07/18 18:44	General View	 Load JPG	☒
67	17/07/18 18:44	General View	 Load JPG	☒
68	17/07/18 18:44	General View	 Load JPG	☒
69	17/07/18 18:44	General View	 Load JPG	☒
70	17/07/18 18:44	General View	 Load JPG	☒
71	17/07/18 18:44	General View	 Load JPG	☒
72	17/07/18 18:44	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/07/18 13:32	TPD SKZ4462G GIA REPORT From: SC - Reg. No: SLL7202H, Claimant: AHMAD SANHAJIE BIN MOHAMED OSMAN	 Load PDF	
2	16/07/18 13:33	Email to TP Lawyer MACRUS PHUAH & CO. with 10 survey name - SLL7202H	 Load PDF	
3	16/07/18 16:41	TPD SH7038D - PRI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012930/UQD3Q2

Date: 26/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80454228QMY

Claimant Vehicle No: SKZ4462G

Insured Vehicle No: SLL7202H

Date of Loss: 13/07/2018

Nature of Claim: TP

Claim No: 564392

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ4462G

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: L15B4028279

Reg. Date: 22/01/2016 (Man. Year: 2015)

Chassis No: RU11108279

Colour: Blue

Odometer: 68296 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,461.52	2,736.08	3,725.44	57.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,140.00	1,690.00	2,450.00	59.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,601.52	4,426.08	6,175.44	58.25
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	10,601.52	3,500.00	7,101.52	66.99

INSPECTION

Date of Assignment: 17/07/2018

Date Inspected: 17/07/2018 Inspected At:

Yi Heng Motor Workshop (HQ)
Blk 1 Kaki Bt Ave 6 #02-19
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKZ4462G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	284.30 FL	*66.50 FL
2	1		*BOOT LID	Dented / Bent	1,420.60 FL	*953.00 FL
3	1		*BOOT LID WEATHERSTRIP	Twisted	235.60 FL	*135.70 FL
4	1		*BOOT LID EMBLEM VEZEL	Necessary	68.00 FL	*56.20 FL
5	2		*BOOT LID STOPPER	Not Necessary	30.40 FL	*- FL
6	1		*BOOT LID LOCK	Bent	398.50 FL	*198.50 FL
7	1		*BOOT LID BADGE	Not Necessary	62.00 FL	*- FL
8	1		*REAR BUMPER	Dented	893.60 FL	*762.70 FL
9	8		*REAR BUMPER CLIP	Necessary	29.60 FL	*29.60 FL
10	2		*REAR BUMPER SIDE ATTACHMENT	Not Necessary	125.00 FL	*- FL
11	2		*REAR BUMPER REFLECTOR	Not Necessary	369.00 FL	*- FL
12	1		*REAR END PANEL	Dented	589.60 FL	*514.00 FL
13	1		*REAR PANEL INNER GARNISH	Twisted	214.50 FL	*184.00 FL
14	1		*SPARE TYRE PANEL	Repair	1,130.60 FL	*- FL
15	1		*SPARE TYRE BOARD	Not Necessary	423.00 FL	*- FL
16	1		*SPARE TYRE SPONGE	Not Necessary	287.10 FL	*- FL
17	1		*REAR EXHAUST SILENCER	Not Necessary	587.00 FL	*- FL
18	2		*REAR EXHAUST MOUNTING	Not Necessary	94.00 FL	*- FL
19	1		*REAR ANTI ANTENNA SENSOR	Cracked	247.00 FL	*182.40 FL
20	1		*REAR WINDSCREEN INNERSEAL	Necessary	60.00 FS	*30.00 FS
21	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS
22	1		*REVERSE SENSOR WITH CONTROL UNIT	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,959.40	3,352.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,497.88	616.52
Total Parts (\$\$)	6,461.52	2,736.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	50.00	20.00
2	TO APPLY UNDERSEALING ON EFFECTED AREAS	New	120.00	60.00
3	TO MOUNT VEHICLE ON CAR O LINER	New	380.00	0.00
4	TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	New	120.00	50.00
5	TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	New	240.00	60.00
6	TO REMOVE AND REFIX REAR EXHAUST SILENCER	New	150.00	0.00
7	TO REMOVE AND REFIX CUSHION ,FLOOR BOARD ,ROOF LINING ,TRIM ,GARNISH ,UPHOLSTERY ETC	New	220.00	80.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	220.00	120.00
9	TO REPLACE NEW PARTS ,CUT ,WELD ,KNOCK ETC	New	1,540.00	600.00
10	TO RESPRAY ON THE AFFECTED AREAS	New	1,100.00	700.00
Gross Labour Cost (\$\$)			4,140.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >