

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 16/7/2018
VEHICLE NO: SGQ2111C
MODEL: LANCER
YEAR: 2008 - 2022
ACCIDENT DATE: 14/7/2018
TYPE OF CLAIM: TP CLAIM
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
REAR BUMPER	1	\$ 719.30 <i>dk</i>
REAR BUMPER CLIPS	10	\$ 30.00 <i>re</i>
REAR BUMPER RETAINER	<i>12</i>	\$ 94.80 <i>RH-wid, RH x 9</i>
LH TAILLAMP	1	\$ 564.20 <i>out</i>
LH REAR FENDER	1	RESTORE

TOTAL: \$ 1,408.30
DISCOUNT 10%: \$ 140.83
\$ 1,267.47

S/NET	PRICE
REVERSE SENSOR	\$ 250.00 <i>OK</i>
	<u>\$ 250.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR - REAR	\$ 800.00 300
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$ 300.00 200
TO RESPRAY AFFECTED AREAS - LH REAR FENDER	\$ 300.00 200
RUST PROOFING	\$ 80.00 300
SUNDARIES	\$ 50.00 20
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$ 250.00 X
TO REMOVE AND REFIT REVERSE SENSOR	\$ 100.00 30
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$ 50.00 30
TOTAL:	\$ 1,930.00

TOTAL: \$ 3,447.47
7% GST: \$ 241.32
\$ 3,688.79

Tanpin 97495749
'WP'
20/7/18 @ 1545
Resing after repair.
03 days
Surv @ 11/11/18.com.