

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

# **Immediate Advice**

To: AXA Insurance Pte Ltd

Date: 18/11/2018

### **Survey Details:**

Date of loss	13-Jul-18
Date of appointment	17-Jul-18
Date of survey	18-Jul-18
Location of survey	1ST AUTOWORKS PTE LTD

# Vehicle Details:

Claim Type:	Third party
Vehicle number	SLD 1629S
Make and Model	OPEL MERIVA 1.4T ENJOY A/T
Date of registration	6/6/2016
Excess	_
Market Value	\$78,000
Parf Rebate	\$50,046
Nett Loss	\$27,954

### Repair details:

Initial Estimate	\$	27,604.40
micial Escillace	7	27,004.40

# Proposed/Revised repair cost:

Parts	\$ 10,471.00
Check items (estimate)	NIL
Labour	\$ 4,315.00
Total	\$ 14,786.00
Lump Sum(if applicable)	\$

Number of days for repair	5	
---------------------------	---	--



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

# Remarks:

# Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 15,821.02	
Loss of use	NIL	
Loss of rental (w/GST)	\$ 749.00	(7days x \$100.00)
Loss of income	NIL	
LTA search fees	NIL	
Others	NIL	
Proposed Total	\$ 16,570.02	

Menu



# Service Request Details

Claim

S8M000M0

Reference

CC4/ASM18012963/pb3 8

Loss Date

13 July 2018

Request Date

21 August 2018

Due Date

17 July 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

ctions	
ext Step	
inish the work	
Complete Work	More *

### Vehicle Information

Incident Vehicle Registration #

SLD1629S

Make

TPVD OPEL

Model

MERIVA-1.4 TURBO (A)

Service Address

111

### Primary Contact/Insured

KOLANTHAVEL ARUN KUMAR S/O 30 WOODLANDS CRESCENT, #15-15, 738086, Singapore 97493831

### Claim Handler

CHAN Kian Chuan 6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics .	Notes	
New Message							
TYPE				0			
SENT		19/	11/18 11:37 AM				
FROM		CHA	AN Kian Chuan				
SUBJECT				S8M00OM0 [AC 9S(TP) / OTHERS			
BODY		TPI	EXCESS @ \$500.0	00			
		4					
TYPE				0			
SENT		19/	11/18 11:36 AM				
FROM		CHA	AN Kian Chuan				

Re:<MANDATE IA> - S8M000M0 [ACCIDENT INVOLVING SKM SUBJECT 3574S(OI) / SLD 1629S(TP) / OTHERS ON 13/07/2018] BODY PLS PROCEED FOR DS AS FOLLOWS: COR \$13,307.40 W/... TYPE 0 SENT 18/11/18 12:05 PM FROM LKK AUTO CONSULTANTS PTE LTD (TP) SUBJECT <MANDATE IA> - S8M00OM0 [ACCIDENT INVOLVING SKM 3574S(OI) / SLD 1629S(TP) / OTHERS ON 13/07/2018] BODY Liability: 100%(BOLA 28). 3 vehicles chain collisi... TYPE 0 SENT 10/8/18 3:58 PM FROM LKK AUTO CONSULTANTS PTE LTD (TP) SUBJECT **RE: Instruction** Hi Ernest, as spoken earlier. This is a 3 vehicle ... BODY TYPE 0 SENT 8/8/18 3:40 PM FROM TAY Ernest SUBJECT Instruction BODY No policy issue; please proceed DS. TP rear end OI...

TYPE

0

SENT

7/8/18 2:40 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

**SUBJECT** 

\*URGENT\* <Request for DS> S8M00OM0 [ACCIDENT INVOLVING SKM 3574S(OI) / SLD 1629S(TP)/ OTHERS ON

13/07/2018]

BODY

Hi, we refer to the above matter. We have uploaded...



Menu



# RE: Re: < MANDATE IA> - S8M000M0 [ACCIDENT INVOLVING SKM 3574S(OI) / SLD 1629S(TP) / OTHERS ON 13/07/2018]

Type

Question

#### Message

Hi, Third party rejected our offer at \$14,056.40(all-in) and proposed \$16,035.02(all-in). The breakdown of third party propose is as follows: - 1)Cost of Repair (w/GST):\$ 15,286.02 + 2.)Loss of Rental(w/GST) (7days x \$100.00): \$749.00 = TOTAL: \$ 16,305.02. For your further mandate / instruction please. Hsiao Tong - 30 Nov 2018

Reply

Menu



# Re:RE: Re:<MANDATE IA> - S8M00OM0 [ACCIDENT INVOLVING SKM 3574S(OI) / SLD 1629S(TP) / OTHERS ON 13/07/2018]

Type

Question

Message

REVISED OFFER @ \$15,000.00 ALL IN

Reply



# RE: Re:RE: Re:<MANDATE IA> - S8M00OM0 [ACCIDENT INVOLVING SKM 3574S(OI) / SLD 1629S(TP) / OTHERS ON 13/07/2018]

Type

Question

#### Message

Hi, Third party rejected our offer at \$15,000.00(all-in) and insisted for \$16,035.02(all-in). The breakdown of third party propose is as follows: - 1)Cost of Repair (w/GST):\$ 15,286.02 + 2.)Loss of Rental(w/GST) (7days x \$100.00): \$749.00 = TOTAL: \$ 16,035.02. For your further mandate / instruction please. Hsiao Tong - 08 Dec 2018

Reply

### Hsiao Tong (LKKAuto)

From:

Shu Pei (LKKAuto)

Sent:

Wednesday, 26 December 2018 5:22 PM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: New message for service request 58103, vehicle number SLD1629S

TYPE	SENT	FROM	SUBJECT	BODY	
0	12/26/18 9:14 AM	CHAN Kian	Re:RE: Re:RE: Re:RE: Re:	REVISED	
		Chuan	<mandate ia=""> -</mandate>	OFFER	
			S8M00OM0 (ACCIDENT	\$15,520.0	
			INVOLVING SKM	O (ALL IN)	
			3574S(OI) / SLD 1629S(TP)		
			/ OTHERS ON		
			13/07/2018]		

Best Regards, Shu Pei| Admin LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----From: Admin-D (LKKAuto)

Sent: Wednesday, 26 December 2018 9:18 AM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: New message for service request 58103, vehicle number SLD1629S

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue

1, #02-25 | S(408933)

----Original Message----

From: kianchuan.chan@axa.com.sg [mailto:kianchuan.chan@axa.com.sg]

Sent: Wednesday, 26 December 2018 9:15 AM

To: admin-d@lkkauto.com

Subject: New message for service request 58103, vehicle number SLD1629S

AXA Insurance has sent you a message for claim number S8M00OM0.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG. https://www.avg.com

### Hsiao Tong (LKKAuto)

From:

Ronnie Tan <ronnie.tan@firstautoworks.com.sg>

Sent:

Monday, 7 January 2019 4:01 PM

To:

Hsiao Tong (LKKAuto)

Cc:

Suhaimi

Subject:

re: SPAM-LOW: RE: Your ref: SLD 1629S \*Our Ref: CC4/ASM18012963/Upb3 [ACCIDENT INVOLVING SKM 3574S(AXA) /SLD 1629S/ OTHERS ON 13/07/2018]

Hi Hsiao Tong

Yes, We please to accept your offer at \$15,520.00(all-in).

Please kindly send us to DV

Accept offer without prejudice for any personal injury claim

Thank you

Regard

Ronnie

From: "Hsiao Tong (LKKAuto)" < <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a>>

Sent: Monday, 7 January, 2019 2:51 PM

To: "ronnie.tan@firstautoworks.com.sg" <ronnie.tan@firstautoworks.com.sg>

Cc: "Suhaimi" <<u>suhaimi@firstautoworks.com.sq</u>>

Subject: SPAM-LOW: RE: Your ref: SLD 1629S \*Our Ref: CC4/ASM18012963/Upb3 [ACCIDENT INVOLVING SKM

3574S(AXA) /SLD 1629S/ OTHERS ON 13/07/2018]

Without Prejudice (save as to costs)

Dear Ronnie,

We refer to your below email.

We have our principal instruction to revise our offer at a global sum of \$15,520.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ronnie Tan < ronnie.tan@firstautoworks.com.sg>

Sent: Monday, 3 December 2018 1:30 PM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com > Cc: Suhaimi < suhaimi@firstautoworks.com.sg >

Subject: RE: Your ref: SLD 1629S \*Our Ref: CC4/ASM18012963/Upb3 [ACCIDENT INVOLVING SKM 3574S(AXA) /SLD 1629S/ OTHERS ON 13/07/2018]

Hi Hsiao Tong,

We do not accept your principal offer of \$15,000 (all in). As stated before, we will give a good will of \$500 discount. Our counter offer still stands at

Cost of repairs: \$15286.02 Loss of Rental: \$749 Total: \$16035.02

From: "Hsiao Tong (LKKAuto)" < <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a>>

Sent: Monday, 3 December, 2018 12:26 PM

To: "ronnie.tan@firstautoworks.com.sg" <ronnie.tan@firstautoworks.com.sg>

Subject: RE: Your ref: SLD 1629S \*Our Ref: CC4/ASM18012963/Upb3 [ACCIDENT INVOLVING SKM 3574S(AXA)

/SLD 1629S/ OTHERS ON 13/07/2018]

Without Prejudice

Hi Ronnie,

We refer to your below email.

We have our principal instruction to improve our offer at a global sum of \$15,000,00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ronnie Tan < ronnie.tan@firstautoworks.com.sg>

Sent: Thursday, 29 November 2018 10:33 AM To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com >

Subject: re: Your ref: SLD 1629S \*Our Ref: CC4/ASM18012963/Upb3 [ACCIDENT INVOLVING SKM 3574S(AXA) /SLD

1629S/ OTHERS ON 13/07/2018]

Hi Hsiao Tong,

Out goodwill, we will give AXA a further discount of \$500 before GST off the total bill. Our counter offer are as follows:

Cost of repairs : \$15286.02 Loss of Rental : \$749 Total : \$16035.02

From: "Hsiao Tong (LKKAuto)" < <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a>>

Sent: Thursday, 29 November, 2018 8:32 AM

To: "ronnie.tan@firstautoworks.com.sg" <ronnie.tan@firstautoworks.com.sg>

Subject: Your ref: SLD 1629S \*Our Ref: CC4/ASM18012963/Upb3 [ACCIDENT INVOLVING SKM 3574S(AXA) /SLD

1629S/ OTHERS ON 13/07/2018]

Your ref: SLD 1629S

WITHOUT PREJUDICE

Our Ref: CC4/ASM18012963/Upb3

Dear Sir/Madam,

### ACCIDENT INVOLVING SKM 3574S(AXA) /SLD 1629S/ OTHERS ON 13/07/2018

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 13,307.40
2. Loss of Rental (7days x \$100.00) (w/GST)	\$ 749.00
TOTAL	\$ 14,056.40

Please confirm acceptance.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<sup>&</sup>quot;Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

# THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKM 3574S (Insd vel	h)	Model:	OPEL MERIVA (A)	
	SLD 1629S (TP veh)	1	1		
Date of Accident:	ate of Accident: 13/07/2018				
Global Sum Settlen	nent : [X] Yes		[ ] No ]		
Repair Estimate	1.11	: \$	29,536.71		
Final Repair Cost		: \$	15,821.02		
Loss of Use		: \$		days at \$0.00 per day	
Rental (if any)		: \$	749.00	7 days	
LTA / GIA Search F	ee	: \$			
Others:		: \$			
		: \$	1		
Final Settlement Su	ım (GLOBAL SUM)	: \$	15,520.00		
below)	kshop GIA Registered		Agreed Liability	X ] NO (Kindly indicate	
B) For GIA Regis				e: Yes/ No BOLA Scenario No:	
_	(%) ability to be filled only for	r chain		ty (*):0(%) ases where BOLA does not apply.	
Remarks					
s <sup>2</sup>					
Payment Instruction	on: Payee's Breakdow	'n			
1) 1ST AUTOWO	ORKS PTE LTD		: \$	15,520.00	
	ILAH BTE ABDOL WAHAB		25/01/2019		
	*		Date		

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		The state of the s	ationale Des Experts En Autor		
AXA INSURANCE PTE LTD  8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Ref : CC4/ASM18012963/Upb3s2		
			Date: 25-01-2019		
ATTN: KIAN CHUAN		Code: ASM			
1.		Policy Particula	ars :- THIRD PARTY CLA	IM	
	Insured Veh.	SKM 3574S	Veh. Inspected	SLD 1629S	
	Policy No.	GA085894/1	Coverage (\$)	0.00	
	Claim No.	S8M00OM0	Excess (\$)	0.00	
	Assign From	KIAN CHUAN	Assign Date	17/07/2018	
2.		Vehicle Pa	articulars & Condition		
	Make & Model	OPEL MERIVA (A)	c.c	1364	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	W0LSH9EM3G4038079	Colour	GREEN	
	Odometer	046733	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Con	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	205/55R16	BRIDGESTONE	8 mm	
	L/H Front Tyre	205/55R16	BRIDGESTONE	8 mm	
	R/H Rear Tyre	205/55R16	BRIDGESTONE	8 mm	
	L/H Rear Tyre	205/55R16	BRIDGESTONE	8 mm	
4.	Description of Damages				
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		Gen	eral Information		
	Accident Date	13/07/2018	Inspection Date	18/07/2018	
	Survey held at	1ST AUTOWORKS PTE LTE	)		
		23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933			
5a.			Remarks		
		ON WAS CONDUCTED ON A"			

Estimate Days of Repair

5 Working Days



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 1629S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER FASCIA UPPER (CONSISTENT)	DENTED / TORN	1,690.00	1,690.00
1	REAR BUMPER FASCIA LOWER, EXTENSION (CONSISTENT)	DENTED / TORN	1,350.00	1,350.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	850.00	850.00
1	REAR END PANEL TOP COVER (CONSISTENT)	NOT NECESSARY	220.00	ii.
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	560.00	19
1	SPARE TIRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,550.00	9
1	SPARE TIRE BOARD (CONSISTENT)	NOT NECESSARY	890.00	8
1	TAIL LID (CONSISTENT)	BADLY DENTED	2,450.00	2,450.00
1	TAIL LID W/STRIP (CONSISTENT)	NOT NECESSARY	320.00	
1	TAIL LID LOCK (CONSISTENT)	TWISTED / SHORTED	250.00	250.00
1	TAIL LID TRIM BOARD (CONSISTENT)	NOT NECESSARY	390.00	13
1	TAIL LID WIPER MOTOR (CONSISTENT)	NOT NECESSARY	1,381.00	
1	TAIL LID WIPER ARM (CONSISTENT)	NOT NECESSARY	121.00	3.5
1	TAIL LID ABSORBER (CONSISTENT)	NOT NECESSARY	330.00	
1	TAIL LID CHROME HANDLE (CONSISTENT)	CRACKED	950.00	950.00
1	LHR TAIL LID LAMP (CONSISTENT)	NOT NECESSARY	780.00	
1	RHR TAIL LID LAMP (CONSISTENT)	NOT NECESSARY	780.00	8
1	RR WINDSCREEN (CONSISTENT)	NOT NECESSARY	798.00	
1	RR WINDSCREEN MOUDLING (CONSISTENT)	NECESSARY	130.00	130.00
1	REAR EMBLEM (CONSISTENT)	NECESSARY	80.00	80.00
1	LETTERING "MERIVA" (CONSISTENT)	NECESSARY	70.00	70.00
1	LETTERING "TURBO" - CHROME (CONSISTENT)	NECESSARY	60.00	60.00
1	GUIDE, RR BPR FASCIA CTR (CONSISTENT)	NOT NECESSARY	90.00	9
1	GUIDE, RR BPR FASCIA OTR RH (CONSISTENT)	BENT	70.00	70.00
1	GUIDE, RR BPR FASCIA OTR LH (CONSISTENT)	BENT	70.00	70.00
1	LHR TAIL LAMP (CONSISTENT)	NOT NECESSARY	850.00	
	RHR TAIL LAMP (CONSISTENT)	NOT NECESSARY	850.00	
	SENSOR RR OBJECT WITH RING, SERVICE KIT (CONSISTENT)	SHORTED	450.00	450.00

Report Ref No. CC4/ASM18012963/Upb3s2



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRT AIG BAG SENSOR (CONSISTENT)	NOT NECESSARY	356.00	
1	AIR BAG CONTROL UNIT (CONSISTENT)	ACTIVATED	980.00	980.00
1	FRT DRIVER SEAT BELT RH (CONSISTENT)	NOT NECESSARY	880.00	
1	FRT DRIVER SEAT BELT PRETENSIONER RH, INNER (CONSISTENT)	ACTIVATED	1,020.00	1,020.00
1	FRT DRIVER SELT BELT LH (CONSISTENT)	NOT NECESSARY	880.00	-
1	FRT DRIVER SEAT BELT PRETENSIONER LH, INNER (CONSISTENT)	ACTIVATED	1,020.00	1,020.00
	LESS 10% DISCOUNT		-2,351.60	-1,149.00
			21,164.40	10,341.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	SCRATCHED	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	REAR TAILGATE INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	78.00	112
1	REAR END PANEL TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
1	SET REVERSE SENSOR (SN) (CONSISTENT)	REPEATED	250.00	
1	REAR END PANEL INSULATION SEAL (SN) (CONSISTENT)	NOT NECESSARY	60.00	107
			600.00	130.00
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND SPARE TIRE PANEL.		2,500.00	1,625.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		2,000.00	1,650.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		70.00	50.00
	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN.		120.00	120.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.		180.00	120.00
	REMOVE AND REFIX SEAT CUSHION / UPHOLSTERY TO FACILITATE REPAIR.		150.00	120.00

Report Ref No. CC4/ASM18012963/Upb3s2



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		150.00	90.00
	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.		160.00	90.00
	TO CONDUCT RESET & REPROGRAM SYSTEM OF AIR BAG & SEAT BELT LIGHT ON.		450.00	450.00
	TOWING SERVICE.	FOC	60.00	0.5
			5,840.00	4,315.00
	GRAND TOTAL		27,604.40	14,786.00

RECOMMENDED COST OF REPAIRS 14,786.00

Report Ref No. CC4/ASM18012963/Upb3s2

Chua Kang Seng

Licensed Appraiser