



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

23 July 2018

HHTPClaims18-72

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore 079120

Attn: Motor Claims Department

ACCIDENT INVOLVING SLZ 2410 H & SKP 3416 A ON 13/07/2018 ALONG BUONA VISTA RD AT ABOUT 0100 HOURS

Insured : HUA HONG PTE. LTD.
Vehicle Registration No : SLZ 2410 H
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No : ZYX102114262
Policy No : 5087272209-01
Date of Accident : 13/07/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 950.00 <i>ex</i>
2	2	Rear Bumper Retainer (LH/RH)	\$ 65.00	\$ 130.00 <i>x</i>
3	15	Rear Bumper Clip	\$ 3.00	\$ 45.00 <i>re</i>
4	1	Rear Bumper Lower Garnish		\$ 650.00 <i>at</i>
5	1	Rear Reinforcement		\$ 520.00 <i>?</i>
6	1	Rear Bumper Tow Cover		\$ 48.00 <i>x</i>
				\$ 2,343.00
Less 20%				\$ (468.60)
				\$ 1,874.40

To dismantle & change rear bumper, rear reinforcement, knocking & pull straight rear panel and all area affected by accident.

\$ 600.00 *250*

To perform wire checking.

\$ 20.00 *✓*

To spray rear bumper, rear reinforcement and rear panel. *photo*

\$ 600.00 *250*

\$ 3,094.40
\$ 216.61
\$ 3,311.01

7% GST
Total



Authorised by Claims Dept
Mrs Tan @ 9639 9195

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taifan 97495749
- WP'
27/7/18 @ 1145
3 days
Resurvey before paint
sure@lkkauto.com