



REPAIR ESTIMATE*

DATE : 18.07.2018

TEL : 6542 5119

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (LH/RH) <i>Destroyed</i>		\$ 619.00	\$ 1,238.00
	SUB TOTAL			\$ 1,238.00
	LESS 20%			\$ 247.60
	DISCOUNTED TOTAL			\$ 990.40
	<i>18/07/2018</i>  <i>Lirk Auto</i> 			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.