

(LKK AUTO CONSULTANTS)
PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 17/07/2018

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : KANG SOOL PENG
: AXA INSURANCE PTE LTD

Certificate No : GA052450

Accident Date : 13/07/2018

Vehicle No : SGX-5364-H

Make & Model : TOYOTA LEXUS IS250C AUTO STD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT FENDER RH	922.15	Est 922.15
1	FRONT FENDER INNER SHIELD RH	397.48	X nn
10	FRONT FENDER INNER SHIELD CLIP	25.00	X nn
1	FRONT BONNET HINGE RH	85.06	Ry
1	FRONT BONNET	RESTORE Ry	} X
1	CENTRE PILLAR RH	RESTORE Ry	
1	ROOF PANEL	RESTORE Ry	
1	FRONT DOOR RH	RESTORE Ry	
1	FRONT DOOR OUTER GARNISH RH	60.76	ant 60.76

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: