



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                |
|--------------------------------------------------------------------------------|
| <b>From :</b>                                                                  |
| PEGASUS ENGINEERING & TRADING PTE LTD<br>74 KIAN TECK ROAD<br>SINGAPORE 628800 |
| Officer in Charge : WEE TZE FAH<br>Tel :<br>Email :                            |

|                                                                                       |
|---------------------------------------------------------------------------------------|
| <b>Customer :</b>                                                                     |
| GRAB RENTALS 2 PTE LTD<br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960 |
| Attn :<br>Tel :<br>Fax No. :                                                          |

|                                      |                                 |                               |
|--------------------------------------|---------------------------------|-------------------------------|
| Quotation No. : QO18/06-1365         | Quotation Date : 20/06/2018     | Terms : 30 DAYS               |
| Vehicle No. : SLQ8115T               | Chassis No. : JM6BN22A8H0153198 | Third Party Insurer : AIG     |
| Model : MAZDA 3                      |                                 | Date of Accident : 20/06/2018 |
| Remarks : INSURED'S VEH NO: SBC3377D |                                 |                               |

| ITEM | DESCRIPTION                    | Qty  | UNIT PRICE | AMOUNT (SGD) |
|------|--------------------------------|------|------------|--------------|
| 1    | REAR BUMPER                    | 1    | 1,075.0000 | 1,075.00     |
| 2    | REAR BUMPER REINFORCEMENT      | 1    | 538.0000   | 538.00       |
| 3    | REAR BUMPER REFLECTOR          | 2    | 51.0000    | 102.00       |
| 4    | REAR BUMPER SIDE RETAINER      | 2    | 92.0000    | 184.00       |
| 5    | REAR BUMPER SIDE HOLDER        | 2    | 74.0000    | 148.00       |
| 6    | REAR BUMPER SIDE HOLDER RIVETS | 4    | 6.0000     | 24.00        |
| 7    | REAR BUMPER TOW COVER          | 1 pc | 17.0000    | 34.00        |
| 8    | REAR BUMPER CLIPS              | 10   | 5.0000     | 50.00        |
| 9    | REAR BUMPER SCREW SPACER       | 2    | 10.0000    | 20.00        |
| 10   | REAR BUMPER SPACER SCREW       | 2    | 15.0000    | 30.00        |
| 11   | BOOTLID                        | 1    | 958.0000   | 958.00       |
| 12   | BOOTLID WEATHERSTRIP           | 1    | 130.0000   | 130.00       |
| 13   | BOOTLID REFLECTOR              | 2    | 265.0000   | 530.00       |
| 14   | BOOTLID MAZDA 3 BADGE          | 1    | 130.0000   | 130.00       |
| 15   | BOOTLID SKYACTIV BADGE         | 1    | 64.0000    | 64.00        |
| 16   | BOOTLID LOCK TOP               | 1    | 153.0000   | 153.00       |
| 17   | BOOTLID LOCK STRIKER BOTTOM    | 1    | 35.0000    | 35.00        |
| 18   | BOOTLID HINGE                  | 2    | 148.0000   | 296.00       |
| 19   | BOOTLID HINGE COVER            | 2    | 34.0000    | 68.00        |
| 20   | BOOTLID HINGE COVER CLIPS      | 6    | 5.0000     | 30.00        |
| 21   | BOOTLID RUBBER STOPPER         | 2    | 16.0000    | 32.00        |
| 22   | BOOTLID INNER TRIM COVER       | 1    | 121.0000   | 121.00       |
| 23   | BOOTLID INNER TRIM COVER CLIPS | 6    | 5.0000     | 30.00        |

C/F 0.00



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                |
|--------------------------------------------------------------------------------|
| <b>From :</b>                                                                  |
| PEGASUS ENGINEERING & TRADING PTE LTD<br>74 KIAN TECK ROAD<br>SINGAPORE 628800 |
| Officer in Charge : WEE TZE FAH<br>Tel :<br>Email :                            |

|                                                                                       |
|---------------------------------------------------------------------------------------|
| <b>Customer :</b>                                                                     |
| GRAB RENTALS 2 PTE LTD<br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960 |
| Attn :<br>Tel :<br>Fax No. :                                                          |

|                                      |                                 |                               |
|--------------------------------------|---------------------------------|-------------------------------|
| Quotation No. : QO18/06-1365         | Quotation Date : 20/06/2018     | Terms : 30 DAYS               |
| Vehicle No. : SLQ8115T               | Chassis No. : JM6BN22A8H0153198 | Third Party Insurer : AIG     |
| Model : MAZDA 3                      |                                 | Date of Accident : 20/06/2018 |
| Remarks : INSURED'S VEH NO: SBC3377D |                                 |                               |

| ITEM | DESCRIPTION                                                                                                             | Qty | UNIT PRICE       | AMOUNT (SGD) |
|------|-------------------------------------------------------------------------------------------------------------------------|-----|------------------|--------------|
|      |                                                                                                                         |     | B/F              | 0.00         |
| 24   | BOOTLID CENTRE LOGO BADGE                                                                                               | 1   | 75.0000 X        | 75.00        |
| 25   | REAR END PANEL                                                                                                          | 1   | 506.0000 Repair  | 506.00       |
| 26   | REAR END PANEL INNER TRIM                                                                                               | 1   | 86.0000 X        | 86.00        |
| 27   | REAR END PANEL INNER TRIM CLIPS                                                                                         | 4   | 5.0000 ✓         | 20.00        |
| 28   | LESS 20% ITEM (1-27)                                                                                                    | 1   | -1,093.8000      | -1,093.80    |
| 29   | REAR BUMPER PARKING SENSOR                                                                                              | 1   | 450.0000 200?    | 450.00       |
| 30   | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                 | 1   | 80.0000 X        | 80.00        |
| 31   | TO RUST-PROOFING OF AFFECTED AREAS.                                                                                     | 1   | 220.0000 20      | 220.00       |
| 32   | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.                                  | 1   | 150.0000 60      | 150.00       |
| 33   | TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AND PERFORM WATER SEEPAGE TEST.                                            | 1   | 120.0000 X       | 120.00       |
| 34   | TO REINSTALL OF REAR BUMPER PARKING SENSOR.                                                                             | 1   | 120.0000 60      | 120.00       |
| 35   | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. | 1   | 980.0000 300 350 | 980.00       |
| 36   | PUTTY AND SPRAY PAINTINGS OF THE AFFECTED PORTION.                                                                      | 1   | 900.0000 400     | 900.00       |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Date:

Please conduct the survey at  
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

Sub Total 7,395.20  
GST(7.00%) 517.66  
Total (SGD) 7,912.86

Resue  
490010068  
3 days  
P/P  
17/07/18 @ 1510

Resue 1/4 paint