

United

"We are always in your journey"....

53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg

UEN No. 201729521C | GST Registered No: 2017259521C

TPA XA. JTFAT 35 Y40K 200810.
Xiao Tong.

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GBB5977P
MAKE MODEL : TOYOTA DYNA
REFERENCE : USG-201807-08
DOA : 14-Jul-18
CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT BUMPER distorted.	1	\$ 498.00	✓
FRONT BUMPER REINFORCEMENT Best.	1	\$ 382.00	✓
FRONT GRILLE 3M	1	\$ 414.00	+
FRONT GRILLE EMBLEM 3M	1	\$ 73.00	x
FRONT LH CORNER PANEL Dented	1	\$ 239.00	✓
FRONT LH HEADLAMP cruled	1	\$ 390.00	✓
AIRCON CONDENSER 3M	1	\$ 780.00	x
AIRCON LIQUID PIPE 3M	1	\$ 392.00	x.
FRONT LH DOOR PANEL Distorted	1	\$ 1,600.00	✓
FRONT LH DOOR STEP PANEL Repair	1	\$ 350.00	x
FRONT LH DOOR STEP GARNISH cruled	1	\$ 189.00	✓
FRONT LH DOOR HINGE Best	2	\$ 88.00	✓
FRONT LH DOOR LOCK Dented	1	\$ 410.00	284.
FRONT DOOR REGULATOR Dented	1	\$ 375.00	✓
FRONT LH DOOR REGULATOR MOTOR M-	1	\$ 410.00	x
FRONT LH DOOR RUBBER cut	1	\$ 195.00	✓
FRONT LH DOOR INNER TRIM M-	1	\$ 318.00	x.

4240

\$ 7,103.00

LESS 25% \$ 1,775.75

380

SUBTOTAL \$ 5,327.25

BALANCE C/F \$ 5,327.25

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 5,327.25	
FRONT GRILLE CLIP M-	1 SET	\$ 40.00	x.
FRONT BUMPER CLIP not M-	1 SET	\$ 30.00	x
FRONT NUMBER PLATE Best	1	\$ 70.00	30.
DOOR STICKER M-	1	\$ 50.00	30

SUBTOTAL \$ 190.00

60

BALANCE C/F \$ 5,517.25

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GBB5977P
MAKE MODEL : TOYOTA DYNA
REFERENCE : USG-201807-08
DOA : 14-Jul-18
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 5,517.25	
CHECK FRONT WIRING AND LIGHTNING SYSTEM	1	\$ 60.00	30
REMOVE AND RENEW CONDENSER AND TOP UP GAS	2	\$ 150.00	x
TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW	3	\$ 200.00	80
PANRL BEATING ON AFFECTED AREAS	4	\$ 800.00	700
SPRAY PAINTING ON AFFECTED AREAS	5	\$ 800.00	700
APPLY ANTI RUST ON AFFECTED AREAS	6	\$ 150.00	x

SUBTOTAL \$ 2,160.00

GRAND TOTAL \$ 7,677.25

1510

total: 4750
H/S 3.8K
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: