

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Jul 005/2018
Date	18/7/2018
Vehicle No	SKR1805M
Make / Model	Mercedes Benz E250

WDD2120472A200495

To: AIG Asia Pacific Insurance Pte Ltd

Address: 78 Shenton Way #07-16 Singapore 079120

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	rear bumper <i>red</i>		\$ 1,987.00 <i>1465</i>
2 pcs	rear bumper side retainer <i>new</i>		\$ 87.00 <i>657</i>
1 pc	o/s tail lamp <i>at</i>		\$ 93.00 <i>2014</i>
1 pc	o/s tail lamp lower bracket <i>new</i>		\$ 93.00 <i>2286.50</i>
1 pc	o/s rear fender <i>Decker</i>		\$ 2,515.00 <i>1050</i>
1 pc	o/s rear fender inner shield <i>fine</i>		\$ 197.00 <i>280</i>
1 set	o/s rear fender inner shield clip		\$ 80.00
1 pc	o/s rear door <i>Decker</i>	8259.5	\$ 2,482.00
1 pc	o/s rear door chrome moulding <i>new</i>		\$ 135.00
1 pc	o/s rear sports rim <i>at</i>	7433.55	\$ 1,614.00
1 pc	o/s rear lower arm (big) <i>new</i>		\$ 257.00
1 pc	o/s rear shock absorber <i>new</i>		\$ 685.00
1 set	rear windscreen glass moulding <i>new</i>		\$ 285.00
1 pc	o/s rear shock absorber link <i>new</i>		\$ 94.00
1 pc	o/s rear side arm <i>new</i>		\$ 197.00
1 pc	o/s rear lower arm (small) <i>new</i>		\$ 185.00
1 pc	o/s rear door windstrip <i>new</i>		\$ 385.00
1 pc	o/s rear knuckle arm <i>new</i>		\$ 1,979.00
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 1,600.00 <i>800</i>
2	to putty and spray painting on affected area		\$ 1,400.00 <i>750</i>
3	anti rust		\$ 200.00 <i>60</i>
4	windscreen		\$ 200.00 <i>120</i>
5	fuel tank	2200	\$ 100.00 <i>80</i>
6	wiring check		\$ 80.00 <i>30</i>
7	rear under carriage		\$ 300.00 <i>180</i>
8	wheel alignment		\$ 150.00 <i>80</i>
9	transfer door <i>fitting</i>		\$ 80.00
Subtotal:			\$ 20,299.00

LHK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
4/5 19/07/18
06 King

BEST SOLUTION AUTOCARE PTE LTD

total: 9633.55

4/5: 7.7k

Authorised Signature

8k

