

ASS. REC. BY:

REF CS/MSG18013172/ Urd3¹²

Special Instruction:

Surveyor
Minimen

Manus

ASSIGNMENT (Office)

From (Person):

Lianel Tan

of

MSIG

Date/Time:

19/7/18 @ 4:24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 14C

Insured:

SGY 6401 Y

at Workshop m/s

Joo Hark Kee

Tel:

6743 1913

of

Blk 3007 Ubi Rd 1 # 01-406

Policy No:

28929438SMA

Claim No:

564749

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

13/07/2018

CA / REV / REP. / REV 24 HRS

(up)

20/07/2018 @ Morning

H.O.D. Endorsement:

Date/Time:

4:30pm @ 19/7/18

Person Contacted:

Nabilah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKJ 14C - X

SGY 6401 - Y - X

Revert thru minimen

(08/11/13) wef

REF: M81G

AGS. REC. BY:

ASSIGNMENT

From: Date: 20/07/2018

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SKJ 14C

at Workshop m/s JOO HUK KEE

of 31K 3007 Ubi Rd 1 #01-406

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 75k.

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SKJ 14C Yr Regn: 111 12

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or CA1

Make: BMW 520i c.c. 1997

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 19/312 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA XG12090 DX50810

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35 ZR 20

R: 285/30 ZR 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/7/18 D.O.I. 20/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27A 63448

44rs. 3rd Rep 15h

18/9/18 confirmed 2/s & 2600 with Nos. 10h.

Red: 5361.45, 67%

RECEIVED 10 SEP 2018

Date/Time, File Pass to?

1) typint

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / 4B.I: (\$ 2600.00)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

150
10

160



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18013172/Urd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 19-07-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGY 6401Y	Veh. Inspected	SKJ 14C
Policy No.	28929438SMA	Coverage (\$)	0.00
Claim No.	564749	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	19/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/07/2018	Inspection Date	20/07/2018
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 18 Sep 2018

Preliminary Advice

Insured Vehicle No	: SGY6401Y	Accident Date	: 13/07/2018
TP Vehicle No	: SKJ14C	Assignment Date	: 19/07/2018
Make	: BMW 520I	Est. Duration of Repair	: 3.00
Date of Inspection	: 20/07/2018		
Inspection At	: JOO HAK KEE AUTO PTE LTD (HQ) BLK 3007 UBI ROAD 1, #01-406 SINGAPORE 408701		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,961.45
Revised Amount	:S\$	3,444.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,444.54

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2018		19 Jul 2018 16:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NG TECK SHENG, ID: S8173525E		
Main Claimant:	CHONG KOK CHEONG, ID: S7229841A		
Vehicle Reg. No.:	SKJ14C	Date of Loss:	13/07/2018 23:00 - :59 [68 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 564749	Policy/Cover Note No.:	28929438SMA (Comprehensive) Coverage: 20/04/2018 - 19/04/2019
Vehicle Reg. No. (Insured):	SGY6401Y	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/07/2018]		
Driver/Custodian (Insured):	HO LIANG KAI (), NRIC: S2760066B		
Adj Asg. Remarks:	SJE : DISAGREED . Liability : NOT CLEAR (NON-REPORTING) Please assist to arrange Surveyor - Adrian Ling from LKK Auto Consultants Pte Ltd for the survey tomorrow morning (20/07/2018). Kindly contact NABILAH SENIN @ 6743 1913 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.: SKJ14C
 Vehicle Type: P10 - Passenger Motor Car
 Vehicle Attachment 1: With Sun Roof
 Vehicle Scheme: Normal
 Vehicle Make: B.M.W.
 Vehicle Model: 520i A
 Chassis No.: WBAXG12090DX50810
 Propellant: Petrol
 Engine No.: A3920287N20B20B
 Engine Capacity: 1997 cc
 Maximum Power Output: 135.0 kW (181 bhp)
 Maximum Laden Weight: 2220 kg
 Unladen Weight: 1685 kg
 Year Of Manufacture: 2012
 Original Registration Date: 09 Nov 2012
 Lifespan Expiry Date: -
 COE Category: E - Open Category
 Quota Premium: \$87,999.00
 COE Expiry Date: 08 Nov 2022
 Road Tax Expiry Date: 08 Nov 2018
 PARF Eligibility Expiry Date: 08 Nov 2022
 Inspection Due Date: 08 Nov 2019
 Intended Transfer Date: 18 Jul 2018
 CO2 Emission: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9841A

Vehicle Details

Vehicle No.: SKJ14C

Vehicle to be Exported: No

Intended De-registration Date: 20 Jul 2018

Vehicle Make: B.M.W.

Vehicle Model: 520i A

Primary Colour: White

Manufacturing Year: 2012

Engine No.: A3920287N20B20B

Chassis No.: WBAXG12090DX50810

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$41,361.00

Original Registration Date: 09 Nov 2012

First Registration Date: 09 Nov 2012

Transfer Count: 0

Actual ARF Paid: \$41,361.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Nov 2022

PARF Rebate Amount: \$28,952.00

Intended COE Rebate Details

COE Expiry Date: 08 Nov 2022

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$87,999.00

COE Rebate Amount: \$34,496.00

Total Rebate Amount: \$63,448.00

The information contained herein is correct as at 20 Jul 2018

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

E-Class E250 Avantgarde.

Original Paintwork. Accident Free. Dark Brown Leather On Shining Silver.
Direct Owner StarAd

HOTLINE: 6741 9997

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

VIEW OUR CARS

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

31 vehicles

bmw 520

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 520		Any	Any	2012	Any	Any	Any	Available
	BMW 5 Series	520i	\$80,800	\$15,300 /yr	27-Jun-2012	1,997 cc	101,000 km	Luxury	Available
The 2012 BMW 5-Series Appears Somewhat Conservative On The Outside, But It Packs An Armada Of Advanced-tech Firepower, And New Fuel-efficient Engines, Without Interrupting Its Sport-sedan Mission! Mos...									
Prem Roy Motoring									
Posted: 20-Jul-2018 Tags: 2012 BMW 520i, BMW 520i, BMW, 520i, Used BMW									
	BMW 5 Series	520i	\$82,800	\$14,890 /yr	28-Sep-2012	1,997 cc	112,000 km	Luxury	Available
Only Owner, Full Service Record With Performance Motor, Excellent Conditions, 100% Accident Free, Unique Brown Exterior And Maroon Leather, View To Believe, Trade In Welcomed, Bank/High In House Avail...									
Posted: 19-Jul-2018 Tags: 2012 BMW 520i, BMW 520i, BMW, 520i, Used BMW									
	BMW 5 Series	520i	\$81,800	\$13,860 /yr	24-Dec-2012	1,997 cc	107,000 km	Luxury	Available
Graded B by STA									
\$13k Depreciation Only! 1 Owner PML Unit In Excellent Condition, Very Well Maintained! Flexible In House Financing Package And Trade In Available, Price Negotiable, View The Car At Our Showroom Today!									
Supreme Cars Pte Ltd									
Posted: 19-Jul-2018 Tags: 2012 BMW 520i, BMW 520i, BMW, 520i, Used BMW									
	BMW 5 Series	520i	\$113,800	\$23,670 /yr	26-Jun-2012	1,997 cc	101,000 km	Luxury	Available
Fully Service History By PML Since Day 1. Facelift F10 Sixth Generation 5 Series, Depre As Low As A 523i. Quiet, Smooth And Responsive Driving Experience. Trade In Welcome. Please Call Our Friendly Sa...									
Doshi Car									
Posted: 19-Jul-2018 Tags: 2012 BMW 520i, BMW 520i, BMW, 520i, Used BMW									
Car Buying	Car Selling	Car Ownership	Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation						
Car Aftermarket	On The Move	Lifestyle							
	BMW 5 Series	520i	\$99,800	\$21,220 /yr	24-Apr-2012	1,997 cc	-	Luxury	Available
Lowest In The Market! Only \$7000 Down Payment With In House Loan Available. High Quotation Given For Trade In At \$0 Down Payment. No Need Guarantor Or Minimum Income. Fast And Flexible Loan Approval. ...									
Posted: 19-Jul-2018 Tags: 2012 BMW 520i, BMW 520i, BMW, 520i, Used BMW									
	BMW 5 Series	520i	\$69,800	\$13,490 /yr	10-Feb-2012	1,997 cc	114,000 km	Luxury	Available
Very Well Maintain, Low Mileage, Come With Full M5 Bodykit, 20" Light Weight Sports Rims, Accident Free, Tip Top. See To Believe. Easy Loan Bank/In House Low Down Payment.									
Posted: 17-Jul-2018 Tags: 2012 BMW 520i, BMW 520i, BMW, 520i, Used BMW									
Compare	BMW 5 Series	520i	\$85,800	\$14,940 /yr	12-Dec-2012	1,997 cc	26,339 km	Luxury	Available

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER : CHONG KOK CHEONG
 INSURER : TOKIO MARINE INSURANCE SINGAPORE LTD
 POLICY NO.: MV012068
 REFERENCE: MSIG DIRECT SETTLE
 DATE OF ACCIDENT: 13/07/2018

REPAIR ESTIMATE

Est. No. : E18070006
 Date : 19/07/2018
 Vehicle Num. : SKJ14C
 Make/Model : B.M.W., 520I A
 Chassis/Eng# : WBAXG12090DX50810
 Yr. of Manu : 2012

Not Alled
 rsk
 1/3 #2600
 3dy.
 take the after
 rep.
 we rcs
 20/7/18

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	REAR BUMPER	1.00	1,467.20	1,467.20
2	REAR BUMPER REINFORCEMENT	1.00	714.25	714.25
3	REAR BUMPER CENTRE RETAINER	1.00	67.32	67.32
4	REAR BUMPER SIDE RETAINER LH	1.00	155.90	155.90
5	REAR BUMPER SIDE RETAINER RH	1.00	155.90	155.90
6	REAR BUMPER CLIPS	10.00	5.00	50.00
7	REAR BOTTOM GUIDE	1.00	58.00	58.00
8	END PANEL	1.00	817.30	817.30
9	REVERSE SENSOR	2.00	236.85	473.70
10	REAR LH EXHAUST MUFFLER	1.00	1,220.90	1,220.90

P-1773.2

57

1684.54

3364.54

Amt S\$ 5,180.47

Discount (5.00%) S\$ 259.02

Subtotal S\$ 4,921.45

Section: SPECIAL NETT ITEMS

11	REAR BUMPER DIFFUSER	1.00	880.00	880.00
----	----------------------	------	--------	--------

Amt S\$ 880.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 880.00

Section: LABOUR

12	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	800.00	800.00
13	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	800.00	800.00
14	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	1.00	120.00	120.00



KK Auto Centre will hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Continue on next page...



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER : CHONG KOK CHEONG
INSURER : TOKIO MARINE INSURANCE SINGAPORE LTD
POLICY NO.: MV012068
REFERENCE: MSIG DIRECT SETTLE
DATE OF ACCIDENT: 13/07/2018

REPAIR ESTIMATE

Est. No. : E18070006
Date : 19/07/2018
Vehicle Num. : SKJ14C
Make/Model : B.M.W., 520i A
Chassis/Eng# : WBAXG12090DX50810
Yr. of Manu : 2012

No	Description	Qty	U/P	Amt
15	TO REMOVE AND REINSTALL REVERSE SENSOR	1.00	140.00	140.00 50
16	TO REMOVE AND REINSTALL REAR EXHAUST MUFFLER	1 1	120.00	120.00 X
17	TO CHECK WIRING AND REWIRE	1.00	60.00	60.00 20
18	TO ANTI-RUST	1 ^	120.00	120.00 X
				Amt S\$ 2,160.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 2,160.00 880



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 4,921.45
SPECIAL NETT ITEMS Subtotal S\$ 880.00
LABOUR Subtotal S\$ 2,160.00
Total S\$ 7,961.45

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
WEBSITE: www.jhk.com.sg

bizSAFE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013172/URD3N2

Date: 19/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28929438SMA
Claimant Vehicle No :	SKJ14C	Insured Vehicle No :	SGY6401Y
Date of Loss:	13/07/2018	Nature of Claim:	TP
		Claim No:	564749

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ14C	Engine No:	A3920287N20B20B
Make & Model:	BMW 520I, 2.0 (A)	Chassis No:	WBAXG12090DX50810
Reg. Date:	09/11/2012 (Man. Year: 2012)	Odometer:	191312 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35ZR20	Rear Tyre Size:	285/30ZR20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,801.45	2,564.54	3,236.91	55.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	880.00	1,280.00	59.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,961.45	3,444.54	4,516.91	56.73
Approved Total (Overridden) (\$\$)		2,600.00		
	7,961.45	2,600.00	5,361.45	67.34
+ GST 7.00/7.00% (\$\$)	557.30	182.00	375.30	67.34
Nett Amount (\$\$)	8,518.75	2,782.00	5,736.75	67.34

INSPECTION

Date of Assignment:	19/07/2018		
Date Inspected:	20/07/2018	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2018)
Parts: 143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKJ14C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,467.20 FL	*1,467.20 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	714.25 FL	*- FL
3	1		*REAR BUMPER CENTRE RETAINER	Not Necessary	67.32 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	155.90 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	155.90 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
7	1		*REAR BOTTOM GUIDE	Cracked	58.00 FL	*58.00 FL
8	1		*END PANEL	Repair	817.30 FL	*- FL
9	1		*REVERSE SENSOR	N/s Shorted	473.70 FL	*198.00 FL
10	1		*REAR LH EXHAUST MUFFLER	Repair	1,220.90 FL	*- FL
11	1		*REAR BUMPER DIFFUSER	Cracked	880.00 FS	*880.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,060.47	2,653.20
- List Item Discount on L Items 5.00/5.00% (S\$)	259.02	88.66
Total Parts (S\$)	5,801.45	2,564.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	New	800.00	350.00
2	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	New	800.00	400.00
3	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	120.00	60.00
4	TO REMOVE AND REINSTALL REVERSE SENSOR	New	140.00	50.00
5	TO REMOVE AND REINSTALL REAR EXHAUST MUFFLER	New	120.00	-
6	TO CHECK WIRING AND REWIRE	New	60.00	20.00
7	TO ANTI-RUST	New	120.00	-
Gross Labour Cost (\$\$)			2,160.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >