



凱摩哆服務

Finalize??

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y



專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 25/07/2018

Attn: The Motor Claims Department
China Taiping Insurance (S) Pte Ltd
3 Anson oad
#16-00
Spring Leaf Tower
Singapore 079909

SFP886E (CTI: SNM18D03565C02)

6389 6171

Dear Sir / Madam

Supplementary Cost repair Bill To Lexus SFP 886 E & YN 8881 B on 18072018

To Supply:-

1pc	Rear lamp LH <i>lt</i>	\$ 751.60	✓
1pc	Rear boot cover lamp (<i>add one more pc</i>) <i>lt</i>	\$ 460.35	✓
1pc	Rear boot inn/fl luggage mat <i>the one</i>	\$ 423.50	X
1pc	Rear boot cover hinge (<i>add one more pc</i>) <i>Bent</i>	\$ 139.60	✓
1pc	Rear spare wheel tray cover <i>Repainted</i>	\$ 408.60	X
1pc	Rear floor sp/wh panel <i>Buckled</i>	\$ 765.80	✓
1pc	Rear ex pipe <i>Rpair</i>	\$ 598.50	X
1pc	Rear ex pipe top muff/insulater <i>newer</i> <i>2829.75</i>	\$ 215.30	X
1pc	Rear fender inner trim <i>comped</i> <i>2546.77</i>	\$ <u>683.50</u> <i>494.20</i>	
1pc	Rear sp/wh side tool board RH <i>del d</i>	\$ 218.20	✓
		\$ 4,664.95	

Less

To remove exhaust pipe.

\$ ~~200.00~~ *80*

Supplementary: *2626.77*