PREMIER TAXIS PTE LTD

23 CHANGI SOUTH AVE 2 #03-02 SINGAPORE 486443

TEL: 65446676, 65446689 FAX: 62141511

Our Ref: SHC6056P

WITHOUT PREJUDICE

Date: 23rd July 2018

Attn: The Motor Claims Department

(BY EMAIL ONLY)

AXA Insurance Pte Ltd No.8 Shenton Way #27-01 Singapore 068811

ACCIDENT INVOLVING SHC6056P & GZ3378X ALONG BATTERY ROAD ON 23.07.18

We are the registered owner of vehicle number of SHC6056P which was involved on the above mentioned accident between GZ3378X.

Investigation reveals that the motor vehicle number GZ3378X was insured with you at the material time of the said accident.


As a result of the accident was caused solely and completely by the negligence of your insured vehicle number GZ3378X. Therefore, we are holding you liable for the repair costs and other consequential loss which was sustained by us.

Kindly arrange your representative to survey our vehicle at 23 Changi South Avenue 2, #01-02, Singapore 486443 within two (2) days from the date hereof as to avoid further LOR/I incur. We enclosed hereby the GIA report of SHC6056P for your kind attention.

Failing which, we have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours Faithfully,

PREMIER TAXIS PT



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCOMSTANCES OF THE ACCIDENT
A: SHC 6056 P
A. 511C 6090 P
enter of the dealer pile of the enter of the
B: GZ 33787X

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

(If driver is not the policyholder)
Date & Time: $\begin{array}{c} (57571845) \\ (6056) \end{array}$

23 JUL 2018

6

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

ON 23/07/2018 @ 1145HRS, I WAS DRIVING MY TAXI (SHC 6056 P) TRAVELLING ALONG BATTERY ROAD IN THE LEFT LANE (ARROW ON ROAD SURFACE SHOWS STRAIGHT & LEFT TURN) WITH A PASSENGER ONBOARD.

WHILE I WAS MOVING STRAIGHT AHEAD, SUDDENLY VEHICLE B (GZ 3378 \times - VAN) WHICH WAS FROM THE RIGHT LANE (ARROW ON ROAD SURFACE SHOWS STRAIGHT AHEAD ONLY) – FAILED TO KEEP FOR PROPER LOOK OUT, HAD ENCROACHED ONTO MY PATH ON MY FRONT RIGHT ABRUPTLY.

AS SUCH, THE LEFT PORTION OF VEHICLE B COLLIDED ONTO THE FRONT RIGHT PORTION OF MY TAXI – WHICH HE WAS MAKING HIS IILEGAL LEFT TURN INTO THE CARPARK DRIVEWAY.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE FRONT RIGHT PORTION & VEHICLE B HAD DAMAGES ON THE LEFT PORTION.

NO INJURY INOVLVED.
NO PASSENGERS ONBOARD VEHICLE B.

* SCENE PHOTOS CAPTURED

