

15/02/2018

INS. CASE OWNER:

Catherine

CC 6/CTI1801

3337,

Upb3

LKK:
IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

21/7/18

Date / Time:

21/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 37AP.

Name of Insured:

LAW WEE TAYE

Insured Tel No.:

HP: 8777719

Excess Sec II :SS

Is driver the owner?

(YES / NO)

D.O.A.:

21/7/18

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SNM18002607C0Y

Policy No.:

DMP65W204247800

Make / Model:

Volkswagen

Place of Accident:

JLN TOR PAYOH 2ND

BENDOMEER RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

fastech

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

27/7/18

LKT

31/7/18

SLE 37AP 2nd/insr 18002607C0Y pay own 2nd

- old rear ended TP

23/8/18 - File pass to marcus to finalise

19/9/18 - File pass to type mandate

30/1/19 - present

21/3/19 - file pass to huber to clear

RECEIVED 1 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

21/9/18

Sent By:

CH

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

30/1/19

Confirm with:

Julian

Email

Call

Final Liability:

SS

%

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

SS

4280.00

Loss of Rental (LOR):

SS

400.00

(S

x

days)

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

4687.45

Global Sum SS:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

4687.45

Name 1:

Fastech Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

COPY SENT
21/7/18

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 534 7819Eat Workshop m/s 22.

of _____

Insured: SLE 379P

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 26

IDAC Accident Rpt: _____ Consistent? : Yes or No

CA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 1860B

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

have G1A 174 18371 net 762928/8/18 1/5 4000 confirmed with Alan(Ref # 11768-34 7561)Veh No: 5347819E Yr Regn: 29/12/09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda civic C.C. 1998Colour: Black A/C: Insured / Std / NI / NASp. Reading: 1283/9 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF D264095200977Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55-216

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 21/7/18 D.O.I. 23/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS \$ _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18013337/Upb3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 23-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 379P	Veh. Inspected	SJU 7819E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/07/2018	Inspection Date	23/07/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM18D03607C02
Our ref: CC6/CTI18013337/Upb3

Date: 14.09.2018

The Motor Claims Department
M/S China Taiping Insurance (Singapore) Pte. Ltd

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO.

SJU 7819E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on
23.07.2018 at the premises of M/s Fastech Auto Pte Ltd
and have the following to report:-

Workshop Estimate Amount	: S\$	15,768.30
Revised Estimate Amount	: S\$	4,000.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	26,000.00
LTA Reimbursement Value	: S\$	18,371.00
Nett Value	: S\$	7,629.00

Description of Damage:

The vehicle sustained damages at the
REAR PORTION



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68% P.A. @ Gv Cars Financing
GV Credit Pte Ltd StarAd



Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted 20 results/page

43 vehicles

Honda Civic

Advanced Search Submit

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Honda Civic		Any	Any	2009	Any	Any	Any	Available



Honda Civic 1.8A

\$21,900

\$9,270 /yr

30-Jun-2009

1,799 cc

152,000 km

Sedan

Available

Road Tax Till 29 Dec 2018. Original Pearl White Paintwork. No Repairs Needed. 100% Accident Free. STA/VICOM Inspection Welcome. Flexible Bank And In-House High Loan Available At Low Interest Rate. Tra...

Imperium Car Motor Pte Ltd

Posted: 22-Jul-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda



Honda Civic 1.8A

\$18,800

\$8,420 /yr

18-Mar-2009

1,799 cc

106,257 km

Sedan

Available

Good Original Condition, Low Mileage Done, Sports Rims, Leather Seats, Reverse Sensor, Road Tax Till 18/3/2019. No Repair Required, Low Depreciation, Good For Short Term Use.

Posted: 21-Jul-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda



Honda Civic 1.6A VTI (New 5-yr COE)

\$35,800

\$7,160 /yr

20-Jan-2009

1,595 cc

Sedan

Available

Wide Range Of Low Down Payment Loan Packages! Affordable Monthly Installment. No Hidden Cost. You Will Never Find One Ride Which Is Well Maintained Other Than This Ride. Accident Free. Well Maintained...

Posted: 21-Jul-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda



Honda Civic 1.8A

\$24,800

\$9,200 /yr

03-Nov-2009

1,799 cc

110,000 km

Sedan

Available

Beautifully Maintained Car! Excellent Condition. Good Car And Deal Wait For No One! Hassle Free Japanese Sedan. Low Maintenance Car. Call Our Friendly Sales Team Now For Viewing Today!

Posted: 21-Jul-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but
Unsure of its Condition?
Get, STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



Honda Civic 1.8A VTI-S

\$24,500

\$7,950 /yr

29-Dec-2009

1,799 cc

103,000 km

Sedan

Available

1 Owner, Low Mileage, Upgraded Breaks And Suspension, Well Taken Car By Owner, Comes With 6 Months Warranty, Island Wide Towing In Case Of Emergencies. STA/Workshop Checks Welcomed! No Hesitation Need...

Posted: 20-Jul-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda



Honda Civic 1.8A VTI-S

\$24,500

\$8,250 /yr

01-Dec-2009

1,799 cc

104,000 km

Sedan

Available

1 Owner, Low Mileage, Car Never Been To Malaysia, Only Local Use, Well Taken Car By Owner, Comes With 6 Months Warranty, Island Wide Towing In Case Of Emergencies. STA/Workshop Checks Welcomed! No Hes...

Posted: 20-Jul-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda

Honda Civic 1.8A VTI-S

\$28,000

\$10,660 /yr

16-Dec-2009

1,799 cc

130,000 km

Sedan

Available

1st Owner, Lady, Handover And Sep - New Car Coming In Oct, Please Whatsapp During Office Hour - View/Test Drive Can Arrange Sat/Sun After 3pm.

Posted: 20-Jul-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda

Compare

23-Jul-18

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	1860B

Vehicle Details

Vehicle No.:	SJU7819E
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 2.0L 5AT
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	K20Z24500978
Chassis No.:	JHMF026409S200977
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$28,722.00
Original Registration Date:	29 Dec 2009
First Registration Date:	29 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$28,722.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2019
PARF Rebate Amount:	\$15,797.00

Intended COE Rebate Details

COE Expiry Date:	28 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,267.00
COE Rebate Amount:	\$2,579.00
Total Rebate Amount:	\$18,376.00

The information contained herein is correct as at 22 Jul 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	1860B

Vehicle Details

Vehicle No.:	SJU7819E
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 2.0L 5AT
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	K20Z24500978
Chassis No.:	JHMFD26409S200977
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$28,722.00
Original Registration Date:	29 Dec 2009
First Registration Date:	29 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$28,722.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2019
PARF Rebate Amount:	\$15,797.00

Intended COE Rebate Details

COE Expiry Date:	28 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,267.00
COE Rebate Amount:	\$2,574.00
Total Rebate Amount:	\$18,371.00

The information contained herein is correct as at 23 Jul 2018

OK

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

VEHICLE NO: SJU 7819E

QTY	PARTICULAR			
1 PCS	REAR BUMPER	638	20/22	\$745.10 ✓
2 PCS	REAR BUMPER SIDE RETAINERS @\$25.20		bed	\$50.40 ✓
1 SET	REAR BUMPER CLIPS		22	\$30.00 ✓
1 PCS	BOOTLID	610-70	20/bed	\$810.70 ✓
1 PCS	BOOTLID 'H' LOGO		22	\$28.80 ✓
1 PCS	BOOTLID 'CIVIC' EMBLEM		22	\$36.60 ✓
1 PCS	BOOTLID 'IVTEC' EMBLEM		22	\$38.20 ✓
1 PCS	BOOTLID '2.0' EMBLEM		22	\$35.50 ✓
2 PCS	BOOTLID REFLECTORS @\$320.20	245.50 x 2 = 491	22	\$640.40 ✓
1 PCS	BOOTLID WEATHERSTRIP		22	\$197.60 ✓
1 PCS	BOOTLID INNER LOCK	199.50	22	\$299.50 ✓
1 PCS	BOOTLID LOCK STRIKER		17	\$48.50 X
2 PCS	BOOTLID HINGES @\$148.50		17	\$297.00 X
1 PCS	BOOTLID INNER TRIM		17	\$252.30 X
1 SET	BOOTLID INNER TRIM CLIPS		17	\$40.00 X
2 PCS	TAILLAMPS @\$365.50	285.30 x 2 = 570.60	22	\$731.00 ✓
2 PCS	TAILLAMP HOUSING PANELS @\$245.50		22	\$491.00 X
1 PCS	REAR END PANEL		30/20	\$316.60 ✓
1 PCS	REAR END PANEL TOP GARNISH		22	\$160.80 ✓
2 PCS	REAR FENDERS @\$899.10		22	\$1,798.20 X
2 PCS	REAR FENDER INNER TRIMS @\$366.20		17	\$732.40 X
1 SET	REAR FENDER INNER TRIM CLIPS		17	\$50.00 X
1 PCS	REAR FLOOR PANEL		22	\$966.50 X
1 PCS	REAR FLOOR PANEL TOP BOARD		22	\$316.00 ✓
1 PCS	REAR FLOOR PANEL TOP TOOLS SPONGE		17	\$305.20 X
1 PCS	REAR EXHAUST		17	\$699.50 X
1 PCS	REAR EXHAUST HEAT SHIELD		17	\$121.00 X
2 PCS	REAR EXHAUST MOUNTINGS @\$35.00		17	\$70.00 X
1 PCS	REAR WINDSCREEN MOULDING	202	17	\$68.50 X
2 PCS	REAR MUDFLAPS @\$80.50		17	\$161.00 X
				\$10,538.30
	S.NETT			
1 SET	REAR BUMPER REVERSE SENSOR		shop	\$280.00 200
1 PCS	REAR END PANEL SEALANT		22	\$50.00 ✓
1 SET	REAR FLOOR PANEL INSULATOR		17	\$300.00 X
1 SET	REAR EXHAUST CHROME PIPE		17	\$180.00 X

NOT ALLOWED
2/5 4000/2
527.
23/7/18

3720.30

1 PCS
1 PCS

REAR WINDSCREEN SEALANT
REAR LICENCE PLATE W/HOLDER

17 \$50.00 X
17 \$50.00 X

LABOUR CHARGES:

TO CHECK WIRING
TO DISMENTLE & REPLACING REVERSE SENSOR
TO DISMENTLE & REPLACING REAR EXHAUST
TO DISMENTLE & REFIX PETROL TANK
TO DISMENTLE & REFIX BOOTLID MECHANISM
TO DISMENTLE & REFIX REAR WINDSCREEN
TO MOUNT VEHICLE ON CAR O-LINER
TO DISMENTLE & REFIX SEAT,CUSHION,UPHOLSTREY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED
& REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 30
\$80.00 50
17 \$100.00 X
17 \$100.00 X
\$100.00 60
17 \$150.00 X
17 \$380.00 X
\$180.00 80
\$150.00 60
\$1,200.00 600
\$1,800.00 900
TOTAL \$15,768.30

5206.24

EKK Auto Centre (hence) notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Tuesday, 24 July 2018 4:56 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SLE379P (OI : CTI - SNM18D03607C02) AND SJU7819E (TP : LKK REF - CC6/CTI18013337/Upb3) on 21.07.2018
Attachments: leeSZ_SNM18D03607C01-SLE379P-LKKDirectSettlementAccidentLtr_CLCR95.097.pdf; MCHM18094546-SLE379P.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Hwang Shiang Yi

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :
This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 24 July, 2018 4:15 PM
To: Claims Dept of CTI
Cc: Sharon Han; Lucas Lee; Hsiao Tong (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SLE379P (OI : CTI - TBA) AND SJU7819E (TP : LKK REF - CC6/CTI18013337/Upb3) on 21.07.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SJU 7819E at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.taiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D03607/C01/9**

Date: **24 JULY 2018**

via Ordinary & Registered Mail

**GAN WEE THYE
BLK 113A MCNAIR ROAD
#32-276 MCNAIR TOWERS
SINGAPORE 322113**

Dear Sir / Madam

**ACCIDENT INVOLVING SLE379P AND SJU7819E ON 21 JULY 2018
ALONG JALAN TOA PAYOH TOWARDS BENDEMEER ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SJU7819E**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC: LKK Auto Consultants Pte Ltd

Attn: HSHAO TONG

Ref: CC6/CTI18013337/UPB3

Contact No: 67423197

via Email: HSHAO TONG@LKKAUTO.COM

CC: Agent - (AN0397A) - INDEX AGENCY PTE LTD

F01/LKKDS-2013

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 14 September 2018 8:28 AM
To: Claims Dept of CTI
Cc: 'catherine.thia@sg.cntaiping.com'; Admin A
Subject: RE: Direct Settlement - Accident Involving SLE379P (OI : CTI - TBA) AND SJU7819E (TP : LKK REF - CC6/CTI18013337/Upb3) on 21.07.2018
Attachments: TP ESTIMATE_MARKED.pdf; Preliminary Advice - SJU 7819E.pdf; LKK Survey Photos.pdf

Hi Sirs/Mdm,

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Tuesday, 24 July 2018 4:15 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Sharon Han <sharon.han@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SLE379P (OI : CTI - TBA) AND SJU7819E (TP : LKK REF - CC6/CTI18013337/Upb3) on 21.07.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SJU 7819E at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S{408933}



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 7819E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	745.10	638.00
2	REAR BUMPER SIDE RETAINERS @\$25.20	BENT	50.40	50.40
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	BOOTLID	DENTED / BENT	810.70	610.70
1	BOOTLID "H" LOGO	NECESSARY	28.80	28.80
1	BOOTLID "CIVIC" EMBLEM	NECESSARY	36.60	36.60
1	BOOTLID "IVTEC" EMBLEM	NECESSARY	38.20	38.20
1	BOOTLID "2.0" EMBLEM	NECESSARY	35.50	35.50
2	BOOTLID REFLECTORS @\$320.20	CRACKED	640.40	491.00
1	BOOTLID WEATHERSTRIP	TWISTED	197.60	197.60
1	BOOTLID INNER LOCK	TWISTED	299.50	199.50
1	BOOTLID LOCK STRIKER	NOT NECESSARY	48.50	-
2	BOOTLID HINGES @\$148.50	NOT NECESSARY	297.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	252.30	-
1	SET BOOTLID INNER TRIM CLIPS	NOT NECESSARY	40.00	-
2	TAILLAMPS @\$365.50	CRACKED	731.00	570.60
2	TAILLAMP HOUSING PANELS @\$245.50	TO REPAIR SEE LABOUR	491.00	-
1	REAR END PANEL	BADLY DENTED	316.60	316.60
1	REAR END PANEL TOP GARNISH	TWISTED	160.80	160.80
2	REAR FENDERS @\$899.10	TO REPAIR SEE LABOUR	1,798.20	-
2	REAR FENDER INNER TRIMS @\$366.20	NOT NECESSARY	732.40	-
1	SET REAR FENDER INNER TRIM CLIPS	NOT NECESSARY	50.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	966.50	-
1	REAR FLOOR PANEL TOP BOARD	WARPED / TORN	316.00	316.00
1	REAR FLOOR PANEL TOP TOOLS SPONGE	NOT NECESSARY	305.20	-
1	REAR EXHAUST	NOT NECESSARY	699.50	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	121.00	-
2	REAR EXHAUST MOUNTINGS @\$35.00	NOT NECESSARY	70.00	-

Report Ref No. CC6/CTI18013337/Upb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	68.50	-
2	REAR MUDFLAPS @\$80.50	NOT NECESSARY	161.00	-
	LESS 20% DISCOUNT		-	-744.06
			10,538.30	2,976.24
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	300.00	-
1	SET REAR EXHAUST CHROME PIPE (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
			910.00	250.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REPLACING REVERSES ENSOR.		80.00	50.00
	TO DISMENTLE & REPLACING REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO DISMENTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	TO DISMENTLE & REFIX BOOTLID MECHANISM.		100.00	60.00
	TO DISMENTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO DISMENTLE & REFIX SEAT,CUSHION,UPHOLSTERY.		180.00	80.00
	TO SPRAY RUST PROOFING.		150.00	60.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED & REPLACING PARTS,INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS,REAR FENDERS AND REAR FLOOR PANEL.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	900.00
	-		-	-
	-		-	-
	-		-	-
			4,320.00	1,780.00
	GRAND TOTAL		15,768.30	5,006.24

Report Ref No. CC6/CTI18013337/Upb3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	----------

Report Ref No. CC6/CT118013337/Upb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.