



Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6 Ark@KB
Singapore 417892
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No. : 201602964H

M/S AIG ASIA PACIFIC INS PTE LTD
78 SHENTON WAY
#07-16 AIG BLDG
SINGAPORE 079120

ESTIMATE
DATE : 23/07/2018
ACC DATE : 21/07/2018
REF NO : VFIX - TP20180504
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO XD5308A VOLVO FMX

DESCRIPTION	AMOUNT S\$
1 1 MIRROR ARM n/s	680.00
2 1 MIRROR GLASS n/s	220.00
3 1 MIRROR FRAME n/s	85.00
4 1 MIRROR HOUSING n/s	195.00
5 1 ROUND MIRROR n/s	230.00
	\$ 1,410.00

(102)
P. 730
102
657

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged parts with all necessary components/attachments new parts.	\$ 120.00

GRAND TOTAL : \$ 1,530.00

SINGAPORE DOLLARS : ONE THOUSAND FIVE HUNDRED & THIRTY ONLY

not Allowed
LKK
Exh. No. Other rep -
23/7/18
1 day.
p/p \$ 737.00/2

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: