Vantage Automotive Limited

305 Alexandra Road S'pore 159942

Date:

17.7.18

RE: VEHICLE REPAIR QUOTATION

Insurance Company : India International Insurance Pte Ltd

Vehicle Reg No : SLS631L

Name of Insured : Sime darby services pte ltd

Policy Number

Date of Accident : 13.07.2018

Tyre of Claim : Third Party Claim

Model : KIA SSORENTO 2.2(A)
Chassis No : KNAPH81BMH5379287

We are please to submit our estimate of repairs to the above mention vehicle.

	 1 Rear bumper 2 Rear bumper lower extension 3 Rear bumper reinforcement 4 Rear bumper centre bracket 5 Rear bumper sponge 6 Rear bumper reverse sensor 7 Rear bumper reflector/ fog lam 8 Tow cover 9 Rear end panel 10 Tail Gate 	Parts \$1,100.3 \$210.0 \$25.0 \$206.0 \$195.0 \$557.2 \$95.0 \$400.0 \$83.8 \$451.8	00 00 00 00 00 00 00	Labour
	Sub Total Parts = <u>\$ 3,324.10</u> Less 10% = <u>\$ 332.41</u>			
		Total Parts = <u>\$ 2,991.69</u>	9	
1 2 3	SUNDRIES ELECTRICAL WIRING CHECK TO REPLACE TAIL GATE, RE	AR BUMPER, REAR END	\$ \$ \$	120.00 120.00 900.00
4	REAR BUMPE BRACKET, CLIPS, LOGOS AND ALL OTHER AFFECTED AREAS TO SPRAY PAINT REAR TAIL GATE, REAR BUMPER, END PANEL AND ALL OTHER		\$	900.00
5	AFEFCTED PARTS AND AREAS TO TRANSFER TAILGATE COMPONENTS AND MECHANISMS		\$	250.00
6	TO REMOVE AND REFIX REAR BUMPER REVERSE SENSOR TO CONDUCT ECU PROGRAMMING, CHECK AND CLEAR FAULT CODES		\$ \$	150.00 450.00
	Total (Labour)		\$	2,890.00
	Sub Total : GST 7%	\$2,991.69 + \$4,290.00	\$	5,881.69 411.72
	Grand Total :		\$	6,293.41

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.