



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18013405/Abs3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 30-06-2020



ATTN: RICHARD ANG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 354M	Veh. Inspected	SFF 9693M
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S8M010L0	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	24/07/2018

### 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 523I	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBAFP32060C546463	Colour	WHITE
Odometer	176408	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	PIRELLI	6 mm
L/H Front Tyre	225/55 R17	PIRELLI	6 mm
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	22/07/2018	Inspection Date	24/07/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------