

COMFORTDELGRO ENGINEERING PTE LT
205 BRADDELL ROAD
SINGAPORE 579701

TEL: 63837466/7730/7656/7362 FAX: 62815767



ATTENTION : _____ ADDRESS : _____
 TEL : _____
 FAX : _____

VEHICLE NO : **SLF2707H** CHASSIS NO. : _____
 MAKE / MODEL : **Honda Vezel** ENGINE NO : _____
 DAYS OF REPAIR : _____ YEAR OF MANUF : _____
 PREPARED BY / DATE : _____ SALES ORDER : _____

CASH DAMAGED REPAIR QUOTATION

S/N	DESCRIPTION OF REPAIR SCOPE	PROPOSED (\$)
1	Parts Replacement	
1.1	Front bumper	\$ 801.80
1.2	Front bumper side retainer LH	\$ 18.90
1.3	Front bumper clips	\$ 30.00
1.4	Front bumper lower spoiler	\$ 395.50
1.5	Front bumper lower spoiler clips	\$ 30.00
1.6	Front bumper fog lamp cover LH	\$ 38.80
1.7	Front bumper fog lamp LH	\$ 318.00
1.8	Headlamp LH	\$ 1,715.10
1.9	Headlamp lower bracket LH	\$ 38.90
1.10	LH front fender wheel arch garnish	\$ 171.10
1.11	LH front fender wheel arch garnish clips	\$ 55.00
2	Labor	
2.1	Labor to repair, panel beat and replace damaged parts	\$ 720.00
2.2	To putty and spray paint front bumper, LH front fender, front bumper lower spoiler and all affected area	\$ 750.00
2.3	To check wiring functions	\$ 50.00
	Total Parts	\$3,613.10
	Less 20%	\$722.62
	Total Parts amount	\$2,890.48
	Total Labor	\$1,520.00
	Total Parts and Labor	\$4,410.48
	GST 7%	\$308.73
	Total Amount	\$4,101.75

Note: Quotation for Cash Repairs/not for Insurance Claims (Valid for 1 month only)

Please sign below if you agree with our quotation and fax to us @ 62815767

Signature : _____
 Name : _____

Company Stamp : _____
 Date : _____