

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/SMO18013459/R1z4d3e2 SOMPO INSURANCE SINGAPORE PL Ref: 50 RAFFLES PLACE #05-01/06 08-08-2018 Date: SINGAPORE LAND TOWER SINGAPORE 048623 Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SKQ 8805Y Veh. Inspected SJM 63G Policy No. Coverage (\$) 0.00 CMTD1803178/NSW Excess (\$) 0.00 Claim No. **Assign From GRACE TEO Assign Date** 24/07/2018 2. **Vehicle Particulars & Condition** Make & Model B.M.W M5 4.4 A 4395 c.c **Engine No. HIDDEN** Year of Reg. 2012 WBSFV92040DX95388 Chassis No. Colour **BLACK** 114048 KM Odometer **IN ORDER** Steering **IN ORDER** Brakes Modification SPORTS RIM FAIR General 3. **Conditions of Tyres** Size Make **Balance MICHELIN** 6 mm R/H Front Tyre 265/35Z R20 265/35Z R20 **MICHELIN** L/H Front Tyre 6 mm R/H Rear Tyre 265/35Z R20 **MICHELIN** 6 mm 265/35Z R20 **MICHELIN** 6 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. **General Information** 5. 20/07/2018 25/07/2018 (12:29 PM) **Accident Date** Inspect Date / Time Survey held at MAXIMUS RACING PTE LTD 7 SOON LEE STREET #05-05 SINGAPORE 627608 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000

Report Ref No. CS3/SMO18013459/R1z4d3e2

**Estimate Days of Repair** 

Inspected By

**Automotive Assessor** 

5b.

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.