

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 26 Jul 2018

Preliminary Advice

Vehicle No	: SGS2069G	Accident Date	: 24/07/2018
Make	: AUDI A6	Policy No.	: 1800019597
Assignment Date	: 25/07/2018	Excess	: S\$400.00
Date of Inspection	: 24/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,911.00
Revised Amount	:S\$	21,262.00
Check Items (Estimated)	:S\$	5,120.00
Total	:S\$	26,382.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	205,000.00
COE / PARF Rebate	:S\$	73,859.00
Salvage Value	:S\$	
Margin for Repair	:S\$	131,141.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :