

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0845/2018/PH
Date : 25-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Jaafar Bin Mohamed
Address : 7 Sembawang Crescent
: #03-13, Skypark Residences
Singapore 757096
Telephone : HP +65 98520060
Type of Claim : Own Damage Claims
Policy No. : 1800019597
Vehicle No : **SGS 2069 G**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Mar-18
Engine No : CYG 018412
Chassis No : WAUZZZ4G8HN081687
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Jul-18
Place of Accident : Sembawang Avenue(Filter out from Sembawang Drive)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 2069 G.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To remove and transfer air con condenser, radiator, additional radiator electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,100.00	?
3	To dismantle and renew front bumper, lhs headlight, lhs front fender and bonnet. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	S/N \$ 5,250.00 1750.	
4	To rep-spray front bumper, lhs front fender and bonnet.	\$ 2,500.00 1650.	
5	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>9,522.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SGS20696

Material List for Accident Vehicle Regn No. ~~SL 9018 R~~

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	<u>Remark</u>
1	BUMPER COVER <i>deformed</i>	\$ 2,650.00	✓
2	FIXING PARTS FOR BUMPER <i>Not nee</i>	\$ 464.00	x
3	BUMPER CLIP SET <i>nee</i>	\$ 43.00	✓
4	GRILLE - LOWER CENTRE <i>He m</i>	\$ 112.00	x
5	ADAPTER - LH/RH	2 \$ 64.00	x
6	CLOSING ELEMENT	\$ 188.00	x
7	SPOILER <i>He m</i>	\$ 216.00	x
8	SPOILER PRIMED	\$ 817.00	x
9	RADIATOR GRILLE	\$ 1,697.00	x
10	AIR GUIDE GRILLE SATIN BLACK	\$ 434.00	?
11	WHEEL SPOILER - LH FRONT	\$ 232.00	?
12	COVER CAP <i>He m</i>	\$ 49.00	x
13	GUIDE PIECE - LH/RH <i>LH Dmg'd</i>	2 \$ 64.00 32	
14	FOAM FILLER PIECE	\$ 203.00	x
15	SIDE REINFORCEMENT	\$ 702.00	x
16	BUMPER COVER <i>He m</i>	\$ 105.00	x
17	CAUTION' SIGN STICKER	\$ 12.00	x
18	STICKER FOR AIR CONDITIONER <i>He m</i>	\$ 17.00	x
19	BRACE - LH/RH <i>LH Bent</i>	2 \$ 50.00 25	
20	SENSOR PRIMED <i>Not nee</i>	2 \$ 392.00	x
SUB - TOTAL SPARE PARTS CHARGES :		\$ 8,511.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER - LH <i>Dislodged</i>	\$ 1,220.00	✓
22	ATTACHMENT PARTS FOR FENDER ?	\$ 88.00	?
23	STONE GUARD FILM WING DOOR <i>new</i>	\$ 105.00	x
24	BRACE WING - LH ?	\$ 72.00	?
25	STONE CHIP GUARD <i>new</i>	\$ 63.00	✓
26	ADHESIVE TAPE ?	\$ 49.00	?
27	WHEEL HOUSING LINER - LH <i>new</i>	\$ 246.00	x
28	ATTACHMENT PARTS FOR WHEEL LINER <i>new</i>	\$ 62.00	x
29	BONNET <i>Detached</i>	\$ 4,771.00	✓
30	ATTACHMENT PARTS FOR BONNET ?	\$ 153.00	?
31	CATCH HOOK } <i>new</i>	\$ 122.00	x
32	LOCK BAR } <i>new</i>	\$ 44.00	x
33	CATCH HOOK } <i>new</i>	\$ 15.00	✓
34	LID LOCK WITH MICRO-SWITCH } <i>new</i>	\$ 188.00	+
35	STOP BUFFER	2 \$ 50.00	x
36	MOUNT FOR MAIN HEADLIGHT-LH ?	\$ 103.00	?
37	LED HEADLIGHT - LH <i>cracked</i>	\$ 8,386.00	✓
38	POWER MODULE FOR DAY RUNNING LIGHT- ?	\$ 501.00	?
39	POWER MODULE FOR DIPPED BEAM ?	\$ 486.00	?
40	FAN FOR HEADLIGHT - LH ?	\$ 345.00	?
SUB - TOTAL SPARE PARTS CHARGES :		\$ 17,069.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved.
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G.

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remark
41	LIFT CYLINDER - LH <i>He ne</i>	\$ 208.00	<i>X</i>
42	LOCK CARRIER FOR COOLANT RADIATOR <i>?</i>	\$ 1,024.00	<i>?</i>
43	COOLANT CONCENTRATE <i>?</i>	4 \$ 133.00	<i>?</i>
44	COVER <i>He ne</i>	\$ 44.00	<i>X</i>
45	SUNDRIES <i>?</i>	\$ 400.00	<i>?</i>
TOTAL SPARE PARTS CHARGES		: \$ 27,389.00	
TOTAL LABOUR CHARGES		: \$ 9,522.00	
GRAND TOTAL		: \$ 36,911.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 24/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant