



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20180722/0065		LOCATION OF FIRE: Along Ayer Rajah Expressway (AYE) towards Jurong Near lamp post no. 11F After Exit 1A (Keppel Road), Singapore	
FIRE REPORTED ON : 22 July 2018			
TIME OF CALL : 01:49:53 hrs			
STATION COVERAGE : Marina Bay Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a Mitsubishi car (SGV187X).			
METHOD OF EXTINGUISHMENT: By SCDF crew using two dry powder fire extinguishers, two compressed air foam backpacks and a 38mm hose line jet from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged. The front part of the car, including the windscreen, was also damaged. The roof and interior of the car sustained heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
 EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.