

006 501 180

13523, 4 p 30

JCR:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A.:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

23

If NO or B 28, Ass. Lia:

Repair Cost:

SS

1819.00

Loss of Rental (LOR):

SS

321.00

(3 days)

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

2100.00

Global Sum SS:

2100.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2100.00

Name 1:

Styletech Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

11/06/19

CEN 1713 waf

ASS REC BY: *MORCJ*

REF:

59/
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *SLK 7869P*at Workshop m/s: *Stylech*

of: _____

Insured: *1N 2669M*

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *3*

days

Res: Yes or No

Lump Sum: *21*

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLK 7869P*Yr Regn: *1 / 17*Type: *CA* / M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda*Colour: *Red*Sp. Reading: *1995-4*

Eng/No: _____

C/No: *RU 31208861*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orMod: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *205/60 R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: *6*R/Bal: *6*L/Bal: *6*D.O.A: *24/7/18*

Survey held at: _____

Des. of Damages: *Rear* / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*None video- can see O/S ph. of vehicle.**23/8/19 confud 1/5 @ 1700 w/ln winston.**(Reel # 3280-94/656)*

Data/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1/

Date/Time, File Return to?

2/

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$ _____

Photos

Others

TOTAL

SLK7869P

Honda Vezel

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bootlid 953-00			\$ 1,253.30	.8 / Ref -
2	Rear Right Boot Reflector 325			# 454 +0	cm -
3	Rear Bootlid Vezel Emblem			\$ 42.90	rm -
4	Hybrid Emblem			\$72.50	rm -
5	Rear Bumper			\$ 949.00	r x
6	Glass Rubber Side LH & RH			\$ 96.80	rm -
7	Bumper Chrome Moulding			\$120 SN	n n X
8	Glass Sealant			\$60 SN	rm 40
9	Rear Bumper Clips			\$30 SN	n n X
10	Reverse Sensor			\$200 SN	n n X
				3278 84	
LRF Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation. - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer: Signature: Date:					
					p- 1490.2
					201-
					1.152-16

Labour					
1	Interior Upholstery			\$ 80.00	u1x
2	Check Wiring			\$ 80.00	20
3	Anti Rust Proofing			\$ 100.00	30
4	Transfer Bootlid Glass			\$ 120.00	120
5	Transfer Boot Fitting			\$ 150.00	60
6	Panel Beating			\$ 500.00	280
7	Paint Work To putty & spray painting			\$ 600.00	400

1630

Not Almd
 2/6 \$1700
 3h.
 to be ph. after 7p
 25/7/18

214216

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9534G

Vehicle Details

Vehicle No.: SLK7869P
Vehicle to be Exported: No
Intended De-registration Date: 25 Jul 2018
Vehicle Make: HONDA
Vehicle Model: VEZEL HYBRID 1.5X A
Primary Colour: Red
Manufacturing Year: 2016
Engine No.: LEB5908871
Chassis No.: RU31208861
Maximum Power Output: 112.0 kW (150 bhp)
Open Market Value: \$25,349.00
Original Registration Date: 25 Jan 2017
First Registration Date: 25 Jan 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Jan 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 24 Jan 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$52,807.00
COE Rebate Amount: \$44,871.00
Total Rebate Amount: \$48,621.00

The information contained herein is correct as at 25 Jul 2018

OK

Shu Pei (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Sunday, 4 August 2019 11:58 AM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - DM18HO03383/JT) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018
Attachments: SAS2641045.PDF

Dear Shu Pei

Attach OI report.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Thursday, July 4, 2019 9:42 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Tuesday, 26 February 2019 4:25 PM

To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Monday, 7 January 2019 8:59 AM

To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Monday, 10 December 2018 3:16 PM
To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>
Subject: FW: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

PART 3

Dear Janet,

Please find attached as per requested.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Monday, 10 December 2018 3:08 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

Dear Janet,

Please find attached as per requested.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Monday, 10 December 2018 1:30 PM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

Dear Shu Pei,

We are following up on non reporting.

Please forward us the video footage if any.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Monday, December 10, 2018 9:27 AM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Monday, 20 August 2018 6:03 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

Dear Janet,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 17 August 2018 1:49 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018
Importance: High

Dear Janet,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Thursday, 26 July, 2018 7:51 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving YN2669M (OI : EQI - TBA) AND SLK7869P (TP : LKK REF - CC6/EQI18013523/Ueb3) on 22.07.2018

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SLK 7869P at M/s Stytech Auto Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Stytech Auto Pte Ltd <stytechent@singnet.com.sg>
Sent: Sunday, 29 September 2019 5:16 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your Ref: SLK7869P *Our Ref: CC6/EQ18013523/Upb3 [ACCIDENT INVOLVING YN 2669M(EQ) AND SLK 7869P ON 22/07/2018]

Dear Hsiao Tong,

We agree your below email of the offer amount \$2100.00 all in.

Thank you

Best Regards

Winston Teo
Stytech Auto Pte Ltd
Email: stytechent@singnet.com.sg | Mobile: +65 9685 8843 | Fax: +65 6445 3310
Address: 2 Kaki Bukit Ave 2 #01-02/ 03, Kaki Bukit Autohub, Singapore 417921



STYTECH AUTO PTE LTD

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Saturday, September 28, 2019 9:30 AM
To: Stytech Auto Pte Ltd <stytechent@singnet.com.sg>
Subject: Your Ref: SLK7869P *Our Ref: CC6/EQ18013523/Upb3 [ACCIDENT INVOLVING YN 2669M(EQ) AND SLK 7869P ON 22/07/2018]

Your Ref: **SLK7869P** Without Prejudice
Our Ref: CC6/EQ18013523/Upb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING YN 2669M(EQ) AND SLK 7869P ON 22/07/2018

We refer to the above matter.

We propose settlement at a global sum of **\$2,100.00(all-in)**.

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #01-03 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98847/08/19
Date: 24/08/2019
To: M/S EQ Insurance Company Ltd.
5 Maxwell Road #17-00
Tower Block MND Complex
Singapore 069110
Attn: Motor Claim Dept

Dear Sir/Mdm,

Re: Claim of repair cost & loss of use for veh no.SLK 7869-P

<u>No.</u>	<u>Description</u>	<u>Price</u>
1.	Lump Sum Repair Cost for Vehicle No. SLK 7869-P	S\$1,819.00
2.	Loss of use for Rental Bill NR: 33765(S\$100X3Days) (Three Repair Days)	S\$ 321.00
3.	GIA Search Fee	S\$ 2.00
Total:		<u>S\$2,142.00</u>



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/EQI18013523/Upb3

29 August 2019

POH TAT HARDWARE TRADER

639 ROWELL RD

#11-96

SINGAPORE 200639

Dear Sir/Madam,

ACCIDENT INVOLVING YN 2669M AND SLK 7869P ON 22/07/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLK 7869P against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as your vehicle reversed and collided onto third party parked vehicle. Under Motor Accident Guide, reversing vehicles must exercise greater care than parked vehicles. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)

Date:

19/08/19

M/S

Ong Kok Hwee

Blk 718 Bedok Reservoir Road

#09-4574 S'pore 470718

To: M/S STYTECH AUTO PTE LTD

2 Kaki Bukit Avenue 2 #01-03

Kaki Bukit Autohub

Singapore 417921

Dear Sir/Mdm,

Repair Cost for Vehicle number

SLK 7869P

Caused by accident dated on

22/07/18

Involving vehicle(s) number

SLK 7869P

at

Car Park at Buddha Tooth Relic

Our Company/I,

Ong Kok Hwee

vehicle number

SLK 7869P


hereby authorized you to liaise with the insurance company and undertake all repairs & any other damages incurred as I am involved in the accident dated on

22/07/18

All legal & repair costs will be deducted from the proceeds of my claim and be released to M/S STYTECH AUTO PTE LTD.

Thank you.

Yours faithfully,





STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #01-03 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98847/08/19
Date: 24/08/2019
To: M/S EQ Insurance Company Ltd.
5 Maxwell Road #17-00
Tower Block MND Complex
S'pore 069110
Attn: Motor Claim Dept

Dear Sir/Mdm,

Re: Accident on 22/07/2018 Involving Vehicle Nos.SLK 7869-P YN 2669-M At Along Banda Street
Open Carpark At Buddha Tooth Relic.

FINAL BILL FOR VEHICLE NO.SLK 7869-P

<u>DESCRIPTION</u>	<u>PRICE</u>
Lump Sum Repair Cost For Vehicle No.SLK 7869-P	S\$1,700.00
GST 7%	S\$ 119.00
TOTAL: S\$1,819.00	

Yours Faithfully,
STYTECH AUTO PTE LTD

Mr. Winston Teo
9685 8843



SLK 7869P

STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
 TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
 GST REG. NO: 201601539K CO. REG. NO: 201601539K

NR No: 33765

Vehicle No: <u>SJ48528M</u>	Make and Type <u>TOYOTA ALTIS</u>
Date/Time Out <u>19/08/19 9.30am</u>	Date/Time In <u>22/08/19 1.20pm</u>

Fuel Gauge

E	1/4	1/2	3/4	F

EXTENSION CHARGES IS \$12.00 PER HOUR (SINGAPORE USE)
 DEPOSIT WILL BE FORFEITED IN ANY ACCIDENT/DAMAGE/FIRE & THEFT
 *NO RETURNING OF VEHICLE AFTER 6 PM & EVE / PUBLIC HOLIDAY

Hirer's Name: <u>Eng Kok Hwee</u>	KM OUT							KM IN				
Hirer's Address: <u>Bkt 718 Bedok Reservoir Road</u> <u>#09-4574 S'pore 470718</u>	RENTALS CHARGES							AMOUNT				
Tel: <u>I/C:</u>	3 Days at S\$ <u>100.00</u> per day							<u>\$300.00</u>				
H/P: <u>Age:</u>	Week at S\$ <u>per week</u>											
Driver's Name: <u>Eng Kok Hwee</u>	Month at S\$ <u>per mth</u>											
Driver's Address: <u>Bkt 718 Bedok Reservoir Road #09-4574</u>	Insurance fee to cover hired vehicle only											
Tel: <u>96955288</u> I/C: <u>S15195344</u>	Delivery/Collection fee											
<u>Age: 1962</u>	Petrol/Diesel											
Driving Licence Date: <u>30/08/79</u> Class: <u>3</u>	Others											
Additional Driver's Name:	Sub-Total											
Driver's Address:	Add GST <u>7%</u>							<u>\$21.00</u>				
Tel: <u>I/C:</u>	Total Nett Charges							<u>\$321.00</u>				
<u>Age:</u>	*Less Total Prepayment/Deposit Received											
Driving Licence Date:	Balance Amount Due/Refundable											
Guarantor's Name:	Add : EXTENSION CHARGES											
Guarantor's Address:												
Tel: <u>I/C:</u>												
<u>Age:</u>												
Occupation:												

IMPORTANT NOTES

- * This vehicle is restricted to SINGAPORE only.
- * No refund will be given for early return or fuel left in vehicle.
- * Hirer is liable to pay all parking fees, traffic summons & other claims.
- * Hirer who carries the number of passengers or load exceeding the MPG label will have to take their own responsibilities & LTA summons.
- * In the event of vehicle breakdown due to no fuel, hirer is liable to pay \$50 service charge plus cost of fuel/diesel.
- * No replacement of vehicle in any accident, damage or loss.
- * Hirer is responsible for the first \$1500/- excess for collision/damage/ fire or theft to first party (i.e. STYTECH AUTO PTE LTD) vehicle (including windscreen) and also first \$1500/- excess for collision/damage/fire & theft to third party's vehicle for each and every accident & damage.

METHOD OF PAYMENT

☐ Cash ☐ Cheque No: ☐ Visa ☐ Bill Co.

Refund Received \$ _____ By Hirer x _____

- * In the event of the rental vehicle is not return on the date due & no contact is made to inform our company of any changes & payment after one week due. Our Company will take action & repossess the vehicle & a service charge of \$120.00 are subject to the Hirer inclusive of the overdue charges with an additional interest of 3% per month.

I/We have read the terms and conditions of the rental agreement and agree thereto:-

Hirer's Signature

Guarantor's Signature

STYTECH AUTO PTE LTD
Signed By



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-112845

Date of Request: 24/07/2018

Your Ref No:

Online Purchase

Stytech Auto Pte Ltd
2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autohub
Singapore 417921

Dear Sir/Madam,

Enquiry Date 24/07/2018
Enquiry By Teo CHoon Kiat Winston
TP Vehicle No. YN2669M
Accident Date 22/07/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YN2669M	EQ Insurance Company Ltd	24/08/2017-23/08/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-112845
Date of Request: 24/07/2018

Your Ref No: Online Purchase

Stytech Auto Pte Ltd
2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autohub
Singapore 417921

Dear Sir/Madam,

Enquiry Date 24/07/2018
Enquiry By Teo CHoon Kiat Winston
TP Vehicle No. YN2669M
Accident Date 22/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 15/10/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YN 2669M (Insd Veh)	Your Ref. No. : DM18HO03383/JT
	SLK 7869P ✓ (TP Veh)	Our Ref. No. : CC6/EQ118013523/Upb3q2
Date of Accident	22/7/2018	

Liability	100%	
Final Repair Cost	: \$ 1,819.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 321.00	3 days
Others:	: \$ 2.00	
	: \$	
	2,142.00	
Final Settlement Sum	: \$ 2,100.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown		
1	STYTECH AUTO PTE LTD	: \$ 2,100.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQ18013523/Upb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 15-10-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2669M	Veh. Inspected	SLK 7869P	
Policy No.	DMCPHQ17-004561	Coverage (\$)	0.00	
Claim No.	DM18HO03383/JT	Excess (\$)	0.00	
Assign From		Assign Date	25/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31208861	Colour	RED	
Odometer	19954	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/07/2018	Inspection Date	25/07/2018	
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 7869P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	DENTED / BENT	1,253.30	953.00
1	REAR RIGHT BOOT REFLECTOR	CRACKED	✓ 454.40	325.00
1	REAR BOOTLID VEZEL EMBLEM	NECESSARY	✓ 42.90	42.90
1	HYBRID EMBLEM	NECESSARY	✓ 72.50	72.50
1	REAR BUMPER	TO REPAIR SEE LABOUR	✓ 949.00	-
2	GLASS RUBBER SIDE LH & RH	NECESSARY	✓ 96.80	96.80
	LESS 20% DISCOUNT		-	-298.04
			2,868.90	1,192.16
<u>SPECIAL NETT ITEMS</u>				
1	BUMPER CHROME MOULDING (SN)	NOT NECESSARY	✓ 120.00	-
1	GLASS SEALANT (SN)	NECESSARY	✓ 60.00	40.00
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	✓ 30.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	✓ 200.00	-
			410.00	40.00
<u>LABOUR</u>				
	INTERIOR UPHOLSTERY .	NOT NECESSARY	✓ 80.00	-
	CHECK WIRING.		✓ 80.00	20.00
	ANTI RUST PROOFING.		✓ 100.00	30.00
	TRANSFER BOOTLID GLASS.		✓ 120.00	120.00
	TRANSFER BOOT FITTING.		✓ 150.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		✓ 500.00	280.00
	TO PUTTY & SPRAY PAINTING.		✓ 600.00	400.00
			-	-
			-	-
			-	-
			1,630.00	910.00
GRAND TOTAL			4,908.90	2,142.16

Report Ref No. CC6/EQ18013523/Upb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00
---	--	--	----------

Report Ref No. CC6/EQ118013523/Upb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Wednesday, 16 October 2019 3:47 PM
To: 'eqiprs@eqinsurance.com.sg'
Cc: 'chewht@lkkauto.com'
Subject: TP Direct Settlement - Accident Involving YN 2669M (OI) and SLK 7869P (TP) on 22/07/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933