

S. REC. BY:

REF: CS/III 13013526/Ksbsr

Special Instruction:

SURVEYOR
MERIMEN

Kenneth
Muenachi

ASSIGNMENT (Office)

From (Person):

of

III

Date/Time: 25/07/08 8:42am

Estimated Cost:

Bill to:

DD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 6225U

Insured:

at Workshop in/s

Comfort Delgado

Tel:

6383 8115

of

205 Briddell Rd

Policy No:

M44792

Claim No:

M20182634

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A

15/07/08

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

25/07/08 10:36am

Person Contacted:

William

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------------------|---|
| | (GBB 6225U - X |
| 27/07/08 @ 09:18 a.m. | revised IA to Muenachi via merimen. |
| 27/07/08 @ 09:39 a.m. | mandate request authorize repair to Muenachi via merimen. |
| 27/07/08 @ 10:29 a.m. | mandate approved by Muenachi. |
| 27/07/08 @ 15:09 p.m. | revert authorize repair to William (repair) via email. |

ASS. REC. BY:

REF: TV /

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop n/s Cum Pri
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: \$ 715
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBB 8225U Yr Regn: 08, 09
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Traller or _____
 Make: Fiat Doblo c.c. 1368
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 125647 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZFA 223 00005693992
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: NIJ / S/Rim / STD A/Rim or
 Tyre Size: F: 185/55R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. D mm Rear R/Bal. D mm
 L/Bal. D mm L/Bal. D mm
 D.O.A. 15/7/18 D.O.I. 25/7/18
 Survey held at _____

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-----------------|---|
| <u>26/7</u> | <u>File pass to Catherine</u> |
| <u>11/10</u> | <u>LI Rep \$4400 Confirmed by email</u> |
| <u>12/10/18</u> | <u>Confirmed HS \$4,400/- @ 5 days with Kenneth</u> <u>(\$ 6,656.50 Red - 60%)</u> |

RECEIVED 12 OCT 2018

Date/Time, File Pass to? 12/10/18
 : Prell. Report
 : Final Report

Date/Time, File Return to? _____

Report Format :

Lump Sum / I.B.I: (\$) 4,400/- HS

Days Of Repair: 5
 Resurvey No. of Trlp: 1

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech Invs (\$))
 : Weekend (\$))

| | |
|-----------------|------------|
| Survey Fee: | <u>350</u> |
| Transportation: | _____ |
| S + RS | _____ |
| Fees | _____ |
| Others | _____ |
| TOTAL | <u>10</u> |

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---|--|---------|---------------|------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 24 Jul 2018 Sendback Est | 24 Jul 2018 18:33 S\$11,056.50 | 25 Jul 2018 08:42 Assign | | | | New Assignment Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

CLAIM SUBFOLDER DETAILS

| | | | |
|-------------------|--|------------------------|---|
| Insured: | STARHUB LTD, Co. Reg. No.: 199802208C | | |
| Vehicle Reg. No.: | GBB6225U | Date of Loss: | 15/07/2018 13:00 - :59 [106 Months and 25 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | OD / MC20182634 | Policy/Cover Note No.: | M494792 (Comprehensive) |
| | | Excess: | S\$500.00 |
| Repairer: | ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118 | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/08/2018] | | |
| Driver/Custodian: | SUNTHER S/O A VEERAMALAI (46 / Male), NRIC: S7176811B, Tel: +6583280245 | | |

ASSOCIATED MAIL RECEIVED [View All](#) | [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 27 July 2018 3:07 PM
To: 'CDGE Braddell Private Cars Crash Repair Operation'
Cc: 'SUR'
Subject: RE: GBB 6225U OD (III)

Dear William/Andrew,

As instructed by our client, please proceed at repair cost not exceeding \$5,000.00 (inclusive supplementary) to repair the insured vehicle
GBB 6225U (Excess \$ 500/-) on lump sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]
Sent: Friday, 27 July 2018 11:52 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: Re: GBB 6225U OD (III)

Hi Shirley,

Kindly refer to the attachment for the undertaking repair.

William Wang

Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767
www.SPARKcarcare.com

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 27 July 2018 9:53:51 AM
To: CDGE Braddell Private Cars Crash Repair Operation
Cc: 'SUR'
Subject: RE: GBB 6225U OD (III)

Hi William,

As spoken, the undertaking letter has been re-send.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Friday, 27 July 2018 9:36 AM
To: 'CDGE Braddell Private Cars Crash Repair Operation' <braddell_operation@sparkcarcare.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: GBB 6225U OD (III)

Dear Andrew/William,

Kindly refer to the attachment.

Please let us have your complete undertaking letter with the signature and workshop stamp.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]
Sent: Thursday, 26 July 2018 5:18 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: Re: GBB 6225U OD (III)

Dear Shirley ,

We will undertake the repair (lump sum) to the said vehicle not exceeding \$5000.00. Please advice us on the authorization.

William Wang

Shirley Hiew (LKK Auto)

From: CDGE Braddell Private Cars Crash Repair Operation
<braddell_operation@sparkcarcare.com>
Sent: Thursday, 26 July 2018 5:18 PM
To: Shirley Hiew (LKK Auto)
Cc: 'SUR'
Subject: Re: GBB 6225U OD (III)

Dear Shirley ,

We will undertake the repair (lump sum) to the said vehicle not exceeding \$5000.00. Please advice us on the authorization.

William Wang

Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767
www.SPARKcarcare.com

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 26 July 2018 3:41:39 PM
To: CDGE Braddell Private Cars Crash Repair Operation
Cc: 'SUR'
Subject: GBB 6225U OD (III)

Dear Andrew/William,

As spoken, Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 5,000.00.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



TO: India International Insurance Pte Ltd

CLAIM NO: MC20182634

WITHOUT PREJUDICE

LETTER OF UNDERTAKING

FOR THE REPAIR OF VEHICLE NO. GBB6225U

We, the undersigned, confirm that we will undertake to repair the vehicle bearing Registration No **GBB6225U** to its pre-accident condition, and to the satisfaction of its owner, at a total cost not exceeding LUMP SUM **5,000.00** (before excess) subject to no breach of Terms & Condition of the POLICY, and to the legal requirement of the local Land Transport Authority (LTA).

There should be **no further supplementary** to the repair cost.

27/07

Date

27/07/2018

Date

COMFORTDELGRO ENGINEERING PTE LTD
EXTERNAL BUSINESS DIV, BRADDELL BRANCH
NAME & SIGNATURE: _____
DESIGNATION: _____ DATE _____

Workshop Stamp/ Signature

Kenneth Kong

Witness by surveyor

TO: Chartis Singapore Insurance Pte Ltd

CLAIM NO: 800579796

View Received Message

This mail is associated with :

GBB6225U (MC20182634)

OD

Jul 15 2018 1:00PM

[STARHUB LTD]

ComfortDelGro Engineering Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 27/07/2018 10:29 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5000.00) - GBB6225U - Claim Handler: C. Meenachi

Approved:5000.00:excess \$500.00

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: C. Meenachi

Date: 26 Jul 2018

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Vehicle No | : GBB6225U | Accident Date | : 15/07/2018 |
| Make | : FIAT DOBLO | Policy No. | : M494792 |
| Assignment Date | : 25/07/2018 | Excess | : S\$500.00 |
| Date of Inspection | : 25/07/2018 | Est. Duration of Repair | : 5 days |
| Inspection At | : ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 11,056.50 |
| Revised Amount | :S\$ | 5,528.00 |
| Check Items (Estimated) | :S\$ | 4,088.25 |
| Total | :S\$ | 9,616.25 |

Lump Sum Repair :S\$

Total Loss Consideration

| | | |
|--------------------|------|----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 7,000.00 |
| COE / PARF Rebate | :S\$ | 1,797.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 5,203.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST NOT EXCEEDING \$ 5,000.00

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: C. Meenachi

Date: 26 Jul 2018

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Vehicle No | : GBB6225U | Accident Date | : 15/07/2018 |
| Make | : FIAT DOBLO | Policy No. | : M494792 |
| Assignment Date | : 25/07/2018 | Excess | : S\$500.00 |
| Date of Inspection | : 25/07/2018 | Est. Duration of Repair | : 5 days |
| Inspection At | : ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 11,056.50 |
| Revised Amount | :S\$ | 5,528.00 |
| Check Items (Estimated) | :S\$ | 4,088.25 |
| Total | :S\$ | 9,616.25 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 7,000.00 |
| COE / PARF Rebate | :S\$ | 1,797.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 5,203.00 |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 16/07/2018 18:15 |
| Date Of Accident | 15/07/2018 13:25 |
| Exact Location Of Accident | HOUANG AVE 2 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------|
| Vehicle Registration Number | GBB6225U |
| Insured/Policyholder | |
| Name Of Registered Owner | STARHUB LTD |
| Co Reg No | 199802208C |
| Email Address | MYWU@STARHUB.COM |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-68255085 |

Vehicle Particulars

| | |
|--------------|--|
| Manufacturer | FIAT |
| Model | DOBLO CARGO 1.4V PETROL (223 ZXP1A AX) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

| | |
|------------------|--------------------|
| Vehicle Category | COMMERCIAL VEHICLE |
|------------------|--------------------|

Insurance Company

| | |
|---------------------------|---------------------------------------|
| Name of Insurance Company | INDIA INTERNATIONAL INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | M494792 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------------------|
| Name of Driver | SUNTHER S/O A VEERAMALAI |
| NRIC No | S7176811B |
| Date Of Birth | 17/11/1971 |
| Occupation | INDOOR |
| Date Of Driving Pass | 31/10/1998 |
| Driving Experience | 19 YEARS AND 8 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-83280245 |
| Fax Number | |
| Contact Number | |
| EMail Address | SUNTHER.SOAVEERAMALAI@STARHUB.COM |

| | |
|---|------------------------------|
| Address | BLK 415B FERVALE LINK #04-50 |
| Postcode | 792415 |
| Was driver an employee of the Insured's Company | YES |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------|
| Type Of Accident | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of Intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER TO ATTACHED.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-----------------------|
| Vehicle Registration Number | SLR9616C |
| Vehicle Make/Model/Colour | HONDA |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | LEONARD TAN KAI SHENG |
| NRIC/Passport Number | S9335810D |
| Contact Number | 96215592 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



V-A SUTER


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 15/7/18 around 1325hrs AT CLEAR WEATHER,
 I WAS DRIVE AT LANE 1. SAW THE TRAFFIC LIGHT
 CHANGED TO GREEN FROM 100 METER AWAY.
 SO I INTEND TO CHANGE TO CENTRE LANE,
 BUT SUDDENLY THE CAR IN FRONT OF ME INTEND
 TO CHANGE CENTRE LANE. I WAS CHANGE
 AGAIN TO LANE 1 AND PULL THE HAND
 BRAKE AND PRESS THE BRAKE. BUT IT WAS
 TO NEAR AND HIT THE CAR BEHIND

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/PIN No.:



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 196703792K | GST Reg. No. M2-0078806-X
 64 Cecil Street #04/ #05/ #06-02 IOB Building Singapore 049711
 Office (65) 63476100 Email insure@iil.com.sg
 Fax (65) 62244174 Website www.iil.com.sg

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

This certificate is not transferable to a new owner of the vehicle. If for any reason the Insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the legislation relating to compulsory Insurance.
 The Certificate must be returned if the Insurance is suspended during its currency.

| | |
|---|--|
| Agency Code: 10827SE Comprehensive | Excess: S\$500/- Sect. 1 & S\$1000/- Sect. 1 for age <21 years or > 65 years &/or D.E. < 1 year Windscreen: S\$100.00 |
| CERTIFICATE NO. | M494792 |
| 1. Index Mark and Registration Number of Vehicle | GBB6225U |
| 2. Name of Policy Holder | StarHub Ltd |
| 3. Effective date of the commencement of Insurance for the purposes of the Act | 01 January 2018 |
| 4. Date of Expiry of Insurance | 31 December 2018 |
| 5. Persons or Classes of Persons entitled to drive* | |
| Any person who is driving on the Policyholder's order or with their permission, Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to use* | |
| (1) Use in connection with the Policyholder's business. (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business. (3) Use for social, domestic and pleasure purposes. The Policy does not cover (1) Use for hire or reward or for racing, pace-making, reliability trial, or speed-testing. (2) Use whilst drawing a trailer except the towing of any orle disabled mechanically propelled vehicle. | |
| *Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings. | |

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Date of Issue: RL/14.12.2017

for India International Insurance Pte. Ltd.
(APPROVED INSURERS)

M.Z. 300C (GOODS CARRYING)
PRIVATE TYPE

Authorized Signatory

IMPORTANT NOTICE

Policyholders are hereby warned that under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person to use or to cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

Policyholders are further warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agree to cover the new owner they will endorse the policy accordingly and will issue a new Certificate of Insurance in the new owner's name.

IN THE EVENT OF AN ACCIDENT NOTIFICATION SHOULD BE GIVEN IMMEDIATELY TO THE COMPANY. FAILURE TO DO SO WILL RESULT IN UNDERWRITERS DECLINING LIABILITY

Agent/Broker Name: ComfortDelgro Ins Brokers

Sketch Plan Pg. 4

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7176811B



Name
SUNTHAR S/O A VEERAMALAI

Race
INDIAN
Date of birth
17-11-1971
Country of birth
MALAYSIA

Sex
M

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S7176811B

Name
SUNTHAR S/O A VEERAMALAI

Birth Date: 17 Nov 1971
Issue Date: 03 Sep 2004

001281116B



8449355

NRIC No. S7176811B



Nationality
MALAYSIAN
Date of issue
03-09-2004

APT BLK 415B FERNVALE LINK #04-50
SINGAPORE 792415

S7176811B

04/08/2015

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| | | PASS DATE |
|----------|--|-------------|
| Class 2B | Motorcycles not exceeding 200 cc | 31 Oct 1998 |
| Class 3 | Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver, and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg | 31 Oct 1998 |



Licence No: S7176811B

NP 426A

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------------|--|
| Owner ID Type: | Company |
| Owner ID: | 2208C |
| Vehicle Details | |
| Vehicle No.: | GBB6225U |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 26 Jul 2018 |
| Vehicle Make: | FIAT |
| Vehicle Model: | DOBLO CARGO 1.4V PETROL (223 ZXP1A AX) |
| Primary Colour: | Silver |
| Manufacturing Year: | 2009 |
| Engine No.: | 350A10005172342 |
| Chassis No.: | ZFA22300005693992 |
| Maximum Power Output: | - |
| Open Market Value: | \$17,660.00 |
| Original Registration Date: | 20 Aug 2009 |
| First Registration Date: | 20 Aug 2009 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$883.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 19 Aug 2019 |
| COE Category: | E - Open Category |
| COE Period(Years): | 10 |
| QP Paid: | \$17,501.00 |
| COE Rebate Amount: | \$1,797.00 |
| Total Rebate Amount: | \$1,797.00 |

The information contained herein is correct as at 26 Jul 2018

OK

Cleoo Singapore - Increase student enrolment.

Leverage our A.I.driven online advertising solution to maximise your ROI.
education-marketing.cleoo.sg



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A



\$2500 Downpayment Monthly
From \$688 Onwards. Lowest
3.69% P.A. (0% Car Financing)
GV Credit Pte Ltd Starlink

PRIME MOTOR & LEASING
(SINGAPORE YONG CHAI ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

1 vehicles

Fiat Doblo

Sort by Date Posted 20 results/page

Advanced Search

Search Selection

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Fiat Doblo Any Any 2009 Any Any Any Available



Fiat Doblo 1.3M
Fuel Type: Diesel
\$5,800 \$7,270 /yr 14-May-2009 1,248 cc Van Available

Free 1 Year Insurance, One And Only Owner, Money Van, Used For Collecting Payment Only, Call Fast! Dont Miss The Freezing Aircon Doblo

Posted: 17-Jul-2018 Tags: 2009 Fiat Doblo, Fiat Doblo, Fiat, Dublo, Used Fiat

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Fiat Doblo, Fiat Doblo Singapore, used Fiat Doblo Singapore, used Fiat Doblo, used vehicles Singapore or even buy used Fiat Doblo Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Jul 2018)
 Parts: N/A FIAT DOBLO 1.3 D SX Cargo (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/GBB6225U/24/07/2018 18:33
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount | |
|-----|-----|----------|--|-------|-------|------------|---|
| 1 | 1 | | *Front number plate with casing | 0 | 0.00 | *45.00 FS | ✓ |
| 2 | 1 | | *Front bumper | 10.00 | 0.00 | *500.00 FL | ✓ |
| 3 | 1 | | *Front bumper fog lamp cover LH | 10.00 | 0.00 | *100.00 FL | ✓ |
| 4 | 1 | | *Front bumper fog lamp cover RH | 10.00 | 0.00 | *100.00 FL | X |
| 5 | 1 | | *Front bumper lower center grille | 10.00 | 0.00 | *112.50 FL | ✓ |
| 6 | 1 | | *Front bumper reinforcement | 10.00 | 0.00 | *450.00 FL | ✓ |
| 7 | 1 | | *Front grille | 10.00 | 0.00 | *200.00 FL | ✓ |
| 8 | 1 | | *Front grille badge logo | 10.00 | 0.00 | *150.00 FL | ✓ |
| 9 | 1 | | *Headlamp LH | 10.00 | 0.00 | *450.00 FL | ✓ |
| 10 | 1 | | *Headlamp RH | 10.00 | 0.00 | *450.00 FL | ✓ |
| 11 | 1 | | *Headlamp lower garnish LH | 10.00 | 0.00 | *145.00 FL | ✓ |
| 12 | 1 | | *Headlamp lower garnish RH | 10.00 | 0.00 | *145.00 FL | X |
| 13 | 1 | | *Bonnet | 10.00 | 0.00 | *575.00 FL | ✓ |
| 14 | 1 | | *Bonnet hinge LH | 10.00 | 0.00 | *87.50 FL | X |
| 15 | 1 | | *Bonnet hinge RH | 10.00 | 0.00 | *87.50 FL | X |
| 16 | 1 | | *Bonnet lock | 10.00 | 0.00 | *137.50 FL | ✓ |
| 17 | 1 | | *Bonnet sticker - starhub | 0 | 0.00 | *200.00 FS | ✓ |
| 18 | 1 | | *LH front fender | 10.00 | 0.00 | *437.50 FL | ✓ |
| 19 | 1 | | *LH front fender indicator lamp | 10.00 | 0.00 | *70.00 FL | X |
| 20 | 1 | | *LH front door sticker - starhub | 0 | 0.00 | *150.00 FS | ✓ |
| 21 | 1 | | *LH front door sticker - company address | 10.00 | 0.00 | *20.00 FL | X |
| 22 | 1 | | *Front support panel (complete) | 10.00 | 0.00 | *450.00 FL | ✓ |
| 23 | 1 | | *Condenser | 10.00 | 0.00 | *580.00 FL | ✓ |
| 24 | 1 | | *Brace panel | 10.00 | 0.00 | *150.00 FL | ✓ |
| 25 | 1 | | *Condenser fan motor with blade | 10.00 | 0.00 | *450.00 FL | ✓ |
| 26 | 1 | | *Condenser fan cowling | 10.00 | 0.00 | *300.00 FL | ✓ |
| 27 | 1 | | *Radiator | 10.00 | 0.00 | *450.00 FL | ✓ |
| 28 | 1 | | *Radiator fan motor with blade | 10.00 | 0.00 | *450.00 FL | ✓ |
| 29 | 1 | | *Radiator fan cowling | 10.00 | 0.00 | *300.00 FL | ✓ |
| 30 | 1 | | *Radiator spare tank | 10.00 | 0.00 | *212.50 FL | X |
| 31 | 1 | | *Coolant | 0 | 0.00 | *30.00 FS | ✓ |
| 32 | 1 | | *Inter cooler | 10.00 | 0.00 | *875.00 FL | ✓ |

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) 8,860.00
 - List Item Discount on L Items (S\$) 843.50

Total Parts (S\$) 8,016.50

ComfortDelGro Engineering Pte Ltd/GBB6225U/24/07/2018 18:33. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3570 SN 75

Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|----------------------------|-----|----------------------|--------|
| <u>Miscellaneous Items</u> | | | |
| 1 | 1 | OD/TP Case (Insurer) | 10.00 |
| Sub Total (S\$) | | | 10.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|-------------------------|---|----------|-------------------------|
| <u>Labour Items</u> | | | |
| 1 | To remove/replace aircond parts, vacuum & recharge gas. | New | (120) 1001 120.00 84 |
| 2 | Labour charges to repair and panel beat the RH front fender, RH front fender inner panel, LH front fender inner panel, LH front door, cutting/welding and replacing damaged parts. | New | 1,120.00 730 |
| 3 | To check wiring functions and focus headlamps. | New | 40.00 20 |
| 4 | To putty, apply primer & spray-paint the front bumper, bonnet, front support panel, LH front fender, LH front fender inner panel, LH front door, RH front fender, RH front fender inner panel and affected areas. | New | 1,750.00 125 |
| Gross Labour Cost (S\$) | | | 3,030.00 |

ComfortDelGro Engineering Pte Ltd/GBB6225U/24/07/2018 18:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2230

To: Kenneth

Parts = 3570.00

- 10% 357.00

= 3213.00

+ SNI 75.00

+ Labour 2230.00

= 5518.00

- 20% 1103.60

= 4414.40

M/S = 4414.40

5/10/18

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837168 /63837118 Fax: 62815767/65462533 Email: denisteo@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

| | | | |
|---------------------|--------------------------|-----------------------|------------|
| Claim Type: | OD (Own Damage) | Ref. No: | |
| Policy No: | M494792 | Date of Loss: | 15/07/2018 |
| Vehicle Reg. No.: | GBB6225U | Driveable? | |
| Driver Age/Info: | 46 / MALE | Party At Fault: | UNKNOWN |
| TP Injury Involved? | NO | Third Party Involved? | YES |
| Insured/Claimant: | STARHUB LTD | | |
| Driver: | SUNTHER S/O A VEERAMALAI | | |

| | | | |
|-----------------|--------------------------------|--------------------|-------------------|
| Make/Model: | FIAT DOBLO, 1.3 D SX Cargo (M) | Vehicle Reg. Date: | 20/08/2009 |
| Vehicle Colour: | Metallic Silver | | |
| Engine No: | 350A10005172342 | Chassis No: | ZFA22300005693992 |
| Odometer: | 125635 KM | | |

Paint Type:
List Item Discount: 10.00 %
Total Loss? **NO**
Est. Duration of Repair (day) *5 day*

For [Signature]
Not With claim
Return After Paint
Fax: 62564315 Ex 85001

Description of Accident/Loss PLEASE REFER TO ATTACHED.
Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

| COST OF CLAIMS | Amount |
|--------------------------|------------------|
| Parts | 8,016.50 |
| Miscellaneous Items | 10.00 |
| Labour | 3,030.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (S\$) | 11,056.50 |
| + GST 7.00% (S\$) | 773.96 |
| Nett Amount (S\$) | 11,830.46 |

This claim is handled by: **WILLIAM WANG KIAT SENG**

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Jul 2018)
Parts: N/A FIAT DOBLO 1.3 D SX Cargo (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDeIGro Engineering Pte Ltd/GBB6225U/24/07/2018 18:33
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|--|------------|-------|------------|
| 1 | 1 | | *Front number plate with casing | B | 0 | *45.00 FS |
| 2 | 1 | | *Front bumper | B | 10.00 | *500.00 FL |
| 3 | 1 | | *Front bumper fog lamp cover LH | CM | 10.00 | *100.00 FL |
| 4 | 1 | | *Front bumper fog lamp cover RH | S | 10.00 | *100.00 FL |
| 5 | 1 | | *Front bumper lower center grille | D | 10.00 | *112.50 FL |
| 6 | 1 | | *Front bumper reinforcement | R | 10.00 | *450.00 FL |
| 7 | 1 | | *Front grille | CD | 10.00 | *200.00 FL |
| 8 | 1 | | *Front grille badge logo | N | 10.00 | *150.00 FL |
| 9 | 1 | | *Headlamp LH | M, CM | 10.00 | *450.00 FL |
| 10 | 1 | | *Headlamp RH | M, CM | 10.00 | *450.00 FL |
| 11 | 1 | | *Headlamp lower garnish LH | CM | 10.00 | *145.00 FL |
| 12 | 1 | | *Headlamp lower garnish RH | S | 10.00 | *145.00 FL |
| 13 | 1 | | *Bonnet | B | 10.00 | *575.00 FL |
| 14 | 1 | | *Bonnet hinge LH | R | 10.00 | *87.50 FL |
| 15 | 1 | | *Bonnet hinge RH | R | 10.00 | *87.50 FL |
| 16 | 1 | | *Bonnet lock | R | 10.00 | *137.50 FL |
| 17 | 1 | | *Bonnet sticker - starhub | (Insured?) | 0 | *200.00 FS |
| 18 | 1 | | *LH front fender | | 10.00 | *437.50 FL |
| 19 | 1 | | *LH front fender indicator lamp | | 10.00 | *70.00 FL |
| 20 | 1 | | *LH front door sticker - starhub | N | 0 | *150.00 FS |
| 21 | 1 | | *LH front door sticker - company address | N | 10.00 | *20.00 FL |
| 22 | 1 | | *Front support panel (complete) | B | 10.00 | *450.00 FL |
| 23 | 1 | | *Condenser | S | 10.00 | *580.00 FL |
| 24 | 1 | | *Brace panel | R | 10.00 | *150.00 FL |
| 25 | 1 | | *Condenser fan motor with blade | S | 10.00 | *450.00 FL |
| 26 | 1 | | *Condenser fan cowling | S | 10.00 | *300.00 FL |
| 27 | 1 | | *Radiator | S | 10.00 | *450.00 FL |
| 28 | 1 | | *Radiator fan motor with blade | S | 10.00 | *450.00 FL |
| 29 | 1 | | *Radiator fan cowling | S | 10.00 | *300.00 FL |
| 30 | 1 | | *Radiator spare tank | S | 10.00 | *212.50 FL |
| 31 | 1 | | *Coolant | N | 0 | *30.00 FS |
| 32 | 1 | | *Inter cooler | S | 10.00 | *875.00 FL |

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) **8,860.00**
 - List Item Discount on L Items (\$\$) **843.50**

Total Parts (\$\$) 8,016.50

ComfortDeIGro Engineering Pte Ltd/GBB6225U/24/07/2018 18:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|----------------------------|-----|----------------------|--------------|
| Miscellaneous Items | | | |
| 1 | 1 | OD/TP Case (Insurer) | 10.00 |
| Sub Total (S\$) | | | 10.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|--------------------------------|---|----------|-----------------|
| Labour Items | | | |
| 1 | To remove/replace aircond parts, vacuum & recharge gas. | New | 120.00 |
| 2 | Labour charges to repair and panel beat the RH front fender, RH front fender inner panel, LH front fender inner panel, LH front door, cutting/welding and replacing damaged parts. | New | 1,120.00 |
| 3 | To check wiring functions and focus headlamps. | New | 40.00 |
| 4 | To putty, apply primer & spray-paint the front bumper, bonnet, front support panel. LH front fender, LH front fender inner panel, LH front door, RH front fender, RH front fender inner panel and affected areas. | New | 1,750.00 |
| Gross Labour Cost (S\$) | | | 3,030.00 |

*1001
8401
7001
201
12501
14001*

ComfortDeIGro Engineering Pte Ltd/GBB6225U/24/07/2018 18:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 24 Jul 2018 Sendback Est | 24 Jul 2018 18:33 S\$11,056.50 | 25 Jul 2018 08:42 Edit Adj Rpt | S\$4,400.00 Edit Estimates | S\$4,400.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

| | | | |
|-------------------|--|------------------------|--|
| Insured: | STARHUB LTD , Co. Reg. No.: 199802208C | | |
| Vehicle Reg. No.: | GBB6225U | Date of Loss: | 15/07/2018 13:00 - :59 [106 Months and 25 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | OD / MC20182634 | Policy/Cover Note No.: | M494792 (Comprehensive) |
| | | Excess: | S\$500.00 |
| Repairer: | ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118 | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/08/2018] | | |
| Driver/Custodian: | SUNTHER S/O A VEERAMALAI (46 / Male), NRIC: S7176811B, Tel: +6583280245 | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (27/07/2018): Alert - Adj Mandate Approved (S\$5000.00) - GBB6225U - Claim Handler: C. Meenachi

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

GBB6225U (MC20182634)
OD
Jul 15 2018 1:00PM
[STARHUB LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|-----------------|--|--|-------------------------------------|
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | Thumbnail | Print |
| 1 | 24/07/18 18:33 | Repairer Estimates | Load HTM | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 27/07/18 09:18 | Adjuster Immediate Advice | Load HTM | |
| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 2 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 3 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 4 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 5 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 6 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 7 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 8 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 9 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 10 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 11 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 12 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 13 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 14 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 15 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 16 | 27/07/18 09:13 | Chassis Number | Load JPG <input checked="" type="checkbox"/> | |
| 17 | 27/07/18 09:13 | Odometer Reading | Load JPG <input checked="" type="checkbox"/> | |
| 18 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| 19 | 27/07/18 09:13 | General View | Load JPG <input checked="" type="checkbox"/> | |
| Documentation | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 25/07/18 08:39 | Singapore Accident Statement | Load PDF | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 27/07/18 09:11 | ESTIMATE | Load PDF | |
| 2 | 12/10/18 10:21 | ESTIMATE MARKED.pdf | Load PDF | |

Linked Accident Report Documents

View View in Browser ▼

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|--------------|-------------------------------------|
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | Thumbnail | Print |
| 1 | 16/07/18 18:29 | Accident Statement | Load HTM | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|----------------------|----------------|--|--|-------------------------------------|
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | Thumbnail | Print |
| Photos/Images | | | | |
| | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | Thumbnail | Print |
| 1 | 16/07/18 18:24 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 16/07/18 18:24 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 16/07/18 18:24 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 16/07/18 18:24 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 16/07/18 18:24 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 16/07/18 18:24 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | |
| | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | Thumbnail | Print |
| 1 | 16/07/18 18:27 | Sketch Plan |  Load TIF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) |
|--|
| <p>Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p> |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III18013526/KSBS2

Date: 12/10/2018

REFERENCE

| | | | | | |
|-------------------|-------------|------------------|---------|-----------|------------|
| Insured/Claimant: | STARHUB LTD | Policy No: | M494792 | | |
| Date of Loss: | 15/07/2018 | Nature of Claim: | OD | Claim No: | MC20182634 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | GBB6225U | | |
| Make & Model: | FIAT DOBLO, 1.3 D SX Cargo (M) | Engine No: | 350A10005172342 |
| Reg. Date: | 20/08/2009 (Man. Year: 2009) | Chassis No: | ZFA22300005693992 |
| Colour: | Silver | Odometer: | 125647 km |
| Engine Capacity: | 1368 cc | | |
| Market Value/New Car Price: | S\$7,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 185/65R15 | Rear Tyre Size: | 185/65R15 |
| Front Left Side: | Yokohama 8 mm | Rear Left Side: | Yokohama 8 mm |
| Front Right Side: | Yokohama 8 mm | Rear Right Side: | Yokohama 8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 8,016.50 | 3,288.00 | 4,728.50 | 58.98 |
| Miscellaneous Items | 10.00 | 10.00 | 0.00 | 0.00 |
| Labour | 3,030.00 | 2,360.00 | 670.00 | 22.11 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 11,056.50 | 5,658.00 | 5,398.50 | 48.83 |
| Approved Total (Overridden) (S\$) | | 4,400.00 | | |
| - Excess (S\$) | 0.00 | 500.00 | -500.00 | |
| (S\$) | 11,056.50 | 3,900.00 | 7,156.50 | 64.73 |
| + GST 7.00/7.00% (S\$) | 773.96 | 273.00 | 500.96 | 64.73 |
| Nett Amount (S\$) | 11,830.46 | 4,173.00 | 7,657.46 | 64.73 |

INSPECTION

Date of Assignment: 25/07/2018

Date Inspected: 25/07/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 12 Oct 2018) | |
| Parts: | N/A | FIAT DOBLO 1.3 D SX Cargo (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBB6225U) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|------------|------------|
| 1 | 1 | | *Front number plate with casing | Bent | 45.00 FS | *45.00 FS |
| 2 | 1 | | *Front bumper | Buckled | 500.00 FL | *500.00 FL |
| 3 | 1 | | *Front bumper fog lamp cover LH | Cracked | 100.00 FL | *100.00 FL |
| 4 | 1 | | *Front bumper fog lamp cover RH | Serviceable | 100.00 FL | *-FL |
| 5 | 1 | | *Front bumper lower center grille | Distorted | 112.50 FL | *112.50 FL |
| 6 | 1 | | *Front bumper reinforcement | Repair | 450.00 FL | *-FL |
| 7 | 1 | | *Front grille | Cracked | 200.00 FL | *200.00 FL |
| 8 | 1 | | *Front grille badge logo | Necessary | 150.00 FL | *150.00 FL |
| 9 | 1 | | *Headlamp LH | Mtg Cracked | 450.00 FL | *450.00 FL |
| 10 | 1 | | *Headlamp RH | Mtg Cracked | 450.00 FL | *450.00 FL |
| 11 | 1 | | *Headlamp lower garnish LH | Cracked | 145.00 FL | *145.00 FL |
| 12 | 1 | | *Headlamp lower garnish RH | Serviceable | 145.00 FL | *-FL |
| 13 | 1 | | *Bonnet | Buckled | 575.00 FL | *575.00 FL |
| 14 | 1 | | *Bonnet hinge LH | Repair | 87.50 FL | *-FL |
| 15 | 1 | | *Bonnet hinge RH | Repair | 87.50 FL | *-FL |
| 16 | 1 | | *Bonnet lock | Repair | 137.50 FL | *-FL |
| 17 | 1 | | *Bonnet sticker - starhub | Not Necessary | 200.00 FS | *-FS |
| 18 | 1 | | *LH front fender | Buckled | 437.50 FL | *437.50 FL |
| 19 | 1 | | *LH front fender indicator lamp | Serviceable | 70.00 FL | *-FL |
| 20 | 1 | | *LH front door sticker - starhub | Not Necessary | 150.00 FS | *-FS |
| 21 | 1 | | *LH front door sticker - company address | Not Necessary | 20.00 FL | *-FL |
| 22 | 1 | | *Front support panel (complete) | Buckled | 450.00 FL | *450.00 FL |
| 23 | 1 | | *Condenser | Serviceable | 580.00 FL | *-FL |
| 24 | 1 | | *Brace panel | Repair | 150.00 FL | *-FL |
| 25 | 1 | | *Condenser fan motor with blade | Serviceable | 450.00 FL | *-FL |
| 26 | 1 | | *Condenser fan cowling | Serviceable | 300.00 FL | *-FL |
| 27 | 1 | | *Radiator | Serviceable | 450.00 FL | *-FL |
| 28 | 1 | | *Radiator fan motor with blade | Serviceable | 450.00 FL | *-FL |
| 29 | 1 | | *Radiator fan cowling | Serviceable | 300.00 FL | *-FL |
| 30 | 1 | | *Radiator spare tank | Serviceable | 212.50 FL | *-FL |
| 31 | 1 | | *Coolant | Necessary | 30.00 FS | *30.00 FS |
| 32 | 1 | | *Inter cooler | Serviceable | 875.00 FL | *-FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 8,860.00 | 3,645.00 |
| - List Item Discount on L Items 10.00/10.00% (S\$) | 843.50 | 357.00 |
| Total Parts (S\$) | 8,016.50 | 3,288.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|----------------------|--------------|--------------|
| Miscellaneous Items | | | | |
| 1 | 1 | OD/TP Case (Insurer) | 10.00 | 10.00 |
| Sub Total (S\$) | | | 10.00 | 10.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | To remove/replace aircond parts, vacuum & recharge gas. | New | 120.00 | 100.00 |
| 2 | Labour charges to repair and panel beat the RH front fender, RH front fender inner panel, LH front fender inner panel, LH front door, cutting/welding and replacing damaged parts. | New | 1,120.00 | 840.00 |
| 3 | To check wiring functions and focus headlamps. | New | 40.00 | 20.00 |
| 4 | To putty, apply primer & spray-paint the front bumper, bonnet, front support panel. LH front fender, LH front fender inner panel, LH front door, RH front fender, RH front fender inner panel and affected areas. | New | 1,750.00 | 1,400.00 |
| Gross Labour Cost (S\$) | | | 3,030.00 | 2,360.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >