

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: C. Meenachi

Date: 26 Jul 2018

Preliminary Advice

Vehicle No	: GBB6225U	Accident Date	: 15/07/2018
Make	: FIAT DOBLO	Policy No.	: M494792
Assignment Date	: 25/07/2018	Excess	: S\$500.00
Date of Inspection	: 25/07/2018	Est. Duration of Repair	: 5 days
Inspection At	: ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,056.50
Revised Amount	:S\$	5,528.00
Check Items (Estimated)	:S\$	4,088.25
Total	:S\$	9,616.25
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	7,000.00
COE / PARF Rebate	:S\$	1,797.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,203.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST NOT EXCEEDING \$ 5,000.00