

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

24 JUL 2018

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47797 Page No. : 1 of 6
Date Estimated : 24/07/2018
Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -
Chong Ai Choo (Zhang AiZhu)
18 Hooper Road

Singapore 229195

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE8118Y	0J00183	08/12/2015	X3 sDrive20	0

DESCRIPTIONVALUE

To replace rear tailgate, rear bumper upp, rear bumper lower,
end panel, kidney frill & all attachment cause
by accident.

4250 5,950.00

Painting on rear tailgate, rear bumper, frt bumper, end
panel & trunk floor

2 - 531

3333 4,255.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

451 531.00

To replace rear windscreen glass

487 574.00

To conduct water leak tests.

63 75.00

To supply and install rear windscreen solar film.

531.00

To check electrical wiring systems for proper function.

150 177.00

To transfer lock mechanism from old to new bootlid
including conduct checks on new bootlid central locking
system for proper function.

451 531.00

To carry out body cavity preservation.
(Per panel).

150 118.00

To carry out body cavity preservation.
(For cut panel).

451? 531.00

To install car I cam recorder

722? 850.00

To supply front and rear emboss number plate.

83 165.00

Sundries.

150.00

Total Labour 1: 14,418.00



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 47797**
Date Estimated : **24/07/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE8118Y	0J00183	08/12/2015	X3 sDrive20	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 31/07/18 @ 1200 Excess S\$ _____Surveyor's Name Rahul Sign _____Surveyor's Tel 90060068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 9-10 days

Labour 1	:	14,418.00
Parts	:	13,156.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,930.24
Grand Total	:	29,505.14

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **