

ASS. REC. BY:

REF: CG/SPF 18013555 / Tirb<sup>52</sup>

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Abdul Rahman of SPF Date/Time: 25072018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLV 68243 Insured: QX 33Cat Workshop m/s Kuh Motor Tel: 9072 1769of 255 Alexandria RdPolicy No: \_\_\_\_\_ Claim No: AEMD / 105 / 009 / 2018 / 082

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 02072018  
(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 25072018 423pm Person Contacted: Sim Hai Vehicle IN OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---------------------------------------------------------------------|
|           | SLV 68243 - X                                                       |
|           | QX 33C - X                                                          |
|           |                                                                     |
|           |                                                                     |
|           | Submit \$6142.20 @ 5 days                                           |
|           | Red: \$5242.45, 46%.                                                |

(08/11/13) wef

ASS. REC. BY:

REF: SPF

## ASSIGNMENT

From: Date: 13/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 68248

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 68248

Yr Regn:

2018, Jan

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda 800 cc 13/8

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

002025

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

175/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

13/8/18 @ 1215

Survey held at

Kah Motor Alexandra

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 31 AUG 2018

Date/Time, File Pass to?

1) typin

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$) 6142.20

780



# SINGAPORE POLICE FORCE

SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333

Your Ref : SLV6824S

Our Ref : AEMD/105/009/2018/082

Date : 25 July 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 #01/02-25  
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

## RTA ON 2 JULY 2018 INVOLVING GOVT VEH QX33C AND OTHER VEH SLV6824S

We refer to the above matter.

- 2 Please arrange for an Inspection of Vehicle No. SLV6824S at M/s Kah Motor Company Sdn Bhd of 255 Alexandra Road, Singapore 159937.
- 3 For appointment, please contact Mr Ng Sin Hai at Tel : 64715419 or HP : 90721769.
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman  
Accident Claims Officer  
for Assistant Director

A FORCE FOR THE NATION

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 02/07/2018 19:18 |
| Date Of Accident           | 02/07/2018 09:15 |
| Exact Location Of Accident | KEPPEL ROAD      |
| Country/State of Loss      | SINGAPORE        |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLV6824S             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | TAY KWANG LIANG      |
| NRIC No                     | S1673658I            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-82685309 |
| Alternative Phone No        | OFFICE-82685309      |

### Vehicle Particulars

|              |              |
|--------------|--------------|
| Manufacturer | HONDA        |
| Model        | JAZZ-1.3 (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
| Type Of Coverage          | COMPREHENSIVE                        |
| Fleet Policy              | NO                                   |
| Policy Number             |                                      |
| Cover Note Number         |                                      |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | TAY KWANG LIANG       |
| NRIC No              | S1673658I             |
| Date Of Birth        | 25/09/1964            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 30/12/1988            |
| Driving Experience   | 29 YEARS AND 6 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-82685309  |
| Fax Number           |                       |
| Contact Number       | OFFICE-82685309       |
| Email Address        | NOEMAIL               |

Address SINGAPORE

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX33C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category GOVERNMENT

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# Sketch Plan

Vehicle No SLV6824S

## SKETCH PLAN

Annex B

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorized Driver.
  3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the insurers or the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available in future.
  8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Signature]*


*[Signature]*

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



Please confirm to Annex C

Vehicle No SLV68248

ASST E

Describe Circumstances of the Accident

refer to police report T/20180702/2066

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



**SINGAPORE  
POLICE FORCE**



T/20180702/2066

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

1 of 3

Report No. T/20180702/2066

**REPORT OF A TRAFFIC ACCIDENT**

|                                            |            |                              |                                                                   |                           |                            |
|--------------------------------------------|------------|------------------------------|-------------------------------------------------------------------|---------------------------|----------------------------|
| Date/Time Report Made:<br>02/07/2018 14:49 |            | Vide Report No.:             |                                                                   | Station Diary No.:<br>126 |                            |
| <b>Informant's Particulars</b>             |            |                              |                                                                   |                           |                            |
| Name of Informant:<br>TAY KWANG LIANG      |            |                              | Address:<br>APT BLK 318 CLEMENTI AVENUE 4 #10-97 SINGAPORE 120318 |                           |                            |
| ID Type / ID No.:<br>NRIC NO / S16736581   |            |                              | Contact No.:<br>Home/Office: Mobile: 82685309                     |                           |                            |
| Nationality:<br>SINGAPORE CITIZEN          |            |                              | Email:                                                            |                           |                            |
| Sex:<br>Male                               | Age:<br>53 | Date of Birth:<br>25/09/1964 | Type of Informant:<br>Driver                                      |                           |                            |
| Race:<br>Chinese                           |            |                              | Language:<br>English                                              |                           | Institution / School Name: |
| Occupation:<br>Landscape architect         |            |                              | Driving Licence Information:<br>Class:                            |                           | Date of Expiry:            |

|                                                              |                              |                                    |                                            |                                    |
|--------------------------------------------------------------|------------------------------|------------------------------------|--------------------------------------------|------------------------------------|
| <b>General Information of the Accident</b>                   |                              |                                    |                                            |                                    |
| Type of Accident:                                            | Non-Injury<br>Police Vehicle | Drink Drive:<br>No                 | Date/Time of Accident:<br>02/07/2018 09:15 | Type of Location:<br>Straight Road |
| Location:<br>Along Road 1<br>KEPPEL ROAD                     |                              |                                    |                                            |                                    |
| Towards Downtown Direction                                   |                              |                                    |                                            |                                    |
| Weather:<br>Clear                                            |                              | Road Surface:<br>Dry               | Road Speed Limit:                          |                                    |
| Traffic Flow:<br>One Way                                     |                              | Traffic Control:<br>Not Controlled | Traffic Volume:<br>Heavy                   |                                    |
| Type of Collision:<br>Between Moving Vehicles - Head To Rear |                              |                                    | Anyone conveyed by ambulance:<br>No        |                                    |

| Details of Vehicle Involved |      |        |              |       |                  |                 |
|-----------------------------|------|--------|--------------|-------|------------------|-----------------|
| Vehicle No.                 | Type | Make   | Model        | Color | Condition        | No of Passenger |
| QX33C                       | Car  | SUBARU | IMPREZA      | White | Slightly Damaged | 0               |
| SLV6824S                    | Car  | HONDA  | JAZZ 1.3 CVT | Blue  | Slightly Damaged | 0               |

| Details of Vehicle Insurance |                                       |               |            |             |
|------------------------------|---------------------------------------|---------------|------------|-------------|
| Vehicle No.                  | Insurance Company                     | Insurance No. | Effective  | Expiry Date |
| SLV6824S                     | TOKIO MARINE INSURANCE SINGAPORE LTD. | MU012972      | 10/01/2018 | 09/01/2020  |



**SINGAPORE  
POLICE FORCE**



T/20180702/2066

2 of 3

Police Station Of Origin:

Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-6729999

Report No. T/20180702/2066

**CONTINUATION OF REPORT**

**Brief Details.**

On the above mentioned date, time and location, I was driving my car bearing the said registration plate number heading towards my work place. At the point of time, my car was in a stationary mode as the lights were red.

Suddenly I felt a impact coming from the rear of my car. I got down and discovered that a police car bearing the said registration plate behind me had collided into my car. No one was injured at the point of time and we exchange particulars.

This is the first time such incident happened to me and there is in-car camera installed in my car.



**SINGAPORE  
POLICE FORCE**



T/20180702/2066

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8728999

3 of 3

Report No. T/20180702/2066

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
D /  
Staff Sgt CLEMENT CHEE WEI JUN


Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
02/07/2018 14:49

Officer In Charge Of Case:  
TP / DDGVT /  
Sr Staff Sgt LIM JUN HUI, ADRIAN  
Contact No.: 65476350

Classification Of Case:

|                                                                                                                                              |                                                                                           |
|----------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|
|  <b>Authentication Stamp</b><br>SINGAPORE<br>POLICE FORCE |  SN 37 |
| SIGNATURE                                                                                                                                    |                                                                                           |

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **S16736581**

Name: **TAY KWANG LIANG**

Birth Date: **25 Sep 1964**  
Issue Date: **20 May 2003**

1000518724B



**REPUBLIC OF SINGAPORE**  
IDENTITY CARD NO. **S16736581**



Name: **TAY KWANG LIANG**

**鄭廣良**

Place: **CHINESE**

Date of Birth: **25-09-1964** Sex: **M**

Country of Birth: **SINGAPORE**



S16736581

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

| Class   | Description                                                                              | PASS DATE   |
|---------|------------------------------------------------------------------------------------------|-------------|
| Class 3 | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 30 Dec 1988 |

NP 428A

Licence No: **S16736581**



**A0051161**



NRIC No: **S16736581**



Blood Group: **B+** Date of issue: **13-08-2001**

Address: **APT BLK 318 CLEMENTI AVENUE 4  
#10-97  
SINGAPORE 120318**

8261  
5301  
WHD

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SINGAPORE POLICE  
 TANGLIN POST OFFICE  
 PO BOX 60  
 SINGAPORE 912402

Registration No : SLV6824S  
 Chassis No : JHMGK3850JX204564  
 Model : JAZZ 1.3LXR CVT 18YM (EURO 6)  
 Owner's Name : TAY KWANG LIANG  
 Ins Policy No. :  
 Date of Accident : 2/7/2018

Document No. : SQT18002726  
 Date : 3. Jul 2018  
 Customer No. : SP0000001  
 Svc Advisor : NG SIN HAI  
 Engine No : L13B11030034  
 Date | Time : 3. Jul 2018 2:47:17 PM  
 Surveyor Name :  
 Survey Date :  
 Authorisation Date :

Page 1

| Item            | Description                                                                                                                                                                                    | Qty                      | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|------------|--------|--------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER:TAY KWANG LIANG<br>OWNER INSURER:TOKIO MARINE<br>ACC DATE:02/07/2018<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER:SINGAPORE POLICE<br>TP VEH:QX33C |                          |            |        |        |               |                  |
| NMRS-4P-TM3040L | 4PCS ACT RR.SENSOR                                                                                                                                                                             | 1 <sup>un</sup> R        | 320.00     |        | 320.00 | 22.40         | 342.40           |
| BO-NUM-COMP-L   | NUMBER PLATE WITH CASING-L(N)                                                                                                                                                                  | 1 <sup>un</sup> X        | 45.00      |        | 45.00  | 3.15          | 48.15            |
| 68100-TAR-U10ZZ | TAILGATE COMP ✓                                                                                                                                                                                | 1 <sup>bt</sup> 716.30   |            | 25     | 537.22 | 37.61         | 574.83           |
| 74440-T5A-003   | WEATHERSTRIPTAILGATE                                                                                                                                                                           | 1 <sup>un</sup> R 92.30  |            | 25     | 69.22  | 4.85          | 74.07            |
| 74801-T5S-K01   | LOCK ASSY,TAILGATE                                                                                                                                                                             | 1 <sup>un</sup> X 77.10  |            | 25     | 57.82  | 4.05          | 61.87            |
| 74810-S6A-003   | HANDLETAILGATE                                                                                                                                                                                 | 1 <sup>un</sup> X 59.20  |            | 25     | 44.40  | 3.11          | 47.51            |
| 75722-T5L-T01   | EMBLEMRR. ✓                                                                                                                                                                                    | 1 <sup>un</sup> R 10.50  |            | 25     | 7.87   | 0.55          | 8.42             |
| 74890-T5A-A11   | GARN ASSY,RR LICE                                                                                                                                                                              | 1 <sup>un</sup> X 103.40 |            | 25     | 77.55  | 5.43          | 82.98            |
| 34100-S60-013   | LIGHT ASSYLICENCE                                                                                                                                                                              | 2 <sup>un</sup> X 33.40  |            | 25     | 50.10  | 3.51          | 53.61            |
| 04715-T5A-J50ZZ | FACE,RR.BUMPER ✓                                                                                                                                                                               | 1 <sup>un</sup> R 492.70 |            | 25     | 369.52 | 25.87         | 395.39           |
| 71502-T5A-J60   | COVER,R.RR.BUMPER                                                                                                                                                                              | 1 <sup>un</sup> R 20.30  |            | 25     | 15.22  | 1.07          | 16.29            |
| 71503-T5A-J50   | COVER,RR.EXPI FIN                                                                                                                                                                              | 1 <sup>un</sup> R 9.10   |            | 25     | 6.82   | 0.48          | 7.30             |
| 71505-T5A-J50   | GARNISH,RR.BUMPER ✓                                                                                                                                                                            | 1 <sup>un</sup> R 37.50  |            | 25     | 28.12  | 1.97          | 30.09            |
| 71507-T5A-J60   | COVER,L.RR.BUMPER                                                                                                                                                                              | 1 <sup>un</sup> X 20.30  |            | 25     | 15.22  | 1.07          | 16.29            |
| 71593-T5A-J50   | SPACER,R.RR.BUMPER SIDE ✓                                                                                                                                                                      | 1 <sup>un</sup> R 16.60  |            | 25     | 12.45  | 0.87          | 13.32            |
| 71598-T5A-J50   | SPACER,L.RR.BUMPER SIDE ✓                                                                                                                                                                      | 1 <sup>un</sup> R 16.60  |            | 25     | 12.45  | 0.87          | 13.32            |
| 91505-TM8-003   | CLIPBUMPER ✓                                                                                                                                                                                   | 7 <sup>un</sup> R 2.00   |            | 25     | 10.50  | 0.74          | 11.24            |
| 66100-TAR-T00ZZ | PANEL COMPRR.                                                                                                                                                                                  | 1 <sup>un</sup> R 314.00 |            | 25     | 235.50 | 16.49         | 251.99           |
| 84640-T5A-003ZA | LINING ASSYRR.PANEL                                                                                                                                                                            | 1 <sup>un</sup> R 60.80  |            | 25     | 45.60  | 3.19          | 48.79            |
| 73127-TY0-000   | RUBBER CWINDSHIELD DAMPER ✓                                                                                                                                                                    | 1 <sup>un</sup> R 11.20  |            | 25     | 8.40   | 0.59          | 8.99             |
| 73214-T5A-013   | RUBBERWINDSHIELD DAMPER ✓                                                                                                                                                                      | 2 <sup>un</sup> R 6.30   |            | 25     | 9.45   | 0.66          | 10.11            |

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SINGAPORE POLICE  
TANGLIN POST OFFICE  
PO BOX 60  
SINGAPORE 912402

Registration No : SLV6824S

Chassis No : JHMGK3850JX204564

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : TAY KWANG LIANG

Ins Policy No. :

Date of Accident : 2/7/2018

Document No. : SQT18002726

Date : 3. Jul 2018

Customer No. : SP0000001

Svc Advisor : NG SIN HAI

Engine No : L13B11030034

Date | Time : 3. Jul 2018 2:47:17 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

| Item          | Description                                        | Qty          | Unit Price | Disc % | Amount         | 0% GST Amount | Amount incld GST |
|---------------|----------------------------------------------------|--------------|------------|--------|----------------|---------------|------------------|
| 73226-SZW-000 | DAMPERSTD 5X5                                      | 1 <i>del</i> | 8.30       | 25     | 6.22           | 0.44          | 6.66             |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N)                             | 2 <i>del</i> | 60.00      |        | 120.00         | 8.40          | 128.40           |
| Sum Item      |                                                    |              |            |        | <b>2104.65</b> | <b>147.37</b> | <b>2,252.02</b>  |
| BOSUN         | SUNDRIES                                           | 1 <i>del</i> | 100.00     |        | 100.00         | 7.00          | 107.00           |
| BA02R         | REMOVE & RENEW REVERSE SENSORS-4PCS (N)            | 1 <i>del</i> | 180.00     |        | 180.00         | 12.60         | 192.60           |
| BOJSE         | SEALANT FOR REAR END PANEL                         | 1 <i>del</i> | 80.00      |        | 80.00          | 5.60          | 85.60            |
| BOJSE         | SEALANT FOR TAILGATE                               | 1 <i>del</i> | 80.00      |        | 80.00          | 5.60          | 85.60            |
| BML02I        | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER      | 1 <i>del</i> | 180.00     |        | 180.00         | 12.60         | 192.60           |
| BMI02D        | REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK      | 1 <i>del</i> | 560.00     |        | 560.00         | 39.20         | 599.20           |
| BKTG02R       | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &  | 1 <i>del</i> | 560.00     |        | 560.00         | 39.20         | 599.20           |
| BG02D         | REMOVE & INSTALL RR. WINDSCREEN.(N)                | 1 <i>del</i> | 560.00     |        | 560.00         | 39.20         | 599.20           |
| BODAMKIT      | WINDSCREEN DAM KIT.                                | 1 <i>del</i> | 100.00     |        | 100.00         | 7.00          | 107.00           |
| BKRP02M       | CUT OFF & RENEW RR PANEL.                          | 1 <i>del</i> | 3500.00    |        | 3500.00        | 245.00        | 3745.00          |
| BP06R         | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1 <i>del</i> | 3000.00    |        | 3000.00        | 210.00        | 3210.00          |
| BKBU01R       | REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA          | 1 <i>del</i> | 380.00     |        | 380.00         | 26.60         | 406.60           |
| Sum Labor     |                                                    |              |            |        | <b>9280.00</b> | <b>649.60</b> | <b>9,929.60</b>  |

Survey By

Date &amp; Time

Excess

Status

Signature

Total Amount 11,384.65 796.97 12,181.62

Total (Inclusive of GST) **12,181.62**

Printed on 3/7/2018 3:01:00 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Passy before paint*

*05 B dgs*

*sure the hands.com*



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer: SP0000001 / SINGAPORE  
Chassis No: JHMGK3850JX204564  
License No: SLV6824S  
Mileage: 1085  
Engine No: L13B11030034

Document No: SVO18044745  
Printed By: SHNG  
Order Date: 31. July 2018  
Order Time: 6:57:05 PM  
Service Advisor: NG SIN HAI

| ITEM            | DESCRIPTION                                                                                                                                                                                                     | QTY | UNIT PRICE | DISC % | AMOUNT          | 7% GST Amount | Amount incld GST |
|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|-----------------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER:TAY KWANG LIANG<br>OWNER INSURER:TOKIO MARINE<br>ACC DATE:02/07/2018<br>SURVEYED BY:TAUFIKH<br>DATE:13/08/2018<br>REF NO:<br>TP INSURER:SINGAPORE POLICE<br>TP VEH:QX33C |     |            |        |                 |               |                  |
| 68100-TAR-U10ZZ | TAILGATE COMP                                                                                                                                                                                                   | 1   | 716.30     | 25     | 537.22          | 37.61         | 574.83           |
| 75722-T5L-T01   | EMBLEMRR.                                                                                                                                                                                                       | 1   | 10.50      | 25     | 7.87            | 0.55          | 8.42             |
| 04715-T5A-J50ZZ | FACE,RR.BUMPER                                                                                                                                                                                                  | 1   | 492.70     | 25     | 369.52          | 25.87         | 395.39           |
| 71505-T5A-J50   | GARNISH,RR.BUMPER                                                                                                                                                                                               | 1   | 37.50      | 25     | 28.12           | 1.97          | 30.09            |
| 71593-T5A-J50   | SPACER,R.RR.BUMPER SIDE                                                                                                                                                                                         | 1   | 16.60      | 25     | 12.45           | 0.87          | 13.32            |
| 71598-T5A-J50   | SPACER,L.RR.BUMPER SIDE                                                                                                                                                                                         | 1   | 16.60      | 25     | 12.45           | 0.87          | 13.32            |
| 91505-TM8-003   | CLIPBUMPER                                                                                                                                                                                                      | 7   | 2.00       | 25     | 10.50           | 0.74          | 11.24            |
| 73127-TY0-000   | RUBBER CWINDOWSHIELD DAMPER                                                                                                                                                                                     | 1   | 11.20      | 25     | 8.40            | 0.59          | 8.99             |
| 73214-T5A-013   | RUBBERWINDOWSHIELD DAMPER                                                                                                                                                                                       | 2   | 6.30       | 25     | 9.45            | 0.66          | 10.11            |
| 73226-SZW-000   | DAMPERSTD 5X5                                                                                                                                                                                                   | 1   | 8.30       | 25     | 6.22            | 0.44          | 6.66             |
| BO-WS-SEALANT   | WINDSCREEN SEALANT (N)                                                                                                                                                                                          | 2   | 60.00      |        | 120.00          | 8.40          | 128.40           |
|                 | <b>SUM PARTS:</b>                                                                                                                                                                                               |     |            |        | <b>1,122.20</b> | <b>78.57</b>  | <b>1,200.77</b>  |
| BOSUN           | 0701<br>SUNDRIES                                                                                                                                                                                                | 1   | 30.00      |        | 30.00           | 2.10          | 32.10            |
| BA02R           | 0701<br>REMOVE & RENEW REVERSE<br>SENSORS-4 PCS (N)                                                                                                                                                             | 1   | 180.00     |        | 180.00          | 12.60         | 192.60           |
| BML02I          | 1438<br>INSPECT RR LIGHTING MECHANISMS.<br>PERFORM WATER<br>TEST.(N)                                                                                                                                            | 1   | 180.00     |        | 180.00          | 12.60         | 192.60           |
| BMI02D          | 1438<br>REMOVE & INSTALL SPEAKER BOARD<br>RR SEATS TRUNK<br>LININGS GARNISHES & ETC.(N)                                                                                                                         | 1   | 280.00     |        | 280.00          | 19.60         | 299.60           |
| BKTG02R         | 1729<br>REMOVE & TRANSFER ITEMS TO NEW<br>TAILGATE. ADJUST &<br>ALIGN TAILGATE.(N)                                                                                                                              | 1   | 280.00     |        | 280.00          | 19.60         | 299.60           |
| BG02D           | 1438<br>REMOVE & INSTALL RR. WINDSCREEN.<br>(N)                                                                                                                                                                 | 1   | 560.00     |        | 560.00          | 39.20         | 599.20           |
| BODAMKIT        | 0701<br>WINDSCREEN DAM KIT.                                                                                                                                                                                     | 1   | 100.00     |        | 100.00          | 7.00          | 107.00           |
| BKRP02M         | 1729<br>CUT OFF & RENEW RR PANEL<br>RR FLOOR PAN & RENEW DAMAGE<br>PARTS.                                                                                                                                       | 1   | 1,680.00   |        | 1,680.00        | 117.60        | 1,797.60         |
| BP06R           | 1718<br>SPRAY PAINTING ON REPAIRED OR<br>REPLACED AREAS. (6P)<br>REAR PORTION                                                                                                                                   | 1   | 1,350.00   |        | 1,350.00        | 94.50         | 1,444.50         |



## SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer:** SP0000001 / SINGAPORE

**Chassis No:** JHMGK3850JX204564

**License No:** SLV6824S

**Mileage:** 1085

**Engine No:** L13B11030034

**Document No:** SVO18044745

**Printed By:** SHNG

**Order Date:** 31. July 2018

**Order Time:** 6:57:05 PM

**Service Advisor:** NG SIN HAI

|         |                                              |   |                    |                 |               |                 |
|---------|----------------------------------------------|---|--------------------|-----------------|---------------|-----------------|
| BKBU01R | 0701                                         | 1 | 380.00             | 380.00          | 26.60         | 406.60          |
|         | REMOVE, RE-FIX AND ALIGN REAR<br>VIEW CAMERA |   |                    |                 |               |                 |
|         |                                              |   | <b>SUM LABOUR:</b> | <b>5,020.00</b> | <b>351.40</b> | <b>5,371.40</b> |
|         |                                              |   | <b>TOTAL SGD</b>   | <b>6,142.20</b> | <b>429.97</b> | <b>6,572.17</b> |

**Total Payable (SGD)** **6,572.17**

GST Amount is calculated from individual line(s)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18013555/T1rbs2

ACCIDENT CLAIM SECTION (SINGAPORE POLICE  
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD  
POLICE ACADEMY SINGAPORE 298333

Date : 03-09-2018



ATTN: ABDUL RAHMAN

Code : SPF

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                       |                |            |
|--------------|-----------------------|----------------|------------|
| Insured Veh. | QX 33C                | Veh. Inspected | SLV 6824S  |
| Policy No.   |                       | Coverage (\$)  | 0.00       |
| Claim No.    | AEMD/105/009/2018/082 | Excess (\$)    | 0.00       |
| Assign From  | ABDUL RAHMAN          | Assign Date    | 25/07/2018 |

## 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | HONDA JAZZ        | c.c          | 1318       |
| Engine No.   | HIDDEN            | Year of Reg. | 2018       |
| Chassis No.  | JHMGK3850JX204564 | Colour       | BLUE       |
| Odometer     | 008025            | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

## 3. Conditions of Tyres

|                | Size      | Make     | Balance |
|----------------|-----------|----------|---------|
| R/H Front Tyre | 175/65R15 | YOKOHAMA | 6 mm    |
| L/H Front Tyre | 175/65R15 | YOKOHAMA | 6 mm    |
| R/H Rear Tyre  | 175/65R15 | YOKOHAMA | 6 mm    |
| L/H Rear Tyre  | 175/65R15 | YOKOHAMA | 6 mm    |

## 4. Description of Damages

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

## 5. General Information

|                |                                                                       |                 |            |
|----------------|-----------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 02/07/2018                                                            | Inspection Date | 13/08/2018 |
| Survey held at | KAH MOTOR CO SDN BERHAD<br>NO. 255 ALEXANDRA ROAD<br>SINGAPORE 159937 |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6824S

| Qty                                            | Description of Parts            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------------------|---------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b>             |                                 |                      |                           |                   |
| 4                                              | ACT RR. SENSOR (SN)             | NOT NECESSARY        | 320.00                    | -                 |
| 1                                              | NUMBER PLATE WITH CASING-L (SN) | NOT NECESSARY        | 45.00                     | -                 |
| 1                                              | TAILGATE COMP (SN)              | BENT                 | 537.22                    | 537.22            |
| 1                                              | WEATHERSTRIP TAILGATE (SN)      | NOT NECESSARY        | 69.22                     | -                 |
| 1                                              | LOCK ASSY, TAILGATE (SN)        | NOT NECESSARY        | 57.82                     | -                 |
| 1                                              | HANDLE TAILGATE (SN)            | NOT NECESSARY        | 44.40                     | -                 |
| 1                                              | EMBLEMRR. (SN)                  | NECESSARY            | 7.87                      | 7.87              |
| 1                                              | GARN ASSY,RR LICE (SN)          | NOT NECESSARY        | 77.55                     | -                 |
| 2                                              | LIGHT ASSYLICENCE (SN)          | NOT NECESSARY        | 50.10                     | -                 |
| 1                                              | FACE,RR.BUMPER (SN)             | DEFORMED             | 369.52                    | 369.52            |
| 1                                              | COVER,R.RR.BUMPER (SN)          | NOT NECESSARY        | 15.22                     | -                 |
| 1                                              | COVER,RR.EXPI FIN (SN)          | NOT NECESSARY        | 6.82                      | -                 |
| 1                                              | GARNISH,RR.BUMPER (SN)          | DEFORMED             | 28.12                     | 28.12             |
| 1                                              | COVER,L.RR.BUMPER (SN)          | NOT NECESSARY        | 15.22                     | -                 |
| 1                                              | SPACER,R.RR.BUMPER SIDE (SN)    | NECESSARY            | 12.45                     | 12.45             |
| 1                                              | SPACER,L.RR.BUMPER SIDE (SN)    | NECESSARY            | 12.45                     | 12.45             |
| 7                                              | CLIP BUMPER (SN)                | NECESSARY            | 10.50                     | 10.50             |
| 1                                              | PANEL COMPRR. (SN)              | TO REPAIR SEE LABOUR | 235.50                    | -                 |
| 1                                              | LINING ASSYRR.PANEL (SN)        | NOT NECESSARY        | 45.60                     | -                 |
| 1                                              | RUBBER CWINDSHIELD DAMPER (SN)  | NECESSARY            | 8.40                      | 8.40              |
| 2                                              | RUBBERWINDSHIELD DAMPER (SN)    | NECESSARY            | 9.45                      | 9.45              |
| 1                                              | DAMPERSTD 5X5 (SN)              | NECESSARY            | 6.22                      | 6.22              |
| 2                                              | WINDSCREEN SEALANT (SN)         | NECESSARY            | 120.00                    | 120.00            |
| 1                                              | SUNDRIES (SN)                   | NECESSARY            | 100.00                    | 30.00             |
| 1                                              | SEALANT FOR REAR END PANEL (SN) | NOT NECESSARY        | 80.00                     | -                 |
| 1                                              | SEALANT FOR TAILGATE (SN)       | NOT NECESSARY        | 80.00                     | -                 |
|                                                |                                 |                      | 2,364.65                  | 1,152.20          |
| <b><u>LABOUR</u></b>                           |                                 |                      |                           |                   |
| REMOVE & RENEW REVERSE SENSORS.                |                                 |                      | 180.00                    | 180.00            |
| INSPECT RR LIGHTING MECHANISMS. PERFORM WATER. |                                 |                      | 180.00                    | 180.00            |
| REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK. |                                 |                      | 560.00                    | 280.00            |

Report Ref No. CS/SPF18013555/T1rbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                | Description of Parts                                               | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                                    | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.                 |           | 560.00                    | 280.00            |
|                                    | REMOVE & INSTALL RR. WINDSCREEN.                                   |           | 560.00                    | 560.00            |
|                                    | WINDSCREEN DAM KIT.                                                |           | 100.00                    | 100.00            |
|                                    | CUT OFF & RENEW RR PANEL. INCLUSIVE OF THE REPAIR OF PANEL COMPRR. |           | 3,500.00                  | 1,680.00          |
|                                    | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.                      |           | 3,000.00                  | 1,350.00          |
|                                    | REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA.                         |           | 380.00                    | 380.00            |
|                                    |                                                                    |           | 9,020.00                  | 4,990.00          |
|                                    | <b>GRAND TOTAL</b>                                                 |           | <b>11,384.65</b>          | <b>6,142.20</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                    |           |                           | <b>6,142.20</b>   |

Report Ref No. CS/SPF18013555/T1rbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.