OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel: +65 6472 1313 Fax: +65 6472 2112

Branch office: 9A Serangoon North Ave 5 Singapore 554500 Tel: +65 6484 9919 Fax: +65 6481 1011

Co. Reg. No. 201212455W

Date:

24 JULY 2018

Third Party Insurer:

AIG

Vehicle No:

SDZ66B

Third Party Veh No:

SKR6824A

Model:

MERCEDES-BENZ C200-1.8 (A)

Date of Accident:

21 MAY 2018

Chassis:

WDD2050422R303264 - 2017

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH		1 \$1,550.00
1	FRONT DOOR WEATHER STRIP RH		ル へ \$270.00
		SUB TOTAL	\$1,820.00
		Less 10%	-\$182.00
		PARTS TOTAL	\$1,638.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$750.00 **25**-1 484 \$750.00 25-1

TO TUFF KOTE / ANTI-RUST

~~ \$60.00 X

TO CHECK WIRING WITH WATER LEAKAGE TEST

\$80.00 201

TO DISMANTLE & REINSTALL FRONT RH DOOR INNER COMPONENT MECHANISM

TO FACILITATE REPAIR WITH CHECK FOR FUNCTION

12 \$180.00 X

LABOUR TOTAL

\$1,820.00

PUI THENG

\$3,458.00

Not Norhanks
Ruhmay Afte Pains
Zday,

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1