

INSURANCE

INS. CASE OWNER:

CC 6/AIG1801

7610, 11/1/18

LINK:

IDAC:

Surveyor:

Taufik

DOI:

ASSIGNMENT

11/1/18

Date / Time:

11/1/18

Registered in Merit:

11/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SW 7425K

Claim No.:

7769109856

Name of Insured:

SIS TECHNOLOGIES (THAILAND) P/L

Policy No.:

210047779-08

Insured Tel No.:

HP:

Make / Model:

MERCEDES

Excess Sec II :SS

D.O.A.:

12/1/18

Place of Accident:

LOWER BELUKO

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Um HWEI HAT

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(VL: YES / NO)

Insured Liability:

Final ? Yes / No

SW 7425K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pegasus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

11/1/18
TH

12/3/2020
Kluang

SW 7425K-x

SW 7425K-x

File pass to mk to close

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

> 19/1/18 Kluang

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject-Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PIP

SS 5,201.20

(8 days) Reduction:

9 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

100%

SS

5,201.20

(Agreed / Assessed) BOLA S/N No.:

WIL

If NO or B 28, Ass. Lia:

Repair Cost:

6,565.25

SS

1,782.64

Loss of Rental (LOR):

SS

550

(11 days)

x \$ 100

Loss of Use (LOU):

SS

-

(S - x - days)

Loss of Income (LOI):

SS

-

(S - x - days)

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

749

SS

7.99

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$

320

Total:

6,677.77

SS

3,340.13

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3,340.13

Name 1:

PEGASUS ENGINEERING & TRADING PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

8/3/2021



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18013610/T1ub3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 26-07-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKW 7425K	Veh. Inspected	SLP 7835K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/07/2018	Inspection Date	24/07/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 528500 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573900 Attn : Tel : Fax No. :
--	--

Quotation No. : QO18/07-1227	Quotation Date : 17/07/2018	Terms : 30 DAYS
Vehicle No. : SLP7835K	Chassis No. : MHF528F3502011948	Third Party Insurer :
Model : VIOS	Date of Accident : 17/07/2018	
Remarks : INSURED'S VEH NO: SKW7425K		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT DOOR SIDE MIRROR ASSY	1	1,212.7000	1,212.70
2	FRONT DOOR RH	1	1,090.6000	1,090.60
3	FRONT DOOR HINGE TOP	1	82.1000	82.10
4	FRONT DOOR HINGE BOTTOM	1	92.1000	92.10
5	FRONT DOOR CHECKER/ARRESTOR	1	153.6000	153.50
6	FRONT DOOR POWER WINDOW MOTOR	1	690.2000	690.20
7	FRONT DOOR REGULATOR	1	230.2000	230.20
8	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	96.9000	96.90
9	FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	46.5000	46.50
10	FRONT DOOR RUBBER STOPPER	1	18.2000	18.20
11	FRONT DOOR WEATHERSTRIP	1	199.1000	199.10
12	FRONT FENDER RH	1	612.5000	612.50
13	FRONT FENDER INNER COWLING RH	1	165.0000	165.00
14	FRONT FENDER INNER COWLING CLIP	4	4.3000	17.20
15	FRONT FENDER 1/4 GARNISH TOP	1	30.7000	30.70
16	FRONT SHOCK ABSORBER	1	378.7000	378.70
17	FRONT SHOCK ABSORBER TOP MOUNT	1	65.0000	65.00
18	FRONT WHEEL BEARING WITH HUB	1	498.2000	498.20
19	FRONT WHEEL KNUCKLE	1	549.6000	549.60
20	FRONT LOWER ARM	1	1,021.1000	1,021.10
21	ROCKER PANEL	1	332.3000	332.30
22	REAR DOOR RH	1	891.8000	891.80
23	REAR DOOR OUTER WEATHERSTRIP MOULDING	1	96.9000	96.90

2797.10
 698.27
 2097.83

C/F 0.00
Page 1 of 4

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :		Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :		GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/07-1227	Quotation Date : 17/07/2018	Terms : 30 DAYS
Vehicle No. : SLP7835K	Chassis No. : MHFB29F3502011948	Thrd Party Insurer :
Model : VIOS		Date of Accident : 17/07/2018
Remarks : INSURED'S VEH NO: SKW7425K		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR DOOR 1/4 GLASS PILLAR	1	119.3000	? 119.30 X un
25	REAR DOOR 1/4 GLASS PILLAR WEATHERSTRIP	1	98.6000	? 98.60 X un
26	REAR DOOR INNER LOCK	1	483.4000	X 483.40 un
27	REAR DOOR LOCK STRIKER	1	37.6000	X 37.60 un
28	REAR DOOR WEATHERSTRIP	1	174.4000	? 174.40 X un
29	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	73.6000	? 73.60 X un
30	REAR DOOR WINDOW FRAME STICKER MATT	1	46.5000	we 46.50
31	REAR DOOR WINDOW FRAME STICKER FRONT	1	46.5000	we 46.50
32	REAR DOOR POWER WINDOW MOTOR	1	590.2000	? 590.20 X
33	REAR DOOR REGULATOR	1	183.6000	X 183.60 un
34	REAR DOOR INNER TRIMBOARD	1	539.4000	X 539.40
35	REAR DOOR HINGE TOP	1	38.0000	XX 38.00
36	REAR DOOR HINGE BOTTOM	1	38.0000	Ry 38.00
37	REAR DOOR CHECKER/ARRESTOR	1	153.5000	X 153.50 un
38	REAR FENDER RH	1	989.6000	Ry 989.60
39	REAR FENDER INNER COWLING RH	1	395.1000	X 395.10 un
40	REAR FENDER INNER COWLING CLIPS	4	4.3000	X 17.20 un
41	REAR FENDER 1/4 GARNISH	1	54.7000	X 54.70 un
42	REAR SHOCK ABSORBER	1	378.7000	? 378.70 X un
43	REAR WHEEL BEARING WITH HUB	1	492.8000	? 492.80 X un
44	REAR WHEEL KNUCKLE	1	221.4000	? 221.40 X un
45	FRONT BUMPER	1	588.1000	Ry 588.10

C/F 0.00
Page 2 of 4

93.25
23.25
69.75

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
--	--

Quotation No. : QO18/07-1227	Quotation Date : 17/07/2018	Terms : 30 DAYS
Vehicle No. : SLP7835K	Chassis No. : MHFB29F3502011948	Third Party Insurer :
Model : VIOS	Date of Accident : 17/07/2018	
Remarks : INSURED'S VEH NO: SKW7425K		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
46	FRONT BUMPER SIDE RETAINER RH	1	65.7000	X 65.70
47	FRONT BUMPER CLIPS	6	4.3000	X 25.80
48	REAR BUMPER	1	504.9000	X 504.90
49	REAR BUMPER SIDE RETAINER RH	1	115.1000	X 115.10
50	REAR BUMPER CLIPS	6	4.3000	X 25.80
51	DOOR CENTRE B PILLAR	1	332.3000	X 332.30
52	DOOR CENTRE B PILLAR MATT BLACK TAPE	1	31.5000	31.50
53	REAR WINDSHIELD GLASS WEATHERSTRIP	1	120.0000	X 120.00
54	LESS 25% ON ITEM 1 - 57	1	-3,888.1000	-3,888.10
55	FRONT WHEEL TYRE RH	1	250.0000	X 250.00
56	FRONT WHEEL RIM RH	1	550.0000	550.00
57	REAR WHEEL TYRE RH	1	250.0000	X 250.00
58	REAR WHEEL RIM RH	1	550.0000	550.00
59	REAR WINDSCREEN GLASS SEALANT	1	100.0000	X 100.00
60	REAR WINDSCREEN GLASS SPONGE	1	120.0000	X 120.00
61	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	120.0000	X 120.00
62	TO TRANSFER OF REAR TYRE, RIM AND ON WHEEL BALANCING	1	100.0000	60 100.00
63	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	120.0000	80 120.00
64	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	60 150.00
65	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000	60 120.00
66	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	100.0000	30 100.00

C/F 0.00

Page 3 of 4

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1227	Quotation Date : 17/07/2018	Terms : 30 DAYS
Vehicle No. : SLP7835K	Chassis No. : MHFB29F3502011948	Third Party Insurer :
Model : VIOS	Date of Accident : 17/07/2018	
Remarks : INSURED'S VEH NO: SKW7425K		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT DOOR SIDE MIRROR ASSY	1	1,212.7000	Ry 1,212.70
2	FRONT DOOR RH	1	1,090.6000	bt 1,090.60
3	FRONT DOOR HINGE TOP	1	82.1000	Ry 82.10
4	FRONT DOOR HINGE BOTTOM	1	92.1000	Ry 92.10
5	FRONT DOOR CHECKER/ARRESTOR	1	153.5000	Ry 153.50
6	FRONT DOOR POWER WINDOW MOTOR	1	690.2000	? 690.20
7	FRONT DOOR REGULATOR	1	230.2000	? 230.20
8	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	96.9000	x 96.90
9	FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	46.5000	x 46.50
10	FRONT DOOR RUBBER STOPPER	1	18.2000	x 18.20
11	FRONT DOOR WEATHERSTRIP	1	199.1000	? 199.10
12	FRONT FENDER RH	1	612.5000	bt 612.50
13	FRONT FENDER INNER COWLING RH	1	185.0000	de 185.00
14	FRONT FENDER INNER COWLING CLIP	4	4.3000	uey 17.20
15	FRONT FENDER 1/4 GARNISH TOP	1	30.7000	x 30.70
16	FRONT SHOCK ABSORBER Ry	1	378.7000	? 378.70
17	FRONT SHOCK ABSORBER TOP MOUNT Ry	1	65.0000	? 65.00
18	FRONT WHEEL BEARING WITH HUB Ry	1	498.2000	? 498.20
19	FRONT WHEEL KNUCKLE Ry	1	549.6000	? 549.60
20	FRONT LOWER ARM Ry	1	1,021.1000	? 1,021.10
21	ROCKER PANEL Ry	1	332.3000	Ry 332.30
22	REAR DOOR RH	1	891.8000	bt 891.80
23	REAR DOOR OUTER WEATHERSTRIP MOULDING	1	96.9000	x 96.90

C/F 0.00

Page 1 of 4

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1227	Quotation Date : 17/07/2018	Terms : 30 DAYS
Vehicle No. : SLP7835K	Chassis No. : MHFB29F3502011948	Third Party Insurer :
Model : VIOS	Date of Accident : 17/07/2018	
Remarks : INSURED'S VEH NO: SKW7425K		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	REAR DOOR 1/4 GLASS PILLAR	1	119.3000	? 119.30
25	REAR DOOR 1/4 GLASS PILLAR WEATHERSTRIP	1	98.6000	? 98.60
26	REAR DOOR INNER LOCK	1	483.4000	X 483.40
27	REAR DOOR LOCK STRIKER	1	37.6000	X 37.60
28	REAR DOOR WEATHERSTRIP	1	174.4000	? 174.40
29	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	73.6000	? 73.60
30	REAR DOOR WINDOW FRAME STICKER MATT	1	46.5000	W 46.50
31	REAR DOOR WINDOW FRAME STICKER FRONT	1	46.5000	W 46.50
32	REAR DOOR POWER WINDOW MOTOR	1	590.2000	X 590.20
33	REAR DOOR REGULATOR	1	183.6000	X 183.60
34	REAR DOOR INNER TRIMBOARD	1	539.4000	X 539.40
35	REAR DOOR HINGE TOP	1	38.0000	R 38.00
36	REAR DOOR HINGE BOTTOM	1	38.0000	R 38.00
37	REAR DOOR CHECKER/ARRESTOR	1	153.5000	X 153.50
38	REAR FENDER RH	1	969.6000	R 969.60
39	REAR FENDER INNER COWLING RH	1	395.1000	X 395.10
40	REAR FENDER INNER COWLING CLIPS	4	4.3000	X 17.20
41	REAR FENDER 1/4 GARNISH	1	54.7000	X 54.70
42	REAR SHOCK ABSORBER	1	378.7000	? 378.70
43	REAR WHEEL BEARING WITH HUB	1	492.8000	? 492.80
44	REAR WHEEL KNUCKLE	1	221.4000	? 221.40
45	FRONT BUMPER	1	588.1000	R 588.10

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1227	Quotation Date : 17/07/2018	Terms : 30 DAYS
Vehicle No. : SLP7835K	Chassis No. : MHFB29F3502011948	Third Party Insurer :
Model : VIOS	Date of Accident : 17/07/2018	
Remarks : INSURED'S VEH NO: SKW7425K		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	FRONT BUMPER SIDE RETAINER RH	1	65.7000	X 65.70
47	FRONT BUMPER CLIPS	6	4.3000	X 25.80
48	REAR BUMPER	1	504.9000	X 504.90
49	REAR BUMPER SIDE RETAINER RH	1	115.1000	X 115.10
50	REAR BUMPER CLIPS	6	4.3000	X 25.80
51	DOOR CENTRE B PILLAR	1	332.3000	X 332.30
52	DOOR CENTRE B PILLAR MATT BLACK TAPE	1	31.5000	all 31.50
53	REAR WINDSHIELD GLASS WEATHERSTRIP	1	120.0000	X 120.00
54	LESS 25% ON ITEM 1 - 57	1	-3,888.1000	-3,888.10
55	FRONT WHEEL TYRE RH	1	250.0000	X 250.00
56	FRONT WHEEL RIM RH	1	550.0000	ent 550.00
57	REAR WHEEL TYRE RH	1	250.0000	X 250.00
58	REAR WHEEL RIM RH	1	550.0000	ent 550.00
59	REAR WINDSCREEN GLASS SEALANT	1	100.0000	X 100.00
60	REAR WINDSCREEN GLASS SPONGE	1	120.0000	X 120.00
61	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	120.0000	X 120.00
62	TO TRANSFER OF REAR TYRE, RIM AND ON WHEEL BALANCING	1	100.0000	60 100.00
63	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	120.0000	80 120.00
64	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	60 150.00
65	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000	60 120.00
66	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	100.0000	30 100.00

C/F 0.00
Page 3 of 4

PEGASUS **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :

Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
--

Quotation No. : QO18/07-1227	Quotation Date : 17/07/2018	Terms : 30 DAYS
Vehicle No. : SLP7835K	Chassis No. : MHFB29F3502011948	Third Party Insurer :
Model : VIOS	Date of Accident : 17/07/2018	
Remarks : INSURED'S VEH NO: SKW7425K		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
67	TO TRANSFER OF FRONT AND REAR RH DOOR FITTINGS, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	180.0000	120 180.00
68	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,200.0000	800 1,200.00
69	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,400.0000	1200 1,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanjun 97495749
 'wp'
 24/7/18 @ 1240
 Resurvey before paint
 sure 1/18/18
 8 days

Sub Total	16,974.30
GST(7.00%)	1,188.20
Total (SGD)	18,162.50

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLP7835K
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NRX159110
Chassis No.:	MHFB29F3502011948
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,744.00
Original Registration Date:	19 Jun 2017
First Registration Date:	19 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$7,744.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2027
PARF Rebate Amount:	\$5,808.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$41,280.00
Total Rebate Amount:	\$47,088.00

The information contained herein is correct as at 18 Jul 2018

OK

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 29 November 2019 10:53 AM
To: Pauline Ngu
Cc: Pegasus Engineering; Lionel Chua; Soon Tat Ng; lohcl.pegasusengrg; Admin A
Subject: RE: LOD - Third party claim - Our ref: SLP7835K Your ref: SKW7425K on 17/07/2018 ***
LKK REF: CC6/AIG18013610/T1kb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We append below our Insured's sketch and statement:

SKETCH PLAN



Circumstances of Accident

THE TRAFFIC AHEAD WAS JAMMED. I CHECKED THAT THE TRAFFIC ON THE LEFT WAS CLEAR SO I SIGNED AND STARTED TO FILTER TO THE LEFT LANE. MY CAR WAS ALMOST 3/4 INTO THE LEFT LANE WHEN CAR B DROVE PAST MY CAR AND GRAZED INTO THE LEFT FRONT CORNER OF MY CAR. WHEN CAR B DROVE PAST, IT WAS IN BETWEEN THE LEFT AND THE LEFT MOST LANE.

We propose settlement as follows on a 50% basis without admission of liability and on a without prejudice basis:

1. Cost of Repair (w/GST)	\$ 5,565.28
2. Loss of Rental/ Loss of Income (11 days x \$100)	\$ 1,100.00
Total	6,665.28
50%	3,332.64
3.LTA Search Fee	\$ 7.49
Total	\$ 3,340.13

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 25 November 2019 11:19 AM
To: Pauline Ngu <pauline.pegasusengrg@gmail.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>; Lionel Chua <lionelchua@pegasusengrg.com.sg>; Soon Tat Ng <ngsoontat@vendaengrg.com.sg>; lohcl.pegasusengrg <lohcl.pegasusengrg@gmail.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: LOD - Third party claim - Our ref: SLP7835K Your ref: SKW7425K on 17/07/2018 *** LKK REF: CC6/AIG18013610/T1kb3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Khanchna,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pauline Ngu <pauline.pegasusengrg@gmail.com>
Sent: Monday, 25 November, 2019 10:42 AM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>; Lionel Chua <lionelchua@pegasusengrg.com.sg>; Soon Tat Ng <ngsoontat@vendaengrg.com.sg>; lohcl.pegasusengrg <lohcl.pegasusengrg@gmail.com>
Subject: LOD - Third party claim - Our ref: SLP7835K Your ref: SKW7425K on 17/07/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

Refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf.

Please inform us the officer in charge as well.

Kindly let me know if you need any hard copy for the LOD, if not we will be sending by email only. Kindly advise.

Thank You

Best Regards,
Pauline
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Office: 65137748
Fax: 62513161

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 25 November 2019 11:19 AM
To: Pauline Ngu <pauline.pegasusengrg@gmail.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>; Lionel Chua <lionelchua@pegasusengrg.com.sg>; Soon Tat Ng <ngsoontat@vendaengrg.com.sg>; lohcl.pegasusengrg <lohcl.pegasusengrg@gmail.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: LOD - Third party claim - Our ref: SLP7835K Your ref: SKW7425K on 17/07/2018 *** LKK REF: CC6/AIG18013610/T1kb3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Khanchna,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pauline Ngu <pauline.pegasusengrg@gmail.com>
Sent: Monday, 25 November, 2019 10:42 AM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>; Lionel Chua <lionelchua@pegasusengrg.com.sg>; Soon Tat Ng <ngsoontat@vendaengrg.com.sg>; lohcl.pegasusengrg <lohcl.pegasusengrg@gmail.com>
Subject: LOD - Third party claim - Our ref: SLP7835K Your ref: SKW7425K on 17/07/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

Refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf.

Please inform us the officer in charge as well.

Kindly let me know if you need any hard copy for the LOD, if not we will be sending by email only. Kindly advise.

Thank You

Best Regards,
Pauline
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Office: 65137748
Fax: 62513161

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 29 November 2019 10:53 AM
To: Pauline Ngu
Cc: Pegasus Engineering; Lionel Chua; Soon Tat Ng; lohcl.pegasusengrg; Admin A
Subject: RE: LOD - Third party claim - Our ref: SLP7835K Your ref: SKW7425K on 17/07/2018 ***
LKK REF: CC6/AIG18013610/T1kb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We append below our Insured's sketch and statement:

SKETCH PLAN



Circumstances of Accident

THE TRAFFIC AHEAD WAS JAMMED. I CHECKED THAT THE TRAFFIC ON THE LEFT WAS CLEAR SO I SIGNALLED AND STARTED TO FILTER TO THE LEFT LANE. MY CAR WAS ALMOST 3/4 INTO THE LEFT LANE WHEN CAR B DROVE PAST MY CAR AND GRAZED INTO THE LEFT FRONT CORNER OF MY CAR. WHEN CAR B DROVE PAST, IT WAS IN BETWEEN THE LEFT AND THE LEFT MOST LANE.

We propose settlement as follows on a 50% basis without admission of liability and on a without prejudice basis:

1. Cost of Repair (w/GST)	\$ 5,565.28
2. Loss of Rental/ Loss of Income (11 days x \$100)	\$ 1,100.00
Total	6,665.28
50%	3,332.64
3.LTA Search Fee	\$ 7.49
Total	\$ 3,340.13

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 13 March 2020 10:59 AM
To: 'Alexx Kuah'
Cc: pauline.pegasusengrg; Hsiao Tong (LKKAuto); Admin A
Subject: RE: Peg Ref:VSR18-24972 AIG Ref:CC6/AIG18013610/T1kb3 Accident Involving SLP7835K(GRAB) & SKW7425K(AIG) On 17.07.2018
Attachments: AIG DV.pdf

WITHOUT PREJUDICE

Dear Sir/Madam,

Thank you for the acceptance.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alexx Kuah <alex.pegasusengrg@gmail.com>
Sent: Wednesday, 11 March 2020 9:28 AM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: pauline.pegasusengrg <pauline.pegasusengrg@gmail.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: Peg Ref:VSR18-24972 AIG Ref:CC6/AIG18013610/T1kb3 Accident Involving SLP7835K(GRAB) & SKW7425K(AIG) On 17.07.2018

Dear Sir,

We refer to above matter.

We accepted your offer of \$3,340.13



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-041221G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.A.400
Cars for Hire

COMMERCIAL VEHICLE - FLEET
Comprehensive

Certificate No. A 29069766 MKF

Excess : SGD2,000

1. Index Mark and Registration Number of Vehicle
SLP7835K

2. Name of Policyholder
Grab Rentals Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act
01/02/2018

4. Date of Expiry of Insurance
31/01/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Chief Executive Officer

JLGS201801281447

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2018 Edit Reg		24 Jul 2018 00:00 Edit Adj Rpt	S\$5,201.20 Edit Estimates	S\$5,201.20 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SIS TECHNOLOGIES (THAILAND) PTE. LTD, Co. Reg. No.: 200517099C		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLP7835K	Date of Loss:	17/07/2018 09:00 - :59 [12 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7369102098SG	Policy/Cover Note No.:	2100437775 (Comprehensive)
Vehicle Reg. No. (Insured):	SKW7425K	Policy No. (Claimant):	A29069766MKF
		Excess:	
Repairer:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road, 628800 Pioneer - Tel: 65137751		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/08/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP7835K (7369102098SG)

[SKW7425K]

TP

GRAB RENTALS PTE LTD

Jul 17 2018 9:00AM

[SIS TECHNOLOGIES (THAILAND) PTE. LTD]

Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser		
Letters/Correspondences											1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown										Edit	
Photos/Images											3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	18/10/19 13:38	General View										Load JPG	☒
2	18/10/19 13:38	Chassis Number										Load JPG	☒
3	18/10/19 13:38	General View										Load JPG	☒
4	18/10/19 13:38	General View										Load JPG	☒
5	18/10/19 13:38	General View										Load JPG	☒
6	18/10/19 13:38	General View										Load JPG	☒
7	18/10/19 13:38	General View										Load JPG	☒
8	18/10/19 13:38	General View										Load JPG	☒
9	18/10/19 13:38	General View										Load JPG	☒
10	18/10/19 13:38	General View										Load JPG	☒
11	18/10/19 13:38	General View										Load JPG	☒
12	18/10/19 13:38	General View										Load JPG	☒
13	18/10/19 13:38	General View										Load JPG	☒
14	18/10/19 13:38	General View										Load JPG	☒
15	18/10/19 13:38	General View										Load JPG	☒
16	18/10/19 13:38	General View										Load JPG	☒
17	18/10/19 13:38	General View										Load JPG	☒
18	18/10/19 13:38	General View										Load JPG	☒
19	18/10/19 13:38	General View										Load JPG	☒
20	18/10/19 13:38	General View										Load JPG	☒
21	18/10/19 13:38	General View										Load JPG	☒
22	18/10/19 13:38	General View										Load JPG	☒
23	18/10/19 13:38	General View										Load JPG	☒
24	18/10/19 13:38	General View										Load JPG	☒
25	18/10/19 13:38	General View										Load JPG	☒
26	18/10/19 13:38	General View										Load JPG	☒
27	18/10/19 13:38	General View										Load JPG	☒
28	18/10/19 13:38	General View										Load JPG	☒
29	18/10/19 13:38	General View										Load JPG	☒
30	18/10/19 13:38	General View										Load JPG	☒
31	18/10/19 13:38	General View										Load JPG	☒
32	18/10/19 13:38	General View										Load JPG	☒
33	18/10/19 13:38	General View										Load JPG	☒
34	18/10/19 13:38	General View										Load JPG	☒
35	18/10/19 13:38	General View										Load JPG	☒
36	18/10/19 13:38	General View										Load JPG	☒
37	18/10/19 13:38	General View										Load JPG	☒
38	18/10/19 13:38	General View										Load JPG	☒
39	18/10/19 13:38	General View										Load JPG	☒
40	18/10/19 13:38	General View										Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	18/10/19 13:38	General View	 Load JPG	☒
42	18/10/19 13:38	General View	 Load JPG	☒
43	18/10/19 13:38	General View	 Load JPG	☒
44	18/10/19 13:38	General View	 Load JPG	☒
45	18/10/19 13:38	General View	 Load JPG	☒
46	18/10/19 13:38	General View	 Load JPG	☒
47	18/10/19 13:38	General View	 Load JPG	☒
48	18/10/19 13:38	General View	 Load JPG	☒
49	18/10/19 13:38	General View	 Load JPG	☒
50	18/10/19 13:38	General View	 Load JPG	☒
51	18/10/19 13:38	General View	 Load JPG	☒
52	18/10/19 13:38	General View	 Load JPG	☒
53	18/10/19 13:38	General View	 Load JPG	☒
54	18/10/19 13:38	General View	 Load JPG	☒
55	18/10/19 13:38	Reinspection Photo	 Load JPG	☒
56	18/10/19 13:38	Reinspection Photo	 Load JPG	☒
57	18/10/19 13:38	Reinspection Photo	 Load JPG	☒
58	18/10/19 13:38	Reinspection Photo	 Load JPG	☒
59	18/10/19 13:38	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/18 19:06	TP ESTIMATE- MARKED	 Load PDF	
2	26/07/18 19:06	TP GIA REPORT	 Load PDF	
3	02/09/19 17:41	LETTER TO OI	 Load PDF	
4	20/03/20 09:04	WORKSHOP INVOICE	 Load PDF	
5	20/03/20 09:04	AUTHORISATION TO ACT FORM	 Load PDF	
6	20/03/20 09:04	Release Voucher	 Load PDF	
7	20/03/20 09:04	RENTAL RATES	 Load PDF	
8	20/03/20 09:04	LTA SEARCH	 Load PDF	
9	20/03/20 09:04	LOD	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/07/18 11:43	OI GIA REPORT	 Load PDF	
2	04/12/19 15:43	OI letter to LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SKW7425K (Insd veh)	Model:	TOYOTA VIOS 1.5 E CVT (A)
	SLP7835K (TP veh)		
Date of Accident:	17/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	18,162.50
Final Repair Cost	:	\$	2,782.64
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	550.00 11 days
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,340.13
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability <u>50</u> (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	:	\$ 3,340.13
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

20 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18013610/T1KS3Q2

Date: 20/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100437775
Claimant
Vehicle No : SLP7835K **Insured Vehicle No :** SKW7425K
Date of Loss: 17/07/2018 **Nature of Claim:** TP **Claim No:** 7369102098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP7835K
 Make & Model: TOYOTA VIOS, 1.5 E CVT (A) Engine No: 2NRX159110
 Reg. Date: 19/06/2017 (Man. Year: 2017) Chassis No: MHFB29F3502011948
 Colour: Silver Odometer: 92028 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,484.30	2,791.20	10,693.10	79.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	2,410.00	1,080.00	30.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,974.30	5,201.20	11,773.10	69.36
+ GST 7.00/7.00% (S\$)	1,188.20	364.08	824.12	69.36
Nett Amount (S\$)	18,162.50	5,565.28	12,597.22	69.36
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
		(S\$) 6,665.28		
Liabile Amount (50.00%) (S\$)		3,332.64		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,340.13		

INSPECTION

Date of Assignment: 24/07/2018
 Date Inspected: 24/07/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (Kian Teck)
 74 Kian Teck Road
 Singapore 628800

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR SIDE MIRROR ASSY	Repair	1,212.70 FL	*- FL
2	1		*FRONT DOOR RH	Bent	1,090.60 FL	*1,090.60 FL
3	1		*FRONT DOOR HINGE TOP	Repair	82.10 FL	*- FL
4	1		*FRONT DOOR HINGE BOTTOM	Repair	92.10 FL	*- FL
5	1		*FRONT DOOR CHECKER/ARRESTOR	Repair	153.50 FL	*- FL
6	1		*FRONT DOOR POWER WINDOW MOTOR	Not Necessary	690.20 FL	*- FL
7	1		*FRONT DOOR REGULATOR	Not Necessary	230.20 FL	*- FL
8	1		*FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	Not Necessary	96.90 FL	*- FL
9	1		*FRONT DOOR OUTER WEATHERSTRIP MOULDING	Not Necessary	46.50 FL	*- FL
10	1		*FRONT DOOR RUBBER STOPPER	Not Necessary	18.20 FL	*- FL
11	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	199.10 FL	*- FL
12	1		*FRONT FENDER RH	Bent	612.50 FL	*612.50 FL
13	1		*FRONT FENDER INNER COWLING RH	Deformed	185.00 FL	*185.00 FL
14	4		*FRONT FENDER INNER COWLING CLIP	Necessary	17.20 FL	*17.20 FL
15	1		*FRONT FENDER 1/4 GARNISH TOP	Not Necessary	30.70 FL	*- FL
16	1		*FRONT SHOCK ABSORBER	Not Necessary	378.70 FL	*- FL
17	1		*FRONT SHOCK ABSORBER TOP MOUNT	Not Necessary	65.00 FL	*- FL
18	1		*FRONT WHEEL BEARING WITH HUB	Not Necessary	498.20 FL	*- FL
19	1		*FRONT WHEEL KNUCKLE	Not Necessary	549.60 FL	*- FL
20	1		*FRONT LOWER ARM	Not Necessary	1,021.10 FL	*- FL
21	1		*ROCKER PANEL	Repair	332.30 FL	*- FL
22	1		*REAR DOOR RH	Bent	891.80 FL	*891.80 FL
23	1		*REAR DOOR OUTER WEATHERSTRIP MOULDING	Not Necessary	96.90 FL	*- FL
24	1		*REAR DOOR 1/4 GLASS PILLAR	Not Necessary	119.30 FL	*- FL
25	1		*REAR DOOR 1/4 GLASS PILLAR WEATHERSTRIP	Not Necessary	98.60 FL	*- FL
26	1		*REAR DOOR INNER LOCK	Not Necessary	483.40 FL	*- FL
27	1		*REAR DOOR LOCK STRIKER	Not Necessary	37.60 FL	*- FL
28	1		*REAR DOOR WEATHERSTRIP	Not Necessary	174.40 FL	*- FL
29	1		*REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	Not Necessary	73.60 FL	*- FL
30	1		*REAR DOOR WINDOW FRAME STICKER MATT	Necessary	46.50 FL	*46.50 FL
31	1		*REAR DOOR WINDOW FRAME STICKER FRONT	Necessary	46.50 FL	*46.50 FL
32	1		*REAR DOOR POWER WINDOW MOTOR	Not Necessary	590.20 FL	*- FL
33	1		*REAR DOOR REGULATOR	Not Necessary	183.60 FL	*- FL
34	1		*REAR DOOR INNER TRIMBOARD		539.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
35	1		*REAR DOOR HINGE TOP	Repair	38.00 FL	*- FL
36	1		*REAR DOOR HINGE BOTTOM	Repair	38.00 FL	*- FL
37	1		*REAR DOOR CHECKER /ARRESTOR	Not Necessary	153.50 FL	*- FL
38	1		*REAR FENDER RH	Repair	969.60 FL	*- FL
39	1		*REAR FENDER INNER COWLING RH	Not Necessary	395.10 FL	*- FL
40	4		*REAR FENDER INNER COWLING CLIPS	Not Necessary	17.20 FL	*- FL
41	1		*REAR FENDER 1/4 GARNISH	Not Necessary	54.70 FL	*- FL
42	1		*REAR SHOCK ABSORBER	Not Necessary	378.70 FL	*- FL
43	1		*REAR WHEEL BEARING WITH HUB	Not Necessary	492.80 FL	*- FL
44	1		*REAR WHEEL KNUCKLE	Not Necessary	221.40 FL	*- FL
45	1		*FRONT BUMPER	Repair	588.10 FL	*- FL
46	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	65.70 FL	*- FL
47	6		*FRONT BUMPER CLIPS	Not Necessary	25.80 FL	*- FL
48	1		*REAR BUMPER	Repair	504.90 FL	*- FL
49	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	115.10 FL	*- FL
50	6		*REAR BUMPER CLIPS	Not Necessary	25.80 FL	*- FL
51	1		*DOOR CENTRE B PILLAR	Not Necessary	332.30 FL	*- FL
52	1		*DOOR CENTRE B PILLAR MATT BLACK TAPE	Necessary	31.50 FL	*31.50 FL
53	1		*REAR WINDSHIELD GLASS WEATHERSTRIP	Not Necessary	120.00 FL	*- FL
54	1		*FRONT WHEEL TYRE RH	Not Necessary	250.00 FS	*- FS
55	1		*FRONT WHEEL RIM RH	Cut	550.00 FS	*300.00 FS
56	1		*REAR WHEEL TYRE RH	Not Necessary	250.00 FS	*- FS
57	1		*REAR WHEEL RIM RH	Cut	550.00 FS	*300.00 FS
58	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
59	1		*REAR WINDSCREEN GLASS SPONGE	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,372.40	3,521.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,888.10	730.40
Total Parts (\$\$)	13,484.30	2,791.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	0.00
2	TO TRANSFER OF REAR TYRE ,RIM AND ON WHEEL BALANCING	New	100.00	60.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	120.00	80.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS,GARNISH AND OTHER ,TO ENABLE REPAIR	New	150.00	60.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	60.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	30.00
7	TO TRANSFER OF FRONT AND REAR RH DOOR FITTINGS ,FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	New	180.00	120.00
8	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,200.00	800.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	1,200.00
Gross Labour Cost (S\$)			3,490.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >