COMFORTDELGRO ENGINEERING PTE LTD

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 8783X

MAKE

MODEL: MERCEDES BENZ

WHOLE LEAST SIDE

VS

Qty	Parts Description/ Labour	Type	Unit Price	Amount	_
	Rear Door (LH)			\$ 2,870.00	
	Rear Door Outer Handle (LH)			\$ 88.15	1
	Door Shell ,Frt,LH			\$ 2,970.00	+1
	SUB TOTAL			\$ 5,928.15	1
	LESS 20%			\$ 1,185.63	
	DISCOUNTED TOTAL			\$ 4,742.52	
	Rear Door Comfort Limo Cab Logo			\$ 60.00	No
	Labour Charge Panel Beating Spray Painting Charge-Fender/ 2x Door			\$ <u>500.00</u> \$ 75 0.00	46
	Tuff Kote		42000		1.
	Transfer Of Door		\$ 120.00	\$ 240.00	1
	TOTAL LABOUR			\$ 1,540.00	
	ESTIMATE TOTAL		LIVI A. A. O	\$ 6,342.52	-
		- 1	LKK Auto Consultants he the Repairer of the follow	vina:	
			• To resurvey before/after spra	painting	
	NAZ LKIC		To display damaged pair(s) o Parts prices are subject to or		
	25/7/18 1550		• Third party survey and a "W	thout rejudice" basis	
	US		No illegal modificate s) is a Supplementary item aust	pe resurveyed and	
	US			m Insurance Company	,
	3 DAYS OFTER REPOR PHOTO		Acknowledged by Repairer		
	- CO 0 PING	1	Signature:		
	OFFTER RELITIK (1010	L	- Committee		-
				75.0	
	This is an initial estimate based on a visual inspection of the	e ahove ve	hicle. The final repair		1
	quantum will be prepared after the vehicle is surveyed by a				