

ASS. REC. BY:

REF: CS/FCI 18013646 / K9d3

Special Instruction:

Surveyor:

CWS

From (Person):

Kenneth
Serene Ler

ASSIGNMENT (Office)

of FCI

Date/Time:

26/7/18 @ 9:11am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JM 5232C

Insured:

SHD 68591

at Workshop m/s

Boeki Auto

Tel:

64521574

of

Blk 10, Sin Ming Ind. Est & Co-C # 01-12

Policy No:

Claim No:

D18005652MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/07/2018

CA / REV / REP. / REV 24 HRS

'DS'

31/07/18 @

After 11am

H.O.D. Endorsement:

Date/Time:

10:28am 26/7/18

Person Contacted:

Anna

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

8JM 5232C - X

SHD 68591 - NS/INC 18010232 / K/vbn2

DOA: 5/6/18

01/8/18 @ 2:27pm revised to Serene Ler by email.

31/8 11am @ 1450t 1450t Confirm (Red @ 2623.20, 64%)

(08/11/13) wef

REF:

FCI

ASS. REC. BY:

ASSIGNMENT

From:

Date:

31/07/2018

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJM 5232C

at Workshop m/s

Boeki Auto

of

Blk 10, Sin Ming Ind Est Sec C # 0142

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

810k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJM 5232C

Yr Regn:

01 / 09

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vio

c.c

1497

Colour:

M. Gold

A/C:

Insured / Std / NI / NA

Sp. Reading

93182

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053HY 930 509 3273

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

24/7/18

D.O.I.

31/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/8 Acc report to Germaine

RECEIVED 05 SEP 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 05/9 minor

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

78

1450

135

50

80+50

15

300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013646/Kqd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 26-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6859J	Veh. Inspected	SJM 5232C
Policy No.		Coverage (\$)	0.00
Claim No.	D1805652MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	26/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/07/2018	Inspection Date	31/07/2018
Survey held at	BOEKI AUTO PTE LTD BLK 176 SIN MING DRIVE #02-15 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005652MFSH

Date: 01 August 2018

Our Ref: CS/FCI18013646/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJM 5232C.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/07/2018 at the premises of M/s BOEKI AUTO. and have the following to report:-

Workshop Estimate Amount	: S\$ 4,073.20 .
Revised Estimate Amount	: S\$ 1,465.05 .
"Check" Items Amount	: S\$ 1,847.85 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the rear o/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	25-07-2018	Our Ref No. D18005652MFSH
Accident Date	24-07-2018	Claim Type. Third Party
Insured Vehicle	SHD6859J	Third Party Vehicle. SJM5232C
Survey Location	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-12	
Contact Person.	ANNA CHUA	
Contact No.	64521574/ 98766876	Fax No. 64521576
Survey Type	DIRECT SETTLEMENT: EST. COR \$4,073.20	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BOEKI AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242685)



PRI Documents



Close



PRI Header Details

Claim No	D18005652MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & BOEKI AU PTE LTD / ON
Workshop Name	BOEKI AUTO PTE LTD (Contact Person : ANNA CHUA)	Survey Location & Contact Details	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-01 Mobile: 98766876 , Phone: 64521574 , Fax: 64521574 EmailId: CLAIMS.BOEKI@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR \$4,073.20		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6859J	TP Vehicle No	SJM5232C
PRI Recieved Date	25-07-2018 07:11:20 PM	Surveyor Appointed Date	26-07-2018 09:10:26 AM	Surveyor Accept Date	26-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-07-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 1 August 2018 2:27 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005652MFSH/1
Attachments: CSFCI18013646Kqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SJM 5232C.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 26 July 2018 10:30 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005652MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 26 July 2018 9:11 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005652MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

[> Back to OneMotoring](#)


Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 25 Jul 2018 / 10:53:54

Receipt Date/Time : 25 Jul 2018 / 10:53:54

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180725-000617

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SHD6859J

As at 24 Jul 2018/08:55:00

Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED

1 Insurance Enquiry - SHD6859J

Enquiry Fee

20180725105256910594

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

TP Search for SJM5232C

TP18-020

Paid By

xxxxxxxxxxxx8261

Credit Card:

Visa/MasterCard

7.45

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9171M
Vehicle Details	
Vehicle No.:	SJM5232C
Vehicle to be Exported:	No
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Beige
Manufacturing Year:	2008
Engine No.:	1NZX840981
Chassis No.:	MR053HY9305093273
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,900.00
Original Registration Date:	07 Jan 2009
First Registration Date:	07 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$3,220.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jan 2019
PARF Rebate Amount:	\$1,610.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$498.00
COE Rebate Amount:	\$332.00
Total Rebate Amount:	\$1,942.00

The information contained herein is correct as at 01 Aug 2018

OK



[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

9171M

Vehicle Details

Vehicle No.:

SJM5232C

Vehicle to be Exported:

No

Intended De-registration Date:

24 Jul 2018

Vehicle Make:

TOYOTA

Vehicle Model:

VIOSE AUTO

Primary Colour:

Beige

Manufacturing Year:

2008

Engine No.:

1NZX840981

Chassis No.:

MR053HY9305093273

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$11,900.00

Original Registration Date:

07 Jan 2009

First Registration Date:

07 Jan 2009

Transfer Count:

1

Actual ARF Paid:

\$3,220.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

06 Jan 2019

PARF Rebate Amount:

\$1,610.00

Intended COE Rebate Details

COE Expiry Date:

06 Jan 2019

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$498.00

COE Rebate Amount:

\$348.00

Total Rebate Amount:**\$1,958.00**

The information contained herein is correct as at 24 Jul 2018.





Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5085545183-01

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: SJM5232C

Chassis Number

: MR053HY9305093273

2. Name of Policyholder

: CARGURU PTE. LTD.

3. Effective Date of Insurance

: 15 May 2018

4. Expiry Date of Insurance

: 14 May 2019

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use for the carriage of goods (other than samples) in connection with any trade or business.

(c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: S\$1,500
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: N/A
NCD PROTECTION	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : COWELL INSURANCE (AGENCY) PTE LTD (00000610380)

Date of Issue : 11 Oct 2017 11:24 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

BUSINESS PROFILE



REQUEST CRITERIA

(You have requested to search on the following)

Date of Request :	20/06/2018
Name of Requestor :	BOEKI AUTO PTE. LTD.
Requested Entity Name :	CARGURU PTE. LTD.
Requested Entity Number :	201209171M
File Reference Number :	

SEARCH RECORD

Entity Name :	1) CARGURU PTE. LTD.
Entity Number :	201209171M

ACCOUNTING AND CORPORATE REGULATORY AUTHORITY
BUSINESS PROFILE (COMPANY)



WHILST EVERY ENDEAVOUR IS MADE TO ENSURE THAT THE INFORMATION PROVIDED IS UPDATED & CORRECT, THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

DETAILS OF COMPANY

Entity Name:	CARGURU PTE. LTD.
Entity Number:	201209171M
Date Of Registration (dd/mm/yyyy):	13/04/2012
Country Of Incorporation:	SINGAPORE
Date Of Change Of Name:	-
Former Name:	-
Type Of Company:	EXEMPT PRIVATE COMPANY LIMITED BY SHARES
Registered Office Address:	178 SIN MING DRIVE #02-15 SIN MING AUTOCARE SINGAPORE 575721
Date Of Change Of Address:	13/04/2012
Principal Activity / Activities:	1)RENTING AND LEASING OF PRIVATE CARS WITHOUT OPERATOR (77101) 2)PASSENGER LAND TRANSPORT N.E.C. (EG PRIVATE CARS FOR HIRE WITH OPERATOR AND TRISHAWS) (49219)
Status:	LIVE COMPANY
Status Date:	13/04/2012

CAPITAL STRUCTURE

Capital Structure:	No. Of Shares	Currency	Amount
ISSUED ORDINARY	100,000.00	SINGAPORE DOLLARS	15,000.00
PAID-UP ORDINARY	-	SINGAPORE DOLLARS	15,000.00

Note: The number of shares is displayed up to two decimal points.

CHARGE(S)

AUDITOR(S)

Name	Date Of Appointment
------	---------------------

OFFICER(S) / AUTHORISED REPRESENTATIVE(S)

Name ID	Address Date Of Change Of Address	Nationality	Date Of Appointment/ Position Held
NG JUN QUAN (HUANG JUNQUAN) 577127068	2 BISHAN STREET 25 #11-05 CLOVER BY THE PARK SINGAPORE 573973 11/10/2017	SINGAPORE CITIZEN	13/04/2012 DIRECTOR

SHAREHOLDER(S)

(Entity Numbers Prefixed with UF Or AGRA are Numbers allotted by AGRA for Purpose of Identification)

Name ID	Nationality	Address Date Of Change Of Address
NG JUN QUAN (HUANG JUNQUAN) 577127068	SINGAPORE CITIZEN	2 BISHAN STREET 25 #11-05 CLOVER BY THE PARK SINGAPORE 573973 11/10/2017
Type	No Of Shares	Currency
ORDINARY	100,000.00	SINGAPORE, DOLLARS

Note: The number of shares is displayed up to two decimal points.

COMPLIANCE RECORD

Date Of Last AGM:	30/09/2017
Date Of Last AR:	10/10/2017
Date Of A/C Laid At Last AGM:	31/12/2016

THE ABOVE INFORMATION IS UPDATED TO 01 DAY FROM 20/06/2018

PLEASE NOTE THAT THE INFORMATION HEREIN CONTAINED IS EXTRACTED FROM FORMS FILED WITH THE AUTHORITY

THIS REPORT MUST NOT BE COMMUNICATED TO THE PERSON/S OR FIRM/S REPORTED ON, OR TO ANY OTHER PARTY. It is furnished by DP Information Network Pte Ltd (URN 1983026536) ("DP Info") in STRICT CONFIDENCE at your request for your exclusive use. In accepting this report you hereby agree to be responsible for all damages arising from a violation or breach of the above confidentiality obligation. This report is not intended to be used as the sole basis for any business decision and is based upon data which is provided by third parties, the accuracy or completeness of which it is not possible for DP Info to check. DP Info shall not be liable for any loss or injury caused by your use or disclosure of this report. For any questions regarding this report, please contact the Customer Service unit at +65 6320 1900 or via email at cs@dpgroup.com.sg. DP Info is part of the Experian Group, www.dpgroup.com.sg.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8014015J**

Name: **ONG KOK YONG, EDDY (WANG GUORONG, EDDY)**

Date of Birth: **18 May 1980**

Issue Date: **05 Aug 2016**

002595989A




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8014015J

Name: **ONG KOK YONG, EDDY (WANG GUORONG, EDDY)**

王 握 漢

Race: **CHINESE**

Date of birth: **18-05-1980**

Country/Place of birth: **SINGAPORE**

Sex: **M**

S8014015J





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ 31 Jan 2001

Licence No: S8014015J

NP 428A



5455021

NRIC No. S8014015J

Date of issue: **16-04-2015**

Address: **APT BLK 350 YISHUN AVENUE 11 #06-235 SINGAPORE 760350**







PLEASE ARRANGE TO SURVEY VEHICLE AT
BLK 10 SIN MING IND ESTATE SECTOR C
#01-12
SINGAPORE 575645

Anna Chua

BOEKI AUTO PTE LTD

TEL: 6452 1574

FAX: 6452 1576

H/P: 9876 6876

Date : 25.07.2018

To : FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

Owner : CARGURU PTE LTD

Owner Insurance : NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Certificate Number : 5085545183-01

Vehicle Number : SJM5232C

Make & Model : TOYOTA VIOS E AUTO

*Not Withheld
61 Sep 814501*

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Accident Date 24.07.2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	BOOTLID	REPAIR	
1	BOOTLID LOGO	\$ 95.90	✓
1	BOOTLID EMBLEM "VIOS"	\$ 91.40	✓
1	BOOTLID EMBLEM "E"	\$ 92.80	✓
1	TAILLAMP RH	\$ 289.60	X
1	TAILLAMP LOWER BRACKET RH	\$ 75.90	X
1	REAR FENDER RH	REPAIR	
10	REAR FENDER INNER SHIELD CLIPS RH	\$ 50.00	X
1	REAR BUMPER	\$ 341.70	✓
1	REAR BUMPER RETAINER (INNER) LH	\$ 69.20	X
1	REAR BUMPER RETAINER (OUTER) LH	\$ 96.80	X
1	REAR BUMPER RETAINER (INNER) RH	\$ 69.20	X
1	REAR BUMPER RETAINER (OUTER) RH	\$ 96.80	X
1	REAR BUMPER BRACKET RH	\$ 92.70	X
1	REAR BUMPER REFLECTOR RH	\$ 121.60	✓
10	REAR BUMPER CLIPS	\$ 50.00	✓
1	REAR END PANEL	\$ 435.50	X
1	REAR END PANEL TOP GARNISH	\$ 198.50	X
6	REAR END PANEL TOP GARNISH CLIPS	\$ 30.00	X
Sub Total		\$ 2,297.60	
Discount 25% on Parts		\$ 574.40	
		\$ 1,723.20	

PAGE : 1

Date : 25.07.2018

To : FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

Owner : CARGURU PTE LTD

Owner Insurance : NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Certificate Number : 5085545183-01

Accident Date 24.07.2018

Vehicle Number : SJM5232C

Make & Model : TOYOTA VIOS E AUTO

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
Special Nett Item			
1	REVERSE SENSOR	<i>Ref</i> \$ 220.00	<i>200.00</i>
1	REAR END PANEL SEALANT	<i>nv</i> \$ 50.00	<i>X</i>
Sub Total		\$ 270.00	
Labour & Misc			
1	LABOUR TO FACILIATE REPAIR	<i>(-360)</i> \$ 800.00	<i>360</i>
1	R & R REVERSE SENSOR	\$ 60.00	<i>7 (to confirm)</i>
1	R & R REAR FENDER INNER TRIM RH, CARPETS & TRIM	\$ 180.00	<i>50</i>
1	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	\$ 60.00	<i>50</i>
1	TO RUST PROOF ON AFFECTED AREAS	<i>nv</i> \$ 80.00	<i>200</i>
1	TO SPRAY PAINT ON AFFECTED AREAS	\$ 900.00	<i>X</i>
Sub Total		\$ 2,080.00	<i>600</i>
Grand Total		\$ 4,073.20	

PAGE : 2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013646/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6859J	Veh. Inspected	SJM 5232C	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005652MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	26/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305093273	Colour	METALLIC GOLD	
Odometer	93182	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R14	YOKOHAMA	7 mm	
L/H Front Tyre	185/60 R14	YOKOHAMA	7 mm	
R/H Rear Tyre	185/60 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R14	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2018	Inspection Date	31/07/2018	
Survey held at	BOEKI AUTO PTE LTD BLK 176 SIN MING DRIVE #02-15 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 5232C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
1	BOOTLID LOGO	NECESSARY	95.90	95.90
1	BOOTLID EMBLEM "VIOS"	NECESSARY	91.40	91.40
1	BOOTLID EMBLEM "E"	NECESSARY	92.80	92.80
1	TAILLAMP RH	SERVICEABLE	289.60	-
1	TAILLAMP LOWER BRACKET RH	SERVICEABLE	75.90	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
10	REAR FENDER INNER SHIELD CLIPS RH	NOT NECESSARY	50.00	-
1	REAR BUMPER	BENT	341.70	341.70
1	REAR BUMPER RETAINER (INNER) LH	SERVICEABLE	69.20	-
1	REAR BUMPER RETAINER (OUTER) LH	SERVICEABLE	96.80	-
1	REAR BUMPER RETAINER (INNER) RH	SERVICEABLE	69.20	-
1	REAR BUMPER RETAINER (OUTER) RH	SERVICEABLE	96.80	-
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	92.70	-
1	REAR BUMPER REFLECTOR RH	SCRATCHED	121.60	121.60
10	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	435.50	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	198.50	-
6	REAR END PANEL TOP GARNISH CLIPS	NOT NECESSARY	30.00	-
	LESS 25% DISCOUNT		-574.40	-198.35
			1,723.20	595.05
SPECIAL NETT ITEMS				
1	REVERSES ENSOR (SN)	DENTED	220.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			270.00	200.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR TO FACILITATE REPAIR, INCLUSIVE OF THE REPAIR OF BOOTLID, REAR FENDER RH, REAR BUMPER BRACKET RH AND REAR END PANEL.		800.00	360.00
	R&R REVERSE SENSOR.		60.00	50.00
	R&R REAR FENDER INNER TRIM RH, CARPETS & TRIM.		180.00	50.00
	TO CHECK & RECONNECT ALL NECESSARY WIRINGS.		60.00	20.00
	TO RUST PROOF ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO SPRAY PAINT ON AFFECTED AREAS.		900.00	600.00
			2,080.00	1,080.00
	GRAND TOTAL		4,073.20	1,875.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00

Report Ref No. CS/FCI18013646/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.